

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI19008677/AQD3N2**Date:** 26/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19101519000
Claimant Vehicle No :	GZ1122E	Insured Vehicle No :	YM9496D
Date of Loss:	14/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202162C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ1122E	Engine No:	5L5627702
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFUF34Y903011358
Reg. Date:	13/12/2005 (Man. Year: 2005)	Odometer:	438933 km
Colour:	Silver		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185R14C	Rear Tyre Size:	155R12C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,849.48	6,248.68	12,600.80	66.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,200.00	3,400.00	1,800.00	34.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,049.48	9,648.68	14,400.80	59.88
Approved Total (Overridden) (\$\$)		7,500.00		
Nett Amount (\$\$)	24,049.48	7,500.00	16,549.48	68.81

INSPECTION

Date of Assignment:	07/06/2019	
Date Inspected:	16/05/2019 Inspected At:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	11.0 days	

Adjuster: SHIAU CHAN**Manager:** ADRIAN LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jan 2022)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ1122E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	1,085.00 FL	*1,085.00 FL
2	1		*FRONT WINDSCREEN MOULDING	Necessary	264.11 FL	*264.11 FL
3	1		*FRONT BUMPER	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BUMPER BRACKET	Not Necessary	115.00 FL	*- FL
5	1		*FRONT CORNER PANEL LH	Distorted	315.00 FL	*315.00 FL
6	1		*FRONT WIPER PANEL	Not Necessary	420.00 FL	*- FL
7	1		*FRONT WIPER PANEL LOWER COVER	Missing	145.00 FL	*145.00 FL
8	1		*FRONT WIPER PANEL LOWER SIDE	Missing	160.00 FL	*160.00 FL
9	1		*FRONT PANEL	Not Necessary	1,091.00 FL	*- FL
10	1		*FRONT PANEL LOGO	Not Necessary	70.00 FL	*- FL
11	1		*FRONT HEADLAMP LH	Cracked	655.00 FL	*655.00 FL
12	1		*FRONT HEADLAMP LOWER RUBBER LH	Not Necessary	148.00 FL	*- FL
13	1		*FRONT DASHBOARD	Not Necessary	1,069.70 FL	*- FL
14	1		*FRONT AIRCON BLOWER COOLANT COIL ASSY	Not Necessary	620.00 FL	*- FL
15	1		*FRONT DOOR	Dented	1,980.00 FL	*1,487.00 FL
16	1		*FRONT DOOR HINGE LH	Bent	187.00 FL	*187.00 FL
17	1		*FRONT DOOR CATCH LH	Not Necessary	108.00 FL	*- FL
18	1		*FRONT DOOR OUTER HANDLE LH	Not Necessary	210.00 FL	*- FL
19	1		*FRONT DOOR SIDE MIRROR ASSY	Distorted	756.80 FL	*756.80 FL
20	1		*FRONT DOOR LOCK LH	Not Necessary	327.80 FL	*- FL
21	1		*FRONT DOOR CENTRE LOCK MOTOR LH	Not Necessary	405.50 FL	*- FL
22	1		*FRONT DOOR RUBBER LOWER LH	Not Necessary	71.60 FL	*- FL
23	1		*FRONT DOOR REGULATOR GEAR LH	Not Necessary	250.00 FL	*- FL
24	1		*FRONT DOOR REGULATOR GEAR MOTOR LH	Not Necessary	475.00 FL	*- FL
25	1		*FRONT DOOR SIGNAL LAMP LH	Not Necessary	210.00 FL	*- FL
26	1		*REAR BOOT COVER	Dented	1,837.50 FL	*1,248.00 FL
27	1		*REAR BOOT COVER SIDE BRACKET L LOCK	Bent	220.00 FL	*220.00 FL
28	1		*REAR BOOT COVER SIDE BRACKET RUBBER	Missing	110.00 FL	*50.00 FL
29	1		*REAR BOOT TOYOTA EMBLEM	Necessary	155.00 FL	*155.00 FL
30	1		*REAR BOOT MEMBER	Repair	425.00 FL	*- FL
31	1		*REAR NUMBER PLATE PANEL	Bent	315.00 FL	*182.00 FL
32	1		*REAR NUMBER PLATE LAMP	Not Necessary	295.00 FL	*- FL
33	2		*REAR LAMP LH & RH	Cracked	550.00 FL	*550.00 FL
34	1		*REAR END PANEL (LOWER MEMBER)	Repair	1,341.90 FL	*- FL
35	2		*REAR LOWER MEMBER BRACKET	Repair	290.20 FL	*- FL
36	1		*REAR CHASSIS FRAME (DECK SUPPORT)	Repair	1,659.00 FL	*- FL
37	1		*REAR FLOOR DECKING	Not Necessary	2,079.00 FL	*- FL
38	1		*REAR CHASSIS FRAME U BOLTS	Not Necessary	367.50 FL	*- FL
39	1		*REAR EXHAUST PIPE	Not Necessary	581.00 FL	*- FL
40	1		*REAR EXHAUST PIPE BRACKET	Not Necessary	126.00 FL	*- FL
41	1		*REAR TOW HOCK	Not Necessary	80.20 FL	*- FL
42	1		*REAR BOOT STEP BRACKET	Bent	85.00 FL	*85.00 FL
43	2		*REAR BOOT HINGES LH & RH	Bent	160.00 FL	*160.00 FL
44	2		*REAR BOOT STOPPER PILLAR LH & RH	Repair	420.00 FL	*- FL
45	2		*REAR BOOT STOPPER LH & RH	Repeated	45.00 FL	*- FL
46	1		*FRONT WINDSCREEN ERP STICKER	Necessary	60.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

1/26/22, 1:41 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BOOT STEP BRACKET STAINLESS STEEL	Necessary	590.62 FS	*250.00 FS
48	1		*70KM/H STICKER	Necessary	80.00 FS	*15.00 FS
49	1		*REAR BOOT DYNA STICKER	Necessary	75.00 FS	*30.00 FS
50	1		*REAR BOOT TAILGATE STICKER	Repeated	90.00 FS	*- FS
51	1		*13 PAX STICKER	Necessary	70.00 FS	*15.00 FS
52	1		*SET REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
53	1		*REAR CAR PLATE	Bent	100.00 FS	*30.00 FS
54	1		*SET FRONT BUMPER CLIPS	Not Necessary	100.00 FS	*- FS
55	1		*SET FRONT HEADLAMP RUBBER CLIPS	Not Necessary	80.00 FS	*- FS
56	1		*FRONT WINDSCREEN INNER SEAL	Necessary	100.00 FS	*40.00 FS
57	1		*FRONT WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					24,557.43	8,174.91
- List Item Discount on L Items 25.00/25.00% (\$\$)					5,707.95	1,926.23
Total Parts (\$\$)					18,849.48	6,248.68
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE PARTS	New	2,000.00	1,500.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,600.00	1,300.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS	New	250.00	60.00
4	TO CARRY OUT CHASSIS ALIGNMENT	New	350.00	0.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	270.00	200.00
6	TO REMOVE AND REPLACE REAR EXHAUST PIPE & RE-ALIGN	New	200.00	0.00
7	TO REMOVE AND REPLACE FRONT WINDSCREEN	New	150.00	120.00
8	TO REMOVE AND REFIX FRONT DASHBOARD	New	380.00	220.00
Gross Labour Cost (\$)			5,200.00	3,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >