				07	
3		153		U 3	
* 194gon	î	W		11 M. K or LKK	
	25	CQ /AIG1900	8676,	IDAG	74
INS. CASE OWNER		ASSIGN	MENT	λ	. 1
22/07/2004	Morning	DOI: ASSIGN	1000	Date / Time :	5/5/14
Surveyor:		- 10x - 1 p /	1000	Registered in Merimen:	16/1-114.
Pre-assign / CCU	/FTF			Registered in Merinica	00/0/00
and the same of th	566 6000	DR.		3279144	52954
Insured Vehicle N	0.		Claim No.		0-
Name of Insured	SOH MUN TE	Wa.	Policy No.	n0047055	. 6
Insured Tel No.	9	IP:	Make / Model	: LEXUS	
Excess Sec II :SS		D.O.A: 17519.	Place of Accid	ent upp THON	you to TWOS
Is driver the owner	-	Nature of Accident :		SEMBA.	
	me/Age: UCAN FOF B		OLCIA REBO	RT: YES / NO : TP GIA	PEPOPT: VES / NO
Driver Tel		(V/L: YES / NO)	Insured Liabili		1? Yes/No
		(VIL. TEST NOT)	made a radion	.,	
300 99	<u>*</u>		12		
I INSRS:	A INSRS:		INSRS:		INSRS:
WSP: KIC	WSP:		WSP:		WSP:
Tel:	QO Tel:	. H H	Tel: Liability:	Н Н	Tel: Liability:
RMKS:	RMKS RMKS		RMKS:		RMKS:
\$0.000,000,00		12570	Market Street		
Date/ Time	Mosar - A	5 66	00006-4	STAGE	DATE/PIC
	11(1)			Non-Reporting ltr (1st):	TONOT 1 200
:1:1:	20.2 6 2 10 2			Non-Reporting ltr (2nd):	
معالة	FILE PAU TO HMU TO C	COM		Non-Reporting ltr (Final): Notification ltr (if non-pick	up).
				Call OI:	/
				After call ltr to OI:	
				Documentation Check Lis	t: Handler Typist
				Notification ltr (if non-pick	up)
				After call ltr to OI:	
				Authorisation To Act:	
				Release Voucher: Final Repair Bill:	
				Car Rental Invoice:	
	-			Towing Invoice	
				LTA/GIA:	
				Medical Bill:	
			77555	PIR:	
				Mandate/Reject Instructi	on:
				LOD	
				Payment Breakdown For	m:
RELIMINARY ADVICE	Date/Time:	Sent By:		Post-Repair Photos:	
				Others:	
TNALIZATION	Date/Time:	Confirm with:		Confirm by:	
tepair Cost:	SS (days) Reduction:	%	Email Coll	Call
INAL SETTLEMENT		Confirm with Assessed) BOLA S/N No.: N	11	Email Call If NO or B 28, Ass. Lia	
thal Liability: Lepair Cost:	SS (Agreed / A	tasessed) nOLA 3/N NO. : N	L	II NO OLD 20, ASS, LIS	-1/4
ass of Rental (LOR):	SS (days)			
oss of Use (LOU):		days)		(a)	ENISC
ARREST LANGUE LEADING	SS (S x			Callol XV	EIL
		days)			A 1-0
oss of Income (LOI):	SS (S x SS (S x		one]	CHAIL	No POIN
oss of Income (LOI): OR only LOU only	SS (S x SS (S x y LOR + LOU LO	days)	one]	644	70 PO II
oss of Income (LOI): OR only LOU only BIA/LTA Search Aedical:	SS (S x SS (S x y LOR + LOU LO SS SS	days) DR + 1.0 Tick only		1) Claim status: Normali	Reject/Private Settle
oss of Income (LOI); OR only LOU only GIA/LTA Search dedical: Disbursement:	SS (S x SS (S x LOR + LOU LO SS SS SS	days)		2) Report Format: Offi	R
oss of Income (LOI); OR only LOU only EIA/LTA Search dedical; Disbursement; egal Cost	SS (S x SS (S x V LOR + LOU LO SS SS SS SS	days) DR + 1.0 Tick only (e.g. Tow/ Independ		1) Claim status: Normall 2) Report Formal: Offi 3) Survey fee:	R
oss of Income (LOI); OR only LOU only GIA/LTA Search dedical; Disbursement; agal Cost Fotal;	SS (S X SS (S X V LOR + LOU LA SS SS SS SS SS	days) OR + 1.0 [Tick only (e.g. Tow/ Independ		2) Report Format: Offi 3) Survey fee: \$10	R
oss of Income (LOI): OR only LOU only IIA/LTA Search Iedical: bisbursement: egal Cost 'otal: INAL PAYMENT	SS (S X SS (S X SS SS	days) DR + 1.0 Tick only (e.g. Tow/ Independ Global Sum S\$: Confirm with:		2) Report Format: Offi	R
oss of Income (LOI); OR only LOU only GIA/LTA Search dedical; Disbursement; .egal Cost	SS (S X SS (S X SS (S X SS SS	days) OR + 1.0 [Tick only (e.g. Tow/ Independ		2) Report Format: Offi 3) Survey fee: \$10	R

1087717131 wef REF:	Ac/ W
ASS. REC. BY: Marcus	
Δ	ASSIGNMENT Victoria 702987 Victoria / /F
From: Date:	ven No.
Estimated Cost:	Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or
To Inspect Vehicle No: JPP997	Make: Hyunder Stgrex c.c 2497
at Workshop m/s R. (0 60	Colour white A/C: Insured/Std/NI/NA
of	Sp.Reading £100 2 T/Radio: Insured / Std / NI / NA
Insured: 566 6000R	Eng/No:
Policy No.	CINO: KMJW A 37KMJU962828
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: morder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 2.5-/70-216
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Ne Xey
Bal, or Market Value:	Front / Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. Mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. p mm L/Bal. mm
Est. Repairs: \	D.O.A. 12/5/19 D.O.I. 16/5/19
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
	The U/C / Chassis frame / Body Structure allected due to collision.
Date / Time Action / Instruction Action / Instruction	
((%) (4/	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add	d Fee: : Site Insp (\$)s+Rssi
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump,Sum / I.B.I: (\$: Weekend (\$



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24 Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com

Tel: 6286 6060 , FAX: 6286 7060

VECHICLE NUM: MAKE & MODEL:

CHASSIS NUM:

JPP 997 HYUNDAI STAREX

81002

Not Alled Not Alled 1/5 & The Mary

NO. DESCRIPTION - PARTS 1 REAR WINDSCREEN MOULDING mer nei -2 THIRD BRAKE LAMP X 11X 3 TAIL GATE V box 4 TAIL GATE WIPER ✓ 5 TAIL GATE WIPER MOTOR X 11 X TAIL GATE LOGO (HYUNDAI) Nu 7 TAIL GATE EMBLEM (HYUNDAI) INC M. R TAIL GATE EMBLEM (GRAND) ru -9 TAIL GATE EMBLEM (STAREX) VAL nu-10 TAIL GATE EMBLEM (ROYALE) nu-TAIL GATE CENTER CHROME TO VOL 11 12 TAIL GATE HANDLE 13 TAIL GATE CARPLATE LAMP (L+R) 11X 14 TAIL GATE BOARD De/cre 15 TAIL GATE DAMPER (L+R) × 16 TAIL GATE HINGER (L+R) X 17 TAIL GATE WIRE PROTECTOR RUBBER (L+R) 7 18 TAIL GATE WEATHER STRIP 19 TAIL GATE STOPPER (L+R) 11 × 20 TAIL GATE INNER LAMP × 21 TAIL LAMP (L+R) 22 TAIL LAMP PANEL (L+R) X 23 REAR BUMPER V d/m 24 REAR BUMPER RETAINER (L+R) 25 REAR BUMPER LOWER CHROME 74 7 26 REAR BUMPER GRILLE (L+R) 27 REAR BUMPER REFLECTOR (L+R) 28 REAR FENDER (L+R) × 29 REAR FENDER LOWER GARNISH (L+R) 30 REAR FENDER INNER TRIM (L+R) % 31 REAR FENDER COWLING 11X 32 REAR DOOR (RH) × 11X 33 REAR DOOR HINGE (UPPER & LOWER) X 11X 34 REAR DOOR CHECKER (RH) 11V 35 REAR DOOR LOWER GARNISH (RH) 11 X 36 END PANEL & / But Rodly in -37 END PANEL TOP GARNISH A 38 SPAREWHEEL PANEL 39 SPAREWHEEL PANEL TOP BOARD × 11X 40 SPAREWHEEL PANEL TOP BOARD TOP MAT X 11X

41 SPAREWHEEL TOOL BOX (L+R)	11/	
MARKET LEGISLE MARKET	11/	
	11/2	
EXHAUST RRACKET (L+R) </td <td>11 V</td> <td></td>	11 V	
EXHAUST HEAT SHIFT D > /	11 ×	
EDONT WINDSCREEN MOULDING 1/41	24	
FRONT WINDSCREEN GARNISH (nu -	
48 FRONT WINDSCREEN NOZZER (L+R)×	11 7	
FRONT WIPER (L+R) V	10.7/	
FRONT WIPER MOTOR V	71 X	
50 FRONT WIPER MOTOR X	2 2	
51 BONNET WAR TRIM V	10 1	
52 BONNET INNER TRIM X	112	-
53 BONNET INNER RUBBER STRIP	NV X	
54 BONNET HINGE (L+R) X	NAX	
55 BONNET LOGO (HYUNDAI) X	u-1 X	
56 FRONT GRILLE BASE 7	cne /	
57 FRONT GRILLE CHROME V CAN	che /	
58 FRONT GRILLE FRAME CHROME / CAN	(Ne)	
59 HEAD LAMP (L+R)	che -	100
60 HEAD LAMP BRACKET (L+R)	11 11 1	
61 HEAD LAMP SIDE LAMP (E+R)	42 11 X	
62 FRONT BUMPER Volum	DIS-	
63 FRONT BUMPER RETAINER (1/4R)	olsone, 4C	
64 FRONT BUMPER GRILLE BASE	Repeated X	1
65 FRONT BUMPER GRILLE CHROME VOW	cm-	
66 FRONT BUMPER GRILLE FRAME CHROME Vam	Republik X	
67 FRONT BUMPER LOWER GRILLE ×	117	
68 FRONT BUMPER FOG LAMP (L+R)	117	
69 FRONT BUMPER FOG LAMP GARNISH (C+R)	11 1	
70 FRONT BUMPER FOG LAMP GARNISH CHROME (JAR)	P4 cmm olsera IPC	
71 FRONT FENDER (LTR) But RHV	0/5 BUC 17C	
72 FRONT FENDER TOP GARNISH (L+R) ×	11 ×	
73 FRONT FENDER COWLING (L+R) ×	111	
74 FRONT FENDER SIGNAL LAMP (L+R) PH?	124	
75 FRONT DOOR (RH) X Sym	K X	
76 FRONT DOOR HINGE (UPPER & LOWER) (RH)≺	11 X	
77 FRONT DOOR CHECKER (RH) ×	11 X	
78 FRONT DOOR LOWER GARNISH (RH)	11 X	
79 FRONT SUPPORT PANEL	sellare -	
FRONT SUPPORT PANEL GARNISH X	11X	
81 AIR CON CONDENSOR X	11X	
82 HIGH PRESSURE HOSE >	111	
83 LOW PRESSURE HOSE ×	11 X	
84 RADIATOR ×	^1 X	
85 DISCHARGE PIP®×	111	
85 SUCTION PIPE ×	12 /	
	7(1)	
87 RADIATOR FAN COWLING X	M1 X	

1/4

)	7, 411		-	
)	WIPER WASHER TANK Vann De			
1	WIPER WASHER MOTOR ×			
-				
	SUBTOTA	L	S	-
	LESS 10	%	s	-
-	PARTS TOTA	L	S	
-	SPECIAL NETT	QTY		PRICE
1	TAIL GATE SPOILER	1	S	1,200.00
-	TAIL GATE WIPER BLADE '	1	s	60.00
3	TAIL GATE EMBLEM (SIME DARBY MOTOR)	1	s	250.00
4	REAR CARPLATE V 35	1	s	120.00
5	TAIL GATE BOARD CLIP V	10	s	100.00
6	TAIL LAMP CLIP (L+R) 7	10	s	100.00
7	REAR BUMPER CLIP / Mg	10	s	100.00
8	REAR FENDER LOWER GARNISH CLIP (RH) ✓	10	S	100.00
-	REAR FENDER INNER TRIM CLIP (L+R) ×	10	s	100.00
	REAR FENDER COWLING CLIP (L+R) X	10	S	100.00
	REAR DOOR LOWER GARNISH CLIP (RH) ×	10	S	100.00
	REVERSE CAMERA ×	1	s	850.00
	REVERSE SENSOR SET ✓	4	S	600.00
	FRONT WINDSCREEN SEALANT V2L	1	S	120:00
	BONNET INNER TRIM CLIP ×	10	S	100.00
	HEAD LAMP CLIP (L+R) ×	10	s	100.00
	EDON'T CARRIATE	1	S	120.00
-	EPONT PUMPED CLID	10	S	100.00
	PRONT FENDER COWLING OF ID 4 - D	10	S	100.00
	PONT DOOR LOWER CARNISH OLD ONE	0000		2174-104019 ²
-	FRONT GRILLE CAMERA	10	S	100.00
	PONT SENSOR SET >	4	5	850.00
	AIRCON CAS V	-	S	600.00
3	nacon das X	1	\$	120.00
+	SPECIAL NETT TOTAL	100	•	6 000 00
	LABOUR	QTY	S	6,090.00 PRICE
1 T	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN	1900		-
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1800	S	5,200.00 3,200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA	7000		100000000000000000000000000000000000000
-	O RNR REAR WINDSCREEN		S	200.00
-	O DATE PRODUCTION OF THE PRODU		S	400.00
-	O RNR FRONT WINDSCREEN / 1		S	400.00
-		-	S	200.00
	O RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS		S	200.00
	O RNR REVERSE SENSOR & CHECK FUNCTION.		\$	120:00
195	O RNR FRONT SENSOR & CHECK FUNCTION		\$	120.00
10.33	O RNR REVERSE CAMERA & CHECK FUNCTION		S	120.00
100	O RNR FRONT CAMERA & CHECK FUNCTION		S	120.00
100	O RNR FRONT GRILLE CAMERA & CHECK FUNCTION		S	1-20:00
T	O RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	I.	S	120.00
0,000	O RNR A/C CONDENSOR ASSY AND REFILL GAS			

16 TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE. X X X S 17 TO DO WATER LEAK TEST. X S 18 TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD Y X S 19 TO RNR FUEL TANK TO ASSIST WORK LOAD Y X S 20 TO CHECK CHASSIS ALIGNMENT X S	120.00 80.00 120.00 120.00 400.00
TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD TO RNR FUEL TANK TO ASSIST WORK LOAD TO CHECK CHASSIS ALLONNENTS	120.00 120.00
TO RNR FUEL TANK TO ASSIST WORK LOAD PA X S	120.00
TO CHECK CHASSIS ALICONOMY	
TO CHECK CHASSIS ALIGNMENT S	400.00
GRAND TOTAL COST S	6,090.00

PAGE 2 OF 2

- 18 days ryn

Home * / New Cars / Hyundai / Grand Starex */ Royale Deluxe

Updated on: May 15, 2019

Hyundai Starex Executive 2.5 MPV BEST OFFER IN TOWN

Updated on: May 15, 2019

Dealer

Selangor » Petaling Jaya »



RM 145,000

Seller Information

Dealer

Selangor »
Petaling Jaya

Key details

Car type

New Car

Make

Hyundai –

Model

Grand Starex

Variant

Royale Deluxe

Year 2018

Engine

Capacity 2497 cc

0

Transmission

Automatic

ė

Seat

Capacity

11

Mileage

Colour



Nivitha (LKK Auto)

From:

Hor, Yinrul < Yinrul.Hor@aig.com>

Sent:

Wednesday, 15 May 2019 4:55 PM

To: Cc:

'assignments@lkkauto.com'; Admin A (admin-a@lkkauto.com)

Subject:

Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur PRE-REPAIR INSPECTION REQUEST - JPP997 vs SGG6000R (OI) on D.O.A.:

12/05/2019

Attachments:

SecureMessageAtt.html

yehile h zororo shanelle sur o menus





This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息,请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

Click here by 2019-05-22 16:55 +08 to read your message. After that, open the attachment.

More Info

Disclaimer: This email and its content are confidential and intented solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights

PRE-REPAIR INSPECTION REQUEST - JPP997 vs SGG6000R (OI) on D.O.A.: 12/05/2019

From: Hor, Yinsul

'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)

Cc: - Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur

PRI Arrangement.pdf

Hi,

Please refer to the enclosed request from RICO 60 AUTO SERVICES PTE. LTD..

Claim no

: 7275044529SG005

Case Owner : NORSIAH BTE MD NOOR

If you have any queries/concerns, please let us know.

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Yin Rul, Hor (Viviane)

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

Yinrul.Hor@aig.com | www.aig.sg

From: claims@rico60.com [mailto:claims@rico60.com]

Sent: Wednesday, May 15, 2019 4:37 PM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh,

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGG6000R AND JPP997 ON 12/05/2019

Dear all,

Please have Marcus survey the said vehicle.

From: Hor, Yinrul

Sent: Wed, 15 May 2019 08:05:05 +0000

To: claims@rico60.com

Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang,

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGG6000R AND JPP997 ON 12/05/2019

Without Prejudice

Your Reference

: JPP997

Our Reference

: 7275044529SG005

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Company Name
AIG Asia Pacific Insurance Pte Ltd
Priority Services
Priority Services
Priority Services
Automobile Inspection Services Pte Ltd
Formteam Adjusters Pte Ltd
Formteam Adjusters Pte Ltd
Formteam Adjusters Pte Ltd

Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing-Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane) AIG Claim Adjuster II, Singapore FNOL, Claims Operations - Auto Yinrul,Hor@aig.com | www.aig.sg

From: Enquiry [mailto:claims@rico60.com] Sent: Wednesday, May 15, 2019 3:49 PM

To: Lee, Ming-Yao; Chin, Lee-Ying; Mithoosingh, Aashweenjeetkaur; Abu Kassim, Noor Mariesa

Subject: [EXTERNAL] PRI Arrangement for JPP 997

This message is from an external sender; be cautious with links and attachments.

Dear All.

Kindly arrange PRI to survey the said vehicle as follows:

Our Client - JPP 997 Your Insured - SGG 6000 R DOA - 12/05/2019

Thank you.

Best Regards, Shanelle Lim



RICO 60 AUTO SERVICES PTE. LTD.

Co. & GST Reg. No.: 201807623M

8 Kaki Bukit Avenue 4, Premier @ Kaki Bukit

#02-24, Singapore 415875

Mobile: +65 9187 8064 | Tel: +65 6286 6060 | Fax: +65 6286 7060

Email: enquiry@rico60.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for

UNDERTAKING

L Chan kuk	Bung	, (NRIC No	51(99742]) hereby
cuntim that the Singapore	Accident Stateme	nt lodged by me	on 13/5/10
SGGCever hours pe	ertaining to the	acodent involve	no motor one Real No.
knowledge information and	d callet	are true and g	occurate to the bast of my
I acknowledge that my insi	urors are not hable	under the contri	aut of insurance if there is
In the event that an unrela	ited unreported this	rd party prepert	or injury claim arises or
there is evidence smorge	s that there is a	preach of policy	Terms and continons it
prevocably undenake to a	Absolve my insure	t from all habit	ty under the contract of
mourance and I underake	to re-pay any su	ms paid by my	insurers pursuant to the
contract of insurance upon	receipt of written o	ismand by my in	surers
		Λ	
Signature		11.12	
	: 7	1 2	
Name of Insured / Driver			
Nric No.			
Date			
Signature	1		
Name of Policyholder	:		
Nric No.			
Date			

Jia Le (LKK Auto)

From: Jia Le (LKK Auto)

Sent: Wednesday, 27 November 2019 3:33 PM

To: Md Noor, Norsiah

Subject: Your ref: JPP997 [ACCIDENT INVOLVING VEHICLES SGG6000R AND JPP997 ON

12/05/2019]

Dear Norsiah,

The said chain collision involved 5 vehicles whereby insured was the 4th vehicle. Since TP was the 3rd vehicle and foreign registered vehicle, no BOLA is applicable.

We have spoke to TP and they had forwarded the claim to Liberty Insurance to claim against the last vehicle.

Therefore, we will temporary close the case.

Best Regards,

Chan Jia Le | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: <u>Jiale@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC4/AIG19008696/Udb3

30 JULY 2019

SOH MUN LENG 35 CASUARINA WALK SINGAPORE 574091

Dear Sir/Madam.

ACCIDENT INVOLVING SGG 6000R(AIG) / JPP 997/ OTHERS ALONG/ AT UPPER THOMSON ROAD TOWARDS SEMBAWANG ROAD ON 12/05/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from JPP 997 against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD - if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE Case Handler

DID: 6749 5792 FAX: 6741 4108

Email: jiale@lkkauto.com

AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

...CLAIM SUBFOLDER...(Pending for Survey Report) Revoked / No settlement

LAIM SUBF	OLDER TRA	CKING							-		
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Sub	mitted	Ins Auth'ed	Status		
Main	14 May 2019 Edit Reg		15 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimate	s	S\$0.00 View R			Pendir Report	ng for Sur t I Case	rvey
М	lain	Re	ference	CIA	aim D	etails		Documer	nts	٦ _	Show All
CLAIM SUB	FOLDER DE	TAILS		Contract of the	10000	Electrical and	[Crosto	d by adjuster]		A STATE OF THE PARTY OF THE PAR	
Insured:	SOH MUN	LENG, ID: S172	1865D				Lcreate	d by adjuster			
Main Claimant: SUERA PETROMART, Co. Reg. No.: -											
Vehicle Reg. No.:	Reg. JPP997				Date (of Loss:	12/05/2019 00:00 - :59 [15 Months and 13 Days From LTA Reg Date (Man Yr)				Man Vell
Claim Type:	im Type: TP / 7275044529SG				Policy Note I	/Cover	1	0558 (Comprehensive)			
Vehicle Reg. No. (Insured):	SGG6000F	i e			Policy						
Repairer:	RICO 60 A	UTO SERVICES I	TE LTD (UO) o	VANT DUNCT	Exces	s:				- Herronius de la constante de	
Handling Insurer:	ALG ASIA P	UTO SERVICES Pacific Insurance Noor@aig.com	Pte. Ltd. (Exp	ress) - Tel: 65	-6419	-3000	[Handled	MIER @ KAKI BUI by MdNoor, No	(IT, 41587 rsiah]	5 Kaki Buk	it - Tel:
Adjuster:		Consultants Pte	Ltd (HQ) - Tel: (6256-3561	Hand	led by N	IARCUS C	HUA1 [Final	Dat due	20/0F/2	0101
ASSOCIATE	D MAIL REC							iion) [I iiiai	KPt due	20/03/2	019]
		Request To Uplo	ad TD CYA Daw						View All	Compose	Case Mail
	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	request to opio	au ir dia kep	ort							
ALL ASSOC	IATED TASK	(SE					View All	Search Tasks	County 11		
Due Date	Priority	Type Task G	roup Subje	ct Handle	e 10	Assiane		Completed On	Create No		Complete
Due Date					52 (3)	maaigiii	ou wy	completed on	Crea	ated On	Done?

Claim Documents

*JPP997 (7275044529SG) [SGG6000R] TP SUERA PETROMART May 12 2019 12:00AM [SOH MUN LENG]
RICO 60 AUTO SERVICES PTE LTD

Pho	otos/Images			View in Brow	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per	page ▼	•
1	16/05/19 18:12	Odometer Reading	0	Thumbnail Load JPG	Prin
2	16/05/19 18:13	Chassis Number	0	2000	-
3	16/05/19 18:14	General View	0	Load JPG	9
4	16/05/19 18:14	General View	0	Load JPG	•
5	16/05/19 18:14	General View	0	Load JPG Load JPG	•
6	16/05/19 18:14	General View	0	Load JPG	•
7	16/05/19 18:14	General View	0		
В	16/05/19 18:14	General View	0	Load JPG	•
9	16/05/19 18:14	General View	0	Load JPG	2
10	16/05/19 18:14	General View	0	Load JPG	2
11	16/05/19 18:14	General View		Load JPG	2
12	16/05/19 18:14	General View	0	Load JPG	2
13	16/05/19 18:14	General View		Load JPG	•
4	16/05/19 18:14	General View	0	Load JPG	•
15	16/05/19 18:14	General View	0	Load JPG	2
6	16/05/19 18:14	General View	0	Load JPG	V
7	16/05/19 18:14	General View	0	Load JPG	
8	16/05/19 18:14	General View	0	Load JPG	•
9	16/05/19 18:14	General View	0	Load JPG	•
0	16/05/19 18:14	General View	0	Load JPG	•
1	16/05/19 18:14	General View	0	Load JPG	Ø
2	16/05/19 18:14	General View	0	Load JPG	€
3	16/05/19 18:14	General View	0	Load JPG	
4	16/05/19 18:14	General View	0	Load JPG	•
5	16/05/19 18:14	General View	0	Load JPG	•
6	16/05/19 18:14	General View	0	Load JPG	€
7	16/05/19 18:14	General View	0	Load JPG	
8	16/05/19 18:14	General View	0	Load JPG	Y
	16/05/19 18:14	General View	0	Load JPG	•
	16/05/19 18:14	A CONTRACTOR OF CASE	0	Load JPG	Ø
	16/05/19 18:14	General View	0	Load JPG	•
	16/05/19 18:14	General View	0	Load JPG	
		General View	0	Load JPG	Ø
	16/05/19 18:14	General View	0	Load JPG	•
	16/05/19 18:14	General View	0	Load JPG	€
	16/05/19 18:14	General View	0	Load JPG	•
	16/05/19 18:14	General View	0	Load JPG	€
	16/05/19 18:14	General View	0	Load JPG	•
	16/05/19 18:14	General View	0	Load JPG	2
	16/05/19 18:14	General View	0	Load JPG	•
	16/05/19 18:14	General View	0	Load JPG	•

1	Photos/Images	Tun	3 pc	r page ▼	
1		1.5 2.6 (1.6)		Thumbnail	_
-		General View	0		
H	12 16/05/19 18:14	General View	0	100000000000000000000000000000000000000	
H	3 16/05/19 18:14	General View	0	-	9
4	4 16/05/19 18:14	General View	0		-
4	5 16/05/19 18:14	General View	0		
4	6 16/05/19 18:14	General View	0		2
4	7 16/05/19 18:14	General View		Load JPG	2
4	8 16/05/19 18:14	General View	0	Load JPG	2
4	9 16/05/19 18:14	General View	0	Load JPG	4
5	0 16/05/19 18:14	General View	0	Load JPG	•
5	1 16/05/19 18:14	General View	0	Load JPG	4
52	2 16/05/19 18:14	General View	0	Load JPG	•
53	3 16/05/19 18:14	General View	0	Load JPG	4
54		General View	0	Load JPG	1
55		General View	0	Load JPG	4
56		General View	0	Load JPG	•
57		General View	0	Load JPG	4
58			0	Load JPG	•
59	and the state of the state of the state of	General View	0	Load JPG	•
60		General View	0	Load JPG	1
0.0	,,	General View	0	Load JPG	•
61		General View	0	Load JPG	1
62		General View	0	Load JPG	•
63	,,	General View	0	Load JPG	•
64		General View	0	Load JPG	•
65	16/05/19 18:14	General View	0	Load JPG	•
66	16/05/19 18:14	General View	0	Load JPG	•
67	16/05/19 18:14	General View	0	Load JPG	2
58	16/05/19 18:14	General View	0	Load JPG	
59	16/05/19 18:14	General View	0		
70	16/05/19 18:14	General View	0	Load JPG	•
1	16/05/19 18:14	General View		Load JPG	2
2	16/05/19 18:14	General View	0	Load JPG	•
3	16/05/19 18:14	General View	0	Load JPG	•
4	16/05/19 18:14	General View	0	Load JPG	•
5	16/05/19 18:14	General View	0	Load JPG	•
6	16/05/19 18:14	General View	0	Load JPG	4
7	16/05/19 18:14	General View	0	Load JPG	1
8	16/05/19 18:14	General View	0	Load JPG	•
9	16/05/19 18:14	General View	0	Load JPG	V
0	16/05/19 18:14	General View	0	Load JPG	•
1	16/05/19 18:14	General View	0	Load JPG (•
2	16/05/19 18:14		0	Load JPG	•
3	16/05/19 18:14	General View	0	Load JPG	•
1		General View	0	Load JPG	1
	16/05/19 18:14	General View	0	Load JPG	•
5	16/05/19 18:14	General View	0		•
,	16/05/19 18:14	General View	0		0
	16/05/19 18:14	General View	0		
		General View	0	Load JPG	-
):		General View	-	Load JPG	-
		General View		Load JPG	-
6	16/05/19 18:14	General View			
	16/05/19 18:14	General View	-	Load JPG	
9	16/05/19 18:14	General View	9	Load JPG 🛮 💆	9

-	notos/Images		3 pe	r page ▼	6
No		LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Pr
94		General View	0	Load JPG	6
95	16/05/19 18:14	General View	0	Load JPG	6
96	16/05/19 18:14	General View	0	Load JPG	6
97	16/05/19 18:14	General View	0	-	8
98	16/05/19 18:14	General View	0	Load JPG	8
99	16/05/19 18:14	General View	0	Load JPG	8
100	0 28/05/19 19:51	Reinspection Photo	0	Load JPG	6
10	1 28/05/19 19:51	Reinspection Photo	0	Load JPG	6
102	2 28/05/19 19:51	Reinspection Photo	0	Load JPG	6
103	3 28/05/19 19:51	Reinspection Photo	0	Load JPG	8
104	4 28/05/19 19:51	Reinspection Photo	0	Load JPG	6
105	28/05/19 19:51	Reinspection Photo	o	Load JPG	6
106	28/05/19 19:51	Reinspection Photo	0	Load JPG	
107	28/05/19 19:51	Reinspection Photo	0	Load JPG	9
108	28/05/19 19:51	Reinspection Photo	0	Load JPG	
109	28/05/19 19:51	Reinspection Photo	0	Load JPG	9
110	28/05/19 19:51	Reinspection Photo	0		
111	28/05/19 19:51	Reinspection Photo	0	Load JPG	-
112	28/05/19 19:51	Reinspection Photo	0	Load JPG	
113		Reinspection Photo		Load JPG	
114		Reinspection Photo	0	Load JPG	
115	28/05/19 19:51	Reinspection Photo		Load JPG	2
116	28/05/19 19:51	Reinspection Photo	0	Load JPG	4
17		Reinspection Photo	0	Load JPG	
18	And the State of t	Reinspection Photo	0	Load JPG	4
119		Reinspection Photo	0	Load JPG	4
20		Reinspection Photo	0	Load JPG	1
21	28/05/19 19:51	Reinspection Photo	0	Load JPG	4
22		Reinspection Photo	0	Load JPG	4
23	28/05/19 19:51	Reinspection Photo	0	Load JPG	4
24	28/05/19 19:51	Reinspection Photo	0	Load JPG	4
25	28/05/19 19:51	Reinspection Photo	0	Load JPG	4
26	28/05/19 19:51	Reinspection Photo	0	Load JPG	V.
27	28/05/19 19:51		0	Load JPG	4
28	28/05/19 19:51	Reinspection Photo	0	Load JPG	1
29	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
30	28/05/19 19:51	Reinspection Photo	0	Load JPG	(1)
31	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
32	28/05/19 19:51	Reinspection Photo	0	Load JPG	
33	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
34	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
35	28/05/19 19:51	Reinspection Photo	0	Load JPG	V
36	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
37		Reinspection Photo	0	Load JPG	•
38	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
39	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
40	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	Ø
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
-	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
16	28/05/19 19:51	Reinspection Photo	0	Load JPG	•

	hotos/Images		3 pe	r page ▼	1 6
No		LKK Auto Consultants Pte Ltd (HQ)		Thumbnai	T
14	47 28/05/19 19:51	Reinspection Photo	0	Load JPG	
14	48 28/05/19 19:51	Reinspection Photo	0	Load JPG	6
14	19 28/05/19 19:51	Reinspection Photo	0	V Description	-
15	50 28/05/19 19:51	Reinspection Photo		Load JPG	
15	1 28/05/19 19:51	Reinspection Photo	0	Load JPG	
15	2 28/05/19 19:51	Reinspection Photo	0	Load JPG	
15	3 28/05/19 19:51	Reinspection Photo	0	Load JPG	9
15	4 28/05/19 19:51	Reinspection Photo	0	Load JPG	•
15	5 28/05/19 19:51	Reinspection Photo	0	Load JPG	9
15	6 28/05/19 19:51	Reinspection Photo	0	Load JPG	
15	7 28/05/19 19:51	Reinspection Photo	0	Load JPG	
15		Reinspection Photo	0	Load JPG	8
15		Reinspection Photo	0	Load JPG	9
160	The state of the s	Reinspection Photo	0	Load JPG	2
16			0	Load JPG	2
163		Reinspection Photo	0	Load JPG	2
163		Reinspection Photo	0	Load JPG	
(B)		Reinspection Photo	0	Load JPG	
164		Reinspection Photo	0	Load JPG	7
165		Reinspection Photo	0	Load JPG	•
166		Reinspection Photo	0	Load JPG	
167		Reinspection Photo	0	Load JPG	
168		Reinspection Photo	0	Load JPG	•
169		Reinspection Photo	0	Load JPG	
170	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
71	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
72	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
73	28/05/19 19:51	Reinspection Photo	0	Load JPG	(2)
74	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
75	28/05/19 19:51	Reinspection Photo	0	14 / 00 / C (14 a 14	•
76	28/05/19 19:51	Reinspection Photo	0	Load JPG	-
77	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
78	28/05/19 19:51	Reinspection Photo	0	Load JPG	2
79	28/05/19 19:51	Reinspection Photo	The second secon	Load JPG	•
80	28/05/19 19:51	Reinspection Photo	0	Load JPG	₹
81	28/05/19 19:51	Reinspection Photo	0	Load JPG	Ø
82	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
83	28/05/19 19:51	Reinspection Photo	0	Load JPG	
84	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
85	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
36	28/05/19 19:51	Reinspection Photo	0	Load JPG	$ \mathbf{Z} $
37	28/05/19 19:51	Reinspection Photo	0	Load JPG	€
38	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
39	28/05/19 19:51		0	Load JPG	•
90		Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
91	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
250	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
ь	28/05/19 19:51	Reinspection Photo	0	Load JPG	•
ocu	ımentation		100-300	1,0	
1 per page		ge ▼	•		
\rightarrow	16/05/19 15:15	LKK Auto Consultants Pte Ltd (HQ) EMAIL FROM AIG DD 15052019	Т	humbnail P	rint

Photos/Images				
No	Relabel/Reorder	THE STATE OF THE S	3 per page ▼	
140		LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
2	16/05/19 15:15	WKSP NOTICE	Load PDF	1 1 1 1 1 1
3	27/05/19 11:25	Log card		+
4	27/05/19 11:25	Police Report		-
5	27/05/19 11:25	INS CERT	1 Load PDF	
-			■ Load JPG	•
6	06/01/20 12:09	EMAIL	● Load PDF	
7	06/01/20 13:07	LETTER TO OI	1 Load PDF	1
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Delet
1	17/05/19 09:14	OI GIA REPORT	1 Load PDF	Print

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.		5015	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19008696/UDA3S2

Date:

06/01/2020

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100470558

Claimant Vehicle No:

JPP997

Insured Vehicle No:

SGG6000R

Date of Loss:

12/05/2019

Nature of Claim:

TP

Claim No: 7275044529SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

JPP997

Make & Model:

HYUNDAI STAREX, 2.5 (A) 29/01/2018 (Man. Year: 2017)

Engine No: Chassis No: D4CBH412259

Reg. Date: Colour:

White

Odometer:

KMJWA37KMJU962829

Engine Capacity:

2497 cc

Market Value/New Car Price: Sum Insured (S\$):

N/A

Market Value/New Car Price

81002 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Yes

Steering (Serviceable): Engine Modification:

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

215/70 R16

Rear Tyre Size:

215/70 R16

Front Tyre Size: Front Left Side: Front Right Side:

Nexen 6 mm Nexen 6 mm Rear Left Side: Rear Right Side:

Nexen 6 mm Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	Dill 70
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

15/05/2019

RICO 60 AUTO SERVICES PTE LTD (HQ)

Date Inspected:

Adjuster:

16/05/2019 Inspected At:

8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @

KAKI BUKIT

Singapore 415875

Estimated Period of Repair:

MARCUS CHUA

18.0 days

Manager:

CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

NO	. Uty Pa	rt No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*.
	1	*THIRD BRAKE LAMP	Not Necessary	0.00 F	*-1
3 4	1	*TAIL GATE	Badly Dented	0.00 F	*-
22_	1	*TAIL GATE WIPER	Not Necessary	0.00 F	*-1
5	1	*TAIL GATE WIPER MOTOR	Not Necessary	0.00 F	*-1
6	1	*TAIL GATE LOGO (HYUNDAI)	Necessary	0.00 F	*-1
7	1	*TAIL GATE EMBLEM (HYBRID)	Necessary	0.00 F	*-1
8	1	*TAIL GATE EMBLEM (GRAND)	Necessary	0.00 F	*-1
9	1	*TAIL GATE EMBLEM (STAREX)	Necessary	0.00 F	*-1
10	1	*TAIL GATE EMBLEM (ROYALE)	Necessary	0.00 F	*-1
11	1	*TAIL GATE CENTER CHROME	Not Necessary	0.00 F	*-1
12	1	*TAIL GATE HANDLE	Not Necessary	0.00 F	*-F
13	2	*TAIL GATE CARPLATE LAMP (L+R)	Not Necessary	0.00 F	*-F
14	1	*TAIL GATE BOARD	Deformed / Cracked	0.00 F	*- F
15	2	*TAIL GATE DAMPER (L+R)	Not Necessary	0.00 F	*-F
16	2	*TAIL GATE HINGE (L+R)	Not Necessary	0.00 F	*- F
17	2	*TAIL GATE WIRE PROTECTOR RUBBER (L+R)	Not Necessary	0.00 F	*- F
18	1	*TAIL GATE WEATHER STRIP	Twisted	0.00 F	*-F
19	2	*TAIL GATE STOPPER (L+R)	Not Necessary	0.00 F	*-F
20	1	*TAIL GATE INNER LAMP	Not Necessary	0.00 F	*-F
21	2	*TAIL LAMP (L+R)	Cracked	0.00 F	*-F
22	2	*TAIL LAMP PANEL (L+R)	Repair	0.00 F	*- F
23	1	*REAR BUMPER	Distorted	0.00 F	*-F
24	2	*REAR BUMPER RETAINER (L+R)	Not Necessary	0.00 F	*-F
25	1	*REAR BUMPER LOWER CHROME	Scratched	0.00 F	*-F
26	2	*REAR BUMPER GRILLE (L+R)	Not Necessary	0.00 F	*-F
27	2	*REAR BUMPER REFLECTOR (L+R)	Not Necessary	0.00 F	*-F
28	2	*REAR FENDER (L+R)	Repair	0.00 F	*-F
29	2	*REAR FENDER LOWER GARNISH (L+R)	Not Necessary	0.00 F	*-F
30	1	*REAR FENDER INNER TRIM (L+R)	N/s Cracked	0.00 F	*-F
31	1	*REAR FENDER COWLING	Not Necessary	0.00 F	*-F
32	1	*REAR DOOR (RH)	Not Necessary	0.00 F	*-F
33	2	*REAR DOOR HINGE (UPPER & LOWER)	Not Necessary	0.00 F	*-F
34	1	*REAR DOOR CHECKER (RH)	Not Necessary	0.00 F	*-F
35	1	*REAR DOOR LOWER GARNISH (RH)	Not Necessary	0.00 F	*-F
36	1	*END PANEL	Badly Dented	0.00 F	*-F
37	1	*END PANEL TOP GARNISH	Distorted	0.00 F	*-F
8	1	*SPARE WHEEL PANEL	Repair	0.00 F	*-F
9	1	*SPARE WHEEL PANEL TOP BOARD	Not Necessary	0.00 F	*-F
0	1	*SPARE WHEEL PANEL TOP BOARD TOP MAT	Not Necessary	0.00 F	*-F
1	2	*SPARE WHEEL TOOL BOX (L+R)	Not Necessary	0.00 F	*-F
2	1	*EXHAUST PIPE	Not Necessary	0.00 F	*-F
3	1	*EXHAUST GASKET	Not Necessary	0.00 F	*-F
4	2	*EXHAUST BRACKET (L+R)	Not Necessary	0.00 F	*-F
5	1	*EXHAUST HEAT SHIELD	Not Necessary	0.00 F	*-F
6	1	*FRONT WINDSCREEN MOULDING	Necessary	0.00 F	*-F
7	1	*FRONT WINDSCREEN GARNISH	Not Necessary	0.00 F	*-F
8	2	*FRONT WINDSCREEN NOZZER (L+R)	Not Necessary	0.00 F	*-F
9	2	*FRONT WIPER (L+R)	Not Necessary	0.00 F	*-F
0	1	*FRONT WIPER MOTOR	Not Necessary	0.00 F	*-F
1	1	*BONNET	Repair	0.00 F	*-F
2	1	*BONNET INNER TRIM	Not Necessary	0.00 F	*-F
3	1	*BONNET INNER RUBBER STRIP	Not Necessary	0.00 F	*-F
4	2	*BONNET HINGE (L+R)	Not Necessary	0.00 F	*-F
5	1	*BONNET LOGO (HYUNDAI)	Not Necessary	0.00 F	*-F

_		- 100	Particulars	Condition	Repairer's	Amount
56	1		*FRONT GRILLE BASE	Cracked	0.00 F	*-1
57	1		*FRONT GRILLE CHROME	Cracked	0.00 F	*-F
58	1		*FRONT GRILLE FRAME CHROME	Cracked	0.00 F	*-F
59	2		*HEAD LAMP (L+R)	Cracked	0.00 F	*-F
60	2		*HEAD LAMP BRACKET (L+R)	Not Necessary	0.00 F	*-F
61	2		*HEAD LAMP SIDE LAMP (L+R)	Not Necessary	0.00 F	*-F
62	1		*FRONT BUMPER	Distorted	0.00 F	*- F
63	1		*FRONT BUMPER RETAINER (L+R)	O/s Cracked	0.00 F	*-F
64	1	18	*FRONT BUMPER GRILLE BASE	Repeated	0.00 F	*-F
55	1	33	*FRONT BUMPER GRILLE CHROME	Cracked	0.00 F	*-F
66	1	-	*FRONT BUMPER GRILLE FRAME CHROME	Repeated	0.00 F	*-F
67	1	- 8	FRONT BUMPER LOWER GRILLE	Not Necessary	0.00 F	*-F
88	2		*FRONT BUMPER FOG LAMP (L+R)	Not Necessary	0.00 F	*-F
9	2		FRONT BUMPER FOG LAMP GARNISH (L+R)	Not Necessary	0.00 F	*-F
0	1		FRONT BUMPER FOG LAMP GARNISH CHROME (L+R)	O/s Cracked		*-F
1	1		FRONT FENDER (L+R)	O/s Buckled	0.00 F	
2	2		FRONT FENDER TOP GARNISH (L+R)	Not Necessary	0.00 F	*-F
3	2		FRONT FENDER COWLING (L+R)		0.00 F	*-F
4	2		FRONT FENDER SIGNAL LAMP (L+R)	Not Necessary	0.00 F	*-F
5	1		FRONT DOOR (RH)	Not Necessary	0.00 F	*-F
6	2			Repair	0.00 F	*-F
7	1		FRONT DOOR HINGE (UPPER & LOWER) (RH)	Not Necessary	0.00 F	*-F
8	1		FRONT DOOR CHECKER (RH)	Not Necessary	0.00 F	*-F
9	1		FRONT DOOR LOWER GARNISH (RH)	Not Necessary	0.00 F	*-F
ATIC:	1		FRONT SUPPORT PANEL	Bent / Cracked	0.00 F	*-F
	- 1		FRONT SUPPORT PANEL GARNISH	Not Necessary	0.00 F	*-F
	1		AIR CON CONDENSER	Not Necessary	0.00 F	*-F
<u> </u>	1		HIGH PRESSURE HOSE	Not Necessary	0.00 F	*-F
730 B	1		LOW PRESSURE HOSE	Not Necessary	0.00 F	*-F
	1	•	RADIATOR	Not Necessary	0.00 F	*-F
100	1	*	DISCHARGE PIPE	Not Necessary	0.00 F	*-F
300	1		SUCTION PIPE	Not Necessary	0.00 F	*-F
	1	*	RADIATOR FAN COWLING	Not Necessary	0.00 F	*-F
8	1		RADIATOR FAN BLADE	Not Necessary	0.00 F	*-F
9	1	*	RADIATOR FAN MOTOR	Not Necessary	0.00 F	*-F
0	1	*	WIPER WASHER TANK	Deformed	0.00 F	*-F
1	1	**	WIPER WASHER MOTOR	Not Necessary	0.00 F	*-F
2	1		TAIL GATE SPOILER	Not Necessary		
3	1		TAIL GATE WIPER BLADE	Not Necessary	0.00 F	*-F
4	1		TAIL GATE EMBLEM (SIME DARBY MOTOR)	Necessary	0.00 F	*-F
5	1		REAR CARPLATE		0.00 F	*-F
3	10		TAIL GATE BOARD CLIP	Cracked	0.00 F	*-F
-	10		TAIL LAMP CLIP (L+R)	Necessary	0.00 F	*-F
2 8	10		REAR BUMPER CLIP	Not Necessary	0.00 F	*-F
,	10		REAR FENDER LOWER GARNISH CLIP (RH)	Necessary	0.00 F	*-F
	10		REAR FENDER INNER TRIM CLIP (L+R)	Not Necessary	0.00 F	*-F
	10		REAR FENDER COWLING CLIP (L+R)	Not Necessary	0.00 F	*-F
2			REAR DOOR LOWER GARNISH CLIP (RH)	Not Necessary	0.00 F	*-F
3				Not Necessary	0.00 F	*-F
)4 4			REVERSE CAMERA	Not Necessary	0.00 F	*-F
			REVERSE SENSOR SET	Shorted	0.00 F	*-F
)5 1			RONT WINDSCREEN SEALANT	Necessary	0.00 F	*-F
6 1			BONNET INNER TRIM CLIP	Not Necessary	0.00 F	*-F
7 1			HEAD LAMP CLIP (L+R)	Not Necessary	0.00 F	*-F
8 1		110000	RONT CARPLATE	Not Necessary	0.00 F	*-F
9 1	100		RONT BUMPER CLIP	Necessary	0.00 F	*-F
0 1	10		RONT FENDER COWLING CLIP (L+R)	Not Necessary	0.00 F	*-F
	10	*F	RONT DOOR LOWER GARNISH CLIP (RH)	Not Necessary	0.00 F	*-F
2 1	j.	*F	RONT GRILLE CAMERA	Not Necessary	0.00 F	*-F
3 4	1		RONT SENSOR SET	Shorted	0.00 F	*-F
	Ř		IRCON GAS	Silvitou	U.UU F	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >