

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19008743/BKA3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800056333

Claimant Vehicle No : SLA5935Y **Insured Vehicle No :** SLZ8727E

Date of Loss: 11/12/2018 Nature of Claim: TP Claim No: 2561015949SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA5935Y**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX534338
 Reg. Date: 08/03/2016 (Man. Year: 2015) Chassis No: MR053REH104540081
 Colour: Silver Odometer: 35612 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,371.52	2,595.22	2,776.30	51.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	540.00	1,310.00	70.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,221.52	3,135.22	4,086.30	56.59
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	7,221.52	2,500.00	4,721.52	65.38
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		45.00		
Nett Liability (S\$)		2,965.00		
Global Sum Settlement (S\$)		2,960.00		

INSPECTION

Date of Assignment: 16/05/2019

Date Inspected: 16/05/2019 Inspected At:

160 SIN MING DRIVE #01-14
 Repairer: Team Autopro Pte Ltd (Sin Ming)

Estimated Period of Repair: 3.0 days

Adjuster: Lim Teow Guan

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	927.50 FL	*594.00 FL
2	2		*FRONT BUMPER RETAINER	Necessary	151.80 FL	*151.80 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	361.00 FL	*- FL
4	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	170.20 FL	*- FL
5	1		*FRONT GRILLE BASE	Not Necessary	515.50 FL	*- FL
6	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	214.60 FL	*- FL
7	1		*FRONT GRILLE LOGO	Not Necessary	76.00 FL	*- FL
8	1		*HEADLAMP	N/S Cracked	1,921.20 FL	*790.00 FL
9	2		*HEADLAMP LOWER BRACKET	Broken (1 PCS ONLY)	210.00 FL	*105.00 FL
10	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
11	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
12	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
13	1		*FRONT NO PLATE WITH GARNISH	Cracked	80.00 FS	*50.00 FS
14	1		*VERTICAL BRACE	Bent	200.00 FS	*200.00 FS
15	1		*A/C CONDENSER	Bent	838.50 FS	*838.50 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,826.30	2,759.30
- List Item Discount on L Items 10.00/10.00% (S\$)	454.78	164.08
Total Parts (S\$)	5,371.52	2,595.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	800.00	200.00
2	RUST PROOFING	New	100.00	60.00
3	SPRAY PAINTING	New	800.00	200.00
4	R&R A/C CONDENSER	New	150.00	80.00
Gross Labour Cost (\$\$)			1,850.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >