

ASS. REC. BY:

REF:

es/FCI19008770/Dvd3ⁿ²

Special Instruction:

Signature: Brynn
cuts

ASSIGNMENT (Office)

From (Person): Henry Kao

of

FCI

Date/Time: 11:08am @ 17/5/2019

Estimated Cost:

Bill to:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 78742

Insured:

SHC 71775

at Workshop m/s

Chunni Motor

Tel:

65425119

of

10 AMK Andopoint #01-05/06

Policy No:

Claim No:

D19003278MP84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/5/2019

CA / REV / REP. / REV 24 HRS

1up

Date/Time: 11:27am @ 17/5/19

Person Contacted:

Lynn

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction

Estimate

✓

SHA 78742 - CS / III / 3015002 / Utd / 1

DUA: 7/8/2013

SHC 71775 - NS / INC18014476 / Cld / 3rd

DUA: 5/8/2018

24/5/19

Email preli revised to FCI

REF:

ASSIGNMENT

JBE 2023 April

April 2016

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop no/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

8

days

Res.: Yes or No

Lump Sum: _____

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SHA 7874-2

Yr Regn: April 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40

C.C. 1685

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

608047

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDEU418616

C/No:

KMHLEB41UMFU068033

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Compton

Front

Rear

P/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

16/05/2019

D.O.I.

17/05/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/8 Rear 4/8 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SHC 71778

10/06/19

Jurnal L/S 8900/- int 8 dgs j m (Ref 6308.72, 41.10)

RECEIVED 8 JUN 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

10/6 - typist

Report Format :

CWS

Lump Sum / I.B.I: (\$

8900/-

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. St

Photos

Other

TOTAL

5115: 75

1704 75

50

50+50

122

517



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003278MFSH

Our ref: CS/FCI19008770/Dvd3

Date: 24/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SHA 7874Z


We thank you for your instruction on 17/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/5/2019 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,208.72
Revised Estimate Amount	: S\$11,128.24
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion and o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang

Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	16-05-2019	Our Ref No. D19003278MFSH
Accident Date	16-05-2019	Claim Type. Third Party
Insured Vehicle	SHC7177S	Third Party Vehicle. SHA7874Z
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65425119/ 0	Fax No. 65427162
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 24 May 2019 3:39 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003278MFSH/1, SHA 7874Z
Attachments: SHA 7874Z PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHA 7874Z
Date of survey: 17/5/2019
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 17 May 2019 12:32 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003278MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 17 May 2019 11:08 AM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003278MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORKS PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7874Z

DATE : 16.05.2019

MAKE :


TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) <i>2 check money broken</i>			\$ 1,388.00 ✓
	SUB TOTAL			\$ 1,388.00
	LESS 20%		1388.00	\$ 277.60
	DISCOUNTED TOTAL		1110.40	\$ 1,110.40
	Front Fender Advertisement Logo (RH) <i>1 pc check</i>		100.00	\$ 100.00 Nett ✓
	Rear Door (RH) <i>Detach</i>			\$ 2,201.10 ✓
	Rear Door Hinge Upper (RH) <i>HL</i>			\$ 45.90 X
	Rear Door Hinge Lower (RH) <i>HL</i>			\$ 45.90 X
	Rear Door Check (RH) <i>HL</i>			\$ 62.90 X
	Front Door (LH) <i>Detach</i>			\$ 2,256.40 ✓
	Front Door Gear / Regulator (RH) <i>HL</i>			\$ 250.60 X
	Front Door Hinge Upper (RH) <i>HL</i>			\$ 36.10 X
	Front Door Hinge Lower (RH) <i>HL</i>			\$ 36.10 X
	Front Door Check (RH) <i>HL</i>			\$ 39.20 X
	Front Door Power Motor, RH <i>HL</i>			\$ 296.40 X
	Door Centre Pillar Outer (RH) <i>Detach</i>			\$ 2,527.80 ✓
	Rear Tyre Rim (RH) <i>HL</i>			\$ 325.30 X
	Rear Wheel Hup-Cap (RH) <i>cut</i>			\$ 107.10 ✓
	Rear Wheelbearing IN & Hub <i>2 Dist</i>			\$ 362.00 ✓ ✓
	Rear Trailing Arm (RH) <i>2 Dist</i>			\$ 192.00 ✓ ✓
	Rear Assist (RH) <i>2 Dist</i>			\$ 145.70 ✓ ✓
	Rear Shock Absorber (RH) <i>2 Dist</i>			\$ 276.30 ✓ ✓
	Rear Shock Absorber Mounting (RH) <i>HL</i>			\$ 81.30 X
	Stabilizer Link <i>2 HL</i>			\$ 85.90 ✓ X
	Rear Upper Arm (RH) <i>2 Dist</i>			\$ 335.75 ✓ ✓
	Rear Lower Arm (RH) <i>2 Dist</i>			\$ 353.80 ✓ ✓
	Rear Knuckle Arm (RH) <i>2 Dist</i>			\$ 545.60 ✓ ✓
	SUB TOTAL			\$ 10,609.15
	LESS 20%			\$ 2,121.83
	DISCOUNTED TOTAL		903 9303.55 7442.84	\$ 8,487.32

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender Advertisement Logo (RH) N/C			\$ 100.00
	Rear Door Advertisement Logo (RH) N/C			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (RH) N/C			\$ 80.00
	Front Door Coloured Comfort Logo (RH) N/C			\$ 75.00
	Front Door Advertisement Logo (RH) N/C			\$ 100.00
	Rear Tyre (RH) N/W			\$ 216.00
			455.00	
				\$ 671.00
	Labour Charge			
	Panel Beating			\$ 1,800.00
	Spray Painting Charge			\$ 1,250.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Transfer of Door		\$ 120.00	\$ 240.00
	Remove/Refix Undercarriage (RR)			\$ -200.00
	Rear Wheel Alignment			\$ -120.00
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System		\$ 200.00	\$ 400.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
			2020.00	
	TOTAL LABOUR			\$ 4,840.00
	ESTIMATE TOTAL			\$ 15,208.72
	17/05/2019 @ 1545m NA Andri 2pm 8 days.  2kt Auto 		1112824 L/S 8900/-	
LKK Auto Consultants hence notify the Reparer of the following: * To resurvey before/after spray painting * To display damaged part(s) during resurvey * Parts prices are subject to confirmation * Third party survey is on a "Without Prejudice" basis * No illegal modification(s) is allowed * Supplementary item(s) must be resurveyed and * Is subject to final approval from Insurance Company Acknowledged by Reparer Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 7874 Z

Technician:

Mileage: 608047

Time Printed 17.5.19 4:50 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°51'		-3°00' 3°00'
3°44'		-0°19' 5°41'
0°35'		-1°30' 1°30'
18°09'		
17°18'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°32'		-3°00' 3°00'
4°15'		-0°19' 5°41'
-0°33'		-1°30' 1°30'
14°50'		
14°18'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	-0°19'		-3°00' 3°00'
Cross Caster	-0°31'		-3°00' 3°00'
Cross SAI	3°19'		-3°00' 3°00'
Total Toe	0°02'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-1°55'		-3°30' 2°30'
0°13'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°26'		-3°30' 2°30'
3°00'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°30'		-3°00' 3°00'
Total Toe	3°14'		-3°00' 3°00'
Thrust Angle	-1°24'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19008770/Dvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7177S	Veh. Inspected	SHA 7874Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003278MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	17/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMFU068033	Colour	BLUE	
Odometer	608047	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CAMPEON	5 mm	
L/H Front Tyre	205/60 R16	CAMPEON	5 mm	
R/H Rear Tyre	205/60 R16	CAMPEON	5 mm	
L/H Rear Tyre	205/60 R16	CAMPEON	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/05/2019	Inspection Date	17/05/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 7874Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP (RH)	MOUNTING BROKEN	1,388.00	1,388.00
1	REAR DOOR (RH)	DENTED	2,201.10	2,201.10
1	REAR DOOR HINGE UPPER (RH)	NOT NECESSARY	45.90	-
1	REAR DOOR HINGE LOWER (RH)	NOT NECESSARY	45.90	-
1	REAR DOOR CHECK (RH)	NOT NECESSARY	62.90	-
1	FRONT DOOR (LH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR GEAR/REGULATOR (RH)	NOT NECESSARY	250.60	-
1	FRONT DOOR HINGE UPPER (RH)	NOT NECESSARY	36.10	-
1	FRONT DOOR HINGE LOWER (RH)	NOT NECESSARY	36.10	-
1	FRONT DOOR CHECK (RH)	NOT NECESSARY	39.20	-
1	FRONT DOOR POWER MOTOR,RH	NOT NECESSARY	296.40	-
1	DOOR CENTRE PILLAR OUTER (RH)	DENTED	2,527.80	2,527.80
1	REAR TYRE RIM (RH)	NOT NECESSARY	325.30	-
1	REAR WHEEL HUP-CAP (RH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-2,399.43	-2,138.31
			9,597.72	8,553.24
SPECIAL NETT ITEMS				
1	FRONT FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR FENDER ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00

Report Ref No. CS/FCI19008770/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00
1	FRONT DOOR ADVERTISEMENT LOGO (RH)(SN)	NECESSARY	100.00	100.00
1	REAR TYRE (RH)(SN)	NOT NECESSARY	216.00	-
			771.00	555.00
	LABOUR			
	PANEL BEATING.		1,800.00	700.00
	SPRAY PAINTING CHARGE.		1,250.00	800.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	150.00
	RE-SET REAR ABS SYSTEM. }		200.00	-
	RE-SET FRT & REAR POWER WINDOW SYSTEM. }		400.00	-
			4,840.00	2,020.00
	GRAND TOTAL		15,208.72	11,128.24
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,900.00

Report Ref No. CS/FCI19008770/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.