| 1 | ASG REC. BY: | | REP CS/CJ11400 | 18771714 d | FALITH 030 Special Instructions | | |
|--------|---|--------------------|-------------------|-------------|---------------------------------|------------|----------------|
| nuinun | From (Person): | Ong thin kin | ASSIGNM of O | 17 | Date/Time: | 17-5-19 9 | 3+ <i>a.</i> η |
| | OD (TP) WS/TP RES/OD RES/EVA/ENV/MV/CS To Inspect Vehicle No: GBF 5277 € nt Workshop m/s Sn/ Ah Tu Motor | | | | Insured: SIM 3116× | | |
| | | | 04h, #01-19 | | Tel: 626961 | 80 | |
| | | pcsn 302299 | 19022 | Claim No: 5 | SVM 190 202097 | (02 | |
| | Sum Insured: Make of Veh: | | | Excess: | D.O.A. 03 | 1061 201 | 7 |
| | (Client's Record) CA / REV / Date/Time: | REP. / REV 24 H | Person Contacted: | Joyce | H.O.D. End | omenenti: | |
| | Date/Time | Action/Instruction | (V) Estimat | e | | | |
| | | S111 ->16 × | - (13) (11 1900 | 8184/18/93 | D CA- | 03/05/2010 | 1 |
| | 26/11- | Pending A | nalise , vepa | iv done. | | | |
| | 1 | | | | | | |

| · · Tille e | TI |
|---|--|
| · main Taufibh | SIGNATEGET |
| | WILLIE GBF5277E WILLIAM 2016-NOV |
| Lean Lind | Type: M.Car J.M. Cycle J. Hurs J. Van. J. Co. J. Law J. Printer Moreon J. |
| Committed Const | Truck / Trailer or |
| OF THE THE RESTORAGE TENETHY INV. | The state of the s |
| To To poor Avenue to Ho | Colom Silver Mr. manual/statement |
| of Mhat-degrees | 92426 |
| r# | |
| lemel | KDY 23/8024791 |
| Tribling Flor | Con. Cont (a) (That (Poor (Burn) |
| Clamis No. | Stoening Inputs / Jammed / Leakerd / Dunit or |
| Sary Insured. | |
| (Cheofs (frowd) | |
| Moles of Vols | 125/17/ |
| i a | Typir Som |
| (Palley Condition) | 145/113 |
| Demail: The soli liad commenced its H/S 336 | |
| repair at the time of inspection. | TOYO I YOKO JI |
| 15d or Marton Valley | 1 10ml 6/ |
| IDAC Accident Epott: Consistent? Yes or No | TORSIA 6 HER HATCH C |
| GIA 7 PK Secry Consistent? Yes or No. | tatal non thin the non |
| Lat Heponia day. Hes Yes or Ho | Su Al Ter 17/5/19 |
| Lumiform = 3 Vol. Yes or Ho | Survey hold at Svy MV / et |
| CA I REV / REP. / 24 HRS VICT | Dass of Danagers, 1'st (10m / ORS / HRS / URC / Rooftop or |
| Vehicle: IREC | |
| Date: Posson Contacted: | The UIC 1 Chassis frame 1 Body Structure affected due to collision |
| Under Time /Action / Instruction | 100 |
| | w w |
| Part by Part \$ 1540: | 20 (Red: 836.60: 36%) |
| , | |
| DECE!\ | ED 3 0 JAN 2020 |
| REGER | |
| | |
| | 4 |
| Date (San Dec. 1 Proff: Report | Days Of Repair: |
| 301 Tupist Final Report | Resurvey No. of Trip: 370 |
| Date Time, the following the | Transportation: |
| a Add | |
| To | Interview (F)) issue. |
| Report Format | Toch free (F |
| Lump Sim / 140 1540 - 1 | Wenkend (9 |

100.00

220

...CLAIM SUBFOLDER...(New Assignment)

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status | |
|---------------------------------|-----------------------------|-------------------------------------|--------------------------------|------------------------------------|--|---|----------------------|-----------------------|
| Main | 16 May 2019 Sendback Est | 16 May 2019 18:00 5\$2,276.80 | 17 May 2019 09:37 Assign | | | | New Assi Cancel C | and the second second |
| | Main | Refere | nce | Claim Det | ails | Documents | | Show All |
| CLAIM S | UBFOLDER DETAI | | | | | | | |
| Insured: | | NA, ID: N | | | | | | |
| Main Clain | nant: | JAD SOLUT | TIONS PTE LTD, | Co. Reg. No.: | 200703726E | 07/05/20 | 19 18:00 - : | |
| Vehicle Reg. No.: | | GBF5277 | 'E | Date of L | 055: | [29 Months and 8 Days From L' Reg Date (Man Yr)] | | s From LTA |
| Claim Typ | 0. | TP / SNM | 19D202097C02 | Policy/Co | Policy/Cover Note No.: DMPCSN30268919022 | | | |
| the second second second second | g. No. (Insured): | SLM2216X | | Policy No. (Claimant): DMCVSN30268 | | 3026851901 | | |
| VEIDER TO | g. rrs. (masses) | | | Excess: | | | | |
| Repairer: | | Pinneer - Te | el: 6268 6183 | | (Ploneer) Blk 3 Pi | | | |
| Handling I | Insurer: | China Taip | ing Insurance (5 | ingapore) Pte | . Ltd. (HQ) - Tel: 6 | 389 6111 [Hai | ndied by Ong | Chin Kiat |
| Claimant's | s Insurer: | China Taip | ing Insurance (S | ingapore) Pte | . Ltd. (HQ) - Tel: 6 | 389 6111 | /0E/20101 | |
| Adjuster: | | LKK Auto | Consultants Pte L | td (HQ) - Tel: | 6256-3561 [Fin: | al Kpt due 29 | [05/2019] | |
| ASSOCIA | ATED MAIL RECEI | VED | | | | View All | Compose | Case Mail |
| There are | no mail for this case | B | | | | | | |
| | 543 (85) 834 84 540 130 | 000 | | | | | | |
| B | | | | | | | | |
| | OCIATED TASKS | | | Viev | All Search Task | is Create ! | New Task | Complete |

50.

Road Tax Start Date

| The | owner and vehicle particulars for Vehicle No. | GBF5277E as at 04 Apr 2018 are as follows: |
|-----|--|--|
| 1. | Name | : JAD SOLUTIONS PTE LTD |
| 2. | Identification No. Type | : Company |
| 3. | Identification No. | : 200703726E |
| 4. | Country/Region | : - |
| 5. | Vehicle No. | : GBF5277E |
| 6. | Previous Vehicle No. | 1 - |
| 7. | | : 04 Apr 2018 |
| 8. | | : 29 Nov 2016 |
| 9. | | : 29 Nov 2016 |
| 10. | Vehicle Type | : B31 - Goods (Open) Lorry (Metal Body)/Pickup |
| 11. | Vehicle Scheme | : Normal |
| 12. | Attachment 1 | : With Hood |
| 13. | Attachment 2 | 2.4 |
| 14. | Attachment 3 | 1- |
| 15. | Vehicle Make | : TOYOTA |
| 16. | Vehicle Model | : DYNA 3.0 MANUAL |
| 17. | Year of Manufacture | : 2016 |
| 18. | Primary Colour | : Silver |
| 19. | | 1. |
| 20. | Passenger Capacity | : 2 |
| 21. | | : KDY2318024791 / - |
| 22. | Propellant | : Diesel |
| 23. | Engine No./Motor No. | : 1KD2613785 / - |
| 24. | Engine Capacity(cc)/Power Rating(kW) | : 2982 / - |
| 26. | Unladen Weight(kg) | : 1800 |
| 27. | Maximum Laden Weight(kg) | : 3425 |
| 28. | | : \$28,595.00 |
| 29. | AND THE RESERVE OF THE PROPERTY OF THE PROPERT | : No |
| 30. | | |
| 31. | | : \$0.00 |
| 32. | | : 1 |
| 33. | | : 1042836990 |
| 34. | | : 2016112905001079C |
| 35. | | : 28 Nov 2026 |
| 36. | | : C - Goods Vehicle & Bus |
| 37. | Quota Premium/Prevailing Quota Premium | : \$16,823.00 / \$16,823.00 |
| 38. | | : \$16,823.00 |
| 39. | | : \$1,430.00 |
| 40. | CO2 Emission(g/km) | : 174.00 |
| 41. | CO Emission(g/km) | |
| 42. | HC Emission(g/km) | |
| 43. | NOx Emission(g/km) | |
| 44. | PM Emission(mg/km) | :- |
| 45. | Actual CEVS/VES Rebate Utilised | |
| 46. | | 1 - |
| 47. | Actual Green Vehicle Rebate Utilised | tt. |
| 48. | | : 28 Nov 2036 |
| 49. | Road Tax Amount | * |

- 51. 52. Road Tax End Date Remarks

: : The vehicle is registered under Early Turnover Scheme.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| STUTTERED. | |
|--|--|
| The state of the s | ACCIDENT STATEMENT |
| Date Of Report | 08/05/2019 16:06 |
| Date Of Accident | 07/05/2019 18:20 |
| Exact Location Of Accident | T-JUNC OF RANGOON RD & RACE COURSE RD |
| Country/State of Loss | SINGAPORE |
| | DETAILS OF OWN VEHICLE |
| Vehicle Registration Number | GBF5277E |
| Insured/Policyholder | |
| Name Of Registered Owner | JAD SOLUTIONS PTE LTD |
| Co Reg No | 200703726E |
| Email Address | ARUN@JAD-VENTURE.COM |
| Mabile Phone No | |
| Alternative Phone No | OFFICE-68418656 |
| Vehicle Particulars | |
| Manufacturer | ТОУОТА |
| Model | DYNA-3.0 D (M) |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | COMMERCIAL VEHICLE |
| Insurance Company | |
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | DMCVSN3026851901 |
| Cover Note Number | |
| Driver | |
| Name of Driver | ATA DE LIA DIDA ATA DE LA CASA DE |

Name of Driver NACHIAPPAN ARUNACHALAM

 NRIC No
 \$7567558E

 Date Of Birth
 25/04/1975

 Occupation
 INDOOR

 Date Of Driving Pass
 15/11/2003

Driving Experience 15 YEARS AND 5 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90068775

Fax Number Contact Number

EMail Address

ARUN@JAD-VENTURE.COM

Address

BLK 6 JLN BKT HO SWEE #01-142

Postcode

161006

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

4

Insurance Company of Driver's Own Vehicle

•

General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

3

involved in the accident

NO

NO

Was any body injured in the Accident?

1100

Was any injured conveyed to hospital by

NO.

ambulance?

-

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 07/05/2019 @ ABT 1830HRS, I WAS WAITING THE FRONT VEHICLE TO MOVE ALONG RANGOON RD ON THE RIGHT LANE. WHILE WAITING, SUDDENLY I FELT AN IMPACT FROM BEHIND. I THEN CAME DOWN FROM MY VEHICLE & SAW THE VEHICLE B SLM2216X KNOCKED ONTO MY VEHICLE AT REAR. THE VEHICLE B SLM2216X CAME OUT FROM RACE COURSE RD HAD KNOCKED ONTO THE VEHICLE C (SHC6086C) & THEN KNOCKED ONTO MY VEHICLE AT REAR AGAIN. THAT'S ALL.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLM2216X

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

KAN TAT SENG

NRIC/Passport Number

S0329683J

Contact Number

97893354

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SHC6086C

TAXI

SEOW TZE WANG, STEVEN

S8023595Z

81258873

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted
 to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name;

NRIC/FIN No.:

I AM AWARED THAT MY IN SURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY DWN POLICY, I WILL CHECK MY POLICY FOR MORE DETAILS.

| SKETCH PLAN | | |
|--|--|--|
| | | |
| | | |
| | | |
| | | |
| Ro | efer to Attachment | |
| | | |
| | | |
| | | |
| | | |
| | | |
| DESCRIBE CIRCUMSTANCE | S OF THE ACCIDENT | |
| | | |
| On 09/05/2019 | @ off 1800hrs. | |
| - 1 | | |
| Refer to circ | cunstances of accide | ent: |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | Claim own policy Claim third party |
| | | ☐ Claim OD / TP at other works hop |
| DECLARATION | | Policy No. DMCVSA3026851901 |
| /We declare the foregoing part | iculars are true in every respect. | Insurer China (C) VehNo. GSF 5277 |
| 01 -m155 | Λ | |
| Mish 18 | N. 15_ 3 (5/2019 | Jann |
| Policyholder's Signature | Driver's Signature | Reporting Centre Personnel's Signature |
| late & Time: | (If driver is not the policyholder) Date & Time: | Name: |
| MARINE State of the State of S | Date of time; | NRIC/FIN No.: |

Ranguan Rd Scene 1 Scene Johnshow By SHCCOBSC

Claim Reference: SNM19D202097/C02/6 Assessment number: GBF5277E - TP CHINA

Version: 1810

Date calculated: 16/05/2019 5:55 PM

Full Report

Registration: GBF5277E - TP CHINA

Printed: 16/05/2019 5:55 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

DARREN SNG SNM19D202097/C02/6 Currency: Date of Incident: SGD 07/05/19

Estimated Repair Time:

Actual Repair Days:

Hire Car Start:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

TOYOTA DYNA

Model: Sub Model:

BASE MODEL

Model Sheet Number:

70 1C 01

Registration:

VIN number:

GBF5277E - TP CHINA

Odometer: Model Specs

FROM 07/2016

"WIDE CAB"

PLATFORM

TWO COAT METALLIC

WHEELBASE 3430 MM

PREPARE OFF VEHICLE

REAR TWIN TYRES

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No idegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dete:

Claim Reference: SNM19D202097/C02/6 Assessment number: GBF5277E - TP CHINA

Version: 1810

Date calculated: 16/05/2019 5:55 PM

Full Report Registration: GBF5277E - TP CHINA

Printed: 16/05/2019 5:55 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Labour

| | Time Base 10 WU/h | Price = 42. | 00 SGD/h |
|-----------|-----------------------------------|-------------|-----------|
| Code | Description | wu | Price SGD |
| NO NUMBER | R + R REAR LOADING LID | 6.0 | 25.20 |
| NO NUMBER | R + R R/FOLDING GATE SUPPORT | 2.0 | 8.40 |
| NO NUMBER | R + R R/R SIDE SECTION | 2.0 | 8.40 |
| 811011 | R + R LEFT TAIL LAMP | 3.0 | 12.60 |
| 811011 | R + R RIGHT TAIL LAMP | 3.0 | 12.60 |
| NO NUMBER | RENEW REAR NUMBER PLATE (REMOVED) | 1.0 | 4.20 |
| NO NUMBER | RENEW R/TAILLAMP ATTACHMENT | 2.0 | 8.40 |
| NO NUMBER | R + R LEFT REAR REFLECTOR | 2.0 | 8.40 |
| NO NUMBER | R + R RIGHT REAR REFLECTOR | 2.0 | 8.40 |
| NO NUMBER | RENEW REAR NUMBER PLATE | 1.0 | 4.20 |
| 811201 | R + R NUMBER PLATE LAMP | 2.0 | 8.40 |
| 5066 | REAR CROSSMEMBER REPAIR | 5.0* | 21.00 |
| 5067 | R/OUT CROSSMEMBER REPAIR | 15.0* | 63.00 |
| 5406 | R/DROP SIDE REPAIR | 10.0* | 42.00 |

Claim Reference: SNM19D202097/C02/6 Assessment number: GBF5277E - TP CHINA

Version: 1810

Date calculated: 16/05/2019 5:55 PM

Full Report Registration: GBF5277E - TP CHINA

Printed: 16/05/2019 5:55 PM

 Labour Cost
 Hrs
 WU

 Panel / Mechanical Labour
 5.60
 56.0
 235.20

 Total of Labour
 235.20

| Paint Work | Paint Work | | s 10WU/h |
|------------|--------------------------------------|------|-----------|
| Code | Description - TWO COAT METALLIC | wu | Price SGD |
| LE 5385 | REAR LOADING LID NEW PART PAINT ST 1 | 15.0 | 63.00 |
| LS 5066 | REAR CROSSMEMBER REPAIR PAINT ST IV | 17.0 | 71.40 |
| LS 5067 | R/OUT CROSSMEMBER REPAIR PAINT ST IV | 17.0 | 71.40 |
| LS 5406 | R/DROP SIDE REPAIR PAINT ST IV | 33.0 | 138.60 |
| NO NUMBER | PREPARE FOR PAINTING | 21.0 | 88.20 |

Total Paint Hrs WU Price SGD 10.30 103.0 432.60

Spare Parts

| opare raits | | | | |
|-----------------------------------|----------------------|-------------|----------|----------------------------|
| 2 . | P2 9000 | 2 5 5 7 | | prices as at 2015-06-01/01 |
| Code | Description | Part Number | Supplier | Price SGD |
| 2702 | REAR NUMBER PLATE | KNPL6 | | H 0.00 |
| 2704 | REAR NO PLATE BACKG | 75102 37030 | | 11/ 120.00 |
| 3281 | L/R LAMP ASSY | 81560 37240 | | ηη × 75.00 |
| 3282 | R/R LAMP ASSY | 81550 37240 | | 75.00 |
| 3290 | R/TAILLAMP PANEL | 75105 37071 | | W- 90.00 |
| 3307 | L/R REFLECTOR | 81910 37070 | | 25.00 |
| 3308 | R/R REFLECTOR | 81910 37070 | | 25.00 |
| 3361 | NUMBER PLATE LAMP | 81270 37171 | | nn X 35.00 |
| 3617 | BADGE MODEL | 75471 25030 | | ₩ 25.00 |
| 3684 | R/R MUDFLAP | 66241 37C32 | | ₹ 75.00 |
| 5385 | REAR LOADING LID | 65700 37240 | | R≠ 450.00 |
| 5420 | R/LOADING LID SUPP | 65507 37051 | | Ry 35.00 |
| 5424 | R/R LOWER SIDE PANEL | 65349 37041 | | R> 90.00 |
| 1001 | R/R TAILLAMP | HOLDER | | Mn x 70.00 |
| 1003 | TAILGATE STOPPER | SIDE (RH) | | - 10 00 |
| 1004 | R/R REFLECTOR | ROUND | | ηη × 10.00 ηη × 25.00 |
| f: OEM Parts | Savings | | | 0.00 |
| n: Non-OEM Parts u: Used parts | Subtotal | | | 1,233.00 |

Audatex System Using Manufacturer Times

Page 3 of 5

PRINT DATE 16/05/2019

REAR U STEP - \$150 H/

Claim Reference: SNM19D202097/C02/6

Assessment number: GBF5277E - TP CHINA Version: 1810

Date calculated: 16/05/2019 5:55 PM

Full Report Registration: GBF5277E - TP CHINA

Printed: 16/05/2019 5:55 PM

Fixed Sundry Parts Price 100.00
Total 1,333.00

| Extras | | |
|--------|--------------------------------------|-------------|
| Code | Description | Price SGD |
| 1000 | REAR NUMBER PLATE WITH CASING | h1-35.00* |
| 1002 | REAR REVERSE SENSOR | di 180.00* |
| 1005 | REAR "1500KG" STICKER | nu 20.00* |
| 1006 | REAR "13PAX" STICKER | 20.00* |
| 1007 | REAR "70KM/H" STICKER | u 20.00* |
| 1008 | T/GATE INN ALUMINIUM BOARD RIVET(20) | nη. × 1.00* |
| | Total Extras | 276.00 |

| | SGD SGD |
|------------------------------------|---------------|
| Parts | 1,233.00 |
| Fixed Sundry Parts Price | 100.00 |
| Total Parts | 1,333.00 |
| Labour Time Base 10 WU/h | |
| Total 56.0 WU X 42.00 SGD/h | 235-20 |
| Total of Labour | 227.60 235.20 |
| Total Of Extras | 276.00 |
| Paint Work Time Base 10 WU/h | |
| Labour Cost 103.0 WU X 42.00 SGD/h | 432.60 |
| Total Paint Including Material | 432.60 |
| Repair Cost Excludes GST | 2,276.80 |
| GST (+7.0%) | 159.38 |
| Repair Cost Included GST | 2,436.18 |

2426.30

Claim Reference: SNM19D202097/C02/6 Assessment number: GBF5277E - TP CHINA

Version: 1810

Date calculated: 16/05/2019 5:55 PM

Full Report Registration: GBF5277E - TP CHINA

Printed: 16/05/2019 5:55 PM

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Insurer Reference: SNM19D202097/C02/6 Repairer Reference: GBF5277E - TP CHINA Date calculated: 23/05/2019 9:49 AM Full Report Registration: GBF5277E - TP CHINA Printed: 07/10/2019 4:23 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

SNG AH TEE SNM19D202097/C02/6 Currency: Date of Incident: Hire Car Start:

Hire Car End:

SGD 07/05/19

Estimated Repair Time: Actual Repair Days:

Vehicle Details

Vehicle

Manufacturer:

TOYOTA DYNA

Model: Sub Model:

BASE MODEL

Model Sheet Number:

70 1C 01

Registration:

GBF5277E - TP CHINA

VIN number: Odometer:

Model Specs FROM 07/2016

PLATFORM

WHEELBASE 3430 MM

REAR TWIN TYRES

"WIDE CAB"

TWO COAT METALLIC

PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody

H



Labour

Time Base 10 WU/h

Price = 42.00 SGD/h

| Code | Description | wu | Price SGD |
|-----------|-----------------------------------|-----------|-----------|
| NO NUMBER | R + R MODEL BADGE | 2.0 | 8.40 |
| 811011 | R + R RIGHT TAIL LAMP | 3.0 | 12.60 |
| NO NUMBER | RENEW REAR NUMBER PLATE (REMOVED) | 1.0 | 4.20 |
| NO NUMBER | RENEW R/TAILLAMP ATTACHMENT | 2.0 | 8.40 |
| NO NUMBER | R + R LEFT REAR REFLECTOR | 2.0 | 8.40 |
| NO NUMBER | R + R RIGHT REAR REFLECTOR | 2.0 | 8.40 |
| NO NUMBER | RENEW REAR NUMBER PLATE | 1.0 | 4.20 |
| 5066 | REAR CROSSMEMBER REPAIR | 5.0* | 21.00 |
| 5067 | R/OUT CROSSMEMBER REPAIR | 15.0* | 63.00 |
| 5385 | REAR LOADING LID REPAIR | 10.0* | 42.00 |
| 5406 | R/DROP SIDE REPAIR | 10.0* | 42.00 |
| | Labour Cost | Hrs WU | |
| | Panel / Mechanical Labour | 5.30 53.0 | 222.60 |
| | Total of Labour | | 222.60 |

| Paint Work | nt Work | | 10 WU/h |
|------------|--------------------------------------|------|-----------|
| Code | Description - TWO COAT METALLIC | wu | Price SGD |
| LE 5385 | REAR LOADING LID NEW PART PAINT ST 1 | 15.0 | 63.00 |
| LS 5066 | REAR CROSSMEMBER REPAIR PAINT ST IV | 17.0 | 71.40 |
| LS 5067 | R/OUT CROSSMEMBER REPAIR PAINT ST IV | 17.0 | 71.40 |
| LS 5406 | R/DROP SIDE REPAIR PAINT ST IV | 33.0 | 138.60 |
| NO NUMBER | PREPARE FOR PAINTING | 21.0 | 88.20 |

Spare Parts

| | | | | prices as at 2015-06-01/01 |
|------------------|---------------------|-------------|----------|----------------------------|
| Code | Description | Part Number | Supplier | Price SGD |
| 2702 | REAR NUMBER PLATE | KNPL6 | | 0.00 |
| 2704 | REAR NO PLATE BACKG | 75102 37030 | | 120.00 |
| 3282 | R/R LAMP ASSY | 81550 37240 | | 75.00 |
| 3290 | R/TAILLAMP PANEL | 75105 37071 | | 90.00 |
| 3307 | L/R REFLECTOR | 81910 37070 | | 25.00 |
| 3308 | R/R REFLECTOR | 81910 37070 | | 25.00 |
| 3617 | BADGE MODEL | 75471 25030 | | 25.00 |
| 1008 | REAR U | STEP | | 150.00 |
| f: OEM Parts | Savings | | | 0.00 |
| n: Non-OEM Parts | Subtotal | | | 510.00 |
| u: Used parts | Fixed Sundry Parts | Price | | 100.00 |
| | Total | | | 610.00 |

Extras

| Code | Description | Price SGD |
|------|-------------------------------|-----------|
| 1000 | REAR NUMBER PLATE WITH CASING | 35.00* |
| 1002 | REAR REVERSE SENSOR | 180.00* |
| 1005 | REAR "1500KG" STICKER | 20.00* |
| 1006 | REAR "13PAX" STICKER | 20.00* |
| 1007 | REAR "70KM/H" STICKER | 20.00* |
| 1007 | Total Extras | 275.00 |

Final Calculation

| Final Calculation | SGD | SGD |
|------------------------------------|--------|----------|
| | 300 | 300 |
| Parts | 510.00 | |
| Fixed Sundry Parts Price | 100.00 | |
| Total Parts | | 610.00 |
| Labour Time Base 10 WU/h | 222.60 | |
| Total 53.0 WU X 42.00 SGD/h | 222.60 | 222.60 |
| Total of Labour | | 222.60 |
| Total Of Extras | | 275.00 |
| Paint Work Time Base 10 WU/h | | |
| Labour Cost 103.0 WU X 42.00 SGD/h | 432,60 | |
| Total Paint Including Material | | 432.60 |
| Repair Cost Excludes GST | | 1,540.20 |
| GST (+7.0%) | | 107.81 |
| Repair Cost Included GST | | 1,648.01 |

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submi | itted Ins Aut | h'ed [5 | tatús | |
|-----------------------------------|--|---|--------------------------------------|-------------------------------|-----------------------|-----------------|--------------|-----------------------------------|--------------|
| Main | 16 May 2019 Sendback Est | 16 May 2019 18:00 \$\$2,276.80 | 17 May 2019 09:37 Edit Adj Rpt | S\$1,540.20 Edit Estimates | 5\$1,540. View Rpt | | | ending fo leport Cancel Cas | illa Illa |
| - | 4ain | Refe | erence | Claim Det | ails | Docu | ments | ٦. | Show All |
| CLAIM SUI | BFOLDER DETA | ILS | | | | | | | |
| Insured: | NA, ID: NA | | | | | | | | |
| Main Claimant: | JAD SOLUTI | ONS PTE LTD, | Co. Reg. No.: 200 | 703726E | | | | | |
| Vehicle Reg. No.: | GBF5277E | GBF5277E Date of Loss: 07/05/2019 18:00 - :59 [29 Months and 8 Days From LTA Reg Date (| | | | | eg Date (M | an Yr)] | |
| Claim Type: | TP / SNM1 | 9D202097C02 | | Policy/Co Note No. | | SN30258919022 | 2 | | |
| Vehicle Reg. No. (Insured): | SLM2216X POINCY NO CLAIMMAN DMCVSN3026851901 | | | | | | | | |
| | | | | Excess: | \$\$0.00 |) | | | |
| Repairer: | Sng Ah Tee | Motor & Panel S | ervice Pte Ltd (P | ioneer) Blk 3 Pione | er Road Nort | h, #01-18, 6284 | 57 Pioneer - | Tel: 6268 (| 5183 |
| Handling Insurer: | China Taipin | ng Insurance (Si | ngapore) Pte. Ltd | d. (HQ) - Tel: 6389 | 6111 [Ha | ndled by Ong Cl | nin Kiat] | | |
| Claimant's Insurer: | China Taipir | ng Insurance (Si | ngapore) Pte. Ltd | d. (HQ) - Tel: 6389 | 6111 | | | | |
| Adjuster: | 29/05/2019 | ensultants Pte Li | td (HQ) - Tel: 625 | 6-3561 [Handled | by MOHD T | AUFIKH BIN H | MID] [Fi | nal Rpt | due |
| ASSOCIAT | ED MAIL RECE | IVED | | | | | View All | Compose | Case Mai |
| There are n | mail for this ca | se. | | | | | | | |
| ALL ASSO | CIATED TASKS | į į | | | View All | Search Tasks | Create No | ew Task | Complete |
| Due Date | Priority | Type Task G | roup Subject | Handler A | ssigned By | Complete | | eated On | Done |

Page 1 of 2

Claim Documents

GBF5277E (SNM19D202097C02)

[SLM2216X]

TP

JAD SOLUTIONS PTE LTD

May 7 2019 6:00PM

[NA]

Sng Ah Tee Motor & Panel Service Pte Ltd

| Ass | essment Reports | | 1 per | page 🔻 | ~ |
|-----|--|--|-------|-----------|----------|
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | - |
| 1 | 08/05/19 17:42 | Accident Statement | 0 | Load HTM | |
| 2 | 16/05/19 18:00 | Repairer Estimates | 0 | Load HTM | |
| Pho | otos/Images | | 3 per | page 🗸 | V |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | | Thumbnall | Print |
| 1 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 2 | 30/01/20 11:24 | General View | 0 | Load JPG | N |
| 3 | 30/01/20 11:24 | General View | 0 | Load JPG | ∀ |
| 4 | 30/01/20 11:24 | General View | 0 | Load 3PG | V |
| 5 | 30/01/20 11:24 | General View | 0 | Load JPG | 2 |
| 6 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 7 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 8 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 9 | 30/01/20 11:24 | General View | 0 | Load 3PG | ₽. |
| 10 | 30/01/20 11:24 | General View | 0 | Load 3PG | V |
| 11 | 30/01/20 11:24 | General View | 0 | Load JPG | Ø |
| 12 | 30/01/20 11:24 | General View | 0 | Load 3PG | 12 |
| 13 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 14 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 15 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 16 | 30/01/20 11:24 | General View | 0 | Load JPG | 120 |
| 17 | 30/01/20 11:24 | General View | 0 | Load 3PG | V |
| 18 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 19 | 30/01/20 11:24 | General View | 0 | Load JPG | Ø |
| 20 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 21 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 22 | 30/01/20 11:24 | General View | 0 | Load JPG | V |
| 23 | 30/01/20 11:24 | General View | 0 | Load JPG | W |
| 24 | 30/01/20 11:40 | Reinspection Photo | 0 | Load JPG | V |
| 25 | 30/01/20 11:40 | Reinspection Photo | ō | Load JPG | V |
| 26 | 30/01/20 11:40 | Reinspection Photo | 0 | Load JPG | <u>S</u> |
| | part of the control o | Tricking Charles (Assets) | | | |
| Doc | cumentation | | 1 per | page 🗸 | V |
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | Print |
| 1 | 16/05/19 15:40 | E-filed GIA report | 0 | Load PDF | |
| 2 | 16/05/19 15:40 | IC,DL,CI | 0 | Load TIF | |
| 3 | 16/05/19 18:01 | AUDATEX REPORT | 0 | Load PDF | |
| No | Finalized On | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) | | Thumbnail | Print |

Linked Accident Report Documents

| Vid | | | [\$ nec | page V | Z |
|---------|--------------------------------|--|---------|------------|-----------------|
| 0,237 | 7.5 | | 1 per | Thumbnail | - |
| No 1 | Finalized On 08/05/19 17:37 | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Video - Accident | 0 | Load MP4 | Print |
| - | 00/03/15 17:37 | Tideo - Accident | | 2000 111 1 | |
| Ass | essment Reports | | 1 per | page 🔻 | V |
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | Print |
| 1 | 04/09/19 01:03 | Accident Statement | 0 | Load HTM | |
| Pho | otos/Images | | 3 per | page V | Z |
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | | Thumbnail | - |
| 1 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 2 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 3 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 4 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 5 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 6 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 7 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 8 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | 1 |
| 9 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 10 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 11 | 08/05/19 17:40 | Accident Photo | 0 | Load JPG | V |
| 12 | 08/05/19 17:40 | Accident Scene Photo | 0 | Load JPG | 1 |
| 13 | 08/05/19 17:40 | Accident Scene Photo | 0 | Load JPG | 2 |
| 14 | 08/05/19 17:40 | Accident Scene Photo | 0 | Load JPG | V |
| 15 | 08/05/19 17:40 | Accident Scene Photo | 0 | Load JPG | N |
| 16 | 08/05/19 17:41 | Accident Scene Photo | 0 | Load JPG | V |
| 17 | 08/05/19 17:41 | Accident Scene Photo | 0 | Load 3PG | V |
| 18 | 08/05/19 17:41 | Accident Scene Photo | 0 | Load JPG | V |
| Dos | cumentation | | 1 per | page V | V |
| No | Finalized On | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) | (3.50) | Thumbnail | and the same of |
| 1 | 08/05/19 17:38 | Sketch Plan | 0 | Load TIF | 7.1.1.1 |
| 2 | 08/05/19 17:42 | IC,DL,CI | 0 | Load TIF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| | | | - |
| | | | 4 |
| Show Remarks To: Repairer Handling Insurer Note: Remarks are private unless you show it to other parties. | | | |

LKK Auto Consultants Pte Ltd (Co.Reg. No.:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI19008776/T1TD3E2

Date:

05/02/2020

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN30268919022

Claimant Vehicle

GBF5277E No:

Insured Vehicle SLM2216X

No:

Date of Loss: 07/05/2019 Nature of Claim: TP

Claim No:

SNM19D202097C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

GBF5277E

Make & Model:

TOYOTA DYNA, 3.0 D (M) 29/11/2016 (Man. Year: 2016) Engine No: Chassis No: Odometer:

1KD2613785 KDY2318024791

97478 km

Reg. Date: Colour:

Silver

Engine Capacity:

2982 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

175 R15

Rear Tyre Size:

145 R13 (D)

Front Left Side:

Yokohama 6 mm

Rear Left Side:

Yokohama 6/6 mm

Front Right Side:

Yokohama 6 mm

Rear Right Side:

Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

| | | | m. 144 | made of |
|------------------------|------------|----------------|------------|---------|
| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
| Parts | 1,333.00 | 610.00 | 723.00 | 54.24 |
| Miscellaneous Items | 276.00 | 275.00 | 1.00 | 0.36 |
| Labour | 235.20 | 222.60 | 12.60 | 5.36 |
| Paintwork Labour | 432.60 | 432.60 | 0.00 | 0.00 |
| Towing | 0.00 | 0.00 0.00 0.00 | | |
| Gross Total (S\$) | 2,276.80 | 1,540.20 | 736.60 | 32.35 |
| + GST 7.00/7.00% (S\$) | 159.38 | 107.81 | 51.57 | 32.36 |
| Nett Amount (S\$) | 2,436.18 | 1,648.01 | 788.17 | 32.35 |
| | | | | |

INSPECTION

Date of Assignment:

17/05/2019 Present Location:

Sng Ah Tee Motor & Panel Service Pte Ltd

(Pioneer)

Date Inspected:

17/05/2019 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd

(Pioneer)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair:

4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| Referen | | (Last Synchronised: 05 Feb 2020) |
|--------------|-------------------------------|---|
| Parts: | N/A | TOYOTA DYNA 3.0 D (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | | no print-code for GBF5277E) |
| Validity: | These estimate numbers with t | es are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page |
| Further Info | : Items/values n | ot in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty Part No. | Particulars | Condition | Repairer's | Amount |
|------|---------------|--------------|------------------------------------|------------|-----------|
| 1 | 1 | *SPARE PARTS | | 1,333.00 F | *460.00 F |
| 2 | 1 | *REAR U STEP | Bent | - | *150.00 F |
| F≖F⊓ | anchise part. | | Total Parts (S\$) | 1,333.00 | 610.00 |
| | | Report was u | insubmitted during this print-out. | | |

| Recommen | nded N | /liscellane | ous Items |
|-----------|--------|------------------|-------------|
| Neconnine | IUCU I | VII SOCIII al IC | ous itellis |

| No | Qty Particulars | | Repairer's | Amount |
|------|----------------------------------|---------------------------------|------------|--------|
| Misc | cellaneous Items | | | |
| 1 | 1 TOTAL SPECIAL NETT SPARE PARTS | | 276.00 | 275.00 |
| | | Sub Total (S\$) | 276.00 | 275.00 |
| Re | commended Labour | | | |
| No | Particulars | Lab.Type | Repairer's | Amount |
| Pair | ntwork Labour | | | |
| 1 | TOTAL PAINTWORK LABOUR | New | 432.60 | 432.60 |
| Lab | our Items | | | |
| 2 TO | TOTAL PANEL/MECHANICAL LABOUR | New | 235.20 | 222.60 |
| | | Gross Labour Cost (S\$) | 667.80 | 655.20 |
| | Report was line | ubmitted during this print-out. | | |

< END OF ESTIMATES >