



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLV 4685 P

Finalised

Parts	(a) Cost / List Price Items	\$ 2909.90	5,740.20
	Plus/Less 25%	\$ 977.48	1,435.05
	Total of Cost / List	\$ 2937.42	4,305.15
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$ 200.00	200.00
Total Parts Cost		\$ 3137.42	4,505.15
Labour		\$ 1810.00	3,260.00
Total		\$ 4947.42	7,765.15

The above total will be subjected to 7% G.S.T.

end panel need to
take photo after
take out front
bumper.

email Jeng 21/10
P/P \$ 4942.42, 6 days

Name of Surveyor

Taufik

97495749 / 67418434

Company

LICK.

Survey conducted on

17/5/19

at

1130am

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 6-7 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Taufik

Date: 17/5/19

WP'
taufik@lkhauto.com
* Resurvey before paint.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SLV 4685 P	Submit By :	Carmen Lim
Make & Model :	TOYOTA AXIO	Year Manufacture :	2017
Chassis No. :	NKE1657144200	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	ru✓
(2)	Rear bumper	1	\$496.40		de✓
3	Rear bumper clip	10	\$39.00		ru✓
4	Rear bumper side retainer LH	1	\$96.10		x ru
5	Rear bumper side retainer RH	1	\$96.10		ru✓
6	Rear bumper bracket LH	1	\$91.70		ru✓ X
7	Rear bumper bracket RH	1	\$91.70		de✓
8	Rear bumper sponge	1	N/A		X✓
9	Rear bumper reinforcement	1	N/A		X✓
10	Rear bumper reflector LH	1	\$62.70		x✓
11	Rear bumper reflector RH	1	\$62.70		x✓
(12)	Bootlid	1	\$821.90		bt✓
(13)	Bootlid lock	1	\$104.30		bt✓
14	Bootlid hinge LH	1	\$126.50		Rp✓
15	Bootlid hinge RH	1	\$126.50		bt✓
16	Bootlid emblem	1	\$67.90		ru✓
17	Wording "HYBIRD"	1	\$47.60		ru✓
18	Bootlid insulator	1	\$206.40		x ru
19	Bootlid insulator clip	10	\$32.10		x ru
(20)	Bootlid chrome	1	\$315.40		de✓
21	Tail end panel	1	\$672.60		Rp✓
22	Tail end panel garnish	1	\$218.90		? ru
23	Tail end panel garnish clip	10	\$22.10		? ru.

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

220680

200 SN

Spare Parts

Vehicle No. : **SLV 4685 P**
Make & Model : **TOYOTA AXIO**
Chassis No : **NKE1657144200**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Boot weatherstrip	1	\$197.10		<i>aut</i>
25	Tail lamp RH	1	\$721.90		<i>Chua</i>
26	Tail lamp clip	10	\$31.10		<i>re</i>
27	RH rear fender	1	\$896.70		<i>Ry</i>
28	RH rear fender undershield	1	\$72.70		X 47
29	RH rear fender undershield clip	10	\$22.10		X 47
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

te: If any of the quoted parts are recommended to be repaired, then an additional labour charge
l be charged accordingly under supplementary.

950.10



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLV 4685 P** Submit By : **Carmen Lim**
Make & Model : **TOYOTA AXIO** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,LHR FENDER END PANEL,SPARE TYRE WELL PANEL)	\$1,200.00	800.
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,LHR FENDER, END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	800
3	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60.
4	To tuff coat.	\$150.00	30.
5	To transfer boot mechanism to new boot	\$120.00	60.
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30.
7	To remove & refit reverse sensor to assist work load	\$120.00	30.

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

SLV 4685 P

Submit By :

CARMEN LIM

Make & Model :

TOYOTA AXIO

Year Manufacture :

2017

Chassis No. :

NKE1657144200

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Tail Lamp LH	1	\$721.90		<i>Car</i>
2	Tail Lamp Clip	1	\$31.10		<i>Car</i>
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

753

