

Repair Estimates

Resurvey

Excess

(e) Signature of surveyor

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Parts (a) Cost / List Price Items	\$ 5,740.20	
Plus/Less25%	\$ 1,435.05	
Total of Cost / List	\$ 4,305.15	
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$ 200.00	
Total Parts Cost	\$ 4,505.15	
Labour	\$ 3,260.00	
Total	\$ 7,765.15	
The above total will be subjected to	7% G.S.T.	
Name of Surveyor	: Tauflu	97495749 67418434
Company	: LICK!	
Survey conducted on	: 17/5/19	at(1 \(\lambda \) O q \(\sigma \)
Remarks By Surveyor		
(a) The repair of this vehicle is	authorized / is not authorized until further	notice.

Required / Not Required

SLV 4685 P



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :	SLV 4685 P	Submit By	:	Carmen Lim
Make & Model:	TOYOTA AXIO	Year Manufacture	:	2017
Chassis No :	NKE1657144200	Engine No.	:	
		Cost / List		

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	1	\$200.00	S.N	111/
2	Rear bumper	1	\$496.40		de
3	Rear bumper clip	10	\$39.00		no-
4	Rear bumper side retainer LH	1	\$96.10		K
5	Rear bumper side retainer RH	1	\$96.10		non
6	Rear bumper bracket LH	1	\$91.70		No. X
7	Rear bumper bracket RH	1	\$91.70		dl/
8	Rear bumper sponge	1	N/A		?
9	Rear bumper reinforcement	1	N/A		7
10	Rear bumper reflector LH	1	\$62.70		×
11	Rear bumper reflector RH	1	\$62.70		×
12	Bootlid	1	\$821.90		bl
13	Bootlid lock	1	\$104.30		be
14	Bootlid hinge LH	1	\$126.50		Rp
15	Bootlid hinge RH	1	\$126.50		H-
16	Bootlid emblem	1	\$67.90		her/
17	Wording "HYBIRD"	1	\$47.60		wer/
18	Bootlid insulator	1	\$206.40		×
19	Bootlid insulator clip	10	\$32.10		X
20	Bootlid chrome	1	\$315.40		de
21	Tail end panel	1	\$672.60		Ry
22	Tail end panel garnish	1	\$218.90		?
23	Tail end panel garnish clip	10	\$22.10		7.

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

will be charged accordingly under supplementary.

Spare	Parts
-------	-------

Vehicle No. :	SLV 4685 P	Submit By	:	Carmen Lim
Make & Model:	TOYOTA AXIO	Year Manufacture	:	2017
Chassis No :	NKE1657144200	Engine No.	:	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Boot weatherstrip	1	\$197.10		aut
25	Tail lamp RH	1	\$721.90		Cuar
26	Tail lamp clip	10	\$31.10		non
27	RH rear fender	1	\$896.70		RY
28	RH rear fender undershield	1	\$72.70		×
29	RH rear fender undershield clip	10	\$22.10		X
30					
31					
32					
33					
34					
35					
36					
37	LKK Auto Consultants hence notify the Repairer of the following:				
38	To resurvey before/after spray painting				
39	To display damaged part(s) during resurvey Parts prices are subject to confirmation				
40	 Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed 				
41	 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 				
42	Acknowledged by Repairer				
43	Signature:				
44	Date:				
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	SLV 4685 P	Submit By :_	Carmen Lim
Make & Model		TOYOTA AXIO	Year of Manufacture:	2017

S/No	Labour Description	Esimated Price	Adjusted Price	
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		V T I I	
	REPAIR AREA. (REAR BUMPER,BOOTLID,LHR FENDER	\$1,200.00	800.	
	END PANEL,SPARE TYRE WELL PANEL)			
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT			
	REPAIR AREA. (REAR BUMPER,BOOTLID,LHR FENDER,	\$1,400.00	800	
-	END PANEL,SPARE TYRE WELL PANEL)			
3	To remove & refit spare tyre, spare tyre board, carpet trim	\$150.00	60.	
	to assist work load.			
4	To tuff coat.	\$150.00	30.	
5	To transfer boot mechanism to new boot	\$120.00	60-	
6	To conduct water leakage tests to ensure proper air and	\$120.00	30.	
	sealing			
7	To remove & refit reverse sensor to assit work load	\$120.00	30.	

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.