

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX

SINGAPORE 069110

INV No. AC2106517

INV Date 17/09/2021

Reference CC4/EQI19008844/Upa3q2

Code EQI

#### PROFESSIONAL SERVICE FEE

Vehicle No. YP 684X

Insured Veh. SLB 9455J

Claim No. DM19HO01414-JG

Policy No. DMPPHQ19-002586

Accident Date 13/05/2019

Inspection Date 21/05/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**LKM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile						
	EQ INSURANCE C	OMPANY LTD	Ref:	CC4/EQI19008844/Upa3q2			
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		Date:	17/09/2021			
			Code:	EQI			
1.		Policy Particulars	- THIRD PARTY CLAIN	1			
	Insured Veh.	SLB 9455J	Veh. Inspected	YP 684X			
	Policy No.	DMPPHQ19-002586	Coverage (\$)	0.00			
	Claim No.	DM19HO01414-JG	Excess (\$)	0.00			
	Assign From	JOEL	Assign Date	18/05/2019			
2.		Vehicle Partic	ulars & Condition				
	Make & Model	MITSUBISHI CANTER	c.c	2998			
	Engine No.	HIDDEN	Year of Reg.	2015			
	Chassis No.	FEB71GA10012	Colour	WHITE			
	Odometer	61404 KM	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	NIL			
	General	GOOD					
3.		Condition	ons of Tyres				
		Size	Make	Balance			
	D/II Frant Time	215/75 R17.5	BRIDGESTONE	6 mm			
	R/H Front Tyre						
	L/H Front Tyre	215/75 R17.5	BRIDGESTONE	6 mm			
	· -	215/75 R17.5 215/75 R17.5 (D)	BRIDGESTONE BRIDGESTONE	6 mm 6/6 mm			
	L/H Front Tyre						
4.	L/H Front Tyre R/H Rear Tyre	215/75 R17.5 (D) 215/75 R17.5 (D)	BRIDGESTONE	6/6 mm			
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	215/75 R17.5 (D) 215/75 R17.5 (D)	BRIDGESTONE BRIDGESTONE on of Damages	6/6 mm			
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	215/75 R17.5 (D) 215/75 R17.5 (D)  Description  STAINED DAMAGES AT THE O/S	BRIDGESTONE BRIDGESTONE on of Damages	6/6 mm			
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	215/75 R17.5 (D) 215/75 R17.5 (D)  Description  STAINED DAMAGES AT THE O/S  ETAILS.	BRIDGESTONE BRIDGESTONE on of Damages	6/6 mm			
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	215/75 R17.5 (D) 215/75 R17.5 (D)  Description  STAINED DAMAGES AT THE O/S  ETAILS.	BRIDGESTONE BRIDGESTONE on of Damages REAR PORTION.	6/6 mm			
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUST	215/75 R17.5 (D) 215/75 R17.5 (D)  Description STAINED DAMAGES AT THE O/S ETAILS.  General	BRIDGESTONE BRIDGESTONE on of Damages REAR PORTION. Information Inspection Date	6/6 mm 6/6 mm			
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE D	215/75 R17.5 (D)  215/75 R17.5 (D)  Description STAINED DAMAGES AT THE O/S ETAILS.  General  13/05/2019	BRIDGESTONE BRIDGESTONE on of Damages REAR PORTION.  Information Inspection Date ERING WORKSHOP	6/6 mm 6/6 mm 21/05/2019			
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE D	215/75 R17.5 (D)  215/75 R17.5 (D)  Description STAINED DAMAGES AT THE O/S ETAILS.  General  13/05/2019  LIU'S BROTHER AUTO ENGINE 1 KAKI BUKIT AVENUE 6 #01-01 SINGAPORE 417883	BRIDGESTONE BRIDGESTONE on of Damages REAR PORTION.  Information Inspection Date ERING WORKSHOP	6/6 mm 6/6 mm 21/05/2019			
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUST DAMAGES SEE D  Accident Date Survey held at	215/75 R17.5 (D)  215/75 R17.5 (D)  Description STAINED DAMAGES AT THE O/S ETAILS.  General  13/05/2019  LIU'S BROTHER AUTO ENGINE 1 KAKI BUKIT AVENUE 6 #01-01 SINGAPORE 417883	BRIDGESTONE BRIDGESTONE On of Damages REAR PORTION.  Information Inspection Date ERING WORKSHOP 1 AUTOBAY @ KAKI BUKI	6/6 mm 6/6 mm 21/05/2019			
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUST DAMAGES SEE D  Accident Date Survey held at	215/75 R17.5 (D)  215/75 R17.5 (D)  Description STAINED DAMAGES AT THE O/S ETAILS.  General  13/05/2019  LIU'S BROTHER AUTO ENGINE 1 KAKI BUKIT AVENUE 6 #01-01 SINGAPORE 417883  Recon WAS CONDUCTED ON A"WIT	BRIDGESTONE BRIDGESTONE On of Damages REAR PORTION.  Information Inspection Date ERING WORKSHOP 1 AUTOBAY @ KAKI BUKI	6/6 mm 6/6 mm 21/05/2019			
5. 5a.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre  THE VEHICLE SUST DAMAGES SEE D  Accident Date Survey held at  A)THE INSPECTIC B)IN ACCORDANCE	215/75 R17.5 (D)  215/75 R17.5 (D)  Description STAINED DAMAGES AT THE O/S ETAILS.  General  13/05/2019  LIU'S BROTHER AUTO ENGINE 1 KAKI BUKIT AVENUE 6 #01-01 SINGAPORE 417883  Recon WAS CONDUCTED ON A"WIT	BRIDGESTONE BRIDGESTONE On of Damages REAR PORTION.  Information Inspection Date ERING WORKSHOP 1 AUTOBAY @ KAKI BUKI EMARKS HOUT PREJUDICE" BASIS E HAVE NOT AUTHORISE Days of Repair	6/6 mm 6/6 mm 21/05/2019			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 684X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR RH BACK DOOR PILLAR	TO REPAIR SEE LABOUR	400.00	-
1	REAR RH 'CORPORATE' ADVERTISEMENT & ARTWORK	NOT NECESSARY	550.00	-
			950.00	-
	SPECIAL NETT ITEMS			
1	REAR RH BACK DOOR PILLAR ALUMINIUM PANEL (SN)	DENTED / BENT	1,800.00	1,200.00
			1,800.00	1,200.00
	<u>LABOUR</u>			
	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF REAR RH BACK DOOR PILLAR .		800.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED .		400.00	300.00
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.	NOT NECESSARY	100.00	-
	TO REMOVE ,REPLACE AND TRANSFER DOOR PANEL,FITTING AND MECHANISMS.	NOT NECESSARY	100.00	-
			1,400.00	600.00
	GRAND TOTAL		4,150.00	1,800.00

RECOMMENDED COST OF LUMP SUM REPAIRS		1,400.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/EQI19008844/Upa3q2

CHUA KANG SENG

**Licensed Appraiser** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315


Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. YP 684X

**INSPECTION** 
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. YP 684X

### **RE-INSPECTION**









