

Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



Report no: 495M1116.HH

Vehicle no: SGT8921B



FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3
#02-15, Veres
Singapore 408865

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : RRN16-114882/RI/GS/cg

Your Reference: MT/CA/TP/009/0923139-002/CH/CK

Date : 24 Feb 2017

Motor Claims Department
NTUC Income Insurance Co-Operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Attention : Ms Corinne Hoo

Dear Sir / Mdm,

RE-INSPECTION OF VEHICLE NO . SGT 8921B

Pursuant to your instructions on 13 Jan 2017, we have conducted a reinspection of the above vehicle at 2 Kaki Bukit Ave 2 #02-13 S'417921 on 07 Feb 2017.

We recommend a repair cost of **\$3,250.00** (see report) based on lump sum repair and the estimated duration of repairs would take **04 days**

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)

Gary Soon 
Automobile Appraiser

(Email : gary@fta.com.sg)

Encl. Re-inspection Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : RKN16-114882/RI/GS/cg
Your Reference : MT/CA/TP/009/0923139-002/CH/CK

Date : 24-Feb-2017

Attention : Ms Corinne Hou

TO : Motor Claims Department
NTUC Income Insurance Co Operative Limited
73 Bras Basah Road
#05-01 NTUC Trade Union House
Singapore 189556

Dear Sir/Madam,

Vehicle No : SGT 8921B
Model : Peugeot 307
Mileage : 161959 km
Chassis No : VF33BRFJ84940237
Workshop : M/S Hiap Hong Motor Repair

Pursuant to your instructions on 13 Jan 2017, we have conducted a reinspection of the above vehicle at 2 Kaki Bukit Ave 2 #02-13 S'417921 on 07 Feb 2017.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Front Bumper	Slight Damage	Repairable	1,192.00	-
2	Frt Bumper Side Retainer LH/RH	Necessary		170.00	170.00
8	Front Bumper Clip	Necessary		48.00	48.00
1	Front Fender LHS	Slight Damage	Repairable	380.00	-
1	Front Fender Splash Shield	To Reuse		-	-
8	Front Fender Splash Shield Clip	To Reuse		-	-
1	Front Fender Indicator Lamp Assy	To Reuse		-	-
1	Front Door Assy LHS	Dented/Scraped		1,950.00	1,740.00
1	Front Door Weatherstrip	To Reuse		86.00	-
1	Front Door Protector	Scraped/Bent		90.00	90.00
2	Front Door Hinge	To Repair		-	-
1	Front Door Glass Regulator Cum Motor	Bent		342.00	342.00
1	Front Door Trim Board	To Reuse		-	-
10	Front Door Trim Board Clip	Necessary		50.00	50.00
1	Front Door Inner Lock Assy	Distorted/Jaws Shaky		190.00	190.00

FormTeam Consultancy Pte Ltd

PAGE : 2

Our Reference : RRN16-114882/RI/GS/cg

Your Reference : MT/CA/TP/009/0923139-002/CH/CK

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Front Door Check	To Repair		-	-
1	Front Door Outer Handle	To Repair		-	-
1	LHS Side Skirt	Dented/Deformed		422.00	422.00
1	Front Door 1/4 Glass Moulding	No Photo Show Damaged		205.00	-
	List Items Sub-Total			5,125.00	3,052.00
	Original Less 10%			512.50	305.20
	Revised Less 10%				
	Total Parts Amount			4,612.50	2,746.80

FormTeam Consultancy Pte Ltd

PAGE : 3

Our Reference : RRN16-114882/RI/GS/cg

Your Reference : MT/CA/TP/009/0923139-002/CH/CK

QTY	DESCRIPTION	SUBMITTED	REVISED
	<u>LABOUR & MISC</u>		
1	To check wirings.	30.00	30.00
2	To remove and refix front door glass and serviceable parts.	60.00	60.00
3	To apply anti-rust undercoating.	90.00	30.00
4	Labour charges to remove and replace, to cut and weld, to knock and reshape affected parts/areas. (including all repair parts)	600.00	400.00
5	Spray painting charges to putty and spray all affected parts/areas.	1,000.00	800.00
	Total Labour Amount	1,780.00	1,320.00
	Total Parts and Labour	6,392.50	4,066.80

FormTeam Consultancy Pte Ltd

PAGE : 4

Our Reference : RRN16-114882/RI/GS/cg

Your Reference: MT/CA/TP/009/0923139-002/CIH/CK

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)		
		\$5,200.00	\$3,250.00

REMARKS :


Our recommended Lump Sum Repair Cost is **\$3,250.00** (instead of the submitted repair cost of **\$5,200.00** . In normal circumstances, repairs to the vehicle would take approximately **04 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FormTeam Consultancy Pte Ltd



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser



Gary Soon
Automobile Appraiser

FormTeam Consultancy Pte Ltd

Vehicle No: SGT 8921B

Workshop: Hiap Hong Motor Repair

Accident Date: 14 November 2016

No. 33 Ubi Ave 3
#02-15 Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorurvey@fta.com.sg
www.fta.com.sg

Co. Reg No: 200819280D

GST Reg. No: 200819280D



