

15/02/01

INS. CASE OWNER:

CC 3/EQ11900

8917

K1 e16 s2

LKK:

IDAC:

Surveyor:

Edlin

DOI:

ASSIGNMENT

1/5/19

Date / Time:

12/5/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBD 4859T

Name of Insured:

GITECH Scaffolding bil

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

10/5/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MURUGAN

EZHIMUTHAVAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

0M1ANV1369

Policy No.:

0M1ANV1369-007240

Make / Model:

TOMPA

Place of Accident:

UPP SEBAMPOON RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHO 45E



INSRS:

WSP:

Tel:

Liability:

RMKS:

trans
cab.

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHO 45E - no (456100486) (26.01.19)
6/10/2019 - 1

20-11-19

FILE PASS TO TYPIST TO PREPARE REPORT.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

ASHER 2/11/19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

(NO NEED)

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: ASH

Repair Cost:

45 \$59,500.00

(5

days) Reduction:

85

%

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 05-03-20

Confirm with: WMS YIN

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

37

If NO or B 28, Ass. Lia:

Repair Cost:

2/15/1

\$510,218.50

OLD REAR ENDED TP

Loss of Rental (LOR):

\$5 715.93

(8

days) x +96.99

Loss of Use (LOU):

\$5 -

(5

x days)

Loss of Income (LOI):

\$5 -

(5

x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$57.49

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

Total:

\$511,001.91

Global Sum \$5:

FINAL PAYMENT

Date/Time: 05-03-20

Confirm with: WMS YIN

Email ☒Call ☐

Payee 1:

\$511,001.91

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

400

COPY SENT
6/3/2020

(08/11/13)

REF:

Surveyor: Kalvin

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 45 E Yr Regn: 23 Mar 2015Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Taxi~~ / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995Colour: M. Red / White A/C: Insured / Std / NI / NASp. Reading: 484086 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABLI5 A4C281528Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD AB / Rim orTyre Size: F: 215 / 60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Arti Comfort

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 10/5/19 D.O.I. 17/5/19Survey held at TranscubDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRen.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>EQ</u>
	<u>46: +9,550 (RED: +43,951.01 82%)</u>
	<u>42</u>

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / I.B.I. (\$) _____



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQI19008917/K1eb3

Date: 21.05.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD45E


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.05.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	52,507.07
Revised Estimate Amount	: S\$	11,916.80
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date Of Registration:

SHD 45E

VF1ABL15AUC281538

RENAULT

LATITUDE

10.5.19

EQ

23/3/2015

		PART		LIST
1	1	BUMPER COVER REAR	BT	\$ 1,108.46
2	1	BUMPER LOWER REAR	CUT	\$ 768.84
3	1	BUMPER BRACKET CTR REAR	BT	\$ 113.47
4	1	BUMPER BRACKET SIDE RH REAR	X } NN	\$ 135.97
5	1	BUMPER RETAINER RH REAR	X	\$ 44.99
6	1	BUMPER REFLECTOR RH	X NN old Panay	\$ 43.61
7	1	BUMPER BRACKET SIDE LH REAR	X NN	\$ 135.97
8	1	BUMPER RETAINER LH REAR	X NN	\$ 44.99
9	1	BUMPER REFLECTOR LH	MIS	\$ 43.61
10	1	BUMPER BEAM REAR	BT	\$ 777.52
11	1	BUMPER BEAM BRACKET LH REAR	BT	\$ 225.95
12	1	BUMPER BEAM BRACKET RH REAR	BT	\$ 225.95
13	1	BOOT REAR	BT	\$ 2,872.68
14	1	BOOT FINISHER	X	\$ 470.06
15	1	BOOT WHEATERSTRIP	X } NN	\$ 323.05
16	1	BOOT REFLECTOR LAMP LH	BROKEN	\$ 493.35
17	1	BOOT REFLECTOR LAMP RH	CUT	\$ 493.35
18	1	BOOT BADGE 'RENAULT'	NEC	\$ 225.36
19	1	BOOT BADGE	NEC	\$ 225.36
20	1	BOOT STRUT LH	X	\$ 276.08
21	1	BOOT STRUT RH	X	\$ 276.08
22	1	BOOT HINGE LH	X	\$ 367.84
23	1	BOOT HINGE RH	X	\$ 367.84
24	1	BOOT INNER TRIM	X } NN	\$ 586.45
25	1	BOOT SWITCH	X	\$ 168.13
26	1	BOOT LOCK	X	\$ 202.67
27	1	BOOT LOCK CATCH	X	\$ 74.40
28	2	LICENCE PLATE LAMP	X	\$ 50.52
29	2	BOOT RUBBER PLUG	X	\$ 221.81
30	1	FENDER PANEL INNER TRIM REAR RH	X NN	\$ 671.45

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

31	1	FENDER PANEL REAR RH	X		\$	3,299.13
32	1	WHEELARCH REAR RH	X		\$	543.47
33	1	FENDER PANEL REAR LH	X		\$	3,299.13
34	1	FENDER PANEL INNER TRIM REAR LH	X		\$	671.45
35	1	WHEELARCH REAR LH	X		\$	543.47
36	1	TAILLAMP RH		Cap	\$	552.55
37	1	TAILLAMP PANEL RH	X	Cap	\$	986.70
38	1	TAILLAMP LH		Cap	\$	552.55
39	1	TAILLAMP PANEL LH	X	Cap	\$	986.70
40	1	OUTER PANEL REAR (End Panel)		DT	\$	1,471.77
41	1	OUTER PANEL REAR (End Panel)TRIM		NEC	\$	404.56
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	X		\$	2,189.88
43	1	SPARE WHEEL PANEL TRIM	X		\$	612.21
44	1	EXHAUST REAR	X		\$	7,489.05
45	1	EXHAUST CAP REAR	X		\$	230.49

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05

Special Nett

1	1SET	PARKING AID		Short	\$	700.00 500
2	1SET	REAR BUMPER CLIP		NEC	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP		NEC	\$	33.00
4	1SET	BUMPER BRACKET SIDE CLIP RH RR		+ NM	\$	10.00
5	1SET	BUMPER RETAINER RH CLIP RR		NEC	\$	20.00
6	1SET	BUMPER BRACKET SIDE CLIP LH RR		+ NM	\$	10.00
7	1SET	BUMPER RETAINER CLIP LH RR			\$	20.00
8	1SET	BUMPER LOWER REAR RIVET		NEC	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP			\$	66.00
10	1	EXHAUST MOUNTING REAR	X	NM	\$	17.82
11	1SET	BOOT FINISHER CLIP	X		\$	24.20
12	1	BOOT STICKER "Trans-cab"		NEC	\$	30.00
13	1	BOOT STICKER "6555-3333"		NEC	\$	30.00
14	1	BOOT INNER TRIM CLIP	X	NM	\$	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP	X		\$	35.00
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	X	NM	\$	385.00
17	1	SPARE TYRE	X		\$	330.00

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

18	1	FENDER INNER TRIM CLIP RH	X ^{NN}	\$	28.00
19	1	TAILLAMP CLIP RH	— NEC	\$	5.00
20	2	REAR WINDSCREEN SEALANT	X } ^{NN}	\$	80.00
21	1	WINDSCREEN MOULDING	X	\$	100.00
22	1	REAR WINDSCREEN INNER SPONGE SEAL	X ^{NN}	\$	100.00
23	1	TAILLAMP CLIP LH	— NEC	\$	5.00
24	1	FENDER INNER TRIM CLIP LH	X	\$	28.00
25	1SET	FENDER WHEELARCH REAR LH CLIP	X } ^{NN}	\$	35.00
26	1	Rear left tyre	X	\$	330.00
27	1	Rear left tyre rim	X	\$	380.00
28	1	Rear right tyre	X	\$	330.00
29	1	Rear right tyre rim	X	\$	380.00
TOTAL				\$	3,645.02

TOTAL PARTS \$ 35,927.07**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 ⁶⁰⁰
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 ⁸⁰⁰
To reinstall rear bumper parking sensor.	\$	170.00 ⁴⁰
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 ⁵⁰
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 ^X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 ⁵⁰
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 ^X

Trans-cab Auto Services Pte Ltd**AAD1905-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 45E

To check steering geometry and computer wheel alignment	\$	220.00 X
To Rust-Proofing Of The Affected Areas.	\$	170.00 50
To repair and realign rear exhaust pipe.	\$	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 X
To Check Electrical Lighting Concerned.	\$	170.00 30
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X

TOTAL \$ 16,580.00**Over All Total \$ 52,507.07****(LUMP SUM) Repair Days 20 DAYS**

Kahin 11/11/19

17/5/19

1715L

5 Days

4/5 After Repair photo

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD45E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002608
Chassis No.:	VF1ABL15AUC281538
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	23 Mar 2015
First Registration Date:	23 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2023
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	22 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$24,601.00
Total Rebate Amount:	\$33,974.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 May 2019

OK

Shu Pei (LKKAuto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 23 May 2019 4:45 PM
To: Shu Pei (LKKAuto)
Cc: Admin A; Asher Sng (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving GBD4859T (OI : EQI - DM19HO01369-JG) AND SHD45E (TP : LKK REF - CC3/EQI19008917/K1eb3) on 10.05.2019
Attachments: GBD4859T.pdf

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh

EQ Insurance Company Limited



EQ Insurance Company Limited

50 Bras Basah Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6223 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

Website: eqinsurance.com.sg

A Member of Citigroup

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]

Sent: Tuesday, May 21, 2019 7:47 PM

To: Janet Tan; Joel Goh

Cc: Admin A; Asher Sng (LKKAuto)

Subject: Direct Settlement - Accident Involving GBD4859T (OI : EQI - TBA) AND SHD45E (TP : LKK REF - CC3/EQI19008917/K1eb3) on 10.05.2019

WITHOUT PREJUDICE

Dear Janet / Joel,

We refer to the above matter.

We have inspected TP vehicle SHD 45E at M/s Trans-cab Auto Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

TP GIA report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI19008917/K1ea3s2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 10-03-2020	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 4859T	Veh. Inspected	SHD 45E
Policy No.	DMCPHQ18-007340	Coverage (\$)	0.00
Claim No.	DM19HO01369-JG	Excess (\$)	0.00
Assign From		Assign Date	17/05/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281538	Colour	METALLIC RED / WHITE
Odometer	484086	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI COMFORT	7 mm
L/H Front Tyre	215/60 R16	GITI COMFORT	7 mm
R/H Rear Tyre	215/60 R16	GITI COMFORT	7 mm
L/H Rear Tyre	215/60 R16	GITI COMFORT	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	10/05/2019	Inspection Date	17/05/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 45E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	BENT	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER RH REAR	NOT NECESSARY	44.99	-
1	BUMPER REFLECTOR RH (NOT NECESSARY)	OLD DAMAGED	43.61	-
1	BUMPER BRACKET SIDE LH REAR	NOT NECESSARY	135.97	-
1	BUMPER RETAINER LH REAR	NOT NECESSARY	44.99	-
1	BUMPER REFLECTOR LH	MISSING	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	BENT	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	NOT NECESSARY	470.06	-
1	BOOT WEATHERSTRIP	NOT NECESSARY	323.05	-
1	BOOT REFLECTOR LAMP LH	BROKEN	493.35	493.35
1	BOOT REFLECTOR LAMP RH	CUT	493.35	493.35
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	NOT NECESSARY	276.08	-
1	BOOT STRUT RH	NOT NECESSARY	276.08	-
1	BOOT HINGE LH	NOT NECESSARY	367.84	-
1	BOOT HINGE RH	NOT NECESSARY	367.84	-
1	BOOT INNER TRIM	NOT NECESSARY	586.45	-
1	BOOT SWITCH	NOT NECESSARY	168.13	-
1	BOOT LOCK	NOT NECESSARY	202.67	-
1	BOOT LOCK CATCH	NOT NECESSARY	74.40	-
2	LICENCE PLATE LAMP	NOT NECESSARY	50.52	-
2	BOOT RUBBER PLUG	NOT NECESSARY	221.81	-
1	FENDER PANEL INNER TRIM REAR RH	NOT NECESSARY	671.45	-
1	FENDER PANEL REAR RH	NOT NECESSARY	3,299.13	-

Report Ref No. CC3/EQI19008917/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEELARCH REAR RH	NOT NECESSARY	543.47	-
1	FENDER PANEL REAR LH	NOT NECESSARY	3,299.13	-
1	FENDER PANEL INNER TRIM REAR LH	NOT NECESSARY	671.45	-
1	WHEELARCH REAR LH	NOT NECESSARY	543.47	-
1	TAILLAMP RH	CRACKED	552.55	552.55
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	DENTED	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	NECESSARY	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	NOT NECESSARY	2,189.88	-
1	SPARE WHEEL PANEL TRIM	NOT NECESSARY	612.21	-
1	EXHAUST REAR	NOT NECESSARY	7,489.05	-
1	EXHAUST CAP REAR	NOT NECESSARY	230.49	-
	LESS 10% DISCOUNT		-3,586.87	-1,055.53
			32,282.05	9,499.80
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	500.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NECESSARY	20.00	20.00
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NECESSARY	20.00	20.00
1	SET BUMPER LOWER REAR RIVET (SN)	NECESSARY	22.00	22.00
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-

Report Ref No. CC3/EQI19008917/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	NOT NECESSARY	385.00	-
1	SPARE TYRE (SN)	NOT NECESSARY	330.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	REAR LEFT TYRE (SN)	NOT NECESSARY	330.00	-
1	REAR LEFT TYRE RIM (SN)	NOT NECESSARY	380.00	-
1	REAR RIGHT TYRE (SN)	NOT NECESSARY	330.00	-
1	REAR RIGHT TYRE RIM (SN)	NOT NECESSARY	380.00	-
			3,645.02	797.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	600.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH AND TAILLAMP PANEL LH.		6,000.00	800.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	40.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	50.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	50.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CC3/EQ19008917/K1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	50.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
			16,580.00	1,620.00
	GRAND TOTAL		52,507.07	11,916.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,550.00

Report Ref No. CC3/EQ19008917/K1ea3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.