

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19008951/UDA3Q2

**Date:** 24/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant**  
**Vehicle No :** GBG4687G

**Insured Vehicle No :** SKL738L

Date of Loss: 18/05/2019

Nature of Claim: TP

Claim No: 3916684208SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG4687G**

Make & Model: SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0  
AT AIRBAG 2WD (A)

Engine No: 67196022687744

Reg. Date: 18/08/2017 (Man. Year: 2017)

Chassis No: KPADA1ETSH304165

Colour: Grey

Odometer: 89526 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/75R16

Rear Tyre Size: 225/75R16

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 13,265.42         | 5,783.85          | 7,481.57          | 56.40         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 2,250.00          | 1,350.00          | 900.00            | 40.00         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>15,515.42</b>  | <b>7,133.85</b>   | <b>8,381.57</b>   | <b>54.02</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>5,700.00</b>   |                   |               |
| <b>(S\$)</b>                                     | 15,515.42         | 5,700.00          | 9,815.42          | 63.26         |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 1,086.08          | 399.00            | 687.08            | 63.26         |
| <b>Nett Amount (S\$)</b>                         | <b>16,601.50</b>  | <b>6,099.00</b>   | <b>10,502.50</b>  | <b>63.26</b>  |
| <b>+ Loss of Use (4.0 x S\$100.00/day) (S\$)</b> |                   | 400.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>6,501.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>6,500.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 21/05/2019

Date Inspected: 21/05/2019 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)  
1 Kaki Bukit Avenue 6 #01-48,  
AutoBay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's | Amount       |
|-----|-----|----------|-----------------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                           | Deep Cut/Torn | 1,866.02 F | *1,250.00 FL |
| 2   | 1   |          | *FRONT BUMPER SIDE RETAINER O/S         | Not Necessary | 99.50 F    | *- FL        |
| 3   | 1   |          | *SET FRONT BUMPER CLIPS                 | Necessary     | 50.00 F    | *50.00 FL    |
| 4   | 1   |          | *FRONT BUMPER FOG LAMP O/S              | Cracked       | 485.00 F   | *425.00 FL   |
| 5   | 1   |          | *FRONT BUMPER CENTRE GRILLE             | Torn          | 305.30 F   | *228.00 FL   |
| 6   | 1   |          | *FRONT GRILLE                           | Not Necessary | 366.50 F   | *- FL        |
| 7   | 1   |          | *HEADLAMP O/S                           | Cracked       | 1,850.00 F | *1,150.00 FL |
| 8   | 1   |          | *FRONT SUPPORT PANEL                    | Repair        | 1,050.50 F | *- FL        |
| 9   | 1   |          | *FRONT FENDER O/S                       | Dented/Bent   | 988.30 F   | *688.00 FL   |
| 10  | 1   |          | *FRONT FENDER INNERSHIELD O/S           | Torn          | 295.40 F   | *226.00 FL   |
| 11  | 1   |          | *SET FRONT FENDER INNERSHIELD CLIPS O/S | Necessary     | 50.00 F    | *50.00 FL    |
| 12  | 1   |          | *FRONT SHOCK ABSORBER O/S               | Not Necessary | 688.10 F   | *- FL        |
| 13  | 1   |          | *FRONT KNUCKLE ARM O/S                  | Bent          | 788.20 F   | *788.20 FL   |
| 14  | 1   |          | *FRONT KNUCKLE ARM BEARING O/S          | Necessary     | 560.50 F   | *560.50 FL   |
| 15  | 1   |          | *FRONT LOWER ARM O/S                    | Twisted       | 699.30 F   | *699.30 FL   |
| 16  | 1   |          | *FRONT TOP ARM O/S                      | Bent          | 311.50 F   | *311.50 FL   |
| 17  | 1   |          | *FRONT STEERING RACK ASSY               | Not Necessary | 2,811.30 F | *- FL        |

F=Franchise part. L=ListItemDisc.

|                                                           |                  |                 |
|-----------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                   | <b>13,265.42</b> | <b>6,426.50</b> |
| <b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b> | 0.00             | 642.65          |

|                           |                  |                 |
|---------------------------|------------------|-----------------|
| <b>Total Parts (\$\$)</b> | <b>13,265.42</b> | <b>5,783.85</b> |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                              |          |                 |                 |
| 1                               | TO CHECK WIRING                              | New      | 50.00           | 20.00           |
| 2                               | TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE | New      | 180.00          | 120.00          |
| 3                               | TO REFILL AIR CON GAS                        | New      | 120.00          | 0.00            |
| 4                               | TO CONDUCT WHEEL ALIGNMENT                   | New      | 120.00          | 60.00           |
| 5                               | TO SPRAY RUST PROOFING                       | New      | 50.00           | 30.00           |
| 6                               | LABOUR FOR PANEL BEATING & REPLACING PARTS   | New      | 880.00          | 520.00          |
| 7                               | TO PUTTY & SPRAY PAINTING                    | New      | 850.00          | 600.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                              |          | <b>2,250.00</b> | <b>1,350.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >