

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19008971/AGA3Q2

Date: 05/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJJ8432M	Insured Vehicle No :	SHA7915P
Date of Loss: 16/05/2019	Nature of Claim: TP	Claim No: MCT19050476

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ8432M	Engine No:	4G18JS1072
Make & Model:	MITSUBISHI LANCER, 1.6 (A)	Chassis No:	JMYSTCS3A8U008953
Reg. Date:	26/09/2008 (Man. Year: 2008)	Odometer:	197565 km
Colour:	Black		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,040.05	6,681.96	9,358.09	58.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,970.00	1,360.00	31.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,370.05	9,651.96	10,718.09	52.62
Approved Total (Overridden) (\$\$)		7,700.00		
(\$\$)	20,370.05	7,700.00	12,670.05	62.20
+ GST 7.00/7.00% (\$\$)	1,425.90	539.00	886.90	62.20
Nett Amount (\$\$)	21,795.95	8,239.00	13,556.95	62.20
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	21/05/2019	
Date Inspected:	21/05/2019 Inspected At:	Green Forest Automobile Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	10.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2020)
Parts:	143	MITSUBISHI LANCER 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ8432M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	650.00 F	*- FL
2	2		*FRONT BONNET HINGES	Not Necessary	98.00 F	*- FL
3	1		*FRONT BONNET INNER RUBBER	Not Necessary	69.00 F	*- FL
4	1		*FRONT BONNET OUTER RUBBER	Not Necessary	67.00 F	*- FL
5	1		*FRONT BONNET LOCK	Not Necessary	98.00 F	*- FL
6	20		*FRONT BONNET RUBBER CLIPS	Not Necessary	70.00 F	*- FL
7	2		*FRONT HEADLAMP	Not Necessary	1,056.00 F	*- FL
8	1		*FRONT WIPER GARNISH	Deformed	561.40 F	*561.40 FL
9	1		*FRONT WIPER GARNISH RUBBER	Not Necessary	131.75 F	*- FL
10	1		*FRONT WIPER	Not Necessary	98.00 F	*- FL
11	6		*FRONT WIPER GARNISH CLIPS	Necessary	77.40 F	*30.00 FL
12	1		*FRONT SUPPORT PANEL	Not Necessary	625.00 F	*- FL
13	1		*FRONT CROSS MEMBER	Bent	750.00 F	*750.00 FL
14	1		*FRONT CHASSIS -RH	Not Necessary	650.00 F	*- FL
15	1		*FRONT BUMPER	Repair	708.00 F	*- FL
16	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	82.00 F	*- FL
17	12		*FRONT BUMPER SIDE BRACKET DEVIT	Not Necessary	42.00 F	*- FL
18	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
19	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	32.00 F	*- FL
20	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	145.00 F	*- FL
21	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	116.00 F	*- FL
22	6		*FRONT BUMPER CLIPS	Not Necessary	48.00 F	*- FL
23	2		*FRONT BUMPER SIDE CLIPS	Not Necessary	25.80 F	*- FL
24	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	285.00 F	*- FL
25	1		*FRONT GRILLE	Not Necessary	135.00 F	*- FL
26	1		*FRONT GRILLE EMBLE LOGO	Not Necessary	35.00 F	*- FL
27	2		*FRONT GRILLE SIDE COVER	Not Necessary	270.00 F	*- FL
28	5		*FRONT GRILLE CLIPS	Not Necessary	40.00 F	*- FL
29	1		*FRONT R/H FENDER	Distorted	460.00 F	*460.00 FL
30	1		*FRONT FENDER COWLING	Torn	107.00 F	*107.00 FL
31	8		*FRONT FENDER COWLING CLIPS	Necessary	40.00 F	*40.00 FL
32	1		*FRONT R/H FENDER SIGNAL LAMP	Cracked	29.00 F	*29.00 FL
33	1		*FRONT WINDSCREEN MOULDING	Necessary	68.00 F	*68.00 FL
34	10		*FRONT WINDSCREEN MOULDING CLIPS	Necessary	75.00 F	*30.00 FL
35	1		*RIM -RH FRONT	Cut	400.00 F	*400.00 FL
36	1		*FRONT TIRE -RH	Not Necessary	350.00 F	*- FL
37	1		*FRONT SAFETY BELT -RH	Not Necessary	450.00 F	*- FL
38	1		*FRONT R/H DOOR	Distorted	954.00 F	*854.00 FL
39	1		*FRONT R/H DOOR GLASS	Not Necessary	411.30 F	*- FL
40	1		*FRONT R/H DOOR INNER GEAR & MOTOR	Not Necessary	432.40 F	*- FL
41	2		*FRONT R/H DOOR TOP & LOWER HINGE	Bent	132.00 F	*132.00 FL
42	1		*FRONT R/H DOOR SIDE MIRROR	Cracked	341.00 F	*341.00 FL
43	1		*FRONT R/H DOOR PILLAR	Dented	628.00 F	*628.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT R/H DOOR SILL PANEL	Dented	759.00 F	*759.00 FL
45	10		*FRONT R/H DOOR LOWER SKIRT CLIPS	Not Necessary	50.00 F	*- FL
46	1		*FRONT R/H DOOR INNER LOCK	Damaged	260.00 F	*260.00 FL
47	1		*FRONT R/H DOOR INNER TRIM BOARD	Deformed	750.00 F	*750.00 FL
48	1		*FRONT R/H DOOR LOWER PROTECTOR	Necessary	125.00 F	*125.00 FL
49	1		*FRONT R/H SHOCK ABSORBER	Bent	387.00 F	*387.00 FL
50	1		*FRONT R/H DRIVE SHAFT	Not Necessary	1,103.00 F	*- FL
51	1		*FRONT R/H KNUCKLE ARM	Damaged	301.00 F	*301.00 FL
52	1		*FRONT R/H KNUCKLE ARM BEARING	Necessary	130.00 F	*130.00 FL
53	1		*FRONT R/H LOWER ARM	Bent	282.00 F	*282.00 FL
					Sub Total (\$\$)	16,040.05 7,424.40
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 742.44
					Total Parts (\$\$)	16,040.05 6,681.96

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL FRONT CROSSMEMBER & CHASSIS	New	450.00	150.00
2	TO REMOVE & REFIX CUSHION	New	150.00	80.00
3	TO REMOVE & REFIX FRONT WINDSCREEN	New	120.00	120.00
4	TO REMOVE & INSTALL FRONT SEAT & SEAT BELT	New	180.00	0.00
5	GUM	New	50.00	50.00
6	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	280.00	220.00
7	TO CHECK WIRING SYSTEM	New	80.00	30.00
8	TO REMOVE & REFIX R/H FRONT & DOOR GLASS ,MOTOR	New	250.00	80.00
9	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	80.00
10	TUFF KOTE	New	120.00	100.00
11	TOWING CHARGE	New	100.00	60.00
12	PANEL BEATING	New	1,200.00	1,000.00
13	SPRAY PAINTING	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			4,330.00	2,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >