. AIGT - LKK - KONNETH



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	S	LM 8450 X	
Parts (a) Cost / List Price Items	\$	5,020.27	Not Nothern
Plus/Less 25%	\$	1,255.07	Me any BEpain
Total of Cost / List	\$	3,765.20	- Grany
(b) Nett Price Items Less Total of Nett Item			LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
(c) Special Nett Items	\$	200.00	Supriementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Total Parts Cost	\$	3,965.20	Acknowledged by Repairer
Labour	\$	2,740.00	Signature: Date:
Total	\$	6,705.20	
The above total will be subjected to	7% G.S.T.		

Nar	me of Surveyor	:	Kenneth
Cor	mpany		CKK
Sur	vey conducted on	:	22/5/19 at
Rer	marks By Surveyor		
(a)		ri zed	/ is not authorized until further notice.
		orized :	/ is not authorized until further notice. O3 day(s)
(a)	The repair of this vehicle is additional to the repair of this vehicle is additional to the repair of the repair o	orized :	02
(a) (b)	The repair of this vehicle is additional Recommended Days of Repair	:: :\$_	day(s)



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

S	pai	re	Pa	rts
-	Jul			

Vehicle No. :	SLM 8450 X	Submit By	:	SERENCE
Make & Model:	TOYOTA PRIUS	Year Manufacture	:	2017
Chassis No :	JTDKB3FUX03555163	Engine No.	:	
		Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	745	1	\$200.00	S.N	?
2	Rear bumper	Bulin	y 1	\$497.50		
3	Rear bumper clip	M	10	\$40.00		
4	Rear bumper side retainer LH	Sn	1	\$112.70		×
5	Rear bumper side retainer RH	Su	1	\$112.70		X
6	Rear bumper reinforcement		1	\$398.90		?
7	Rear bumper lower garnish centre	Polle	22 1	\$582.60		
8	Rear bumper lower garnish LH	my,	11	\$149.70		2
9	Rear bumper lower garnish RH	Sin	1	\$149.70		X
10	Rear bumper tow cover	Su	1	\$31.70		X
11	Rear bumper under cover	S2	. 1	\$355.20		×
12	Rear bumper under cover clip	n.	4	\$14.00		X
13	Tail door lock	n	1	\$487.70		X
14	Tail door emblem	n.	. 1	\$61.70		×
15	Wording "PRIUS"	n	1	\$51.90		*
16	Wording "HYBRID"	N	- 1	\$55.47		X
17	Tail door plate garnish	Pm.	1	\$782.50		X
18	Tail end panel	~	1	\$596.60		7
19	Tail end panel garnish	Sa	1	\$151.60		×
20	Tail end panel garnish clip	1.	10 ا	\$35.00		×
21	Boot weatherstrip	Su	- 1	\$353.10		X
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Laboui	

Vehicle No.	:	SLM 8450 X	Submit By :	SERENCE	
Make & Model	: -	TOYOTA PRIUS	Year of Manufacture:	2017	

S/No	Labour Description	Esimated Price	Adjusted Price
- 2	TO DEVISION DAMAGED DADTO A VALORY OUT A COLDENT	Price	FIICE
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER		2501
-	SPARE TYRE COMPARTMENT)	\$1,000.00	1500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER		
	SPARE TYRE COMPARTMENT)	\$1,000.00	2601
3	To tuff coat.	\$150.00	X
4	TO Check wiring	\$50.00	15%
5	To transfer boot mechanism to new boot	\$120.00	X
6	To conduct water leakage tests to ensure proper air and		
	sealing	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	501
8	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	?

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.