

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

Co Reg No : 197701469G	ESTIMATE	GST Reg No : MR-8500111-X			
Invoice Name & Address	Owner Name & Vehicle Info				
LAU YI YONG	Cust No/Name	KCV09582/LAU YI YONG			
	Reg No/Reg Date	SMF243E / 25/10/201			
BLK 804B KEAT HONG CLOSE	Date In/Mileage	/ 0			
#16-30 SINGAPORE 682804 Contact No Mobile: 90018367	Chassis No	MMBSTA13AJH003987			
	Engine No	3A92UHJ2725			
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT			
	Colour/Trim	WO5 WHITE PEARL / BK BLACK			

Account No	Terms	Date/Time Printed	CSE	Оре	erator	12 (15)	WIP No		
CSM00041	Cash	21/05/2019/ 20:26	QUD	247	/ DonBong		39964		
		Description of Good	ds / Service			Qty	Unit Price	Disc%	
REAR SPO REPAIR RI E PNT88000 REMOVE AI E PNT88000 REMOVE AI REPAIR WI E PNT98000 PAINT WO REAR SPO AND AFFE M SUNDRY APPLY BO A 54900099 CHECK WI M SUNDRY PERFORM A 10028901 TO CARRY USING HI M SUNDRY APPLY BO M SUNDRY SUPPLY BO M SUNDRY SUPPLY BO M SUNDRY SUPPLY P	ILER, REI H REAR FI ND INSTAI ND INSTAI ORK RK SPRAY ILER, RE CTED POR DY SEALA RING AND RUST PRE OUT DIA -SCAN PR	AMAGED PARTS ON REAF PAIR REAR END PANEL ENDER, REPAIR LH REA LL PARKING ASSIST LL REAR CABIN, SIDE REAR END PANEL, REAR AR BODY KITS, RH REATION NT CHASSIS ELECTRICAL VENTION GNOSTIC CHECK USING O TEST AND REAR SPOILER SEA	R BOOT LID AR FENDER TRIM TO F AR BUMPER, AR FENDER, SYSTEM HI-SCAN P	REAR B	OOT LID,	Qty	Unit Price	Disc%	Amount 2200 3300.00 80.00 200 300.00 /680 3360.00 700.00 60.80.00 60.80.00 700.00 700.00 700.00 700.00 700.00 700.00 700.00 700.00
M SUNDRY SUPPLY R M SUNDRY	RTONA CO	ATING ON AFFECTED PA	ANEL 5^	les eg	erment.				7 320.00 × 50.00 20.50.00
Confirm & a		by							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

Co Reg No : 197701469G	ESTIMATE	GST Reg No : MR-8500111-X			
Invoice Name & Address	Owner Name & Vehicle Info				
LAU YI YONG	Cust No/Name	KCV09582/LAU YI YONG			
	Reg No/Reg Date	SMF243E / 25/10/201			
BLK 804B KEAT HONG CLOSE #16-30 SINGAPORE 682804 Contact No Mobile: 90018367	Date In/Mileage	/ 0			
	Chassis No	MMBSTA13AJH003987			
	Engine No	3A92UHJ2725			
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT			
	Colour/Trim	WO5 WHITE PEARL / BK BLACK			

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.