

22/03/2009

ASS. REC. BY:

REF: CS/FCI19009024/Krd3n2 Special Instruction:

Survey: Kennedy

ASSIGNMENT (Office)

From (Person): Henry Kno of FCI Date/Time: 2.56pm 22/5/19

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 9878U Insured: SHA 8690E

at Workshop m/s: Tmrsclab Tel: 6287 6666

of No. 2 Amk St. 63

Policy No: Claim No: D19003337MFst

Sum Insured: Excess:

Make of Veh: D.O.A. 18/5/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS / up

H.O.D. Endorsement:

Date/Time: 3.11pm 22/5/19 Person Contacted: Candy Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SHB 9878U - CC3 / AIG / 19007129 / Ken3		
	SHA 8690E - NA / INC08021582 / el		
23/5/19	Email preli revised to FCI		

DOA: 17/11/2019

DOA: 31/07/2008

ASS. REC. BY:

REF:

1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB9874

Yr Regn:

08.13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Permit Contide

C.C

1995

Colour:

m White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

637370

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VFIABL15AUC. 273383

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti Giti

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

18/5/19

D.O.I.

22/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

30/5

L1 Sp @ 8950h Summit (Rad 36, 628-34, 8010)

RECEIVED 30 MAY 2019

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 30/5 - typist

Report Format:

CWS

Lump Sum / I.B.I. (\$) 8950/p

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fixings

Others

TOTAL

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003337MFSH

Our ref: CS/FCI19009024/Kvd3

Date : 23/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9878U


We thank for your instruction on 22/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/5/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$41,606.54
Revised Estimate Amount	: S\$5,873.84
"Check" Items Amount	: S\$3,058.56
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s front portion and undercarriage



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	21-05-2019	Our Ref No. D19003337MFSH
Accident Date	18-05-2019	Claim Type. Third Party
Insured Vehicle	SHA8690E	Third Party Vehicle. SHB9878U
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 23 May 2019 3:20 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003337MFSH/1, SHB 9878U
Attachments: SHB 9878U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 9878U

Date of survey: 22/5/2019

Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 22 May 2019 3:30 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003337MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 22 May 2019 2:56 PM
To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003337MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9878U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000361
Chassis No.:	VF1ABL15AUC273363
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2021
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$54,952.00
COE Rebate Amount:	\$15,602.00
Total Rebate Amount:	\$24,350.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 May 2019

OK

Trans-cab Auto Services Pte Ltd

AAD1905-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

Not Authorized
CSing &

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB 9878U

VF1ABL15AUC273363

RENAULT

LATITUDE

18.5.19

FIRST CAPITAL

30/8/2013

PART		LIST	
1	BUMPER COVER FRT	\$	<i>CM</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Di</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>mg CM</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>CM</i> 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79 X
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84 X
1	TOW COVER FRT	\$	<i>Sn</i> 28.61 X
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73
1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
1	BONNET STRUT RH	\$	<i>Sn</i> 88.61
1	BONNET HINGE LH	\$	<i>R</i> 348.31
1	BONNET HINGE RH	\$	<i>R</i> 348.31
1	BONNET LOCK	\$	<i>R</i> 305.48
1	BONNET CABLE	\$	<i>Sn</i> 119.19

Trans-cab Auto Services Pte Ltd**AAD1905-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

1	BONNET CABLE COVER	\$	Su	161.03	X
1	BONNET SEAL OUTER	\$	Su	92.36	X
1	BONNET SEAL INNER	\$	Su	157.28	X
1	DOOR PANEL FRT RH	\$	R	2,844.66	X
1	DOOR MIRROR ASSY RH	\$	Su	1,483.40	X
1	DOOR MIRROR GLASS RH	\$	Su	148.20	X
1	DOOR MIRROR BACK COVER RH	\$	Su	218.46	X
1	LOWER ARM RH L70Y	\$		685.76	?
1	KNUCKLE ARM RH L70Y	\$	B	846.98	✓
1	ABSORBER FRT RH L70Y	\$		360.54	?
1	DRIVESHAFT RH	\$		1,747.45	?
1	STABILIZER BAR FRT	\$		604.65	?
1	WIPER RESERVOIR MOTOR	\$	Su	270.06	X
1	WIPER RESERVOIR	\$	Ref	348.25	✓
1	WIPER RESERVOIR NECK	\$	Su	136.11	X
1	DOOR HARNESS WIRE RH	\$	Su	2,670.00	X

TOTAL \$ 27,137.40**10% \$ 2,713.74****\$ 24,423.66****Special Nett**

1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	X
1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00	X
1	BUMPER CLIP FRT	\$	nn	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	} X
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	} 240
1	WHEELARCH CLIP FRT RH	\$	nn	30.50	
1	FRONT RIGHT TYRE	\$	R	300.00	207.00
1	FRONT RIGHT TYRE RIM	\$	R	380.00	✓
1SET	Front licence plate with holder	\$	Su	80.00	X
1SET	RADIATOR GRILLE SCREW	\$	Su	16.00	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	X
1	WINDSCREEN SEALANT	\$	nn	253.80	X
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	} X
6	BONNET INSULATOR CLIP L70Y	\$	nn 7.30	
2	BONNET STRUT L70Y	\$	nn 88.61	
2	BONNET CABLE CLIP L70Y	\$	nn 6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	nn 10.85	
TOTAL		\$	1,882.88	
TOTAL PARTS		\$	26,306.54	

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	4001
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	1801
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-155**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

To transfer of front door fittings, attachment and
perform water seepage test.

\$ *na* 380.00 *X*

To transfer of bonnet fittings, attachment and perform
water seepage test.

\$ *na* 380.00 *X*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *2cl*

To Check Electrical Lighting Concerned.

\$ 170.00 *2cl*

Towing Fees

\$ 120.00 *5cl*

TOTAL \$ **15,300.00**

Over All Total \$ **41,606.54**

LUMP SUM (REPAIR DAY)*20 DAYS**3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U**AAD1905-155***Not authorized
C/Sing &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHB 9878U

VF1ABL15AUC273363

RENAULT

LATITUDE

18.5.19

FIRST CAPITAL

30/8/2013

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>cm</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>sn</i> 181.75	X
1	BUMPER ABSORBER FRT	\$	<i>sn</i> 394.68	X
1	BUMPER RETAINER FRT RH	\$	<i>dis</i> 151.41	✓
1	BUMPER SUPPORT FRT	\$	<i>sn</i> 123.88	X
1	BUMPER UNDERTRAY FRT	\$	<i>sn</i> 472.83	X
1	BUMPER GRILLE LOWER FRT	\$	<i>sn</i> 266.80	X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>sn</i> 207.21	X
1	BUMPER BEAM FRT	\$	<i>n</i> 914.08	X
1	HEADLAMP RH	\$	<i>m3 cm</i> 1,184.43	✓
1	HEADLAMP PANEL FRT RH	\$	<i>n</i> 152.15	X
1	FENDER PANEL FRT RH	\$	<i>B1</i> 783.83	✓
1	WHEELARCH FRT RH	\$	<i>cm</i> 278.84	✓
1	FENDER BRACKET LOWER RH	\$	<i>sn</i> 15.79	X
1	FENDER INSULATOR RH	\$	<i>sn</i> 130.84	X
1	TOW COVER FRT	\$	<i>sn</i> 28.61	X
1	FRONT BRACE PANEL	\$	<i>n</i> 177.22	X
1	RADIATOR GRILLE	\$	<i>sn</i> 1,707.78	} X
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>nn</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>sn</i> 1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	<i>sn</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>n</i> 89.79	
1	BONNET	\$	<i>n</i> 1,941.63	
1	BONNET INSULATOR	\$	<i>sn</i> 405.73	
1	BONNET STRUT LH	\$	<i>sn</i> 88.61	
1	BONNET STRUT RH	\$	<i>sn</i> 88.61	
1	BONNET HINGE LH	\$	<i>n</i> 348.31	
1	BONNET HINGE RH	\$	<i>n</i> 348.31	
1	BONNET LOCK	\$	<i>n</i> 305.48	
1	BONNET CABLE	\$	<i>sn</i> 119.19	

Trans-cab Auto Services Pte Ltd

AAD1905-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

1	BONNET CABLE COVER	\$	Sm	161.03	X
1	BONNET SEAL OUTER	\$	Sm	92.36	X
1	BONNET SEAL INNER	\$	Sm	157.28	X
1	DOOR PANEL FRT RH	\$	R	2,844.66	X
1	DOOR MIRROR ASSY RH	\$	Sm	1,483.40	X
1	DOOR MIRROR GLASS RH	\$	Sm	148.20	X
1	DOOR MIRROR BACK COVER RH	\$	Sm	218.46	X
1	LOWER ARM RH L70Y	\$	R	685.76	✓
1	KNUCKLE ARM RH L70Y	\$	R	846.98	✓
1	ABSORBER FRT RH L70Y	\$	R	360.54	✓
1	DRIVESHAFT RH	\$	R	1,747.45	X
1	STABILIZER BAR FRT	\$	Sm	604.65	X
1	WIPER RESERVOIR MOTOR	\$	Sm	270.06	X
1	WIPER RESERVOIR	\$	Ref	348.25	✓
1	WIPER RESERVOIR NECK	\$	Sm	136.11	X
1	DOOR HARNESS WIRE RH	\$	Sm	2,670.00	X
Steering Pinion		R	3443.11	✓	
		TOTAL	\$	27,137.40	
		10%	\$	2,713.74	
			\$	24,423.66	

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	X
1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00	X
1	BUMPER CLIP FRT	\$	nn	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	} X
1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	} X
1	WHEELARCH CLIP FRT RH	\$	nn	30.50	
1	FRONT RIGHT TYRE	\$	240sn R	300.00	240sn
1	FRONT RIGHT TYRE RIM	\$	R	380.00	✓
1SET	Front licence plate with holder	\$	Sm	80.00	X
1SET	RADIATOR GRILLE SCREW	\$	Sm	16.00	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	X
1	WINDSCREEN SEALANT	\$	nn	253.80	X
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	X

Trans-cab Auto Services Pte Ltd

AAD1905-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn 100.00	} X
6	BONNET INSULATOR CLIP L70Y	\$	nn 7.30	
2	BONNET STRUT L70Y	\$	nn 88.61	
2	BONNET CABLE CLIP L70Y	\$	nn 6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	nn 10.85	
TOTAL		\$	1,882.88	

TOTAL PARTS	\$	26,306.54
--------------------	-----------	------------------

LABOUR

Putty and spray painting of the affected portion.	\$	6,000.00 4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00 4001
To rust-proofing of the affected areas.	\$	170.00 301
To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 601
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 1201
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd

AAD1905-155

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>200</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
Towing Fees	\$	120.00 <i>500</i>

TOTAL \$ 15,300.00**Over All Total** \$ 41,606.54**LUMP SUM (REPAIR DAY)***20 DAYS* 45,578.34
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 30 May 2019 12:32 PM
To: Ng Wai Yin; 'calvin.er@transcab.com.sg'; SUR
Cc: jasminetan@transcab.com.sg
Subject: SHB 9878U-DOA: 18/5/2019
Attachments: EST.pdf

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$8950 @ 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009024/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-05-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8690E	Veh. Inspected	SHB 9878U	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003337MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	22/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC273363	Colour	METALLIC WHITE / RED	
Odometer	637370	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/05/2019	Inspection Date	22/05/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9878U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH	DISTORTED	151.41	151.41
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP RH	MTG CRACKED	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-

Report Ref No. CS/FCI19009024/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNE CABLE	SERVICEABLE	119.19	-
1	BONNE CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS RH	SERVICEABLE	148.20	-
1	DOOR MIRROR BACK COVER RH	SERVICEABLE	218.46	-
1	LOWER ARM RH L70Y	BENT	685.76	685.76
1	KNUCKLE ARM RH L70Y	BENT	846.98	846.98
1	ABSORBER FRT RH L70Y	BENT	360.54	360.54
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	WIPER RESERVOIR	DENTED	348.25	348.25
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	DOOR HARNESS WIRE RH	SERVICEABLE	2,670.00	-
1	STEERING PINION	BENT	4,413.11	4,413.11
	LESS 10% DISCOUNT		-3,155.05	-1,031.26
			28,395.47	9,281.31
	SPECIAL NETT ITEMS			
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER "CLASSIC" (SN)	NOT NECESSARY	80.00	-
1	BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-

Report Ref No. CS/FCI19009024/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	FRONT RIGHT TYRE (80%)(SN)	PUNCTURE	300.00	240.00
1	FRONT RIGHT TYRE RIM (SN)	BENT	380.00	380.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	SET RADIATOR GRILLE SCREW (SN)	SERVICEABLE	16.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	SERVICEABLE	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
			1,882.87	686.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT RH,FRONT BRACE PANEL,FRAME FULL SUPPORT BRACKET,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,DOOR PANEL FRT RH AND DRIVESHAFT RH.		6,000.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	180.00
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TOWING FEES.		120.00	50.00
			15,300.00	1,200.00
	GRAND TOTAL		45,578.34	11,167.31
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,950.00

Report Ref No. CS/FCI19009024/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.