

ASS. REC. BY:

REF: CS/MSG19009040/Dtd312

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Mudd Ashik B Madi of MSIG Date/Time: 22.5.19 4.06 PM

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 8887M Insured: SKC 8069D

at Workshop m/s Channi Moto Tel: 65425119

of BIK ID # 01-05106

Policy No: 2912312 Tmc Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A 4.5.2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS rup

Date/Time: 22.5.2019 5:35 PM Person Contacted: 24 PM H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SH 8887M - CS/PC119009040/JSd3 DOA - 4/05/2019
	SKC 8069D - X
22/5/19 @ 4:31 PM	Vehicle sent to Mudd Ashik via Memon.

REF:

## ASSIGNMENT

COR Sept 2024

2016 Sept

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 13 # days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SH 8887 M

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C.C.

1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

435710

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDGU671695

C/No:

KNHLB41UMGU093560

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

P/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

17/05/2019

D.O.I.

23/05/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front y. Rr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MSIG SKC 8069D

19/06/19

Final 45 20000/- with 13 days of work  
Uled: 23165.06, 530/-

RECEIVED 20 JUN 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 20/6 Typist

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. (\$

TR  
20,000/-

Days Of Repair: 13

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250

11

261

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 27 May 2019

**Preliminary Advice**

Insured Vehicle No	: SKC8069D	Accident Date	: 17/05/2019
TP Vehicle No	: SH8887M	Assignment Date	: 22/05/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 11.00
Date of Inspection	: 23/05/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,165.06
Revised Amount	:S\$	25,397.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	25,397.70

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 May 2019		22 May 2019 17:06 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b>			<b>[Created by insurer]</b>																					
Insured:	Premier Rent A Car Pte Ltd, Co. Reg. No.: 200612929E																							
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R																							
Vehicle Reg. No.:	SH8887M	Date of Loss:	17/05/2019 23:00 - :59 [31 Months and 18 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP	Policy/Cover Note No.:	29123112TMC (Comprehensive) Coverage: 01/05/2019 - 30/04/2020																					
Vehicle Reg. No. (Insured):	SKC8069D	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/05/2019]																							
Adj Asg. Remarks:	LIAB: DISPUTE - OI NON REPORTING. TP AGREE ON SJE - ASSIGN LKK AUTO CONSULTANTS. CONTACT: MS LYNN / IRENE @ 6542 5119 / 6542 7162.																							
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a> <a href="#">Compose Case Mail</a>																					
There are no mail for this case.																								
<div> <input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> </div> <div> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

MCD619064836 / ComfonDelGro Engineering Pte Ltd - Loyang  
 ENTRY DATE & TIME: 21/05/2019 07:21  
 SUBMITTED BY: Catherine Por May Juan

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 21/05/2019 07:21  
 Date Of Accident 17/05/2019 23:00  
 Exact Location Of Accident PIE TWDS BKE AFTER ENG NEO EXIT  
 Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SH8887M  
 Insured/Policyholder  
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD  
 Co Reg No 199303821R  
 Email Address FLEETSAFETY@COGTAXI.COM.SG  
 Mobile Phone No  
 Alternative Phone No OFFICE-65508768  
 Vehicle Particulars  
 Manufacturer HYUNDAI  
 Model I40  
 Exact Purpose for which vehicle was being used at time of accident  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category TAXI  
 Insurance Company  
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy YES  
 Policy Number D-18088936MFSH  
 Cover Note Number  
 Driver  
 Name of Driver LIM CHIN KHUAN  
 NRIC No S1487540I  
 Date Of Birth 15/02/1961  
 Occupation OUTDOOR  
 Date Of Driving Pass 25/08/1981  
 Driving Experience 37 YEARS AND 8 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-91254171  
 Fax Number  
 Contact Number  
 Email Address RCHROLIM@YAHOO.COM

Address 522 #17-293 JELAPANG ROAD  
 Postcode 670522  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (Including own vehicle) involved in the accident 3  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : -  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 POLICE STATION NAME [OTHER] BT PANJANG NPC  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

SEE POLICE REPORT.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: -  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKC8069D  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver YU JUN HO  
 NRIC/Passport Number G3036742T  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SLE9193Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NGOI CHUN KIAT FRANCIS

NRIC/Passport Number

S8800323C

Contact Number

91458324

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

LIM CHIN KHUAN

Approximate Age

58

Injuries Sustain

NECK,BACK,HEADACHE

Injured person in which vehicle?

SH8887M

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

**DETAILS OF INJURED PERSON 2**

Name

SABARIAH BINTE RABAE

Approximate Age

Injuries Sustain

FACE

Injured person in which vehicle?

SH8887M

Were seat belts worn?

Was this Injured conveyed to hospital by ambulance?

NO

Address

Postcode



**SKETCH PLAN****IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

Policyholder's Signature  
Date & Time: 18/5/2019

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 18/5/2019 @ 12:30hrs

Lisa Diong  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLAN


A-SH 8887M  
B-SKC-8069D  
C-SLE 9193Z

Along PIE towards BKE after Eng Neo exit

Along PIE towards BKE after Eng Neo exit

[illegible]

I/We declare the foregoing particulars are true in every respect.



Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 18/5/2019 @ 12:30hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190518/2027

1 of 3

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

Report No. T/20190518/2027

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 18/05/2019 08:46		Vide Report No.:		Station Diary No.: 40
<b>Informant's Particulars</b>				
Name of Informant: LIM CHIN KHUAN		Address: APT BLK 522 JELAPANG ROAD #17-293 SINGAPORE 670522		
ID Type / ID No.: NRIC NO / S14875401		Contact No.: Home/Office: Mobile: 91254171		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 58	Date of Birth: 15/02/1961	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/05/2019 23:00	Type of Location: Straight Road
Location:  PAN ISLAND EXPRESSWAY  PIE towards BKE before filter lane to BKE. At the 4th lane.				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
A SH8887M	Car				Slightly Damaged	1
B SKC8069D	Car				Slightly Damaged	1
C SLE9193Z	Car				Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20190518/2027

2 of 3

Police Station Of Origin:

Bukit Panjang N.P.C

1 Segar Road #01-05 SINGAPORE 677738

Tel No: 1800-8929999

Report No, T/20190518/2027

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	LIM CHIN KHUAN	ID No.	S1487540I
Related Vehicle	SH8887M (Car)	Contact No.	91254171
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Passenger</b>			
Name	Sabariah Binte Robae	ID No.	S8633168C
Related Vehicle	SH8887M (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On the 17/05/2019 at above 2300hrs, I was driving my ComfortDelgro Taxi SH8887M along PIE towards BKE at the 4th lane, on board with a passenger(Sabariah Binte Robae S8633168C) seated at the rear left seat. Due to heavy traffic I have to stop behind a vehicle (SLE9193Z). However a vehicle (SKC8069D) could not stop in time and collided to my vehicle rear. Due to the impact my vehicle move forward and hit onto the rear of the vehicle in front. After which we exchange particulars and my passenger suffer a bump on the face, she left in a hurry on another vehicle after giving me her particulars.

**SINGAPORE  
POLICE FORCE**

T/20190518/2027

Police Station Of Origin:  
Bukit Panjang N.P.C  
1 Segar Road #01-05 SINGAPORE 677738  
Tel No: 1800-8929999

3 of 3

Report No. T/20190518/2027

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sr Staff Sgt YUEN KHOONG WAI KELVIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED

MOHD SAID

Contact No.: 65476172

SN 117

Authentication Stamp

NP168

Signature:

Singapore Police Force

Signature Of Informant:

Date/Time:

18/05/2019 08:46

Classification Of Case:

(10 survey by UK

DATE :21.05.2019

**TEL : 6542 5119**

**FAX : 6542 6039**

MSIG®

MODEL	Parts Description/ Labour	Type	Unit Price	Amount
HYUNDAI i40	Bonnet <i>ENG</i>			\$ 2,265.90
	Bonnet Hinge (LH/RH) <i>NH</i>	S	41.00	\$ 82.00
	Bonnet Lock <i>ST</i>			\$ 36.90
	Bonnet Absorber <i>NH</i>	S	58.10	\$ 116.20
	Bonnet Insulator <i>SVL</i>			\$ 196.50
	Bonnet Insulator Clips <i>NH</i>			\$ 8.40
	Radiator Grille <i>broken</i>			\$ 1,110.10
	Radiator Grille H Emblem <i>broken</i>			\$ 120.30
	Front Bumper Cover <i>Dented</i>			\$ 1,052.20
	Front Bumper Sponge <i>horn</i>			\$ 99.20
	Front Bumper Reinforcement <i>Dented</i>			\$ 402.10
	Front Bumper Lip <i>NH</i>			\$ 54.90
	Front Bumper Bracket Top (LH/RH) <i>NH</i>	S	22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>N/S broken o/s NH</i>	S	24.60	\$ 49.20
	Headlamp Support Top Cover <i>broken</i>			\$ 222.60
	Headlamp Support Panel Assy <i>ST / broken</i>			\$ 907.40
	Headlamp (LH/RH) <i>mainly broken</i>	S	1,388.00	\$ 2,776.00
	Radiator <i>ST / punctured</i>			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95
	Radiator Bracket (RH/LH) <i>NH</i>	S	6.50	\$ 13.00
	Radiator Hose Upper <i>NH</i>			\$ 105.80
	Radiator Hose Lower <i>NH</i>			\$ 52.70
	Radiator Guard <i>NF</i>	S	20.00	\$ 40.00
	Horn Unit (LH/RH) <i>NH</i>	S	73.80	\$ 147.60
	Horn Wire <i>NH</i>			\$ 156.50
	Front Fender (LH) <i>Dented</i>			\$ 663.00
	Front Fender Shield (LH) <i>NH</i>			\$ 174.90
	Air Cleaner Assy <i>NH</i>			\$ 118.60
	Air Duct <i>broken</i>			\$ 134.60
	Air Flow Sensor <i>NH</i>			\$ 502.20
	Air Cleaner Bottom Assy <i>NH</i>			\$ 325.00
	Aircon Condenser <i>punctured</i>			\$ 927.50
	Aircon Suction & Liquid Hose <i>NH</i>			\$ 624.00
	Aircon Discharge Hose <i>NH</i>			\$ 162.60
	Battery Tray <i>NH</i>			\$ 52.00
	Inter Cooler <i>punctured</i>			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) <i>NH</i>			\$ 25.90
	Hose B To Inter Cooler <i>NH</i>			\$ 229.70
	Hose C To Inter Cooler Inlet <i>NH</i>			\$ 294.50
	Pipe To Inter Cooler <i>NH</i>			\$ 167.05
	Pipe To Inter Cooler Outlet <i>NH</i>			\$ 244.55
	Wiring-Engine <i>NH</i>			\$ 3,326.00
				\$ 20,556.15
				\$ 4,111.23
				\$ 16,444.92



SH 8887M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate <i>broken</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>vt</i>			\$ 30.00	Nett ✓
	Front Fender Advertisement Logo (LH/RH) <i>hec 2/5 RT</i>			\$ 100.00	Nett <del>✓</del>
			145.00	\$ 155.00	
	<b>Labour Charge</b>				
	Panel Beating			\$ 1,000.00	600/-
	Spray Painting Charge			\$ 750.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	40/-
	Towing Charge			\$ 50.00	24
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Remove/Refix Dashboard		1256.00	\$ 450.00	24
	Remove/Refix Fuse Box			\$ 180.00	24
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	24
	<b>TOTAL LABOUR</b>			\$ 3,160.00	
	Boot Lid <i>vt   Dented</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>torn   deformed</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>24</i>	\$	142.30	\$ 284.60	X
	Boot Lid Lock Upper <i>vt</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>vt</i>			\$ 31.70	✓
	Boot Lid 'H' Emblem <i>hec</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>hec</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>crack</i>	\$	565.60	\$ 1,131.20	✓
	Boot Lid Trimboard <i>torn</i>			\$ 116.40	✓
	Boot Lid Trimboard Clips (10pcs) <i>hec</i>			\$ 11.00	✓
	Bootlid Moulding <i>hec</i>			\$ 85.00	✓
	Bootlid i40 Emblem <i>hec</i>			\$ 27.90	✓
	Bootlid Lower Garnish <i>cut</i>			\$ 227.90	✓
	Rear Bumper <i>Dented</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>Dented</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>vt</i>	\$	80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>hec</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>24</i>	\$	35.60	\$ 71.20	X
	Rear Bumper Sponge <i>torn</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>broken</i>			\$ 228.00	✓
	Rear Bumper Reflector Lamp (LH/RH) <i>crack</i>	\$	30.60	\$ 61.20	✓
	Tail Lamp (LH/RH) <i>crack</i>	\$	697.80	\$ 1,395.60	✓
	Tail Lamp Quarter Panel (LH) <i>Dented</i>			\$ 226.50	✓
	Rear Panel <i>Dented</i>			\$ 526.70	✓
	Rear Panel Garnish <i>deformed mounting</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>Dented</i>			\$ 495.50	✓
	Spare Tyre Holder <i>2. Dem   vt</i>			\$ 223.10	✓

SH 8887M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Spare Tyre Panel <i>Dented</i>			\$ 852.80	✓
	Spare Tyre Panel Cushion <i>HH</i>			\$ 209.05	X
	Rear Towing Hook <i>HH</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>HH</i>			\$ 570.40	X
	Panel Assy-Rear Floor Side (LH) <i>HH</i>			\$ 90.10	X
	Rear Floor Chassis Member (LH) <i>HH</i>			\$ 3,636.20	X
	Exhaust Pipe Insulator <i>HH</i>	S	58.55	\$ 117.10	X
	Exhaust Silencer <i>1/4"</i>	S	967.70	\$ 1,935.40	<i>not 7.1</i>
	Exhaust Pipe Hanger <i>HH</i>	S	58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>HH</i>			\$ 730.10	X
	Rear Fender With Housing (LH) <i>Dented</i>		<i>2620.20</i>	<del>\$ 4,736.80</del>	✓
	Rear Fender Inner Lining (LH) <i>HH</i>			\$ 169.30	X
	Rear Fender Air-Duct <i>HH</i>			\$ 51.60	X
	Rear Fender Trim Board (LH) <i>HH</i>			\$ 188.75	X
	Rear Windscreen Moulding <i>HH</i>			\$ 28.30	✓
	<b>SUB TOTAL</b>			\$ 22,441.80	
	<b>LESS 20%</b>			\$ 4,488.36	
	<b>DISCOUNTED TOTAL</b>			\$ 17,953.44	
	Boot Lid Comfort Logo & Tel No. Sticker <i>Nuc</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>Nuc</i>			\$ 100.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Dent</i>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>Nuc</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>Nuc</i>	S	100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>Nuc</i>			\$ 46.00	Nett ✓
			<i>561.70</i>	\$ 561.70	
	<b>Labour Charge</b>				
	Panel Beating			\$ 2,000.00	1000/-
	Spray Painting Charge			\$ 1,500.00	900/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Rear Chassis Alignment Charge			\$ 400.00	HH
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Fuel Tank			\$ 150.00	HH
	Remove/Refix Exhaust Pipe			\$ 200.00	60/-
			<i>2230.00</i>	\$ 4,890.00	
	<b>TOTAL LABOUR</b>			\$ 4,890.00	
	<b>ESTIMATE TOTAL</b>			\$ 43,165.06	
			<i>25515.70</i>		
			<i>4/\$ 20 000/-</i>		

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: *23/05/19*

*23/05/2019 @ 0900h*

*Wt Andrew*

*4/Steve*

*J Ryan*

*LKK Auto*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009040/DTD3N2

Date: 27/06/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29123112
Claimant Vehicle No :	SH8887M	Insured Vehicle No :	SKC8069D
Date of Loss:	17/05/2019	Nature of Claim:	TP
		Claim No:	594199

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SH8887M	Engine No:	D4FDGU671695
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU093560
Reg. Date:	29/09/2016 (Man. Year: 2016)	Odometer:	435710 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	35,115.06	22,035.70	13,079.36	37.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,050.00	3,480.00	4,570.00	56.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>43,165.06</b>	<b>25,515.70</b>	<b>17,649.36</b>	<b>40.89</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>20,000.00</b>		
<b>(S\$)</b>	43,165.06	20,000.00	23,165.06	53.67
<b>+ GST 7.00/7.00% (S\$)</b>	3,021.55	1,400.00	1,621.55	53.67
<b>Nett Amount (S\$)</b>	<b>46,186.61</b>	<b>21,400.00</b>	<b>24,786.61</b>	<b>53.67</b>

## INSPECTION

Date of Assignment: 22/05/2019

Date Inspected: 23/05/2019 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)  
Blk 10 #01-05/06, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 13.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2019)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SH8887M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	2,265.90 FL	*2,265.90 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	82.00 FL	*- FL
3	1		*BONNET LOCK	Bent	36.90 FL	*36.90 FL
4	2		*BONNET ABSORBER	Not Necessary	116.20 FL	*- FL
5	1		*BONNET INSULATOR	Serviceable	196.50 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
7	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
8	1		*RADIATOR GRILLE H EMBLEM	Broken	120.30 FL	*120.30 FL
9	1		*FRONT BUMPER COVER	Dented	1,052.20 FL	*1,052.20 FL
10	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	402.10 FL	*402.10 FL
12	1		*FRONT BUMPER LIP	Not Necessary	54.90 FL	*- FL
13	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
14	2		*FRONT BUMPER BRACKET (LH/RH)	N/s Broken /O/s Not Necessary	49.20 FL	*24.60 FL
15	1		*HEADLAMP SUPPORT TOP COVER	Broken	222.60 FL	*222.60 FL
16	1		*HEADLAMP SUPPORT PANEL ASSY	Bent / Broken	907.40 FL	*907.40 FL
17	2		*HEADLAMP (LH/RH)	Mtg Broken	2,776.00 FL	*2,776.00 FL
18	1		*RADIATOR	Bent / Punctured	698.30 FL	*698.30 FL
19	1		*RADIATOR FAN BLADE, COWLING, MOTOR ASSY	Broken	792.95 FL	*792.95 FL
20	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
21	1		*RADIATOR HOSE UPPER	Not Necessary	105.80 FL	*- FL
22	1		*RADIATOR HOSE LOWER	Not Necessary	52.70 FL	*- FL
23	2		*RADIATOR GUARD	Not Fitted	40.00 FL	*- FL
24	2		*HORN UNIT (LH/RH)	Not Necessary	147.60 FL	*- FL
25	1		*HORN WIRE	Not Necessary	156.50 FL	*- FL
26	1		*FRONT FENDER (LH)	Dented	663.00 FL	*663.00 FL
27	1		*FRONT FENDER SHIELD (LH)	Not Necessary	174.90 FL	*- FL
28	1		*AIR CLEANER ASSY	Not Necessary	118.60 FL	*- FL
29	1		*AIR DUCT	Broken	134.60 FL	*134.60 FL
30	1		*AIR FLOW SENSOR	Not Necessary	502.20 FL	*- FL
31	1		*AIR CLEANER BOTTOM ASSY	Not Necessary	325.00 FL	*- FL
32	1		*AIRSON CONDENSER	Punctured	927.50 FL	*927.50 FL
33	1		*AIRSON SUCTION & LIQUID HOSE	Not Necessary	624.00 FL	*- FL
34	1		*AIRSON DISCHARGE HOSE	Not Necessary	162.60 FL	*- FL
35	1		*BATTERY TRAY	Not Necessary	52.00 FL	*- FL
36	1		*INTER COOLER	Punctured	1,032.50 FL	*1,032.50 FL
37	1		*INTER COOLER MOUNTING (2PCS)	Not Necessary	25.90 FL	*- FL
38	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
39	1		*HOSE C TO INTER COOLER INLET	Not Necessary	294.50 FL	*- FL
40	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*- FL
41	1		*PIPE TO INTER COOLER OUTLET	Not Necessary	244.55 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*WIRING-ENGINE	Not Necessary	3,326.00 FL	*- FL
43	1		*BOOT LID	Bent / Dented	2,174.90 FL	*2,174.90 FL
44	1		*BOOT LID RUBBER	Torn / Deformed	96.50 FL	*96.50 FL
45	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
46	1		*BOOT LID LOCK UPPER	Bent	102.60 FL	*102.60 FL
47	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
48	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
49	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
50	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
51	1		*BOOT LID TRIMBOARD	Torn	116.40 FL	*116.40 FL
52	1		*BOOT LID TRIMBOARD CLIPS (10PCS)	Necessary	11.00 FL	*11.00 FL
53	1		*BOOTLID MOULDING	Necessary	85.00 FL	*85.00 FL
54	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
55	1		*BOOTLID LOWER GARNISH	Cut	227.90 FL	*227.90 FL
56	1		*REAR BUMPER	Dented	553.00 FL	*553.00 FL
57	1		*REAR BUMPER REINFORCEMENT	Dented	428.40 FL	*428.40 FL
58	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	160.60 FL	*160.60 FL
59	1		*REAR BUMPER CLIP 10PCS	Necessary	22.00 FL	*22.00 FL
60	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
61	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
62	1		*REAR BUMPER UNDER COVER	Broken	228.00 FL	*228.00 FL
63	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Cracked	61.20 FL	*61.20 FL
64	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
65	1		*TAIL LAMP QUARTER PANEL (LH)	Dented	226.50 FL	*226.50 FL
66	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
67	1		*REAR PANEL GARNISH	Mounting Deformed	57.70 FL	*57.70 FL
68	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
69	1		*SPARE TYRE HOLDER	Damaged / Bent	223.10 FL	*223.10 FL
70	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
71	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
72	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
73	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	570.40 FL	*- FL
74	1		*PANEL ASSY-REAR FLOOR SIDE (LH)	Not Necessary	90.10 FL	*- FL
75	1		*REAR FLOOR CHASSIS MEMBER (LH)	Not Necessary	3,636.20 FL	*- FL
76	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
77	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
78	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
79	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
80	1		*REAR FENDER (LH)	Dented	4,736.80 FL	*2,020.20 FL
81	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
82	1		*REAR FENDER AIR-DUCT	Not Necessary	51.60 FL	*- FL
83	1		*REAR FENDER TRIM BOARD (LH)	Not Necessary	188.75 FL	*- FL
84	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
85	1		*FRONT NUMBER PLATE}	Broken	25.00 FS	*45.00 FS
86	1		*FRONT NO. PLATE TRIM COVER}	Bent	30.00 FS	*- FS
87	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
88	1		*BOOT LID COMFORT LOGO & TEL NO. STICKER	Necessary	30.00 FS	*30.00 FS
89	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
90	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
91	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
92	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
93	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	43,714.65
					27,367.95	
					- List Item Discount on L Items 20.00/20.00% (S\$)	8,599.59
					5,332.25	
					Total Parts (S\$)	35,115.06
					22,035.70	

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING.	New	3,000.00	1,600.00
2	SPRAY PAINTING CHARGE.	New	2,250.00	1,400.00
3	WIRING CHARGE.	New	100.00	60.00
4	TUFF KOTE.	New	150.00	80.00
5	TOWING CHARGE.	New	50.00	0.00
6	REMOVE / REFIX AIRCON & REFILL GAS.	New	150.00	80.00
7	REMOVE / REFIX DASHBOARD.	New	450.00	0.00
8	REMOVE / REFIX FUSE BOX.	New	180.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	New	480.00	0.00
10	REAR CHASSIS ALIGNMENT CHARGE.	New	400.00	0.00
11	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
12	REMOVE / REFIX REAR WINDSCREEN GLASS.	New	120.00	80.00
13	REMOVE / REFIX REVERSE SENSOR.	New	120.00	40.00
14	REMOVE / REFIX FUEL TANK.	New	150.00	0.00
15	REMOVE / REFIX EXHAUST PIPE.	New	300.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>8,050.00</b>	<b>3,480.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;