

22/03/2007

ASS. REC. BY:

REF: CS3/MSG19007366 / CHD3-1

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

Merimen

From (Person): chia Myut Rui

of MSG

Date/Time:

23.5-2019.

26.4.19 9.11 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SEF 4840D

Insured: FBL 33452

at Workshop m/s Sat motor

Tel: 98599677

of 24 Dafa Lane 12

Policy No: MSD/VMS/19-998829

Claim No: MSC/VI/19-000470

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.4.19

(Client's Record)

26.4.2019 2-4pm

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 26.4.19 10.27am

Person Contacted: Jessie

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLF4840D - CS/INC 14013003/Ktm 302

D.O.A - 06/09/2018

FBL 33452 - X

Wump Sum \$4250/- (Red: 19459.09; 82%)

4 days

Submit Merimen

19/8/2019

RECEIVED 20 AUG 2019

COST ESTIMATE

Vehicle No: SKF4840D

Date

: 26.04.2019

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front M5 Bumper	Broken	\$ 2,985.12	1244.02
2	2	Front Bumper Bracket	Necessary	\$ 163.08	1119.62
3	1	Front Right M5 Fender	Damaged	\$ 1,840.65	178.55
4	1	Front Right Door	Damaged	\$ 1,954.20	1656.59
5	1	Front Right M5 Side Mirror Complete	Broken	\$ 1,983.15	1758.78
6	1	Front Right Door Hinge	Impacted	\$ 183.95	1784.84
7	1	Rear Right Door	Damaged	\$ 1,950.29	165.56
8	1	Rear Right Door Hinge	Impacted	\$ 183.95	1755.26
9	1	Rear Right Fender	Damaged	\$ 2,986.30	165.56
10	1	Rear M5 Bumper	Damaged	\$ 2,600.35	2,687.67
11	1	Rear Bumper Bracket	Necessary	\$ 296.58	2,340.32
12	1	Front Headlamp	Broken	\$ 2,517.15	266.92
13	1	Front Headlamp Retainer	Necessary	\$ 159.12	1631
14	1	Front Right Fender Signal Lamp	Damaged	\$ 195.20	116
				\$ 19,999.09	\$ 17,999.18

Total (Parts): \$ 19,999.09

Less 10% \$ 1,799.92

3996.92

Labour Charges

- 15 To fix & dismantle and remove damaged parts Frontal to Rear; affected damaged portion.
- 16 To apply anti rust coat and affected areas
- 17 To check wiring
- 18 Welding and cutting of affected panels, including chassis alignment.
- 19 Spray painting for frontal to rear affected portions.
- 20 Full Diagnostics one ECU for fault code.

\$ 1,000.00

\$ 800.00

200

\$ 60.00

\$ 48.00

X NN

\$ 80.00

\$ 64.00

30

\$ 1,200.00

\$ 960.00

300

\$ 1,250.00

\$ 1,000.00

800

\$ 120.00

\$ 96.00

X NN

Total Labour: \$ 3,710.00

Less 20% \$ 2,968.00

1330

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 23,709.09

\$ 20,967.18

5326.92 5222.52
5385.62

20% 4300 4250

4 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Apr 2019		26 Apr 2019 09:11 Edit Adj Rpt	S\$4,250.00 Edit Estimates	S\$4,250.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NUR LIYANA BINTE NASSER, ID: S9803105G		[Created by insurer]
Main Claimant:	SAT MOTORS, Co. Reg. No.: SAT MOTORS		
Vehicle Reg. No.:	SKF4840D	Date of Loss:	23/04/2019 21:00 - :59 [110 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000470	Policy/Cover Note No.:	MSD/VMS/19-998829-WTT(TPFT) (TP, Fire & Theft) Coverage: 16/02/2019 - 15/02/2020
Vehicle Reg. No. (Insured):	FBL3345Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/08/2019]		
Adj Asg. Remarks:	on WP. LIAB: DISPUTE. TP DISAGREE ON SJE - ASSIGN LKK AUTO CONSULTANTS. CONTACT: JONATHAN @ 9126 9987 / JESSIE @ 9859 9677.		

ASSOCIATED MAIL RECEIVED

- MSIG_SG (19/08/2019): Report Send Back Alerts - SKF4840D (TP)

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Claim Documents

*SKF4840D (MSC/V/19-000470)
[FBL3345Z]
TP
SAT MOTORS
Apr 23 2019 9:00PM
[NUR LIYANA BINTE NASSER]
Sat Motors

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	☒
1	25/04/19 17:01	Accident Statement From: SC - Reg. No: FBL3345Z, Claimant: NUR LIYANA BTE NASSER	Thumbnail	Print
			Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	☒
1	29/04/19 09:24	General View	Thumbnail	Print
2	29/04/19 09:24	General View	Load JPG	☒
3	29/04/19 09:24	General View	Load JPG	☒
4	29/04/19 09:24	General View	Load JPG	☒
5	29/04/19 09:24	General View	Load JPG	☒
6	29/04/19 09:24	General View	Load JPG	☒
7	29/04/19 09:24	General View	Load JPG	☒
8	29/04/19 09:24	General View	Load JPG	☒
9	29/04/19 09:24	General View	Load JPG	☒
10	29/04/19 09:24	General View	Load JPG	☒
11	29/04/19 09:24	General View	Load JPG	☒
12	29/04/19 09:24	General View	Load JPG	☒
13	29/04/19 09:24	General View	Load JPG	☒
14	29/04/19 09:24	General View	Load JPG	☒
15	29/04/19 09:24	General View	Load JPG	☒
16	29/04/19 09:24	General View	Load JPG	☒
17	29/04/19 09:24	General View	Load JPG	☒
18	29/04/19 09:24	General View	Load JPG	☒
19	29/04/19 09:24	General View	Load JPG	☒
20	29/04/19 09:24	General View	Load JPG	☒
21	29/04/19 09:24	General View	Load JPG	☒
22	29/04/19 09:24	General View	Load JPG	☒
23	29/04/19 09:24	General View	Load JPG	☒
24	29/04/19 09:24	General View	Load JPG	☒
25	29/04/19 09:24	Chassis Number	Load JPG	☒
26	29/04/19 09:24	Odometer Reading	Load JPG	☒

Documentation

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	1 per page ▼	☒
1	25/04/19 16:07	TP PRI	Thumbnail	Print
2	25/04/19 16:30	SURVEY DISAGREE ON SJE - ASSIGN LKK	Load PDF	
3	25/04/19 17:01	E-FILE REPORT (SKF4840D) From: SC - Reg. No: FBL3345Z, Claimant: NUR LIYANA BTE NASSER	Load PDF	

Assessment Reports

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd, (HQ)	1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/19 11:03	PRS INVOICE	Thumbnail	Print
			 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset

Save

Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

 (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

 Our File No: CS3/MSG19007366/GTD3S2-1
 Date: 20/08/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/19-998829-WTT(TPFT)
Claimant Vehicle No:	SKF4840D	Insured Vehicle No:	FBL3345Z
Date of Loss:	23/04/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000470

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF4840D	Engine No:	07477200N52B25AF
Make & Model:	BMW 525i, 2.5 XL (E60) (A)	Chassis No:	WBANU52040C229006
Reg. Date:	05/02/2010 (Man. Year: 2009)	Odometer:	237447 km
Colour:	Pink		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/30ZR19	Rear Tyre Size:	275/30ZR19
Front Left Side:	Achilles 6 mm	Rear Left Side:	Achilles 6 mm
Front Right Side:	Achilles 6 mm	Rear Right Side:	Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	17,999.21	3,996.92	14,002.29	77.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,968.00	1,330.00	1,638.00	55.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,967.21	5,326.92	15,640.29	74.59
Approved Total (Overridden) (S\$)		4,250.00		
(S\$)	20,967.21	4,250.00	16,717.21	79.73
+ GST 7.00/7.00% (S\$)	1,467.70	297.50	1,170.20	79.73
Nett Amount (S\$)	22,434.91	4,547.50	17,887.41	79.73

INSPECTION

Date of Assignment:	26/04/2019	Inspected At:	Sat Motors (HQ) 24 Defu Lane 12 Singapore 539131
Date Inspected:	26/04/2019		
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2019)
Parts: 143	BMW 525i 2.5 XL (E60) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKF4840D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MS BUMPER	Cracked	2,686.61 F	*1,244.02 FL
2	2		*FRONT BUMPER BRACKET	Not Necessary	146.77 F	*- FL
3	1		*FRONT RIGHT MS FENDER	Repair	1,656.59 F	*- FL
4	1		*FRONT RIGHT DOOR	Dented	1,758.78 F	*1,450.00 FL
5	1		*FRONT RIGHT MS SIDE MIRROR COMPLETE	Not Necessary	1,784.84 F	*- FL
6	1		*FRONT RIGHT DOOR HINGE	Not Necessary	165.56 F	*- FL
7	1		*REAR RIGHT DOOR	Repair	1,755.26 F	*- FL
8	1		*REAR RIGHT DOOR HINGE	Not Necessary	165.56 F	*- FL
9	1		*REAR RIGHT FENDER	Repair	2,687.67 F	*- FL
10	1		*REAR MS BUMPER	Repair	2,340.32 F	*- FL
11	1		*REAR BUMPER BRACKET	Not Necessary	266.92 F	*- FL
12	1		*FRONT HEADLAMP	Broken	2,265.44 F	*1,631.00 FL
13	1		*FRONT HEADLAMP RETAINER	Not Necessary	143.21 F	*- FL
14	1		*FRONT RIGHT FENDER SIGNAL LAMP	Cracked	175.68 F	*116.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	17,999.21	4,441.02
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	444.10
Total Parts (\$\$)	17,999.21	3,996.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FIX & DISMANTLE AND REMOVE DAMAGED PARTS FRONTAL AND REAR; AFFECTED DAMAGED PORTION.	New	800.00	200.00
2	TO APPLY ANTI RUST COAT AND AFFECTED AREAS.	New	48.00	0.00
3	TO CHECK WIRING.	New	64.00	30.00
4	WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT.	New	960.00	300.00
5	SPRAY PAINTING FOR FRONTAL TO REAR AFFECTED PORTIONS.	New	1,000.00	800.00
6	FULL DIAGNOSTICS ONE ECU FOR FAULT CODES.	New	96.00	0.00
Gross Labour Cost (S\$)			2,968.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >