Adjuster Report Page 1 of 5

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19009086/KEA3Q2

Date: 18/08/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SHC5135B Insured Vehicle No: SH7921D

Vehicle No:

TP Date of Loss: 17/05/2019 Nature of Claim: Claim No: MCT19050615

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SHC5135B** Reg No:

Make & Model: RENAULT LATITUDE, 2.0 L (A) Engine No: M9R8839C000850 Chassis No: Reg. Date: 27/12/2013 (Man. Year: 2013) VF1ABL15AUC276700 Odometer: 602126 km

Colour: Metallic White/Red

1995 сс **Engine Capacity:** Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16 Front Left Side: Giti 7 mm Rear Left Side: Giti 8 mm Front Right Side: Rear Right Side: Giti 8 mm Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,826.19	1,893.82	13,932.37	88.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,890.00	490.00	8,400.00	94.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,716.19	2,383.82	22,332.37	90.36
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	24,716.19	1,900.00	22,816.19	92.31
+ GST 7.00/7.00% (S\$)	1,730.13	133.00	1,597.13	92.31
Nett Amount (S\$)	26,446.32	2,033.00	24,413.32	92.31
+ Loss of Use (2.0 x S\$4	+ Loss of Use (2.0 x S\$40.00/day) (S\$) + Car Rental (2.0 x S\$81.13/day) (S\$)			_
+ Car Rental (2.0 x S\$8				
Net	t Liability (S\$)	2,275.26		

**INSPECTION** 

Date of Assignment: 22/05/2019

Date Inspected: 22/05/2019 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jul 2020)

Parts: 143 RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHC5135B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Repairer's

Amount

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qty Part No. Particulars

NO.	Qty	Fait NO.	railiculais	Condition	Repairer 5	Amount
1	1		*BUMPER COVER REAR	Dented	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Cracked	43.61 FL	*43.61 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
34	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
36	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
43	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
			Report was unsubmitted during th	nis print-out.		
			1			

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
45	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
46	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*-FS
47	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
48	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
49	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
50	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
51	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
52	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (\$\$)  - List Item Discount on L Items 10.00/10.00% (\$\$)			<b>17,430.88</b> 1,604.69	<b>2,085.91</b> 192.09	
				Total Parts (S\$)	15,826.19	1,893.82
Report was unsubmitted during this print-out						

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	<u>Labour Items</u>						
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00			
2	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00			
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00			
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00			
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00			
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00			
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00			
8	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	200.00			
9	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00			
10	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00			
11	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00			
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00			
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00			
14	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00			
15	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00			
	Gross Labou	r Cost (S\$)	8,890.00	490.00			

Report was unsubmitted during this print-out.

< END OF ESTIMATES >