Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19009092/EGA3Q2

Date: 26/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant GBH7851Z Insured Vehicle No: SHA7271M

Vehicle No:

Date of Loss: 09/05/2019 Nature of Claim: TP Claim No: MCT19050376

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBH7851Z Reg No:

Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2826402

Reg. Date: 24/09/2018 (Man. Year: 2018) Chassis No: JTFHT02P000245067

Colour: Odometer: 10918 km Silver

Engine Capacity: 2982 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Yes Footbrake (Serviceable): General Condition: Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	866.00	826.00	40.00	4.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	960.00	320.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S	2,146.00	1,786.00	360.00	16.78
+ GST 7.00/7.00% (S	150.22	125.02	25.20	16.78
Nett Amount (S	2,296.22	1,911.02	385.20	16.78
+ Car Rental (5.0 x S\$100.00/day) (S\$) + Doc/Search Fee (S\$)		500.00		
		36.45		
	Nett Liability (S\$)	2,447.47		

INSPECTION

Estimated Period of Repair:

Date of Assignment: 22/05/2019

Date Inspected: 23/05/2019 Inspected At: Chew Goon Motor (AMK)

Global Sum Settlement (S\$)

Blk 10 Ang Mo Kio Industrial Park 2A,

#01-15/16 & 17, AMK Autopoint

2,400.00

Singapore 568047

3.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=... 26/11/2020

Adjuster Report Page 2 of 4

Adjuster: CHEN TSUE YEE Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2020)	
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for GBH7851Z)			
Validity:	idity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT CORNER PANEL LH	Dented	232.40 FL	*232.40 FL	
2	1		*FRONT CORNER PANEL SEAL	Crushed	72.50 FL	*72.50 FL	
3	1		*HEADLAMP LH	Broken	523.10 FL	*523.10 FL	
4	1		*FRONT DOOR STICKER LH	Necessary	200.00 FS	*160.00 FS	
5	1		*FRONT DOOR REG LABEL	Necessary	45.00 FS	*45.00 FS	
F=Fra	F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	1,073.00	1,033.00	
	- List Item Discount on L Items 25.00/25.00% (S\$)			207.00	207.00		
				Total Parts (S\$)	866.00	826.00	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	Labour Items					
1	TO CONDUCT FRONT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	30.00		
2	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	50.00	30.00		
3	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT DOOR ,BONNET ,BUMPER AND PARTS REPLACEMENT	New	450.00	300.00		
4	TO RESPRAY AFFECTED AREAS	New	750.00	600.00		
	Gross Labour Cost (S\$)		1,280.00	960.00		
	Report was unsubmitted duri	ing this print-out.				

< END OF ESTIMATES >