

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465 *ESIC*
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Third Party

Policy No: _____

21.05.2019

Date: _____

Accident Date : 09.05.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Toyota Hiace" Reg. No. GBH7851Z Claiming Against Your Insured Veh. No. SHA7271M		
1pc	Front Corner Panel LH / <i>DD</i>		232.40
1pc	Front Corner Panel Seal / <i>CR4</i>		72.50
1pc	Headlamp LH / <i>RR</i>		523.10
			828.00
			207.00
	Less 25%		621.00
	Front Door Sticker LH NEC		<i>160</i> 200.00 SN
	Front Door Reg Label NEC		45.00 SN
	To Conduct Front Electrical Check, Focus Headlamp		30.00 /
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		50.00 <i>80</i>
	Labour Charge - Panel Beating, Repairing Of Front Door, Bonnet, Bumper and Parts Replacement		450.00 <i>300</i>
	To Respray Affected Areas		750.00 <i>600</i>
		Total :	2,146.00

Steve (LKK) W/L Mr. J. 23/5/19, 3.00pm
8322 8813

3 days

P/P

Ry bef spray

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: