

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 22/05/2019 5:53 PM

Full Report
Registration: SME2417M TP
Printed: 22/05/2019 5:53 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	JOON LIAN TAN	Currency:	SGD
Claim Reference:		Date of Incident:	17/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES-BENZ
Model:	ML-CLASS (W164)
Sub Model:	ML 300 CDI 4-MATIC
Model Sheet Number:	03 46 14
Registration:	SME2417M TP
VIN number:	WDC1641822A717077
Odometer:	95907

Model Specs

FROM VIN A661926	MODEL CHANGE 2011	BLUE TINT WINDOWS	RAIN SENSOR
DIPPING DOOR MIRROR	B-XENON/CORNERING LA	HEADLAMP WASHER UNIT	ALCANTARA TRIM
INTERIOR LAMP PACK	SPORTS PACK EXTERIOR	SPORTS PACK INTERIOR	FOLDING DOOR MIRRORS
ASHTRAY PACKAGE	WOOD EQUIPM POPLAR	AUTO TAILGATE CONTR	ELEC DRIVER SEAT MEM
NECK-PRO HEADREST	PRE-SAFE SYSTEM	FRT SPORT SEATS	LUGGAGE COVER
BOOT PARTITION NET	7-SPEED AUTOMATIK	PARAMETER STEERING	TYRE PRESSURE SENSOR
TYRES 285/45 ZR 19	WHEELS 8.5J X 19 ALU	SPARE WHEEL	AUDIO SYSTEM 20 CD
PARKTRONIC	MEDIA INTERFACE	STEP BOARDS ST/STEEL	UNDERBODY PROTECTION
ROOF RAILS	TWO COAT PEARL/MICA		

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 22/05/2019 5:53 PM

Full Report
Registration: SME2417M TP
Printed: 22/05/2019 5:53 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
88-8802 01	R + R REAR BUMPER		8.0	36.00
88-8909 01	ADDITION TO R + R REAR BUMPER (VEHICLE WITH PARKTRONIC)		1.0	4.50
88-8805 02	DIS + ASS REAR BUMPER AFTER FINDING: RENEW PARTS (REMOVED)		8.0	36.00
88-8883 01	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)		3.0	13.50
88-8956 02	R + R REAR LOWER BUMPER CROSSMEMBER (BUMPER REMOVED)		13.0	58.50
88-1052 01	R + R REAR NUMBER PLATE		2.0	9.00
72-4573 01)	R + R TAILGATE LOCK STRIKER		3.0	13.50
68-3080 01	R + R CENTRE REAR PANEL TRIM		3.0	13.50
82-4905 01	R + R BOTH REAR LAMP UNITS		4.0	18.00
54-7989 01	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)		3.0	13.50

HIN LUNG WORKSHOP

1008 Bukit Merah Lane 3, #01-20

159722

Claim Reference:
 Assessment number: HLW00044
 Version: 1810
 Date calculated: 22/05/2019 5:53 PM

Full Report
 Registration: SME2417M TP
 Printed: 22/05/2019 5:53 PM

Code	Description	WU	Price SGD
49-4965 01	R + R RIGHT REAR SILENCER	8.0	36.00
49-8415 01	R + R R/R EXHAUST COVER	2.0	9.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		5.80	58.0
Total of Labour			261.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	RR UPP BUMPER COVER NEW PART PAINT K1R	10.0
	LWR RR BUMPER COVER NEW PART PAINT K1R	8.0
	RR TOWING LUG COVER NEW PART PAINT K1R	3.0
	L/R OUTER SENSOR NEW PART PAINT K1R	3.0

Paint Material Per Part

Code	Description	Price SGD
2583	RR UPP BUMPER COVER NEW PART PAINT K1R	44.77
2585	LWR RR BUMPER COVER NEW PART PAINT K1R	34.44
2597	RR TOWING LUG COVER NEW PART PAINT K1R	0.49
2669	L/R OUTER SENSOR NEW PART PAINT K1R	0.49

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	45.00 SGD/h			
Time Paint			24.0	
Preparation Comp. Work Plastic		0.90	9.0	40.50
Total	10 WU/h	3.30	33.0	148.50

Material Cost - Paint		Price SGD
New Part Painting - Plastic K1R		80.19
Material-constant Plastic		16.20
Total		96.39

Spare Parts

prices as at 2015-06-01

HIN LUNG WORKSHOP

1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:

Assessment number: HLW00044

Version: 1810

Date calculated: 22/05/2019 5:53 PM

Full Report

Registration: SME2417M TP

Printed: 22/05/2019 5:53 PM

Code	Description	Part Number	Supplier	Price SGD
2583	RR UPP BUMPER COVER	164 880 2940 9999	✓ (UT)	1,265.00
2585	LWR RR BUMPER COVER	164 885 6925	✓ (UT)	500.00
		7C45		
2593	BUMPER COVER CAP	164 885 3323	✗ (Chmro) ✓ DD (UT)	645.00
2597	RR TOWING LUG COVER	164 885 3223 9999	✗ ?	40.00
2600	RR BUMPER CTR COVER	164 880 0111	✗ (Chmro) ?	150.00
2618	R/R BUMPER BRACKET	164 885 2865	?	80.00
2625	L/R C-MEMBER	164 640 1131	X	200.00
	CONSOLE			
2626	R/R C-MEMBER	164 640 1231	?	200.00
	CONSOLE			
2640	REAR BUMPER C-MEMBER	164 619 0122	?	450.00
			?	
2641	RR INNER BUMPER PART	164 885 1765	?	210.00
2669	L/R OUTER SENSOR	221 542 0417	?	165.00
2681	L/R OUT SPACER RING	221 542 0051	✓ 116C	8.00
2682	R/R OUT SPACER RING	221 542 0051	✓ 116C	8.00
2813	L/R GASKET FLANGE	164 619 0098	X	32.00
2814	R/R FLANGE GASKET	164 619 0098	?	32.00
3282	R/R LAMP	164 906 4300	X	500.00
3286	R/R REFLECTOR	164 820 1574	✓ OR	42.00
8828	R/R SILENCER	164 490 8415	X	1,010.00
8848	R/R END PIPE	164 490 2327	✓ (UT)	240.00
2584	L/R BUMPER CONSOLE	164 885 0031	X	55.00
2585	R/R BUMPER CONSOLE	164 885 0131	?	55.00
2586	R/R OUT SENSOR BRKT	221 542 0417		0.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Savings

Subtotal

Addition(+15.00%)

Total

0.00

5,887.00

883.05

6,770.05

Extras

Code	Description	Price SGD
2583	[S]: RR UPP BUMPER C OVER: INCLUDES	0.00*
2583	REAR BUMPER PDC SENS OR	0.00*

HIN LUNG WORKSHOP
1008 Bukit Merah Lane 3, #01-20
159722

Claim Reference:
Assessment number: HLW00044
Version: 1810
Date calculated: 22/05/2019 5:53 PM

Full Report
Registration: SME2417M TP
Printed: 22/05/2019 5:53 PM

Final Calculation

	SGD	SGD
Parts	5,887.00	
Addition(+15.00%)	883.05	
Total Parts		6,770.05
Labour Time Base 10 WU/h		
Total 58.0 WU X 45.00 SGD/h	261.00	
Total of Labour		261.00
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 33.0 WU X 45.00 SGD/h	148.50	
Material Cost	96.39	
Total Paint Including Material		244.89
Repair Cost Excludes GST		7,275.94
GST (+7.00%)		509.32
Repair Cost Included GST		7,785.26

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Steve (LKK) wh Mr. 27/5/19, 11.30 am
8322 8813 3 days

P/P

Ry before spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: