

AIG



# ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Repair Estimates

SLQ 5382 H

Not Whorin  
Mummy Aka Pain

Parts	(a) Cost / List Price Items	\$	3,085.85
	Plus/Less 25%	\$	771.46
	<b>Total of Cost / List</b>	<b>\$</b>	<b>2,314.39</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items	\$	200.00
<b>Total Parts Cost</b>		<b>\$</b>	<b>2,514.39</b>
<b>Labour</b>		<b>\$</b>	<b>2,240.00</b>
<b>Total</b>		<b>\$</b>	<b>4,754.39</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : LKK  
Survey conducted on : 23/5/19 at \_\_\_\_\_

### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : LK Date: 23/5/19



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

### Spare Parts

Vehicle No. : SLQ 5382 H  
Make & Model : TOYOTA PRIUS  
Chassis No : JTDKB3FU103562003

Submit By : SERENCE  
Year Manufacture : 2017  
Engine No. :

### Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>SL</i>	1	\$200.00	S.N	X
2	Rear bumper <i>SL</i>	1	\$497.50		X
3	Rear bumper clip <i>SL</i>	10	\$40.00		X
4	Rear bumper side retainer LH <i>SL</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>SL</i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		?
7	Rear bumper lower garnish centre <i>Not / Dry</i>	1	\$582.60		✓
8	Rear bumper lower garnish LH <i>SL</i>	1	\$149.70		X
9	Rear bumper lower garnish RH <i>SL</i>	1	\$149.70		X
10	Rear bumper tow cover <i>SL</i>	1	\$31.70		X
11	Tail lamp LH - UPPER <i>SL</i>	1	\$498.75		X
12	Tail lamp LH - LOWER <i>SL</i>	1	\$511.60		X
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

### Labour

Vehicle No. : **SLQ 5382 H** Submit By : **SERENCE**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	1201
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, SPARE TYRE COMPARTMENT)	\$800.00	2201
3	To tuff coat. <i>nn</i>	\$50.00	X
4	TO Check wiring	\$50.00	101
5	To transfer boot mechanism to new boot <i>nn</i>	\$120.00	X
6	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
7	To remove & refit reverse sensor	\$150.00	X
8	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.