

198200

INS. CASE OWNER:

CC } /CTI1900

9127, Kpbh.52

LKK:
IDAC:

Surveyor:

Finnelan

DOI:

22/1/19

Date / Time:

22/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GL 11 Y

Claim No.:

SWM19022264

Name of Insured:

GU INDUSTRIAL SUPPLY & SERVICES

Policy No.:

DMV/SW200 541904

Insured Tel No.:

HP:

Make / Model:

MSSHW

Excess Sec II :SS

D.O.A:

14/1/19

Place of Accident:

7-THRU OF TAMPINGS ARE 10 & 418 9

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE POH CHUAN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHC 54534



INRS:
WSP:
Tel:
Liability:
RMKS:

Trans Cab



INRS:
WSP:
Tel:
Liability:
RMKS:



INRS:
WSP:
Tel:
Liability:
RMKS:



INRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
19-06-19 @ 10-50	Call OI:	EMPA 19.619
	After call ltr to OI:	
	Documentation Check List:	Handler Tyst
21/1/19	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: KSC

Repair Cost: 43 \$59,450 (5 days) Reduction: 81 % Email Call

FINAL SETTLEMENT Date/Time: 20.09.19 Confirm with: WAH YIH Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia:

Repair Cost: 21627 \$510,111.50 O/D REAR ENDED TP.

Loss of Rental (LOR): \$5 1,066.89 (5 days) x 216.99

Loss of Use (LOU): \$5 - (5 x 11 days)

Loss of Income (LOI): \$5 550.00 (\$50 x 11 days)

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search \$5 1.99

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost \$5 -

Total: \$5 11,135.88 Global Sum \$5:

FINAL PAYMENT Date/Time: 20.09.19 Confirm with: WAH YIH Email Call

Payee 1: \$5 11,135.88 Name 1: TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Trans Cob

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S4C 5453H Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading 322174 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1A9L15A4C 280938

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NI / S/RIm / STD A/RIm or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front 6 mm Rear 7 mm

R/Bal. 6 mm L/Bal. 7 mm

L/Bal. 6 mm D.O.I. 17/5/19

D.O.I. 22/5/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>
	<u>45 → 9,130 (REP: 40,497.01 81%)</u>

Date/Time, File Pass to? : Prell. Report : Final Report

1) _____
2) _____

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:
Transportation:
S - RS. SI
Fixtms
Others
TOTAL

Report Format :
Lump Sum / I.B.I: (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 URAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19009127/Kpb3

Date: 23.05.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC5453H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.05.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	49,947.07
Revised Estimate Amount	: S\$	11,829.45
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHC 5453H

AAD1905-166

*Not Authored
 C/Bump &*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date Of Registration:

SHC 5453H

VF1ABL15AUC280938
 RENAULT
 LATITUDE
 17.5.19

CHINA TAIPING

18/12/2014

PART		LIST
1	1 BUMPER COVER REAR	\$ <i>Buy</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$ <i>Dallay</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$ <i>D.V</i> 113.47 ✓
4	1 BUMPER BRACKET SIDE RH REAR	\$ <i>Sn</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$ <i>Sn</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$ <i>Sn</i> 43.61 X
7	1 BUMPER BRACKET SIDE LH REAR	\$ <i>Sn</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$ <i>Sn</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$ <i>Sn</i> 43.61 X
10	1 BUMPER BEAM REAR	\$ <i>Bz</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ <i>Bz</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$ <i>D.V</i> 225.95 ✓
13	1 BOOT REAR	\$ <i>Bz</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$ <i>CADWAY</i> 470.06 ✓
15	1 BOOT WHEATERSTRIP	\$ <i>Dis Int</i> 323.05 <i>50% extra @ 161.50</i>
16	1 BOOT REFLECTOR LAMP LH	\$ <i>CM</i> 493.35 ✓
17	1 BOOT REFLECTOR LAMP RH	\$ <i>CM</i> 493.35 ✓
18	1 BOOT BADGE 'RENAULT'	\$ <i>nu</i> 225.36 ✓
19	1 BOOT BADGE	\$ <i>nu</i> 225.36 ✓
20	1 BOOT STRUT LH	\$ <i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$ <i>Sn</i> 276.08
*22	1 BOOT HINGE LH	\$ <i>R</i> 367.84
*23	1 BOOT HINGE RH	\$ <i>R</i> 367.84
24	1 BOOT INNER TRIM	\$ <i>Sn</i> 586.45
25	1 BOOT SWITCH	\$ <i>Sn</i> 168.13
*26	1 BOOT LOCK	\$ <i>R</i> 202.67
*27	1 BOOT LOCK CATCH	\$ <i>R</i> 74.40
28	1 LICENCE PLATE LAMP	\$ <i>CMS</i> 50.52 ✓
29	2 BOOT RUBBER PLUG	\$ <i>Sn</i> 221.81 X
30	1 FENDER PANEL INNER TRIM REAR RH	\$ <i>Sn</i> 671.45 X

Trans-cab Auto Services Pte Ltd

AAD1905-166

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5453H

31	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
32	1	WHEELARCH REAR RH	\$	Sn	543.47	X
33	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
34	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
35	1	WHEELARCH REAR LH	\$	Sn	543.47	X
36	1	TAILLAMP RH	\$	mjc m	552.55	✓
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	mjc m	552.55	✓
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	cm	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,868.94
10%	\$	3,586.89
	\$	32,282.05⁴³

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	R	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	R	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
17	1	SPARE TYRE	\$	Sn	330.00	X

Trans-cab Auto Services Pte Ltd

AAD1905-166

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5453H

18	1	FENDER INNER TRIM CLIP RH	\$	<i>nn</i> 28.00 X
19	1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 ✓
20	2	REAR WINDSCREEN SEALANT	\$	<i>nn</i> 80.00 X
21	1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 X
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 X
23	1	TAILLAMP CLIP LH	\$	<i>nn</i> 5.00 ✓
24	1	FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 X
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i> 35.00 X
TOTAL			\$	2,225.02
TOTAL PARTS			\$	34,507.07

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>6001</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>6601</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	} <i>601</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>601</i>

Trans-cab Auto Services Pte Ltd

AAD1905-166

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5453H

To repair and realign rear exhaust pipe.	\$	<i>na</i>	170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	<i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i>	380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i>	170.00	<i>X</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>

TOTAL \$ 15,440.00

Over All Total \$ 49,947.07⁴⁵

(LUMP SUM) Repair Days

20 DAYS

5 days

11829.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5453H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002284
Chassis No.:	VF1ABL15AUC280938
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$23,061.00
Total Rebate Amount:	\$32,434.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 May 2019

OK

Shu Pei (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 24 May 2019 11:28 AM
To: Shu Pei (LKKAuto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GL11Y (OI : CTI - TBA) AND SHC5453H (TP : LKK REF - CC3/CTI19009127/Kpb3) on 17.05.2019 / our ref: SNM19D202264
Attachments: insured report.pdf

Dear Shu Pei,

Pls find insured report and claim reference.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 23 May, 2019 7:14 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving GL11Y (OI : CTI - TBA) AND SHC5453H (TP : LKK REF - CC3/CTI19009127/Kpb3) on 17.05.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 5453H at M/s Trans-cab Auto Services Pte Ltd – Ang Mo Kio on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19009127/Keb3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 01-10-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GL 11Y	Veh. Inspected	SHC 5453H
Policy No.	DMCVSN3012541904	Coverage (\$)	0.00
Claim No.	SNM19D202264C03/1	Excess (\$)	0.00
Assign From		Assign Date	22/05/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC280938	Colour	METALLIC WHITE / RED
Odometer	322174	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	6 mm
L/H Front Tyre	215/60R16	GITI	6 mm
R/H Rear Tyre	215/60R16	GITI	7 mm
L/H Rear Tyre	215/60R16	GITI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/05/2019	Inspection Date	22/05/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5453H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	CRACKED / WARPED	470.06	470.06
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	CRACKED	493.35	493.35
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
1	LICENCE PLATE LAMP	CRACKED	50.52	50.52

Report Ref No. CC3/CTI19009127/Keb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	TAILLAMP RH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	MTG CRACKED	552.55	552.55
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,554.59	-1,103.23
			31,991.28	9,929.07
1	BOOT WEATHERSTRIP (50%) (SN)	DISTORTED / DENTED	323.50	161.53
	LESS 10% DISCOUNT		-32.35	-
			291.15	161.53
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00

Report Ref No. CC3/CTI19009127/Keb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
1	FENDER INNER TRIM CLIP LH	NOT NECESSARY	28.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
			2,225.02	235.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	600.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL REAR RH, FENDER PANEL REAR LH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR AND EXHAUST CAP REAR.		6,000.00	660.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
			15,440.00	1,520.00
	GRAND TOTAL		49,947.45	11,845.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,450.00

Report Ref No. CC3/CT19009127/Keb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.