



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2018 12:42
Date Of Accident	04/04/2018 08:20
Exact Location Of Accident	ALONG BUKIT BATOK RD TOWARDS JURONG EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX280B
Insured/Policyholder	
Name Of Registered Owner	TAN GIM HOO
NRIC No	S1632383G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93202865
Alternative Phone No	OFFICE-93202865

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10700397
Cover Note Number	

Driver

Name of Driver	TAN QIFAN
NRIC No	S9647145I
Date Of Birth	26/12/1996
Occupation	INDOOR
Date Of Driving Pass	30/08/2017
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-93202865
Fax Number	
Contact Number	
Email Address	JUDY@SANWAGROUP.COM.SG

Nature Of Damage

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJU4153L

Vehicle Make/Model/Colour SJU4153L/ ACCORD 2.0A

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver JEFF TAN CHEE WEE

NRIC/Passport Number S8703308B

Contact Number 96255411

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 1

Sketch Plan #2 Pg. 1

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG BUKIT BATOK ROAD TOWARDS JURONG EAST AND AFTER THE JUNCTION OF BUKIT BATOK WEST AVE 7, VEHICLE SGJ8638Y SUDDENLY JAMMED BRAKE AND I COLLIDED ONTO THE REAR PORTION OF THE VEHICLE. I STEPPED TO NOTICE A THREE VEHICLE COLLISION INVOLVING ANOTHER VEHICLE SJU4153L AS THE FIRST VEHICLE. NO INJURIES WERE INVOLVED.


Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AMMAR HAMIZAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:


Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S96471451**
Name: **TAN QIFAN**

Birth Date: **26 Dec 1996**
Issue Date: **30 Aug 2017**

002719153J



Identification Card

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S9647145I**



Name

TAN QIFAN

陈 麒 帆

Race

CHINESE

Date of birth

26-12-1996

Sex

M

Country of birth

SINGAPORE



ECLIPSE AUTO PTE LTD

155 KAKI BUKIT AVENUE 1, SHUN LI INDUSTRIAL PARK LEVEL 1 & 2, SINGAPORE 416012

TEL : (65) 6844 2814 FAX : (65) 6748 3762

Co. Reg. No.: 201221209k

Vehicle No: SJU 4153L

Made / Model: HONDA ACCORD 2.0 A

Name: JEFF TAN CHEE WEE

Address: C/o: 155 Kaki Bukit Avenue 1, Shun Li Industrial Park
#01-00 Singapore 416012

Accident Date: 4/4/18

RE: FINAL BILL FOR VEHICLE NO. SJU 4153L

(LUMP SUM REPAIR)

\$ 7,000.00

Singapore Dollars: Seven Thousand Only.



INVOICE

TO : JEFF TAN CHEE WEE
C/O: ECLIPSE AUTO PTE LTD
155 KAKI BUKIT AVE 1 #01-00,
SHUNLI INDUSTRIAL PARK
SINGAPORE 416012

Invoice No.: 418/EA604
Date: 30-Apr-2018

PARTICULARS

Vehicle Registration No.: SJU 4153 L
Date of Loss: 04-Apr-2018
Date of Assessment: 05-Apr-2018

SERVICES

FEES

1. Assessment with report Photographs - Including films, developing, storage and Transport.	\$500.00
--	----------

TOTAL \$500.00

SINGAPORE DOLLARS FIVE HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97697958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: JEFF TAN CHEE WEE
C/O: ECLIPSE AUTO PTE LTD
155 KAKI BUKIT AVE 1 #01-00,
SHUNLI INDUSTRIAL PARK
SINGAPORE 416012

Our Reference: 418/EA604
Date: 30-Apr-2018

ASSESSMENT OF VEHICLE NO. SJU 4153 L

DATE OF LOSS: 04-Apr-2018

We have carried out a physical assessment at **ECLIPSE AUTO PTE LTD**,
155 Kaki Bukit Ave 1 #01-00 Shunli Industrial Park, Singapore 416012, according to your instruction
on **05-Apr-2018** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SJU 4153 L
Make & Model: HONDA ACCORD 2.0 A
Year of Registration: 2006
Engine Capacity: 1998
Chassis No.: CL73200864
Engine No.: K20A6041095
Colour: BLACK
Mileage (km): 183108

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION

Front
RH Make/Size/Thread: BRIDGESTONE 205/55 R16 - 70%
LH Make/Size/Thread: BRIDGESTONE 205/55 R16 - 70%


Rear
RH Make/Size/Thread: BRIDGESTONE 205/55 R16 - 70%
LH Make/Size/Thread: BRIDGESTONE 205/55 R16 - 70%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the REAR portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$11,570.76
Adjusted Amount:	\$9,797.36
Lump Sum:	\$7,000.00
Estimated Repair Days:	7 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.
The assessment was conducted on a "Without Prejudice" basis.
If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SJU 4153 L

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	REAR BOOTLID	Bent	561.60	561.60 ✓
2	REAR BOOTLID HINGES GARNISH CLIPS	Necessary	11.00	11.00 X
2	REAR BOOTLID HINGES GARNISH L/R	Bent	70.00	70.00 X
2	REAR BOOTLID HINGES L/R	Bent	176.00	176.00 X
1	REAR BOOTLID INNER L'PHOSLTERY TRIM	Cracked	157.30	157.30 X
10	REAR BOOTLID INNER L'PHOSLTERY TRIM CLIPS	Necessary	55.00	55.00 ✓
1	REAR BOOTLID MECHANISM LOCK	Bent	189.20	189.20 ✓
2	REAR BOOTLID REFLECTOR LAMP L/R	Cracked	314.60	314.60 157.3
2	REAR BOOTLID REFLECTOR CLIPS	Necessary	11.00	11.00 X
2	REAR BOOTLID NUMBER PLATE LAMP L/R	Bent	52.80	52.80 X
4	REAR BOOTLID RUBBER GUIDE STOPPER	Bent	28.00	28.00 X
1	REAR BOOTLID WEATHER STRIP	Cut	100.10	100.10 ✓
2	REAR TAILLAMP L/R	Cracked	382.00	382.00 ✓
4	REAR TAILLAMP CLIPS	Necessary	22.00	22.00 ✓
2	REAR FENDER L/R	Repair	1,616.00	-
2	REAR FENDER INNER U'PHOSLTERY TRIM L/R	Cracked	314.60	314.60 X
1	REAR BUMPER	Cracked	976.00	976.00 ✓
2	REAR BUMPER CORNER BRACKET L/R	Bent	27.00	27.00 X
1	REAR BUMPER EXHAUST COVER	Cracked	36.00	36.00 X
2	REAR BUMPER INNER BRACKET L/R	Bent	13.20	13.20 X
2	REAR BUMPER REFLECTOR L/R	Cracked	80.80	80.80 ✓
2	REAR BUMPER SIDE RETAINER L/R	Bent	37.00	37.00 ✓
1	REAR END PANEL	Bent	381.90	381.90 ✓
1	REAR END PANEL INNER TOP GARNISH	Cracked	69.10	69.10 ✓
4	REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	22.00	22.00 ✓
1	SPARE TYRE PANEL TOP CARD BOARD WITH CARPET	Cut	560.00	560.00 X
1	SPARE TYRE PANEL TOP TOOL COMPARTMENT SPONGE	Cracked	180.00	180.00 X
1	SPARE TYRE PANEL INSULATOR MAT	Necessary	325.30	325.30 X
1	SPARE TYRE RETAINER LOCK	Bent	22.00	22.00 X
1	SPARE TYRE PANEL LOWER GARNISH	Cracked	125.00	125.00 X
8	SPARE TYRE PANEL LOWER GARNISH CLIPS	Necessary	44.00	44.00 X
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	Bent	55.00	55.00 X
3	REAR EXHAUST RUBBER MOUNTING	Bent	33.60	33.60 ✓
1	REAR EXHAUST END CHROME PIPE	Bent	112.30	112.30 ✓
1	REAR EXHAUST SILENCER BOX	Bent	1,033.30	1,033.30 X
			<u>8,194.70</u>	<u>6,578.70</u>
Less 20% discount			1,638.94	1,315.74
Parts Total:			<u>6,555.76</u>	<u>5,262.96</u>

3179.9

20%: 2543.92

ASSESSMENT REPORT FOR VEHICLE NO. SJU 4153 L

SPECIAL NETT ITEMS

1	REAR BOOTLID NUMBER PLATE	Cracked	25.00	25.00 X
1	REAR BOOTLID NUMBER PLATE GARNISH	Cracked	50.00	NN 50.00 X
2	REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R - SET	Necessary	60.00	60.00 X
1	REAR BUMPER CLIPS - SET	Necessary	30.00	30.00
1	REAR BUMPER REVERSE SENSOR - SET	Cracked	350.00	350.00 200
1	REAR TAILGATE REVERSE CAMERA	Faulty	800.00	NN 800.00 X
Special Nett Total :			1,315.00	1,315.00

230

LABOUR

S/N	Description	Workshop's Estimate	Our Assessment
1	To provide towing charge.	50.00	NN 50.00
2	To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	150.00	60 130.00
3	To remove, reinstall top trim upholstery, cushion seat, trim garnish, trim liner carpet.	140.00	60 120.00
4	To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	140.00	1 120.00
5	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,400.00	800 1,200.00
6	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,700.00	800 1,500.00
7	To apply anti-rust chemical on repaired and replaced panel.	120.00	60 100.00
Labour Total :		3,700.00	3,220.00
TOTAL (PARTS & LABOUR) \$		11,570.76	9,797.96

1900

4673.92

20% : 3700

7 Days.

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$7,000.00

(SINGAPORE DOLLARS SEVEN THOUSAND ONLY)



Amas Ong
Automobile Assessor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Your Ref: 18.25274 PD-O

Date: 01st July 2019

Our Ref: CS3/ASM18015108/Gsd3s2-1

M/s AXA Insurance Pte Ltd
C/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJU 4153L
INSURED VEHICLE: SGJ 8638Y ACCIDENT DATE: 04/04/2018**

We thank you for your instruction on 23/05/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJU 4153L from M/s AEON Auto Consultant LLP.
- b) Final Repair Bill of SJU 4153L from M/s Eclipse Auto Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJU 4153L, SGJ 8639Y and SKX 280B.
- d) Damaged vehicle photographs of SJU 4153L.

Pre-Repair Inspection Date: 10/04/2018 at M/s Eclipse Auto Pte Ltd, 155 Kaki Bukit Avenue 1
#01-00 Shun Li Industrial Park Singapore 416012.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJU 4152L
Make & Model	: Honda Accord 2.0 A
Year of Registration	: 2006
Chassis Number	: CL73200864
Engine Capacity	: 1998 cc
2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 4153L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	BENT	561.60	561.60
2	REAR BOOTLID HINGES GARNISH CLIPS	NOT NECESSARY	11.00	-
2	REAR BOOTLID HINGES GARNISH L/R	NOT NECESSARY	70.00	-
2	REAR BOOTLID HINGES L/R	NOT NECESSARY	176.00	-
1	REAR BOOTLID INNER UPHOLSTERY TRIM	NOT NECESSARY	157.30	-
10	REAR BOOTLID INNER UPHOLSTERY TRIM CLIPS	NECESSARY	55.00	55.00
1	REAR BOOTLID MECHANISM LOCK	BENT	189.20	189.20
2	REAR BOOTLID REFLECTOR LAMP L/R	N/S NOT NECESSARY / O/S SCRATCHED	314.60	157.30
2	REAR BOOTLID REFLECTOR CLIPS	NOT NECESSARY	11.00	-
2	REAR BOOTLID NUMBER PLATE LAMP L/R	NOT NECESSARY	52.80	-
4	REAR BOOTLID RUBBER GUIDE STOPPER	NOT NECESSARY	28.00	-
1	REAR BOOTLID WEATHER STRIP	CUT	100.10	100.10
2	REAR TAILLAMP L/R	CRACKED	382.00	382.00
4	REAR TAILLAMP CLIPS	NECESSARY	22.00	22.00
2	REAR FENDER L/R	TO REPAIR SEE LABOUR	1,616.00	-
2	REAR FENDER INNER UPHOLSTERY TRIM L/R	NOT NECESSARY	314.60	-
1	REAR BUMPER	CRACKED	976.00	976.00
2	REAR BUMPER CORNER BRACKET L/R	NOT NECESSARY	27.00	-
1	REAR BUMPER EXHAUST COVER	NOT NECESSARY	36.00	-
2	REAR BUMPER INNER BRACKET L/R	NOT NECESSARY	13.20	-
2	REAR BUMPER REFLECTOR L/R	CRACKED	80.80	80.80
2	REAR BUMPER SIDE RETAINER L/R	BENT	37.00	37.00
1	REAR END PANEL	BENT	381.90	381.90
1	REAR END PANEL INNER TOP GARNISH	CRACKED	69.10	69.10
4	REAR END PANEL INNER TOP GARNISH CLIPS	NECESSARY	22.00	22.00
1	SPARE TYRE PANEL TOP CARD BOARD WITH CARPET	NOT NECESSARY	560.00	-
1	SPARE TYRE PANEL TOP TOOL COMPARTMENT SPONGE	NOT NECESSARY	180.00	-
1	SPARE TYRE PANEL INSULATOR MAT	NOT NECESSARY	325.30	-
1	SPARE TYRE RETAINER LOCK	NOT NECESSARY	22.00	-
1	SPARE TYRE PANEL LOWER GARNISH	NOT NECESSARY	125.00	-
8	SPARE TYRE PANEL LOWER GARNISH CLIPS	NOT NECESSARY	44.00	-

Report Ref No. CS3/ASM18006455/Gpa3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	NOT NECESSARY	55.00	-
3	REAR EXHAUST RUBBER MOUNTING	BENT	33.60	33.60
1	REAR EXHAUST END CHROME PIPE	BENT	112.30	112.30
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	1,033.30	-
	LESS 20% DISCOUNT		-1,638.94	-635.98
			6,555.76	2,543.92
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOTLID NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR BOOTLID NUMBER PLATE GARNISH (SN)	NOT NECESSARY	50.00	-
2	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS L/R (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	CRACKED	350.00	200.00
1	REAR TAILGATE REVERSE CAMERA (SN)	NOT NECESSARY	800.00	-
			1,315.00	230.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING CHARGE.	NOT NECESSARY	50.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		150.00	60.00
	TO REMOVE, REINSTALL TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET.		140.00	60.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		140.00	120.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,400.00	800.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FENDER L/R.		1,700.00	800.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			3,700.00	1,900.00
GRAND TOTAL			11,570.76	4,673.92

Report Ref No. CS3/ASM18006455/Gpa3s2-1



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,700.00
---	--	--	----------

Report Ref No. CS3/ASM18006455/Gpa3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.