



Case Details

Case Reference Number : BUS/05/19/5035
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB326X

Company Type : SMRT Buses Ltd
 Estimation ID : EST-6964-ID
 Assigned By : Bus Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 14/05/2019 06:28 AM
 Vehicle Age(In Months) : 78

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main	BODY LH	6010159	MIRROR,VIEW:FRONT,LH,FOR MAN	1	1,903.30	1,903.30	10.00	1,712.97	Replace	<input type="text" value="1"/>	<input type="text" value="1,712.97"/>	Replace ▾	CRA
Standard	Main	BODY LH	6010160	ARM,MIRROR VIEW:FRONT,LH,FOR MAN	1	684.30	684.30	10.00	615.87	Replace	<input type="text" value="1"/>	<input type="text" value="615.87"/>	Replace ▾	CRA
Total Spare Part Cost									2,328.84	Surveyor Total		2,328.84		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		<input type="text" value="20"/>		
Final Spare Part Cost									1,863.07	Final Sur Total		1,863.07		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL FRONT VIEW MIRROR LH	<input type="text" value="530.00"/>	<input type="text" value="265"/>	
Total:			530.00	265.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	<input type="text" value="462.00"/>	<input type="text" value="262"/>	
Total:			462.00	262.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	1,863.07	<input type="text" value="1,863.07"/>
Total Labour Cost	530.00	<input type="text" value="265.00"/>
Total Spray Painting	462.00	<input type="text" value="262.00"/>

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Other	0.00	<input type="text" value="0.00"/>
Overall Total	2,855.07	<input type="text" value="2,390.07"/>
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	0.00	<input type="text" value="2,400.00"/>
Surveyor Approved Amount		<input type="text" value="2,400.00"/>
No of Repair Days*	2	<input type="text" value="1"/>
Remarks	-	<input type="text" value="L/S REPAIR, AFTER PAINT PHOTO"/>
Surveyor Name		<input type="text" value="Hwee jie"/>
Signature		<input type="text" value="C"/> <input type="button" value="Save"/> <input type="button" value="Clear"/>
Survey Date	<input type="text" value="23/05/2019"/>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: