

Alu

not Admin
Han
28/5/19
2/5 # 6800/
Fahy
Zoh, the Affair

GBF4565E Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,260.00
2	1	Rear bumper left bracket	\$ 86.00
3	1	Rear bumper inner beam	\$ 287.00
4	1	Rear bumper step garnish	\$ 296.00
5	1	Rear tailgate assy	\$ 1,862.00
6	1	Rear tailgate lock mechanism	\$ 266.00
7	1	Rear tailgate lock catch	\$ 62.00
8	2	Rear tailgate hinges	\$ 162.00
9	2	Rear tailgate damper	\$ 375.00
10	1	Rear tailgate weatherstrip	\$ 288.00
11	1	Rear tailgate inner board	\$ 190.00
12	1	Rear tailgate centre logo	\$ 68.00
13	1	Rear tailgate windscreen glass moulding	\$ 295.00
14	1	Rear tailgate lock actuator	\$ 189.00
15	1	Rear tailgate outer garnish	\$ 176.00
16	1	Rear tailgate lock cylinder	\$ 191.00
17	1	Rear left taillamp	\$ 785.00
18	1	Rear left taillamp lower panel	\$ 109.00
19	1	Rear left fender panel assy	\$ 6,800.00
20	1	Rear left air duct	\$ 96.00
21	1	Rear left lower side panel	\$ 580.00
22	1	Rear end lower panel	\$ 1,274.00
			\$ 15,697.00
Less 25%			\$ 3,924.25
			\$ 11,772.75

Special Nett Items

1	10	Rear bumper clips	\$ 50.00
2	12	Rear tailgate inner board clips	\$ 30.00
3	4	Rear tailgate outer garnish clips	\$ 20.00
4	1	Rear tailgate '70km/h' sticker	\$ 30.00
5	1set	Rear tailgate company advertisement sticker	\$ 250.00
6	1	Rear end lower panel sealant	\$ 100.00
7	1	Rear view camera	\$ 300.00
8	2	Rear bumper reverse sensor	\$ 250.00
9	1	Rear left fender panel sealant	\$ 80.00
10	1	Rear left lower side panel sealant	\$ 80.00
11	1	Rear windscreen glass sealant	\$ 80.00
12	1	Rear left quarter glass sealant	\$ 100.00
13	1	Rear no plate	\$ 80.00
			\$ 1,450.00

Total Parts

\$ 13,222.75

7214.9
262
5411.17

600

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBF4565E Toyota Hiace

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear, rear left affected area and replace rear and rear left damaged parts.	\$ 1,400.00	1200
2	To putty and spray painting rear and rear left portion.	\$ 1,400.00	900
3	To check rear lighting and wiring.	\$ 50.00	30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00	X
6	To apply anti rust proofing to rear and rear left affected area.	\$ 120.00	100
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	100
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear view camera.	\$ 80.00	
10	To remove and install rear left quarter glass.	\$ 100.00	80
11	Towing service.	\$ 100.00	X

Total labour : \$ 3,700.00

Total parts : \$ 13,222.75

Total labour : \$ 3,700.00

Total repair cost : \$ 16,922.75

2420
\$31.17

I hereby acknowledge and notify
my insurer of the following:
* The repair work for spray painting
* The repair work for tailgate reverse
* The repair work for windscreen
* The repair work for bumper reverse sensor
* The repair work for rear view camera
* The repair work for rear left quarter glass
* The repair work for towing service
* The repair work for rear inner garnish and trim

Acknowledged by Repairer

Signature:

Date: