

Think One Autocare Pte Ltd  
 No.18 Defu Avenue 2  
 Singapore 539522  
 Tel: 6844 3300 Fax: 6842 4988

*not Admin*  
*Mar*  
*28/5/19*  
*2/5/19*  
*Poh*  
*Technical Advisor*

**GBF4565E Toyota Hiace**

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	D/S \$ 1,260.00
2	1	Rear bumper left bracket	3P \$ 86.00
3	1	Rear bumper inner beam	\$ 287.00 ?
4	1	Rear bumper step garnish	NS \$ 296.00 X
5	1	Rear tailgate assy	body \$ 1,862.00
6	1	Rear tailgate lock mechanism	rod/ym \$ 266.00
7	1	Rear tailgate lock catch	11 \$ 62.00 X
8	2	Rear tailgate hinges	11 \$ 162.00 X
9	2	Rear tailgate damper	11 \$ 375.00 X
10	1	Rear tailgate weatherstrip	\$ 288.00 ?
11	1	Rear tailgate inner board	\$ 190.00 ?
12	1	Rear tailgate centre logo	nu \$ 68.00
13	1	Rear tailgate windscreen glass moulding	NS \$ 295.00 X
14	1	Rear tailgate lock actuator	11 \$ 189.00 X
15	1	Rear tailgate outer garnish	11 \$ 176.00 X
16	1	Rear tailgate lock cylinder	11 \$ 191.00 X
17	1	Rear left taillamp	one \$ 785.00
18	1	Rear left taillamp lower panel	D/S \$ 109.00
19	1	Rear left fender panel assy	body/suc \$ 6,800.00
20	1	Rear left air duct	D/S \$ 96.00
21	1	Rear left lower side panel	body \$ 580.00
22	1	Rear end lower panel	body \$ 1,274.00
			\$ 15,697.00
Less 25%			\$ 3,924.25
			<u>\$ 11,772.75</u>

Special Nett Items

1	10	Rear bumper clips	nu \$ 50.00
2	12	Rear tailgate inner board clips	nu \$ 30.00
3	4	Rear tailgate outer garnish clips	11 \$ 20.00 X
4	1	Rear tailgate '70km/h' sticker	nu \$ 30.00
5	1 set	Rear tailgate company advertisement sticker	nu \$ 250.00 150
6	1	Rear end lower panel sealant	nu \$ 100.00 X
7	1	Rear view camera	11 \$ 300.00 X
8	2	Rear bumper reverse sensor	one \$ 250.00 200
9	1	Rear left fender panel sealant	nu \$ 80.00 50
10	1	Rear left lower side panel sealant	11 \$ 80.00 X
11	1	Rear windscreen glass sealant	nu \$ 80.00 40
12	1	Rear left quarter glass sealant	nu \$ 100.00 50
13	1	Rear no plate	11 \$ 80.00 X
			<u>\$ 1,450.00</u>

**Total Parts**

**\$ 13,222.75**

**Think One Autocare Pte Ltd**  
**No.18 Defu Avenue 2**  
**Singapore 539522**  
**Tel: 6844 3300 Fax: 6842 4988**

**GBF4565E Toyota Hiace**

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear, rear left affected area and replace rear and rear left damaged parts.	\$ 1,400.00 1200
2	To putty and spray painting rear and rear left portion.	\$ 1,400.00 900
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 60
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ <del>150.00</del> X
6	To apply anti rust proofing to rear and rear left affected area.	\$ 120.00 100
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 100
8	To remove and install rear bumper reverse sensor.	\$ 80.00 50
9	To remove and install rear view camera.	\$ 80.00
10	To remove and install rear left quarter glass.	\$ 100.00 80
11	Towing service.	<del>1</del> \$ 100.00 X
<b>Total labour :</b>		<b>\$ 3,700.00</b>

**Total parts : \$ 13,222.75**

**Total labour : \$ 3,700.00**

**Total.repair cost : \$ 16,922.75**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: