

22/03/2019

ASS. REC. BY:

REF:

CE/FCI19009214/D&D302

Special Instruction:

Surveyor: Bryan**ASSIGNMENT (Office)**From (Person): Gerene (CDS)

of

FCI

Date/Time:

23/5/2019 6.42pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 2755G

Insured:

RHD 6939Lat Workshop m/s Chunni Mohr

Tel:

65421726of BK10 AMC #03-19

Policy No:

Claim No:

DI9003383MFEH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

24/5

Person Contacted:

LynnVehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SHC 2755G-X
	RHD 6939L-X
30/5/19	revised PA to Gerene via email.

REF:

ASSIGNMENT

05 June 2024

2016 June

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 2755 G

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C.C. 1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

N.A

T/Radio: Insured / Std / NI / NA

Eng/No:

D4FDGU650732

C/No:

KMHLB41UMGU091323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

P/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

19/05/2019

D.O.I.

24/05/2019

Survey held at

Chennai DMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/tp or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First capital SHD 6939L

19/06/19

Jurnal 1/5 22000/- with 14 days of 14

(\$ 26,953.28 Rd - 55%)

RECEIVED 19 JUN 2019

Date/Time, File Pass to?

19/06/19

1)

Type

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$ 22,000/- 45)

Days Of Repair:

14

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + BS, SI

Photos

Other:

TOTAL

19/06/19

38/15: 570

170+570

50

50+50

190

1080



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003383MFSH

Date: 30 May 2019

Our Ref: CS/FCI19009214/Dsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 2755G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/05/2019 at the premises of M/s Chunni Motor Work Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>48,953.28</u> .
Revised Estimate Amount	: S\$ <u>33,405.64</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u> </u> .
LTA Reimbursement Value	: S\$ <u> </u> .
Nett Value	: S\$ <u> </u> .

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 14 Days

Yours faithfully,
Bryan Ang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	22-05-2019	Our Ref No. D19003383MFSH
Accident Date	19-05-2019	Claim Type. Third Party
Insured Vehicle	SHD6939L	Third Party Vehicle. SHC2755G
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65425119/ 0	Fax No. 65427162
Survey Type	WITHOUT PREJUDICE: EST, COR - \$48,953.28	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veh lu

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 30 May 2019 2:36 PM
To: 'CWS Motor Claims'; 'Serene Ler'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003383MFSH/1
Attachments: SHC 2755G- Preli Advise .pdf

Dear Serene,

Enclosed preliminary revised of vehicle SHC 2755G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 30 May 2019 2:32 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19003383MFSH/1

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 23 May 2019 6:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003383MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 2755G

DATE : 22.05.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>Bnc</i>			\$ 2,265.90	✓
	Bonnet Hinge (LH/RH) <i>new</i> new <i>✓</i>	\$	41.00	\$ 82.00	✓
	Bonnet Lock <i>✓</i>			\$ 36.90	✓
	Bonnet Absorber <i>new</i>	\$	58.10	\$ 116.20	X
	Bonnet Insulator <i>SVL</i>			\$ 196.50	X
	Bonnet Insulator Clips <i>new</i>			\$ 8.40	X
	Radiator Grille <i>broken</i>			\$ 1,110.10	✓
	Radiator Grille H Emblem <i>broken</i>			\$ 120.30	✓
	Front Bumper Cover <i>turn</i>			\$ 1,052.20	✓
	Front Bumper Sponge <i>turn</i>			\$ 99.20	✓
	Front Bumper Reinforcement <i>Denda</i>			\$ 402.10	✓
	Front Bumper Grille (LH) <i>dislodged</i>			\$ 93.60	✓
	Front Bumper Grille Airduct (LH) <i>dislodged</i>			\$ 26.20	✓
	Front Bumper Lip <i>turn</i>			\$ 54.90	✓
	Front Bumper Bracket Top (LH/RH) <i>new</i>	\$	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) <i>new</i> <i>broken</i> <i>new</i>	\$	24.60	\$ 49.20	✓
	Headlamp Support Top Cover <i>new</i>			\$ 222.60	X
	Headlamp Support Panel Assy <i>broken</i> <i>✓</i>			\$ 907.40	✓
	Headlamp (LH/RH) <i>new</i> <i>broken</i> <i>new</i> <i>new</i>	\$	1,388.00	\$ 2,776.00	✓
	Headlamp Halogen Bulb (LH) <i>new</i>			\$ 14.40	X
	Radiator <i>new</i> <i>✓</i>			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy <i>new</i>			\$ 792.95	X
	Front Fender (LH) <i>Bnc</i>			\$ 663.00	✓
	Front Fender Apron Panel (LH) <i>new</i> <i>Denda</i>			\$ 637.00	✓
	Front Fender Shield (LH) <i>turn</i> <i>detached</i>			\$ 174.90	✓
	Air Cleaner Assy <i>new</i>			\$ 118.60	X
	Air Duct <i>new</i>			\$ 134.60	X
	Air Flow Sensor <i>new</i>			\$ 502.20	X
	Air Cleaner Bottom Assy <i>broken</i>			\$ 325.00	✓
	Aircon Condenser <i>new</i> <i>✓</i>			\$ 927.50	✓
	Battery Tray <i>new</i> <i>broken</i>			\$ 52.00	✓
	Frt Safety Belt (Assy) (LH/RH) <i>activated</i>	\$	475.40	\$ 950.80	✓
	Front Wheel Rim (LH) <i>new</i>			\$ 325.30	X
	Front Wheel Hub Cap (LH) <i>new</i>			\$ 107.10	X
	Front Wheel Bearing <i>new</i> <i>Dan</i>			\$ 540.50	✓
	Front Shock Absorber (Assy) (LH) <i>new</i> <i>✓</i>			\$ 342.20	✓
	Front Shock Absorber Mounting (LH) <i>new</i>			\$ 108.80	X
	Front Drive Shaft (LH) <i>new</i> <i>Dan</i>			\$ 1,030.80	✓
	Rack & Pinion Assy <i>new</i> <i>Dan</i>			\$ 1,191.30	✓
	STG Tie End <i>new</i> <i>✓</i>			\$ 62.60	✓
	Stabilizer Bar <i>new</i> <i>detached</i>			\$ 252.30	✓
	Stabilizer Bar Bush (LH) <i>new</i>			\$ 16.40	X
	Stabilizer Bar Link <i>new</i> <i>detached</i>			\$ 61.10	✓
	Stabilizer Bracket <i>new</i>			\$ 24.00	X
	Front Suspension Lower Arm (LH) <i>new</i> <i>✓</i>			\$ 529.30	✓
	Knuckle Arm (LH) <i>new</i> <i>detached</i>			\$ 552.00	✓

SHC 2755G

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Engine Under Cover turn			\$ 334.60	✓
	Engine Crossmember broken			\$ 2,094.40	✓
	Front Seat Adjuster (Outer) (LH/RH) NH		\$ 450.00	\$ 900.00	X
	Gearbox Mounting and cross			\$ 215.40	✓
	Steering Wheel Horn Button Assy NH			\$ 864.00	X
	Inter Cooler and turn			\$ 1,032.50	✓
	ABS Sensor (LH) NH			\$ 234.00	X
	Wiring-Engine 2 hours broken			\$ 3,326.00	✓
	Wiring-Front NH			\$ 4,035.30	X
	Wiring-FEM, LH NH			\$ 168.00	X
	Auto Gear Oil NH			\$ 110.40	X
	Airbag Complete driven activation			\$ 2,948.50	✓
	Airbag Control Module activation			\$ 1,140.40	✓
	Steering Angle Assy 2.0m			\$ 1,150.60	✓
	Sensor Assy Impact -Frt Impact NH			\$ 198.30	X
	Airbag Sensor activation		\$ 580.00	\$ 1,160.00	✓
	Electric Power Steering NH			\$ 3,641.00	X
			31444.40		
			25155.52		
	SUB TOTAL			\$ 44,352.85	
	LESS 20%			\$ 8,870.57	
	DISCOUNTED TOTAL			\$ 35,482.28	
	Front Number Plate dislodged			\$ 25.00	Nett ✓
	Front No Plate Trim Cover 1st			\$ 30.00	Nett ✓
	Front Fender Advertisement Logo (LH) Nuc			\$ 100.00	Nett ✓
	Front Tyre (LH) NH		145.00	\$ 216.00	Nett X
	Gearbox NH			\$ 7,000.00	Nett X
				\$ 7,371.00	
	Labour Charge				
	Panel Beating			\$ 1,600.00	1000/-
	Spray Painting Charge			\$ 1,000.00	700/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	NH
	Front Chassis Alignment Charge			\$ 400.00	NH
	Remove/Refix Undercarriage (FRT)			\$ 200.00	150/-
	FRT Wheel Alignment			\$ 120.00	60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Remove/Refix Gearbox		2550.00	\$ 450.00	NH
	Remove/Refix Dashboard			\$ 450.00	180/-
	Remove/Refix Fuse Box			\$ 180.00	50/-
	Remove/Refix Seat Adjuster			\$ 120.00	80/-
	Re-set Frt ABS System			\$ 200.00	
	Re-programme Air Bag & Safety Belt System		27850.52	\$ 550.00	180/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	
			4/s 22000/-		
	TOTAL LABOUR			\$ 6,100.00	
	ESTIMATE TOTAL			\$ 48,953.28	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

24/05/2019 @ 1630m 14 days.

NA Andri

L/Sun

LKK Andri



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009214/Dsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6939L	Veh. Inspected	SHC 2755G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003383MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	23/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU091323	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/05/2019	Inspection Date	24/05/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2755G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BUCKLED	2,265.90	2,265.90
2	BONNET HINGE (LH/RH) @\$41.00	BENT	82.00	82.00
1	BONNET LOCK	BENT	36.90	36.90
2	BONNET ABSORBER @\$58.10	NOT NECESSARY	116.20	-
1	BONNET INSULATOR	SERVICEABLE	196.50	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	8.40	-
1	RADIATOR GRILLE	BROKEN	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	BROKEN	120.30	120.30
1	FRONT BUMPER COVER	TORN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	DENTED	402.10	402.10
1	FRONT BUMPER GRILLE (LH)	DISLODGE	93.60	93.60
1	FRONT BUMPER GRILLE AIRDUCT (LH)	DISLODGE	26.20	26.20
1	FRONT BUMPER LIP	TORN	54.90	54.90
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	N/S BROKEN / O/S NOT NECESSARY	49.20	24.60
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN / BENT	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	N/S BROKEN / O/S MOUNTING CRACKED	2,776.00	2,776.00
1	HEADLAMP HALOGEN BULB (LH)	NOT NECESSARY	14.40	-
1	RADIATOR	BENT	698.30	698.30
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	NOT NECESSARY	792.95	-
1	FRONT FENDER (LH)	BUCKLED	663.00	663.00
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	TORN / DEFORMED	174.90	174.90
1	AIR CLEANER ASSY	NOT NECESSARY	118.60	-
1	AIR DUCT	NOT NECESSARY	134.60	-
1	AIR FLOW SENSOR	NOT NECESSARY	502.20	-
1	AIR CLEANER BOTTOM ASSY	BROKEN	325.00	325.00

Report Ref No. CS/FCI19009214/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIRCON CONDENSER	BENT	927.50	927.50
1	BATTERY TRAY	BROKEN	52.00	52.00
2	FRT SAFETY BELT (ASSY)(LH/RH) @\$475.40	ACTIVATED	950.80	950.80
1	FRONT WHEEL RIM (LH)	NOT NECESSARY	325.30	-
1	FRONT WHEEL HUB CAP (LH)	NOT NECESSARY	107.10	-
1	FRONT WHEEL BEARING	DAMAGED	540.50	540.50
1	FRONT SHOCK ABSORBER (ASSY)(LH)	BENT	342.20	342.20
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	108.80	-
1	FRONT DRIVE SHAFT (LH)	DAMAGED	1,030.80	1,030.80
1	RACK & PINION ASSY	DAMAGED	1,191.30	1,191.30
1	STG TIE END	BENT	62.60	62.60
1	STABILIZER BAR	DISTORTED	252.30	252.30
1	STABILIZER BAR BUSH (LH)	NOT NECESSARY	16.40	-
1	STABILIZER BAR LINK	DISTORTED	61.10	61.10
1	STABILIZER BRACKET	NOT NECESSARY	24.00	-
1	FRONT SUSPENSION LOWER ARM (LH)	BENT	529.30	529.30
1	KNUCKLE ARM (LH)	DISTORTED	552.00	552.00
1	ENGINE UNDER COVER	TORN	334.60	334.60
1	ENGINE CROSSMEMBER	BROKEN	2,094.40	2,094.40
2	FROTN SEAT ADJUSTER (OUTER)(LH/RH) @\$450.00	NOT NECESSARY	900.00	-
1	GEARBOX MOUNTING	CRACKED	215.40	215.40
1	STEERING WHEEL HORN BUTTON ASSY	NOT NECESSARY	864.00	-
1	INTER COOLER	PUNCTURE	1,032.50	1,032.50
1	ABS SENSOR (LH)	NOT NECESSARY	234.00	-
1	WIRING-ENGINE	HOUSING BROKEN	3,326.00	3,326.00
1	WIRING-FRONT	NOT NECESSARY	4,035.30	-
1	WIRING-FEM,LH	NOT NECESSARY	168.00	-
1	AUTO GEAR OIL	NOT NECESSARY	110.40	-
1	AIRBAG COMPLETE DRIER	ACTIVATED	2,948.50	2,948.50
1	AIRBAG CONTROL MODULE	ACTIVATED	1,140.40	1,140.40
1	STEERING ANGLE ASSY	DAMAGED	1,150.60	1,150.60
1	SENSOR ASSY IMPACT-FRT IMPACT	NOT NECESSARY	198.30	-
2	AIRBAG SENSOR @\$580.00	ACTIVATED	1,160.00	1,160.00

Report Ref No. CS/FC119009214/Dsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ELECTRIC POWER STEERING	NOT NECESSARY	3,641.00	-
	LESS 20% DISCOUNT		-8,870.57	-6,288.88
			35,482.28	25,155.52
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE TRIM COVER (SN) }	BENT	30.00	45.00
1	FRONT NUMBER PLATE (SN) }	DISLODGE	25.00	-
1	FRONT FENDER ADVERTISEMENT LOGO (LH)(SN)	NECESSARY	100.00	100.00
1	FRONT TYRE (LH)(SN)	NOT NECESSARY	216.00	-
1	GEARBOX (SN)	NOT NECESSARY	7,000.00	-
			7,371.00	145.00
	LABOUR			
	PANEL BEATING.		1,600.00	1,000.00
	SPRAY PAINTING CHARGE.		1,000.00	700.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	FRONT CHASSIS ALIGNMENT CHARGE.	NOT NECESSARY	400.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE/REFIX GEARBOX.	NOT NECESSARY	450.00	-
	REMOVE/REFIX DASHBOARD.		450.00	180.00
	REMOVE/REFIX FUSE BOX.		180.00	50.00
	REMOVE/REFIX SEAT ADJUSTER.		120.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	180.00
	RE-SET FRT ABS SYSTEM. }		200.00	-
	RE-PROGRAMME AIR BAG & SAFETY BELT SYSTEM. }		550.00	-
			6,100.00	2,550.00
	GRAND TOTAL		48,953.28	27,850.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			22,000.00



Report Ref No. CS/FCI19009214/Dsd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.