

ASS. REC. BY:

REF:

CS/FCI19009217/Kvd3n2

Special Instruction:

Assigner: Kenneth

ASSIGNMENT (Office)

From (Person): Henry Kao (WS) of FCI Date/Time: 24/5/19

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP7809L Insured: SHC7797C

at Workshop m/s EM Solution Tel: 64560226

of 160 S/M Drive #03-18/19

Policy No: Claim No: D19003352MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 19/5/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 24/5 Person Contacted: Bernard Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimate (✓)
	SLP7809L - X
	SHC7797C - X
27/5/19	Email preli revised to FCI

ASS. REC. BY:

REF: PC21

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 892k

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 03 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 78092Yr Regn: 06, 17Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HyundaiColour: M. GreySp. Reading: 23492

Eng No: _____

C/No: KMH2851CV14404178Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 225/45R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 19/5/19

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 24/5/19

Survey held at _____

Des. of Damages: Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to26/5@308pm / By 8150d email confirmed with Bernard (Real 7092.00, 8392)

RECEIVED 29 MAY 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. \$

Parking

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

2) 28/5 - typist

Report Format :

Lump Sum / I.B.I. (\$

CWS

1500p

160
50
50 + 50
18
328



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003352MFSH

Our ref: CS/FCI19009217/Kvd3

Date : 27/5/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 7809L


We thank for your instruction on 24/5/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/5/2019 at the premises of M/s E M SOLUTION PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$8,792.20
Revised Estimate Amount	: S\$2,147.80
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	22-05-2019	Our Ref No. D19003352MFSH
Accident Date	19-05-2019	Claim Type. Third Party
Insured Vehicle	SHC7797C	Third Party Vehicle. SLP7809L
Survey Location	160, SIN MING DRIVE, #03-18/19, SIN MING AUTOCITY,	
Contact Person.	SALLY CHONG	
Contact No.	64560226/ 91018302	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	E M SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veh In
Kenneth

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 27 May 2019 3:11 PM
To: 'Claim Workflow System'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003352MFSH/1, SLP 7809L
Attachments: SLP 7809L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLP 7809L
Date of survey: 24/5/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 24 May, 2019 9:47 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003352MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 53102178E

Quek Zhan Quan

23.05.2019

Not Authorized
61 Smp & 1 Foot
3 days

REPAIR ESTIMATE FOR HYUNDAI IONIQ - SLP 7809 L

1 pc.	rear bumper	459.40	Bu/nd	559.00	✓
1 pc	rear bumper lower garnish		nd	89.00	✓
1 pc	rear bumper center padding	270.10	nd	369.00	✓
2 pcs	rear bumper reflectors		46.00	sn	92.00 x
1 pc	rear bumper top lamp		sn	221.00	x
1/4 pcs	reverse sensors	135.70	nd	170.00	680.00 ✓
1 pc	rear number plate lamp		sn	70.00	x
2 pcs	rear bumper side retainers		38.00	sn	76.00 x
1 pc	rear bumper reinforcement	284.80	Bu	379.00	✓
2 pcs	rear bumper brackets		138.00	n	276.00 x
1 pc	rear end panel		n	599.00	x
1 pc	rear end panel top garnish		sn	89.00	x
2 pcs	tail lamps assy		380.00	sn	760.00 x
1 pc	boot lid		n	2,385.00	x
1 pc	boot inner lock		n	224.00	x
1 pc	boot rubber		sn	169.00	x
1 pc	boot emblem		an	68.00	x
1 pc	boot "Ioniq" badge		an	33.00	x
1 pc	boot "hybrid" badge		an	33.00	x
1 pc	rear exhaust silencer		n	995.00	x
2 pcs	rear exhaust mountings		34.00	sn	68.00 x
				8,234.00	
			Less 20%	1,646.80	
				6,587.20	

1 pcs	rear number plate
1 pcs	rear windscreen sealant
1 set	rear bumper clips
1 set	rear end panel top garnish clips

nd	60.00	SN 45sn
an	60.00	SN x
an	45.00	SN ✓
an	30.00	SN x

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

- 1) Check electrical wirings
- 2) Repair accident damages and renew parts.
- 3) Spray paint on affected portions.
- 4) Remove and refit rear windscreen
- 5) Renew reverse sensor
- 6) Renew rear exhaust silencer
- 7) Rust proofing on affected portions.

	60.00	15%
	780.00	3001
	780.00	4401
nn	150.00	x
	80.00	501
nn	100.00	x
nn	60.00	x
\$	<u>8,792.20</u>	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19009217/Kvd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 30-05-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7797C	Veh. Inspected	SLP 7809L
Policy No.		Coverage (\$)	0.00
Claim No.	D19003352MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	24/05/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ HYBRID (A)	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KMHC851CVHU041178	Colour	METALLIC GREY
Odometer	23492	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	8 mm
L/H Front Tyre	225/45 R17	MICHELIN	8 mm
R/H Rear Tyre	225/45 R17	MICHELIN	8 mm
L/H Rear Tyre	225/45 R17	MICHELIN	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/05/2019	Inspection Date	24/05/2019
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 7809L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED / DENTED	559.00	459.40
1	REAR BUMPER LOWER GARNISH	DISTORTED	89.00	89.00
1	REAR BUMPER CENTER PADDING	DENTED	369.00	270.10
2	REAR BUMPER REFLECTORS @\$46.00	SERVICEABLE	92.00	-
1	REAR BUMPER TOP LAMP	SERVICEABLE	221.00	-
4	REVERSE SENSORS @\$170.00	DENTED (1 PC ONLY)	680.00	135.70
1	REAR NUMBER PLATE LAMP	SERVICEABLE	70.00	-
2	REAR BUMPER SIDE RETAINERS @\$38.00	SERVICEABLE	76.00	-
1	REAR BUMPER REINFORCEMENT	BUCKLED	379.00	294.80
2	REAR BUMPER BRACKETS @\$138.00	TO REPAIR SEE LABOUR	276.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	599.00	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	89.00	-
2	TAIL LAMPS ASSY @\$380.00	SERVICEABLE	760.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	2,385.00	-
1	BOOT INNER LOCK	TO REPAIR SEE LABOUR	224.00	-
1	BOOT RUBBER	SERVICEABLE	169.00	-
1	BOOT EMBLEM	NOT NECESSARY	68.00	-
1	BOOT "IONIQ" BADGE	NOT NECESSARY	33.00	-
1	BOOT "HYBRID" BADGE	NOT NECESSARY	33.00	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	995.00	-
2	REAR EXHAUST MOUNTINGS @\$34.00	SERVICEABLE	68.00	-
	LESS 20% DISCOUNT		-1,646.80	-249.80
			6,587.20	999.20
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	DENTED	60.00	45.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS/FCI19009217/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	45.00	45.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	30.00	-
			195.00	90.00
	LABOUR			
	CHECK ELECTRICAL WIRINGS.		60.00	15.00
	REPAIR ACCIDENT DAMAGES AND RENEW PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKETS,REAR END PANEL,BOOT LID,BOOT INNER LOCK AND REAR EXHAUST SILENCER.		780.00	300.00
	SPRAY PAINT ON ACCIDENT PORTIONS.		780.00	440.00
	REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	RENEW REVERSE SENSOR.		80.00	50.00
	RENEW REAR EXHAUST SILENCER.	NOT NECESSARY	100.00	-
	RUST PROOFING ON AFFECTED PORTIONS.	NOT NECESSARY	60.00	-
			2,010.00	805.00
	GRAND TOTAL		8,792.20	1,894.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/FCI19009217/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.