

Vivian

05/23/2019

Estimate Report

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1905/015
Policy No:	5088294969-02	Date of Loss:	22/05/2019
Vehicle Reg. No.:	SLB6922Y	Driveable?	yes
Driver Age:	22/10/1961	Third Party Vehicle No.:	SKW1320T
Any Injuries?	no	Contact No:	96156627
Insured/Claimant:	LANG LIONG KEE	Driver:	LANG LIONG KEE

Make/Model:	Honda, Odyssey	Vehicle Reg. Date:	19/04/2016
Vehicle Colour:	SILVER	Engine Number:	K24W72011241
Chassis No:	JHMRC1890GC202817	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	1,750.10
Labour	255.00
Paintwork Labour	710.00
Towing	880.00
	0.00
Gross Total(S\$):	3,595.10
GST 7.00%(S\$):	251.66
Nett Amount(S\$):	3,846.76

This claim is handled by: Sky Toh T C

C/S \$1800/- 4days.

Parts = \$975.70

SM = \$230.00

Labour = \$460.00

SIP = \$630.00

Total = \$2295.70

- 80%

\$1836.56

≈ \$1800 (C/S 4days)

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER DEF /	0.00	494.00	+10.00	543.40
2	1	REAR BUMPER SIDE RETAINER LH any	0.00	19.00	+10.00	20.90
3	1	REAR BUMPER SIDE RETAINER RH any	0.00	19.00	+10.00	20.90
4	1	REAR BUMPER REFLECTOR RH any	0.00	45.00	+10.00	49.50
5	1	REAR BUMPER LOWER GARNISH RH any	0.00	104.00	+10.00	114.40
6	1	REAR TAILGATE Repair	0.00	0.00	0.00	0.00
7	1	REAR CORNER PANEL RH DEF /	0.00	270.00	+10.00	297.00
8	1	REAR FENDER RH Repair	0.00	0.00	0.00	0.00
9	1	REAR TAILLAMP RH any	0.00	570.00	+10.00	627.00
10	1	REAR TAILLAMP LOWER BRACKET RH any	0.00	70.00	+10.00	77.00
				<u>\$975.70</u>		
Total Parts (\$\$)						1,750.10

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS any	0.00	35.00	0.00	35.00 30
2	1	REAR BUMPER SENSORS (1 SET) any	0.00	220.00	0.00	220.00 200
Sub Total (\$\$)				<u>\$255.00</u>		255.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 30
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	600.00	0.00	600.00 400
Gross Labour Cost (\$\$)				<u>\$460.00</u>		710.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 x
2	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	40.00	40.00	0.00	40.00 50
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	800.00	0.00	800.00 600
Gross Labour Cost (\$\$)				<u>\$680.00</u>		880.00

< END OF ESTIMATES >

Have 22 - LKLC
27/5/19
L/S 4 days
27