LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jowyn Tay Mei Ling Date: 29 May 2019

Preliminary Advice

Insured Vehicle No : SLV2331Z

TP Vehicle No : SDF2445H **Accident Date** : 23/05/2019 Make : NISSAN CEFIRO Assignment Date : 27/05/2019

Date of Inspection : 27/05/2019 Est. Duration of Repair : -

Inspection At : Mje Motor (HQ)

BLK 7 SIN MING SECTOR C, #01-82

Singapore 575642

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ **TOTAL LOSS Revised Amount TOTAL LOSS** :S\$ Check Items (Estimated) :S\$ 0.00 Total :S\$ **TOTAL LOSS**

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

' ·) The	vehicle	is econ	omical/not	economical	for	repair.
	,						

The above survey was conducted on a 'without prejudice' basis. Vehicle recommended total loss due to (X) not economical for repair.