



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003247
INV Date 17/04/2020
Reference CC6/CTI19009267/Uka3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLM 2676B
Insured Veh. CB 7735X
Claim No. SNM19D204913
Policy No. DBISN3021931900
Accident Date 29/03/2019
Inspection Date 03/04/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19009267/Uka3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 17-04-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7735X	Veh. Inspected	SLM 2676B
Policy No.	DBISN3021931900	Coverage (\$)	0.00
Claim No.	SNM19D204913	Excess (\$)	0.00
Assign From		Assign Date	03/04/2019

2. Vehicle Particulars & Condition

Make & Model	BMW 16D (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA1V72050V725489	Colour	WHITE
Odometer	34367	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	6 mm
L/H Front Tyre	205/55 R16	PIRELLI	6 mm
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/03/2019	Inspection Date	03/04/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 2676B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	NOT NECESSARY	1,483.50	-
2	FRONT BONNET HINGE @\$126.50	NOT NECESSARY	253.00	-
1	FRONT LOGO	NECESSARY	74.80	74.80
1	FRONT BONNET INSULATOR	NOT NECESSARY	175.00	-
2	FRONT BONNET ABSORBER @\$125.00	NOT NECESSARY	250.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	295.00	-
2	FRONT BONNET SIDE LOCK @\$85.00	NOT NECESSARY	170.00	-
1	FRONT TOP PANEL	TO REPAIR SEE LABOUR	235.00	-
2	HEADLAMP @\$2850.00	N/S CRACKED	5,700.00	2,850.00
2	HEADLAMP HID SENSOR @\$862.00	NOT NECESSARY	1,724.00	-
2	HEADLAMP LED CENTROL MOLUDE @\$945.00	NOT NECESSARY	1,890.00	-
1	FRONT NUMBER PLATE BASE	BENT	48.00	48.00
2	FRONT HEADLAMP PANEL @\$175.00	NOT NECESSARY	350.00	-
2	FRONT HEADLAMP BRACKET @\$85.00	NOT NECESSARY	170.00	-
1	FRONT BUMPER	DENTED	1,550.00	1,215.35
1	FRONT BUMPER REINFORCEMENT	BENT	685.00	685.00
2	FRONT BUMPER REINFORCEMENT BRACKET @\$45.00	NOT NECESSARY	90.00	-
1	FRONT BUMPER SPONGE	TORN	560.00	245.50
2	FRONT BUMPER FOG LAMP COVER @\$120.00	N/S DEFORMED	240.00	120.00
1	FRONT BUMPER PDC SENSOR N/S	SHORTED	220.00	220.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	65.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	165.00	-
1	FRONT GRILLE N/S	CRACKED	190.00	190.00
2	FRONT GRILLE MOULDING @\$75.00	NOT NECESSARY	150.00	-
2	HORN @\$90.00	NOT NECESSARY	180.00	-
1	RADIATOR	NOT NECESSARY	955.00	-
1	RADIATOR AIR DUCT	NOT NECESSARY	155.00	-
1	AIRCON CONDENSOR	NOT NECESSARY	1,350.90	-
1	AIRCON FAN MOTOR ASSY	NOT NECESSARY	758.00	-
1	AIR CLEANER BOX ASSY	NOT NECESSARY	565.00	-

Report Ref No. CC6/CTI19009267/Uka3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR DUCT	NOT NECESSARY	155.00	-
1	OIL COOLER	NOT NECESSARY	751.00	-
1	AIR CLEANER BOX HOSE	NOT NECESSARY	76.00	-
1	RADIATOR TOP HOSE	NOT NECESSARY	155.00	-
1	RADIATOR TOP BY PASS HOSE	NOT NECESSARY	175.00	-
1	FRONT MUDGUARD LH	NOT NECESSARY	1,600.00	-
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	380.00	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	950.00	-
1	FRONT WHEEL BEARING LH	NOT NECESSARY	225.00	-
1	FRONT WHEEL BEARING HUB LH	NOT NECESSARY	292.00	-
1	FRONT LOWER ARM LH	NOT NECESSARY	750.00	-
1	FRONT CONTROL ARM LH	NOT NECESSARY	552.00	-
2	ENGINE MOUNTING @\$780.00	NOT NECESSARY	1,560.00	-
2	GEARBOX MOUNTING @\$620.00	NOT NECESSARY	1,240.00	-
	LESS 5% DISCOUNT		-1,477.91	-282.43
			28,080.29	5,366.22
	<u>SPECIAL NETT ITEMS</u>			
8	FRONT BONNET INSULATOR CLIPS @\$8.00 (SN)	NOT NECESSARY	64.00	-
6	FRONT SUPPORT PANEL TOP GARNISH CLIPS @\$8.00 (SN)	NOT NECESSARY	48.00	-
1	FRONT NUMBER PLATE (SN)	BENT	60.00	40.00
1	FRONT SPORT RIM LH (SN)	NOT NECESSARY	1,800.00	-
1	FRONT TYRE LH (SN)	NOT NECESSARY	850.00	-
			2,822.00	40.00
	<u>LABOUR</u>			
	TO CHECK WIRING & DIAGNOSTIC HEADLAMP SENSOR.		380.00	50.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	REMOVE AND REPLACE AIRCON CONDENSER & REFILL GAS.	NOT NECESSARY	250.00	-
	REMOVE AND REPLACE RADIATOR .	NOT NECESSARY	160.00	-
	REMOVE AND REFIX ENGINE & GEAR MOUNTING.	NOT NECESSARY	350.00	-
	REMOVE AND REFIX FRONT UNDER CARRIAGE ,SUSPENSION ETC.	NOT NECESSARY	450.00	-

Report Ref No. CC6/CTI19009267/Uka3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RECHECK WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT TOP PANEL .		1,500.00	400.00
	TO SPRAY PAINT AFFECTED PORTION.		1,500.00	400.00
			4,860.00	850.00
GRAND TOTAL			35,762.29	6,256.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,000.00

Report Ref No. CC6/CTI19009267/Uka3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.