

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009278/R1EA3Q2

Date: 16/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100509097

Claimant
Vehicle No : GBE1053R **Insured Vehicle No :** SLN7069R

Date of Loss: 18/05/2019 Nature of Claim: TP Claim No: 4948835316SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE1053R		
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Engine No:	1KD2502825
Reg. Date:	01/09/2015 (Man. Year: 2015)	Chassis No:	KDH2010163240
Colour:	White	Odometer:	175736 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	700.00	600.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,300.00	700.00	600.00	46.15
+ GST 7.00/7.00% (\$\$)	91.00	49.00	42.00	46.15
Nett Amount (\$\$)	1,391.00	749.00	642.00	46.15
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (\$\$)		321.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,077.45		

INSPECTION

Date of Assignment: 24/05/2019

Date Inspected: 29/05/2019 Inspected At:

AAK Logistics Services Pte Ltd
(Penjuru)
4 Penjuru Close
Singapore 608574

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	300.00
2	SPRAY PAINTING	New	300.00	250.00
3	LOGO STICKERS	New	200.00	150.00
Gross Labour Cost (S\$)			1,300.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >