



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 9074Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	L/F WING CLAMP KIT (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	L/SCREW (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F WHEELARCH TRIM (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	LEFT FRONT DOOR (NPA)(CONSISTENT)	BENT	-	-
1	L/F DOOR TRIM (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F DOOR MOULDING (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F DOOR TRIM RR (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F MOUNTING KIT (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/FASTENING CLIP (NPA)(CONSISTENT)	* CHECK	-	-
1	L/R DOOR (NPA)(CONSISTENT)	BENT	-	-
1	L/R LOWER DOOR HINGE (NPA)(CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	L/R DOOR MOULDING (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/R DOOR TRIM (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/R DOOR TRIM REAR (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/R DOOR TRIM (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/R MOUNTING KIT (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/FASTENING CLIP (NPA)(CONSISTENT)	NOT NECESSARY	-	-
1	L/F SILL EXTENSION (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/R SILL EXTENSION (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/R WHEELHOUSE COVER(NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/R WHEELARCH TRIM (NPA)(CONSISTENT)	DENTED	-	-
1	L/F TRACK CONT ARM (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F STEERING KNUCKLE (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F SHOCK ABSORBER (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F S-ABSORB BRACKET (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/S/ABSORBER BUFFER (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F S-ABSORB BOOT (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F WHEEL HUB (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F DR BLACK STICKER (NPA)(CONSISTENT)	NECESSARY	-	-
1	L/R DOOR BLACK (NPA)(CONSISTENT)	NECESSARY	-	-

Report Ref No. CC4/ASM19009279/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	L/R FENDER OUT GARN (NPA)(CONSISTENT)	NECESSARY	-	-
1	L/F FENDER IN SHIELD (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/SIDE SKIRTING CLIP (NPA)(CONSISTENT)	NOT NECESSARY	-	-
1	L/F KNUCKLE ARM BRG (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	L/F ABS SENSOR (NPA)(CONSISTENT)	SERVICEABLE	-	-
			-	-
	<u>SPECIAL NETT ITEMS</u>			
1	AUDATEX FEE(SN)(CONSISTENT)	NOT NECESSARY	42.00	-
1	L/F FRONT TYRE (SN)(CONSISTENT)	SERVICEABLE	280.00	-
1	L/F SPORT RIM RIM (SN) (NPA)(CONSISTENT)	DENTED	-	-
1	LEFT REAR SPORT RIM RIM (SN) (NPA)(CONSISTENT)	SERVICEABLE	-	-
			322.00	-
	<u>LABOUR</u>			
	WHEEL ALIGNMENT.		80.00	60.00
	132.0 WU X 45.00 SGD/H.		594.00	594.00
	LABOUR COST 112.0 WU X 45.00 SGD/H.INCLUSIVE OF THE REPAIR OF L/R LOWER DOOR HINGE.		504.00	504.00
	MATERIAL COST.		210.56	210.56
			1,388.56	1,368.56
GRAND TOTAL			1,710.56	1,368.56
RECOMMENDED COST OF REPAIRS				1,368.56

Report Ref No. CC4/ASM19009279/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.