



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY			Ref: CC4/ASM19009279/Kga3q2 Date: 09/05/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 8407K	Veh. Inspected	SJZ 9074Y
	Policy No.	GA447836	Coverage (\$)	0.00
	Claim No.	S9M01N5G	Excess (\$)	0.00
	Assign From		Assign Date	27/05/2019
2. Vehicle Particulars & Condition				
	Make & Model	CHEVROLET CAPTIVA (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	KL1CD26RJ9B520341	Colour	METALLIC BLACK
	Odometer	137503 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60 R17	NEXEN	5 mm
	L/H Front Tyre	235/60 R17	NEXEN	5 mm
	R/H Rear Tyre	235/60 R17	NEXEN	6 mm
	L/H Rear Tyre	235/60 R17	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	10/05/2019	Inspection Date	27/05/2019
	Survey held at	K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	