

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III19009284/GES3Q2

Date:

18/05/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No : SML683L**Insured Vehicle No :**

SHC8685K

Date of Loss: 23/05/2019

Nature of Claim:

TP

Claim No:

MCT19050629

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SML683L**

Make & Model: MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)

Engine No: 27091030688174

Reg. Date: 16/02/2016 (Man. Year: 2015)

Chassis No: WDC1569422J141066

Colour: Grey

Odometer: 28184 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size: 235/50 R18

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,816.00	711.00	2,105.00	74.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	150.00	750.00	83.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,716.00	861.00	2,855.00	76.83
+ GST 7.00/7.00% (S\$)	260.12	60.27	199.85	76.83

Nett Amount (S\$)	3,976.12	921.27	3,054.85	76.83
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		988.72		

INSPECTION

Date of Assignment: 24/05/2019

Date Inspected: 29/05/2019

Estimated Period of Repair: 1.0 days

Inspected At:

8 KAKI BUKIT AVE 4 #06-48

Repairer: CarCrafters Singapore Pte Ltd (HQ)

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2021)
Parts:	M1-SUV	MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML683L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,459.00 F	*- FL
2	1		*REAR BUMPER LOWER TRIM	Deformed	790.00 F	*790.00 FL
3	1		*REAR BUMPER MIDDLE PIECE TRIM	Not Necessary	380.00 F	*- FL
4	1		*MIDDLE BUMPER GUIDE PIECE	Not Necessary	100.00 F	*- FL
5	1		*TOW CAP	Not Necessary	87.00 F	*- FL
					Sub Total (\$\$)	2,816.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	79.00
					Total Parts (\$\$)	711.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE /REFIT /PANEL BEAT OF REAR BUMPER	New	350.00	150.00
2	TO PUTTY AND SPRAY PAINT OF REAR BUMPER	New	450.00	0.00
3	TO DIAGNOSE AND CLEARING OF FAULTS CODE BEFORE AND AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			900.00	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >