| 200:000017 | 1040 |
|------------|---------------------------|
| | Cd3 (Special Instruction: |
| | Date/Time: 27/5/2019 |
| Bill to: | |
| /-CS | |
| | Insured: GBB 5739 K |
| | Tel: 62810087 |
| | 161, 003,008,1 |
| Claim No. | 418198639686 |
| | 418178637630 |
| | D.O.A. 25 5 2019 |
| 28/5/2019 | |
| 7. 1 | H.O.D. Endorsement: |
| Ivy | Vehicle IN OUT |
| | |
| | |
| | |
| | |
| | |
| | |
| | Excess: |

....

| PRS | ASSIGNMENT |
|---|---|
| 1.1 | 1009 Veh No: JSM 6326 Yr Regn: 2014 |
| Estimated Cost: | Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / |
| OD (TP) WS / TP RES / OD RES / EVA / INV / MV | Truck / Trailer or |
| To Inspect Vehicle No: TCM 6306 | Make: Hyunda Sant Fo. c.c 23 |
| | 62810087 Colour white A/G: Insured/Std/NI/N. |
| of 13 Kaki Bulcit Rd 4 *01-20. | Sp.Reading T/Radio: Insured / Std / NI / N |
| Insured: | Eng/No: |
| Policy No. * | C/No: PL884058(18013002) |
| Claims No. | Gen. Cond: 600 / Fair / Poor / Burnt |
| | Steering: Inorder / Jammed / Leaked / Burnt or |
| Sum Insured: Excess: | Brake: Inorder / Jammed / Leaked / Burnt or |
| (Client's Record) Make of Veh: | Modi: Nil / S/Rim / STD A/Rim or , |
| many M YVIII | |
| (Delfor Condition) | |
| (Policy Condition) Remark: The veh had commenced its | N/S O/S BS/DUN/EXNOVA/GY/ES/LIZA/N/G/OHTSU/PIR/SUMI/ |
| repair at the time of inspection. | N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / N/C OHTSU / PIR / SUMI / TOYO / YOKO or |
| L | |
| Bal. or Market Value: | Front Rear |
| IDAC Accident Rport: Consistent? : Yes or | Ma I Pad (|
| GIA / PR Seen: Consistent? : Yes or | 229 / 25 |
| Est. Repairs: days Res.: Yes or | 0/5// |
| Lum Sum: % 3 Val.: Yes or | V 11101 |
| CA / REV / REP. / 24 HRS | Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or |
| Date: Person Contacted: | ehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision |
| Date / Time Action / Instruction Gate | • |
| PRS. | • |
| | • |
| | |
| | |
| | • |
| | |
| | |
| | |
| processory. | |
| Dale/Time, File Pass to? : Preli. Report | Days Of Repair: 7 |
| : Final Report | Days Of Repair: 7 Resurvey No. of Trip: 3 Survey Fee: 180 |
| : Final Report | Resurvey No. of Trip: Survey Fee: Transportation: |
| Date/Time, File Return to? | Resurvey No. of Trip: Survey Fee: 180 Add Fee: :Site Insp (\$)s+Rssi |
| Date/Time, File Return to? | Resurvey No. of Trip: Survey Fee: 180 Add Fee: :Site Insp (\$)s+Rssi :Interview (\$) Photos |
| 1) : Final Report Date/Time, File Return to? 2) | Resurvey No. of Trip: Survey Fee: Transportation: Add Fee: Site Insp (\$)S+RSSI |

...CLAIM SUBFOLDER...(Pending for Survey Report)

| Case | Notified | otified Est Submitted Adj Assigned Adj Rpt | | Adj Sub | Adj Submitted | | Status | | | |
|---------------------------------|-------------------------|--|--------------------------------------|------------|---------------------------|-----------|---|---|-------------|--|
| Main | 27 May 2019 Edit Reg | | 27 May 2019 00:00 Edit Adj Rpt | | | | | Pending for Su Report Cancel Case | rvey | |
| | Main | Re | ference | | Claim Details | | Documer | nts | Show All | |
| CLAIM S | UBFOLDER DE | TAILS | | | | [Create | ed by adjuster] | | | |
| Insured: | MPR INTE | RNATIONAL PT | ELTD, Co. Reg. | No.: 19950 |)1819E | | | | | |
| Main Claimant: | NG SOON | SONG, ID: F77 | 78907M | | | | | | | |
| Vehicle Re No.: | g. JSM632 | JSM6326 | | | | | 019 16:00 - :59 | | | |
| Claim Type | e: TP / 418 | TP / 4181986396SG | | | Policy/Cover Note No.: | | 2100146734 (Comprehensive) Coverage: 24/06/2018 - 23/06/2019 | | | |
| Vehicle Re No. (Insured): | GBB5739 | GBB5739K | | | Policy No. (Claimant): | | | | | |
| | | | | | Excess: | | 100 100 100 100 100 100 100 100 100 100 | | | |
| Repairer: | Motor Int | el Automo Pte L | td (HQ) 13 Kaki | Bukit Road | 4, #01-20 Bartle | y Biz Cer | tre, 417807 Kaki I | Bukit - Tel: | | |
| Handling Insurer: | | | | | | 3 | | (ao] MingYao.Lee@ | | |
| Adjuster: | LKK Auto | Consultants Pte | Ltd (HQ) - Tel: | 6256-3561 | [Handled by] | KING GU | O QIANG] [Fi | nal Rpt due 06/ | 06/2019 | |
| ASSOCIA | TED MAIL RE | CEIVED | | | | | | View All Compo | se Case Mai | |
| AIG_SC | 3 (28/05/2019): | Request To Upl | oad TP GIA Rep | oort | | | | | | |
| ALL ASS | OCIATED TAS | KS⊡ | | | | View A | Search Tasks | Create New Task | Complet | |
| Due Da | | Type Task | Group Subj | ect Han | dler Assign | ed By | Completed O | n Created Or | Done | |
| No results | | | | | | | | | | |

Nivitha (LKK Auto)

From:

Shu Pei (LKKAuto) <shupei@lkkauto.com>

Sent:

Monday, 27 May 2019 5:01 PM

To:

assignments

Subject:

FW: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE

GBB5739K AND JSM6326 ON 25/05/2019

Attachments:

SecureMessageAtt.html

Hi Nivitha,

Workshop detail:

In this respect, please contact Ms.Ivy Pang of Motor Intel Automo Pte Ltd at tel no. 6281 0087 for a pre-re at 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Monday, May 27, 2019 4:06 PM

To: Fan, Winnie-LW; 'admin-a@lkkauto.com'; 'assignments@lkkauto.com'

Cc: Fong, Andy-SY; Chin, Lee-Ying

Subject: [EXTERNAL] RE: - RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE

GBB5739K AND JSM6326 ON 25/05/2019

This message is from an external sender; be cautious with links and attachments.

Dear Winnie,

Thank you for the assignment.

Please provide workshop details.

Best Regards,

G.Nivitha | Admin

- RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED V...

From:

Fan, Winnie-LW

To:

Cc: Fong, Andy-SY, Chin, Lee-Ying

Sent: 5

5/27/2019 2:16:39 PM

Attachments:

tmp6A48.tif

Hi LKK.

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

1) 4

Our Ref.: RSS/1905-7274 (MI)(PD)

Your Ref .:

W: Lua Siew Hui / Wendy Jiang

E : lua_siewhui@rssolomon.com/wendy_jiang@rssolomon.com

27 May 2019



R. S. SOLOMON LLC ADVOCATES & SOLICITORS

By FAX: 6835 7416 & PDX: 8181

AIG Asia Pacific Insurance Pte Ltd

No. 78 Shenton Way #07-16 Lippo Centre Singapore 079120 Attn: Motor Claims Dept

Dear Sirs.

PRE-REPAIR SURVEY
ACCIDENT INVOLVING JSM6326, GBB5739K & SHD8872G ON 25TH MAY 2019 AT ABOUT
1630HRS

We act for the owner ("our client") of vehicle no. JSM6326.

- 2. We hereby notify you of a road traffic accident on 25th May 2019 at about 1630 hours along junction of Marina Boulevard and Sheares Avenue Lamp post no. 53F involving our Client's vehicle and vehicle registration no. GBB5739K driven by your insured. A copy of our Client's Police report is enclosed.
- 3. As a result of the accident, our Client's vehicle has been damaged. Before our Client proceed to repair the damaged vehicle, please let us know within 2 working days upon receipt of this notice whether you would intend to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our Client shall proceed to repair his vehicle without further reference to you.

Yours faithfully,

R. S. SOLOMON LLC
ADVOCATES & SOLICITORS

ENCL

SIJIL PEMILIKAN KENDERAAN JABATAN PENGANGKUTAN JALAN

No Pendaftaran No. RO

Nama Kempinya Berdaftar Alamat

770903016574 . JSM6326

TEONS HO! MO!

17 JLN PI 10/9 TMN PULAI INDAH 81110 JOHOR BAHRU JOHOR PL84D58GRD1300234 / G4KEDU087463

No Chasis No Enjin

Buatan/Nama Model Keupaysan Enjin

INDKOM CORPORATION SDN BHD / SAMIA FE 2 4 G GA

PETROL

Baitari Bakar Status Asal

PEMASANGAN TEMPATAN

PSDN-JIP/VAN/BAS/KVN IND

Jenis Badan/Ishun Dibuat

23/03/2014

Tarikh Pendaftaran

Kelas Kegunaan

B. D. H. B. G. K/BTM

Sydrat Pendaftaran 2

Syarat Pendaftaran 1

Syarat Pendaftaran 3



CONFIRMATION OF PURCHASE OF INSURANCE SLIP

e-COVER NOTE DETAILS

Cover Note No.

HMC0134095 [New Business - Old Vehicle, Old Registration]

JPJ Status Sent

Agent Code/Agent Name

1389K06 / AMBANK-BRH BANKING SKUDAI

Cover Note Issued Date Policy Number

10-01-2019 12:47:53 PM

Hire Purchase Co. INSURED DETAILS

Insured Address

TEONG HOI MOI NO 17 JALAN PI 10/9 TAMAN PULAI INDAH 81110 JOHOR BAHRU

Postcode

: 81110 JOHOR BAHRU

New IC/Old IC/BusReg

770903016574

VEHICLE DETAILS

Vehicle No./Trailer No./Year Make: JSM6326 / - / 2014

Type of Vehicle

PRIVATE CAR EX GOODS

Use of Vehicle/Add Usage

: NOT APPLICABLE TO ABOVE USAGE / Not Applicable

Type of Coverage

: COMPREHENSIVE PREMIER

Period of Insurance Region (W/E Malaysia) 00:00:01 AM 15-01-2019 To 14-01-2020

: VV

Make/Model/Body/Anti-

: INOKOM SANTA FE ELEGANCE / 4D WAGON / -

Theft

Sum Insured/Trailer SI /Excess 70,000.00 / RM 0.00 / RM 0.00

Vehicle / Seating Capacity

Engine/Motor/Chassis No. : G4KEDU087463 / PL884D58GRD1300234

: 2359.00 CC / 7

Logbook No. Name Driver

: ANY AUTHORISED DRIVER

Marital Status/Occupation

: Married / OTHERS

Optional Cover

Legal Liability Of Passengers, Legal Liability To Passengers, Windscreen Damage

(Tempered/Laminated Glass Inclusive Labour Cost)(RM 600.00)

Premium

: RM 2,383.26 / 0.00

NCD % 25.00

: RM 595.82

Optional Cover Premium

: RM 159.35

Service Tax % 6

: RM 116.81

Stamp Duty

: RM 10.00 RM 2,073.60

PREMIUM PAYABLE

RM 2.073.60

PREMIUM PAYABLE (OTC) Issued by

NURRINI BINTI ROSLI No 5 & 7 Jin Naxnoda 1 Tmn Ungku Tun Aminah

81300 Skudai Johar Darul Takzin Tel: 0075568867 Fax:

210210100119M247

opertant Notice." Kenyatean Penting.:
For interventional conservation, we have adopted pay less pending consert Please tog on to our website to view the Babasa Makaysia language policy wordings terms and conditions and examinish in further sequence and accordance on a condition of content Contact Centre. I done perceibbase along execution measures kanning the improper plant kensep terms perceibbase. Sits layer one work and white a layer perceibbase will be a layer on the content of inst Postgram April.
Is an advised to read and understand the aumnian — this product as contained in the Product Discussive Sheet on our website. Finds diseased expays members dan menchanis registers to some finds diseased and the American April of the American Ap

AmGeneral Insurance Berhad (44101-F

A morror of the Ambain Group

Ambain Service of the Ambain Group

Management of the Ambain Gro

(Service Tex Reg. No. 816-1808-310 (54.63)

10-01-2019 12:47:56 PM



NON-MOTOR CONFIRMATION SLIP

| Name and Address of Insured / Nama dan Alamat Pihak Diinsuranskan | e-Cover Note No. No. e-Nota Perlindungan | HNC0057188 |
|--|---|------------------------------|
| TEONG HOI MOI NO 17 JALAN PI 10/9 TAMAN PULAI INDAH | Agent Code Kod Ejen | 1389K06 |
| 81110 JOHOR BAHRU 81110 JOHOR BAHRU | Cover Note Type Jenis Nota Perlindungan | PA-AMDRIVE PLUS NEW BUSINESS |
| | Class Of Insurance Insurans Kelas | AMDRIVE PLUS |
| | Gross Premium Premium Kasar | RM 86.00 |
| Postcode / Poskod 81110 JOHOR BAHRU | 6 % Service Tax 6 % Cukai Perkhidmatan | RM 5.16 |
| NRIC / Business Registration No. No. Kad Pengenalan / No. Pendaftaran Pemiagaan 770903016574 | Stamp Duty Duti Setem | RM 10.00 |
| Business / Occupation Perniagaan / Pekerjaan OTHERS | Total Payable Jumlah Berbayar | RM 101.16 |
| | Total Payable (OTC) Jumlah Berbayar Di Kaunter | RM 101.15 |

With reference to this application, you are hereby held covered from the date stated below for a period not exceeding 30 days or until a policy has been delivered to you by the Company or notice has been given by the Company that they cannot accept the risk, whichever is earlier.

Period of Insurance / Tempoh Insurans

from 00:00:01 AM 15-01-2019 to 14-01-2020 (both dates inclusive)

Description of Risk / Clauses Deskripsi Risiko / Fasal

Vehicle Number: JSM6326

Seating Capacity: 7

Sum Insured / Jumlah Diinsuranskan RM 30,000.00

Master Policy No. /

No. Polisi Induk

Renewal of Policy No. / Pembaharuan No. Polisi

Endorsement on Policy No. / Endorsmen Keatas No. Polisi

Date of Proposal or

Declaration / Tankh

Cadangan atau

Pengisytiharan

Date of Issue / Time / Tarikh Dikeluarkan / Waktu

10-01-2019

10-01-2019 / 12:50:10 PM

Issued By / Dikeluarkan Oleh

NURRINI BINTI ROSLIAMBANK-BRH

BANKING SKUDAI No 5 & 7 Jln Nakhoda 1 Tmn Ungku Tun Aminah

81300 Skudai Johor Darul Takzim Tel: 0075568867

Fax:

For / untuk

AmGeneral Insurance Berhad

AmGeneral Insurance

Authorised Signature / Tandatangan Yang Diberi Kuasa





1 of 3

Report No. T/20190525/2148

Police Station Of Origin: Rochor N.P.C 11 Kampong Kapor Road SINGAPORE 208678

Tel No: 1800-2949999

REPORT OF A TRAFFIC ACCIDENT

| Date/Time Report Made: | Vide Report No.: | Station Diary No.: |
|------------------------|------------------|--------------------|
| 25/05/2019 19:34 | A/20190525/0098 | 103 |

| | | | | 100 | | |
|------------------------------------|-------------------------|---------------------------|--|--------------------------------------|--|--|
| Informa | nt's Partic | ulars | | | | |
| Name of Informant: NG SOON SONG | | | Address: 42 PANDAN ROAD SINGAPO | ORE 609284 | | |
| | / ID No.: / F7778907 | | | | | |
| Nationality: MALAYSIAN | | | Email: | With the second second second second | | |
| Sex: Male | Age: 56 | Date of Birth: 22/11/1962 | Type of Informant: | | | |
| Race: Chinese | | 1 | Language: Institution / School I | | | |
| Occupat CONSTR | | SUPERVISOR | Driving Licence Information: Class: 2B,3,4 Date of Expiry | | | |

| Type of Accident: | Injury Attended by Police | Drink Drive: No | Date/Time of Accident: 25/05/2019 16:30 | Type of Location X-Junction | |
|---|------------------------------|-----------------------|---|--------------------------------|--|
| Location: Along Road 1 MARINA BOL junction of Ma Lamp Post Nu | rina Boulevard and She | eares Avenue. | | | |
| Weather: Clear | | Road Surface: Dry | | Road Speed Limit: | |
| Teeffe Flance | | Traffic Control: | ing | Traffic Volume: Moderate | |
| Traffic Flow: One Way | | Traffic Light - Work | irig | Moderate | |

| Details of V | ehicle Invo | lved | | | | |
|--------------|-------------|------|-------|-------|----------------------|-----------------|
| Vehicle No. | Туре | Make | Model | Color | Condition | No of Passenger |
| GBB5739K | Lorry | | | | Seriously Damaged | |
| JSM6326 | Car | | | | Seriously Damaged | 2 |
| SHD8872G | Car | H/r. | 9856 | 3843 | Slightly Damaged | 1 |





Police Station Of Origin: Rochor N.P.C 11 Kampong Kapor Road SINGAPORE

Tel No: 1800-2949999

2 of 3

Report No. T/20190525/2148

CONTINUATION OF REPORT

| Details of Perso | n Involved | | | | | | |
|---------------------------------|-------------------|-----|-----------|-------------------------------------|----------|--------------------------------------|--|
| Any Pedestrian I | nvolved: No | | | | | | |
| No. of Pedestrians Injured: NIL | | | Use of Pe | Use of Pedestrian Crossing: NA | | | |
| Driver | | | | | | | |
| Name | NG SOON SONG | | | ID No | - | F7778907M | |
| Related Vehicle | JSM6326 (Car) | | Conta | ct No. | 88664840 | | |
| Hospital/Clinic | NIL | | | Class Drivin Licend Expiry | g | Class: 2B,3,4 Date of Expiry: NIL | |
| Date Treatment | NIL | | Date Disc | charge | NIL | | |
| No. of Days gran | ted Medical Leave | NIL | Degree o | f Injury | Slight | | |

Brief Details.

On the above date, time and location, I was driving along marina boulevard, on the 3rd lane. I was the first car in front of the stop line when the traffic light was red. when it turn green, I moved on to move my vehicle, suddenly, I see one lorry that came at a high speed from my left, I could not brake in time and we collided. The impact was between his front part of his car to my front side of my car. His lorry toppled and my car was unable to drive anymore, after the lorry had the first impact with me, he had second impact with another taxi that was on my right side. I do not have any particulars of any drivers that was at scene. I do not need medical attention now but I might be going to see the doctor if the pain is unbearable.

that is all.





3 of 3

Report No. T/20190525/2148

Police Station Of Origin: Rochor N.P.C 11 Kampong Kapor Road SINGAPORE 208678

Tel No: 1800-2949999

CONTINUATION OF REPORT

Sketch Plan

NP168

Singapore Felice Force

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

| Signature Of Officer Recording The Report: A / Sgt 1 NG WEI XIANG ALLAN | Signature Of Informant: |
|---|-----------------------------|
| Signature Of Interpreter: Not applicable | Date/Time: 25/05/2019 19:34 |
| Officer In Charge Of Case: TP / GIT / Sgt 3 RASHIDAH BINTE AZMAN Contact No.: 65476216 | Classification Of Case: |
| Authentication Stamp | |

52

ASTRUMOR:

No of Items:

CV_INCLEON Ang 2005

(1)Replace (\(\structure{\pi} \) (2)Repair (\(\times \) (ViCheck (7)

(4)Not Consistant (NC) TSM (231

| NAC | Portion | Item | | 212 | - I | _ | | | Vehicle No: JSM | 1 03 | 2 | - 4 |
|----------------------|--------------------------------|---|------|------------|----------|-------|-----|---------|---|------|-----|--------------|
| 1001 | | Frt Number Plate | CO | NA | CQI | NA | - | INC | Item | CO | NA | C |
| 1002 | | Frt Number Plate Base . | B | 1- | 1_ | 107 | | | Fuse Box | 6 | | |
| 1003 | 991889 | Frt Number Plate Garnish | - | - | - | 107 | _ | 994011 | | | | |
| 1004 | 991300 | Frt Bumper | 100 | , | _ | 107 | _ | | Wiper Washer Tank | | | |
| 1005 | | Frt Bumper Clips | NE- | | 1 | 107 | 74 | 995052 | Wiper Washer Tank Motor | | | |
| 1006 | 001325 | Frt Bumper Bracket | ME | (/ | 9 | 107 | 75 | 990159 | Alternator Assy | | | |
| 1007 | 9914621 | Fet Dumper Side Deci | | - | _ | 107 | 76 | 990160 | Alternator Belt | | | |
| 1008 | 001433 | Frt Bumper Side Retainer | 218 | | - 2 | 107 | 77 | 992688 | Power Steering Pump | | _ | |
| | 991433 | Frt Bumper Reinforcement | DI | >- | + | 107 | 78 | 992669 | Power Steering Belt | _ | - | 1 |
| 1009 | 991318 | Frt Bumper Beam | | | | 107 | | | Power Steering Cooler Pipe | - | - | \dashv |
| 1010 | 991468 | Frt Bumper Sponge | (RP) | 1 | | 108 | 30 | 992692 | Power Steering Hose | | + | + |
| 1011 | 991427 | Frt Bumper Protector | | | | 108 | 31 | 990010 | ABS Pump Control Unit | _ | - | - |
| 1012 | 991420 | Frt Bumper Pad | | | | 108 | 12 | 990427 | Brake Master Pump Assy | - | - - | + |
| 1013 | 991363 | Frt Bumper Grille | 30 | 1 | 1 | 108 | 13 | 990403 | Brake Booster Pump Assy | - | - | + |
| 014 | 991301 | Frt Bumper Moulding | | | | 108 | 4 | 991005 | Engine Top Cover | - | - | + |
| 1015 | 991407 | Frt Bumper Lower Spoiler | BR | 1/ | 1 | 108 | 5 | 991011 | Engine Under Cover | 00 | 1 | \downarrow |
| 1016 | 991438 | Frt Bumper Sensor | | 1 | \vdash | 108 | 6 | 221011 | Engine Mounting | ORF | 1 | 1 |
| 1017 | 995100 | Frt LH Bumper Fog Lamp Cover | BR | 1 | - | 108 | 7 | 220240 | Engine Mounting | | | 4 |
| 018 | 991355 | Frt RH Bumper Fog Lamp Cover | 80 | - | - | 108 | 9 | 000000 | Engine Mounting Frt | - | - | |
| 019 | 995079 | Frt LH Bumper Fog Lamp | BR | 1 | - | 108 | 0 | 330320 | Engine Mounting LH | | | 1 |
| 020 | 995080 | Frt RH Bumper Fog Lamp | CRA | 1 | - | - | 0 | 990952 | Engine Mounting RH | | | 1 |
| 021 | 991793 | Frt Grille | ORF | 1 | - | 109 | 0 | 990951 | Engine Mounting Rear | | 1 | |
| 022 | 991328 | Frt Grille Emblem | MIS | | - | 109 | 1 | 992234 | Gear Box Mounting | | | T |
| 023 | 991799 | Frt Grille Chrome Moulding | CRA | 1 | - | 1093 | 2 | 991520 | Fit LH Chassis Member | | | |
| 024 | 991222 | Frt Apron Panel | CKF | 4 | - | 109 | | | Frt RH Chassis Member | | | 1 |
| - | 992013 | Frt Support Panel | CRA | - | - | 109 | | 990728 | Frt Vertical Cross Member | | | |
| 026 | 992025 | Frt Support Panel Top Garnish Cover | | | _ | 109 | 5 9 | 991863 | Frt Lower Cross Member | | 1 | |
| 027 | 992416 | Horn | DIS | | | .1090 | 6 9 | 995070 | Frt LH Fender | | 1 | 1 |
| | | Frt Brace Panel | DD | | 1_ | 1097 | | 995072 | Frt LH Fender Inner Panel | - | 1 | + |
| 029 | 995153 | rt LH Headlamp Assy | PS | / | 1_ | 1098 | 8 9 | 995147. | Frt LH Fender Lamp | | | + |
| 030 | 991821 | rt RH Headlamp Assy | (RO) | - | | 1099 | 9 9 | 995148 | Frt LH Fender Lamp Frt LH Fender Frolector | 100 | / | + |
| 031 | 995088 | r: LH Side Lamp | RA | - | | 1100 | 0 5 | 991740 | Frt LH Fender finer Shield | 88 | - | + |
| 032 | 995080 | rit RH Side Lamp | 0 | | | 1101 | | | Frt LH Mudflap | 3(4) | 1 | + |
| 033 | 990248 | A KET SIDE LAMP | _ | | | 1102 | 2 5 | 995170 | Frt LH Wheel Rim | 1 | 1 | + |
| | | | BUC | / | | 1103 | 3 9 | 994025 | Frt LH Rim Cover | | - | + |
| 035 | 990297 | Bonnet Emblem Bonnet Lock | _ | | | 1104 | 1 5 | 995065 | Frt LH Tyre | | + | + |
| 036 | 0000246 | Jonnet Lock | 81 | | | -1105 | | | Frt RH Fender | Buc | - | + |
| 030 | 000277 | Bonnet Insulator Bonnet Hinge | - | | | 1106 | 5 9 | 991739 | Frt RH Fender Inner Panel | DW | 1 | + |
| 038 | 000261 | Sonnet Hinge | 57 | _ | 2 | 1107 | 1 9 | 991744 | Frt RH Fenderd amn | - | + | + |
| 339 | 000205 1 | Bonnet Damper | BR | | | 1108 | 9 | 91752 | Frt RH Pender Protector | ORA | | - |
| 340 | 00000CD D | Jonnet Rubber | | | | 1109 | 9 | 91740 | Frt RH Fender Inner Shield | RA | | - |
| | | Sonnet Cable | | | | 1110 | 9 | 91884 | Frt RH Mudflap | Cari | | \vdash |
| | 990311 E | onnet Stand | | | | 1111 | 9 | 92087 | Frt RH Wheel Rim | | - | ┝ |
|)42 (| 990119 A | ir Con Condenser | DD. | | | 1112 | | 94025 | Frt RH Rim Cover | - | - | - |
| 43 9 | 990122 1 | ir Con Fan Assy | CRA | - | - | 1113 | 0 | 95065 | Frt RH Tyre | - | - | - |
| 44 9 | 990134 A | ir Con Suction Pipe (Low Pressure) * | DD | 1 | - | 1114 | | | Frt Windscreen Glass | - | - | - |
| 42 1 , | 990118 V | ir Con Suction Flore | | | | 1115 | 0 | 02117 | Frt Windscreen Rubber | - | - | - |
| 46 5 | 990133 A | ir Con Discharge Pipe (High Pressure) | BI | - | - | 1116 | 0 | 02100 | Get Windscreen Rubber | - | | _ |
| 45 3 | 90114 A | ir Con Discharge Hose | 1 | | - | | 19 | 03000 | Frt Windscreen Moulding | | | _ |
| 48 9 | 90149 A | ir Con Liquid Pipe | - | - | - | 1117 | 9 | 01010 | Frt Windscreen Sealant | | | |
| 49 9 | 95066 A | ir Con Receiver Drier | | | | 1118 | | | ERP Bracket | | | |
| 50 9 | 90111 A | ir Con Compressor Assy | - | - | - | 1119 | | | ERP Unit | | | |
| 51 9 | 95294 A | ir Con Belt | | - | _ | 1120 | | | Frt Wiper Arm | | | - |
| 52 9 | 95074 R | adiator | 00 | | _ | 1121 | 99 | 92142 | rt Wiper Blade | | | |
| 53 9 | 92738 R | adiator Cowling | DD | 1 | _ | 1122 | 99 | 95045 | Wiper Panel Garnish | | | |
| 4 9 | 92742 R | idiator Fan Assy | ORA. | | | 1123 | 99 | 91126 F | irewall Panel | | | |
| 5 9 | 92745 P | idiator Fan Clutch | CUCT | | _ | 1124 | 99 | 90753 I | Dashboard Assy | BR | | |
| 6 9 | 92758 0 | idiator Hose Top | BY. | 1 | | 1125 | 99 | 92282 | Hove Box Cover | | | |
| 7 9 | 92757 0 | ulinton Hose 10p | 157 | 1 | | 1126 | 99 | 92281 C | love Box Compartment | | | |
| 8 9 | 02741 C | idiator Hose Bottom | | | | 1127 | 99 | 94483 5 | teering Wheel Airbag | Bus | | - |
| 0 2 | 72/41 IC | diator Expansion Tank | | | | 1128 | 99 | 04485 5 | teering Wheel Airbag Sensor | WEL | - | |
| 9 9 | 90151 Ai | r Duct | BR | 1 | | 1129 | 90 | 00749 F | Pashboard Airbag | | | - |
| 0 9 | 90070 Ai | r Cleaner Assy . | | | | 1130 | 00 | 00750 F | Pashboard Airbag Sensor | BUS | | |
| 1 9 | 90056 Ai | r Cleaner Hose | | - | | 1131 | 00 | 00000 | Asinoara Airbag Sensor | NEC | 5 | |
| 2 95 | 1A 08000 | r Cleaner Resonator | CRA | - | - | | 99 | MODEL A | Airbag Control Unit | L | 4 | |
| 3 99 | 21712 Fri | r Cleaner Resonator Exhaust Manifold | | | - | 1132 | | | nt Driver Seat | _ | _ | _ |
| 4 99 | 1713 Fr | Exhaust Manifold Cover | TW | - | - | 1133 | | | rt RH Seat Belt Assy | DM | | |
| 5 99 | 1054 Fe | Exhaust Manifold Sensor (Oxygen) | | | | 1134 | | | rt Passenger Scat | | | |
| 6 99 | 1714 Fee | ont Exhaust Pipe | 20 | | + | 1135 | | | rt LH Seat Belt Assy. | JM. | / | |
| - 23 | 0219 Ba | Herse | 11 | سله | # | 1136 | 29 | 0247 8 | ticker | | | |
| 7 00 | | | m | × | - | | Air | Conc | magroe side Ar Defeder | CRA | 1 | |
| 7 99 | CILL CCC | | | | - 11 | | - | | | | | |
| 7 99 8 99 | 0224 Ba | nery Cover | (1) | _ | | | | | | 1 | | |
| 7 99 8 99 9 99 | 0224 Ba 0223 Bat 0229 Ba | ttery Bracket | + | 1 | 1 | | | | | | | _ |

Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

| Main Still Pop 1 00:00 S\$0.00 S\$0.00 Report | | LDER TRA | CKING | | | | | | | | |
|--|------------|---------------------------|------------------|--------------------|--------------|-------------|------------------|----------------|-----------------------------|----------|-----------|
| Main Reference Claim Details Documents | Case No | tified | Est Submitted | Adj Assigned | Adj Rpt | A | dj Submitted | Ins Auth'ed | Statu | S | |
| CLAIM SUBFOLDER DETAILS [Created by adjuster] | Main | 2/ May 2019 Edit Peo 1 | | | | - 1 | | | Pending Report Cancel | | Survey |
| Main Claimant: NG SOON SONG, ID: F7778907M | Ma | in | R | eference | | laim Detail | s | Document | ts | s | how All |
| Main Claimant: NG SOON SONG, ID: F7778907M Date of Loss: 25/05/2019 16:00 - :59 [62 Months and 2 Days From LTA Reg Days From L | AIM SUBF | OLDER DE | TAILS | | | | [Created | by adjuster] | | | |
| Date of Loss: 25/05/2019 16:00 - :59 [62 Months and 2 Days From LTA Reg Days F | sured: | MPR INTE | RNATIONAL PT | ELTD, Co. Reg. No | o.: 1995018 | 319E | 1.5 | | | | |
| No.: Date of Loss: [62 Months and 2 Days From LTA Reg Discovering to the No.: TP / 4181986396SG Policy/Cover Note No.: Vehicle Reg. No. (Insured): GBB5739K GBB5739K Policy No. (Claimant): Excess: Repairer: Motor Intel Automo Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel: Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 [Handled by Lee, Ming-Yao] MingYao. Let | 533.00 | NG SOON | SONG, ID: F77 | 78907M | | | | | | | |
| Claim Type: TP / 41819863965G Note No.: Coverage: 24/06/2018 - 23/06/2019 Vehicle Reg. No. (Insured): Policy No. (Claimant): Excess: Repairer: Motor Intel Automo Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel: Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 [Handled by Lee, Ming-Yao] MingYao.Left | | JSM6326 | | | | Date of Los | | | m LTA Reg | Date (Ma | n Yr)] |
| No. (Insured): Claimant Excess: | aim Type: | TP / 418 | 1986396SG | | | | | | | " | |
| Repairer: Motor Intel Automo Pte Ltd (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel: Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 [Handled by Lee, Ming-Yao] MingYao.L. | 0. | GBB5739 | ĸ | | | | | | | | |
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 [Handled by Lee, Ming-Yao] MingYao.L. | | | | | | Excess: | | | | | |
| Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 [Handled by Lee, Ming-Yao] MingYao.L. | pairer: | Motor Int | el Automo Pte L | td (HQ) 13 Kaki Bu | kit Road 4, | #01-20 Bar | tley Biz Centre, | 417807 Kaki Bu | kit - Tel: | | |
| Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Handled by XING GUO QIANG] [Final Rpt due | | AIG Asia | Pacific Insuranc | e Pte. Ltd. (Expre | ss) - Tel: 6 | 5-6419-300 | 0 [Handled b | y Lee, Ming-Ya | o] MingYao | .Lee@aig | .com |
| | ijuster: | LKK Auto | Consultants Pte | Ltd (HQ) - Tel: 62 | 56-3561 | [Handled b | XING GUO Q | IANG] [Fina | al Rpt du | e 06/06 | /2019] |
| ASSOCIATED MAIL RECEIVED View All Co | SSOCIATED | MAIL RE | CEIVED | | | | | Vi | ew All | Compose | Case Mail |
| AIG_SG (28/05/2019): Request To Upload TP GIA Report | AIG_SG (28 | 3/05/2019) | Request To Up | load TP GIA Repor | rt | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New To | LL ASSOCI | ATED TAS | KS⊟ | | | | View All S | Search Tasks | Create New | Task | Complete |
| Due Date Priority Type Task Group Subject Handler Assigned By Completed On Create | Due Date | Priority | Type Task | Group Subject | t Hand | ler Ass | igned By | Completed On | Crea | sted On | Done? |
| | | | | | nee needle | | | | | | |

Claim Documents

*JSM6326 (4181986396SG) [GBB5739K] NG SOON SONG May 25 2019 4:00PM [MPR INTERNATIONAL PTE LTD] Motor Intel Automo Pte Ltd

| Pho | tos/Images | | 3 per page | |
|-----|-----------------|-----------------------------------|------------|----------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbna | man . |
| 1 | 08/07/19 17:56 | General View | Load JPG | V |
| 2 | 08/07/19 17:56 | General View | 1 Load JPG | ✓ |
| 3 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 4 | 08/07/19 17:56 | General View | ■ Load JPG | V |
| 5 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 6 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 7 | 08/07/19 17:56 | General View | Load JPG | |
| 8 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 9 | 08/07/19 17:56 | General View | 1 Load JPG | |
| 10 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 11 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 12 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 13 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 14 | 08/07/19 17:56 | General View | 1 Load JPG | ✓ |
| 15 | 08/07/19 17:56 | General View | ■ Load JPG | |
| 16 | 08/07/19 17:56 | General View | ■ Load JPG | |
| 17 | 08/07/19 17:56 | General View | ■ Load JPG | V |
| 18 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 19 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 20 | 08/07/19 17:56 | General View | 1 Load JPG | ✓ |
| 21 | 08/07/19 17:56 | General View | 1 Load JPG | ∀ |
| 22 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 23 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 24 | 08/07/19 17:56 | General View | 1 Load JPG | ∀ |
| 25 | 08/07/19 17:56 | General View | ■ Load JPG | V |
| 26 | 08/07/19 17:56 | General View | 1 Load JPG | · • |
| 27 | 08/07/19 17:56 | General View | 1 Load JPG | |
| 28 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 29 | 08/07/19 17:56 | General View | 1 Load JPG | Z |
| 30 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 31 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 32 | 08/07/19 17:56 | General View | 1 Load JPG | V |
| 33 | 08/07/19 17:56 | General View | 1 Load JPG | · • |
| 34 | 08/07/19 17:56 | General View | 1 Load JPG | |
| 35 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 36 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | · 🗹 |
| 37 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | · 🗹 |

| Pho | tos/Images | | | ✓ |
|-----|-----------------|--|------------|-----|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbn | _ |
| 38 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | 14 |
| 39 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | _ |
| 10 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPe | |
| 1 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G ✓ |
| 12 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JPe | G ☑ |
| 13 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | G ☑ |
| 14 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 🔽 |
| 15 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G ⋤ |
| 16 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G ⋤ |
| 17 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 🖳 |
| 18 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 💽 |
| 19 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JP | |
| 0 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JP | - |
| 61 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| 52 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | |
| | | | 1 Load JP | - |
| 3 | 08/07/19 17:57 | Photographs of Damaged Parts | | _ |
| 54 | 08/07/19 17:57 | Photographs of Damaged Parts | | - |
| 55 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | _ |
| 56 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | |
| 57 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | _ |
| 8 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | |
| 59 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| 50 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 51 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 52 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 53 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JP | G 5 |
| 54 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 55 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 56 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 57 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 58 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JP | G G |
| 69 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JP | _ |
| 70 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JP | G G |
| 71 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JP | _ |
| 72 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| | | ANN A CONTRACTOR OF THE STATE O | 1 Load JP | - |
| 73 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| 74 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| 75 | 08/07/19 17:57 | Photographs of Damaged Parts | | |
| 76 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | |
| 77 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | |
| 78 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| 79 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| 30 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | _ |
| 31 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | - |
| 32 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | |
| 33 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | _ |
| 34 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G [|
| 85 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G 5 |
| 86 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G [|
| 87 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JP | G G |

| Pho | tos/Images | | 3 per page 🔻 | V |
|-----|--------------------------|-----------------------------------|-----------------------|-----------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | |
| 88 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u> </u> |
| 39 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | ¥ |
| 90 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | ₹ |
| 1 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 2 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 3 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 94 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 95 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 96 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 97 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 98 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JPG | V |
| 99 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JPG | V |
| 100 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | - |
| 101 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 102 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | |
| 103 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 2 |
| _ | | | Load JPG Load JPG | 2 |
| 104 | 08/07/19 17:57 | Photographs of Damaged Parts | | 2 |
| 105 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | - |
| 106 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u> </u> |
| 107 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 2 |
| 108 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u> </u> |
| 109 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u> -</u> |
| 110 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | |
| 111 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 2 |
| 112 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 2 |
| 113 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u>-</u> |
| 114 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | - |
| 115 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 5 |
| 116 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JPG | 5 |
| 117 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JPG | - |
| 118 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JPG | 5 |
| 119 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JPG | 1 |
| 120 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JPG | 5 |
| 121 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | - G |
| 122 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | [Z |
| | | Photographs of Damaged Parts | D Load JPG | <u>-</u> |
| 123 | 08/07/19 17:57 | | | - X |
| 124 | | Photographs of Damaged Parts | 6 Load JPG | _ |
| 125 | Programme and the second | Photographs of Damaged Parts | 1 Load JPG | Z |
| 126 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u> </u> |
| 127 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u>-</u> |
| 128 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | |
| 129 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | ~ |
| 130 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | <u> </u> |
| 131 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | - |
| 132 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 5 |
| 133 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 5 |
| 134 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 2 |
| 135 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 5 |
| 136 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | 5 |
| 137 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |

| Photos/Images 3 per page | | | | |
|--------------------------|--------------------------|---|-------------------|----------|
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbna | il Prin |
| 138 | 08/07/19 17:57 | Photographs of Damaged Parts | 6 Load JPG | Y |
| 139 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 140 | 08/07/19 17:57 | Photographs of Damaged Parts | ■ Load JPG | V |
| 141 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | ~ |
| 142 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JPG | V |
| 143 | 08/07/19 17:57 | Photographs of Damaged Parts | Load JPG | V |
| 144 | 08/07/19 17:57 | Photographs of Damaged Parts | 1 Load JPG | V |
| 145 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 146 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 147 | 08/07/19 18:22 | Photo After Spray | Load JPG | V |
| 148 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 149 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 150 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 151 | 08/07/19 18:22 | Photo After Spray | 6 Load JPG | ▼ |
| 152 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 153 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 154 | 08/07/19 18:22 | Photo After Spray | Load JPG | V |
| 155 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 156 | 08/07/19 18:22 | Photo After Spray | Load JPG | V |
| 157 | 08/07/19 18:22 | Photo After Spray | Load JPG | V |
| 158 | 08/07/19 18:22 | Photo After Spray | 6 Load JPG | V |
| 159 | 08/07/19 18:22 | Photo After Spray | Load JPG | V |
| 160 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 161 | 08/07/19 18:22 | Photo After Spray | Load JPG | V |
| 162 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 163 | 08/07/19 18:22 | Photo After Spray | Load JPG | V |
| 164 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 165 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 166 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 167 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| 168 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | |
| 169 | 08/07/19 18:22 | Photo After Spray | 1 Load JPG | V |
| | DESCRIPTION OF THE PARTY | 1 | | 7 - |
| | umentation | | 1 per page | 4 - |
| No | Finalized On | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbna Load PDF | |

Documents Checklist

| DOCUMENTS CHECKLIST | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. | | | |
| Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) | | | |
| | | | ^ |
| | | | ~ |
| Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties. | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG19009303/T1CD3E2

Date:

19/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100146734

Claimant Vehicle No:

JSM6326

Insured Vehicle No:

GBB5739K

Date of Loss:

25/05/2019

Nature of Claim:

TP

Claim No: 4181986396SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

JSM6326

Make & Model:

HYUNDAI SANTA FE, 2.4 (A)

Engine No:

G4KEDU087463

Reg. Date:

23/03/2014 (Man. Year: 2014) White

Chassis No: Odometer:

PL84D58GRD1300234

Colour: Engine Capacity:

2359 cc

Market Value/New Car Price: N/A Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

235/60 R18

Rear Tyre Size:

235/60 R18

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

0 km

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment:

27/05/2019

Date Inspected:

28/05/2019 Inspected At:

Motor Intel Automo Pte Ltd (HQ)

13 Kaki Bukit Road 4, #01-20 Bartley Biz

Centre

Singapore 417807

Estimated Period of Repair:

7.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 19/7/2019

Adjuster Report Page 2 of 4

REPAIR DETAILS

Recommended Parts

| No. | Qty Part No | . Particulars | Condition | Repairer's | Amount |
|----------|-------------|--|------------------|------------|--------|
| 1 | 1 | *FRT NUMBER PLATE | Bent | 0.00 F | *- F |
| 2 | 1 | *FRT BUMPER | Broken | 0.00 F | *- F |
| 3 | 6 | *FRT BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 1 | 2 | *FRT BUMPER SIDE RETAINER | Distorted | 0.00 F | *- F |
| 5 | 1 | *FRT BUMPER REINFORCEMENT | Dented | 0.00 F | *- F |
| 3 | 1 | *FRT BUMPER SPONGE | Cracked | 0.00 F | *- F |
| 7 | 1 | *FRT BUMPER GRILLE | Cracked | 0.00 F | *- F |
| 3 | 1 | *FRT BUMPER LOWER SPOILER | Broken | 0.00 F | *- F |
| 9 | 1 | *FRT LH BUMPER FOG LAMP COVER | Broken | 0.00 F | *- F |
| 10 | 1 | *FRT RH BUMPER FOG LAMP COVER | Broken | 0.00 F | *- F |
| 11 | 1 | *FRT LH BUMPER FOG LAMP | Cracked | 0.00 F | *- F |
| 12 | 1 | *FRT RH BUMPER FOG LAMP | Cracked | 0.00 F | *- F |
| 13 | 1 | *FRT GRILLE | Cracked | 0.00 F | *- F |
| 14 | 1 | *FRT GRILLE EMBLEM | Missing | 0.00 F | *- F |
| 15 | 1 | *FRT GRILLE CHROME MOULDING | Cracked | 0.00 F | *- F |
| 16 | 1 | *FRT SUPPORT PANEL | Cracked | 0.00 F | *- F |
| 17 | 1 | *FRT SUPPORT PANEL TOP GARNISH COVER | Distorted | 0.00 F | *- F |
| 18 | 1 | *HORN | Dented | 0.00 F | *- F |
| 19 | 1 | *FRT BRACE PANEL | Bent | 0.00 F | *- F |
| 20 | 1 | *FRT LH HEADLAMP ASSY | Cracked | 0.00 F | *- F |
| 21 | 1 | *FRT RH HEADLAMP ASSY | Cracked | 0.00 F | *- F |
| 22 | 1 | *BONNET | Buckled | 0.00 F | *- F |
| 23 | 1 | *BONNET LOCK | Bent | 0.00 F | *- F |
| 23 24 | 2 | *BONNET HINGE | Bent | 0.00 F | *- F |
| | | 3321-3-321-321-321-321-321-321-321-321-3 | THE STOPPAT | 0.00 F | *- F |
| 25 | 1 | *BONNET DAMPER | Broken Dented | 0.00 F | *- F |
| 26 | 1 | *AIR CON CONDENSER | | | *-F |
| 27 | 1 | *AIR CON FAN ASSY | Cracked | 0.00 F | *- F |
| 28 | 1 | *AIR CON SUCTION PIPE (LOW PRESSURE) | Dented | 0.00 F | *-F |
| 29 | 1 | *AIR CON DISCHARGE PIPE (HIGH PRESSURE) | Bent | 0.00 F | *- F |
| 30 | 1 | *RADIATOR | Dented | 0.00 F | |
| 31 | 1 | *RADIATOR COWLING | Cracked | 0.00 F | *- F |
| 32 | 1 | *RADIATOR FAN ASSY | Cut | 0.00 F | *- F |
| 33 | 1 | *RADIATOR FAN CLUTCH | Jammed | 0.00 F | *- F |
| 34 | 1 | *RADIATOR HOSE TOP | Bent | 0.00 F | *- F |
| 35 | 1 | *AIR DUCT | Broken | 0.00 F | *- F |
| 36 | 1 | *AIR CLEANER RESONATOR | Cracked | 0.00 F | *- F |
| 37 | 1 | *FRT INLET MANIFOLD | Cut | 0.00 F | *- F |
| 38 | 1 | *ENGINE UNDER COVER | Cracked | 0.00 F | *- F |
| 39 | 1 | *FRT LH FENDER WHEEL ARCH PROTECTOR | Cracked | 0.00 F | *- F |
| 40 | 1 | *FRT LH FENDER INNER SHIELD | Cracked | 0.00 F | *- F |
| 41 | 1 | *FRT RH FENDER | Buckled | 0.00 F | *- F |
| 42 | 1 | *FRT RH FENDER WHEEL ARCH PROTECTOR | Cracked | 0.00 F | *- F |
| 43 | 1 | *FRT RH FENDER INNER SHIELD | Cracked | 0.00 F | *- F |
| 44 | 1 | *DASHBOARD ASSY | Broken | 0.00 F | *- F |
| 45 | 1 | *STEERING WHEEL AIRBAG | Buckled | 0.00 F | *- F |
| 46 | 1 | *STEERING WHEEL AIRBAG SENSOR | Necessary | 0.00 F | *- F |
| 47 | 1 | *DASHBOARD AIRBAG | Buckled | 0.00 F | *- F |
| 48 | 1 | *DASHBOARD AIRBAG SENSOR | Necessary | 0.00 F | *- F |
| 49 | 1 | *AIRBAG CONTROL UNIT | * Check | 0.00 F | *- F |

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 19/7/2019

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|--------|----------|---------------------------------------|-------------------|------------|--------|
| 50 | 1 | | *FRT RH SEAT BELT ASSY | Jammed | 0.00 F | *-F |
| 51 | 1 | | *FRT LH SEAT BELT ASSY | Jammed | 0.00 F | *-F |
| 52 | 2 | | *AIR CON CONDENSER SIDE AIR DEFLECTOR | Cracked | 0.00 F | *-F |
| F=Fra | nchise | part. | | Total Parts (S\$) | 0.00 | 0.00 |
| | | | Report was unsubmitted during this | print-out. | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >