

ASS. REC. BY:

REF: CS/CT19009385/Aqd302

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CT1

Date/Time: 28.5.19 15.30p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLZ 27267

Insured: GY 47239

at Workshop m/s Hiap Hong Motor Repair

Tel: 67459633

of 2 Kaki Bukit Area 2 # 02-13

Policy No: DMCVSN30670718000

Claim No: SNM19D202349C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 235.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28.5.19 5.38p.m

Person Contacted: Ah Kong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLZ 27267 - X
	GY 47239 - (C3/E&I/6012915/HI=6392 D.O.A-10/07/2016
	LS \$4800, 6 days cred \$5379, 55%.)

REC BY:

REF:

ASSIGNMENT

Adrian

Front:

Date:

Estimated Cost:

OD / TF / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL22726Y

Yr Regn:

2018 April

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

kia Cerato KC3

C.C.

1591

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

17211

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAFX411MJ5768005

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

28/05/19

Survey held at

Hiap Hong

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Chian

RECEIVED 07 JUN 2019

mv:

pv:

Nett:

Date/Time, File Pass to?

1) 07/6/19

Date/Time, File Return to?

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 May 2019		28 May 2019 15:30 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All																					
CLAIM SUBFOLDER DETAILS								[Created by insurer]																					
Insured:		TOP GRADE RESOURCES, Co. Reg. No.: 52980785L																											
Main Claimant:		NEO POH CHENG RICHARD, ID: S0283179A																											
Vehicle Reg. No.:		SLZ2726Y		Date of Loss:		23/05/2019 15:00 - :59 [12 Months and 26 Days From LTA Reg Date (Man Yr)]																							
Claim Type:		TP / SNM19D202349C02		Policy/Cover Note No.:		DMCVSN30640718000																							
Vehicle Reg. No. (Insured):		GY4723G		Policy No. (Claimant):		GA459067																							
				Excess:		S\$0.00																							
Repairer:		Hiap Hong Motor Repair (HQ) 2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel: 67459633																											
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]																											
Claimant's Insurer:		AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288																											
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2019]																											
Driver/Custodian (Insured):		LIM AH NGUAN (58 / Male) , NRIC: S6804139B Email:																											
Adj Asg. Remarks:		please assign Mr Adrian Ling for SJE. thank you																											
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail																					
There are no mail for this case.																													
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>										Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?																				
No results.																													



PEOPLES AUTO TRADING
BLK 3007 UBI ROAD 1 #01-400
TEL 6741 4646



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	HIAP HONG	DATE	May 28, 2019 12:59:59 PM
LICENSE NO.	SLZ 2726 Y		
MILEAGE	27513		
REFERENCE	CUSTOM	MODEL	KIA FORTE K3 (FX411)

Front Wheel SPECS DIAGNOSIS ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			-8.30				-8.60		
PARTIAL TOE	-0.50	0.00	0.50		-5.00		-3.30		-8.60		0.00	
SET BACK	---	---	---			-0°24"				-0°24"		
CAMBER	-0°44"	0°00"	0°44"		-0°14"		-0°48" 0°34"		-0°10"		-0°50" 0°40"	
CASTER	2°44"	3°44"	4°44"		4°42"		3°54" 0°46"		4°42"		3°54" 0°46"	
KING-PIN	---	---	---		13°44"		13°18" 0°26"		13°44"		13°18" 0°26"	
INCL.ANGLE	---	---	---		13°30"		12°30"		13°34"		12°26"	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel SPECS DIAGNOSIS ADJUSTMEN

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	---	---	---			4.40				4.40		
PARTIAL TOE	---	---	---		2.60		1.70		2.60		1.70	
SET BACK	---	---	---			0°00"				0°00"		
CAMBER	---	---	---		-1°14"		-1°38" 0°22"		-1°14"		-1°38" 0°22"	
THRUST ANGLE	-0°08"	0.00	0°08"			0°04"				0°04"		

TP China.
Xiao Chen.

SLZ2726Y

Kia Cerato LC3

KNAFX411MJ5768005

Front Bumper. Deformed	637 ✓
	30 ✓
Front Bumper Lips. New	
Front Bumper Side Holder x 02 ^{LH} Dmgd	40 x 2 = 80 40.
Front Bumper Reinforcement New	496 X
Front Bumper Sponge New	118 X
Front Bumper Side Air Vent LH ^{MT} New	35 X
Front Bumper Fog Lamp LH. Cracked	263 ✓
Front Bumper Lower Grille	185 ✓
Headlamp LH Cracked	1870 ✓
Front Support Panel. Cracked	662 ✓
Front LH Fender Dented	435 —
Front LH Fender Inner Shield	Torn 116 —
Front LH Fender Inner Shield Clips	^{MT} 20 ✓
Front LH Wheel Rim. At	850 (SN) 480 (SN)
Front LH Tyre New	280 (SN) X.

SLZ2726Y.

Front LH Lower Arm	{ NH all	352x
Front LH Knuckle Arm		399x
Front LH Shock Absorber		326x
Front LH Wheel Hub & Bearing		Damaged 345. —

4603 SN: 480.
A14270.

Panel Beating
Spray Painting.
Wiring.

~~1300~~ 700
~~1000~~ 400
~~50~~ 30

To undersend

150 x

To remove condensers,
radiators and to top up air con gas

~~180~~ 120

To perform wheel alignment

~~150~~ 80 1450

To dismantle front undercarriage

~~350~~ 120

LKK Auto Consultants hereby notifies the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 6072.70.

L/S: A-8K
06 Days

10674

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009385/AQD3N2

Date: 10/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30640718000	
Claimant Vehicle No :	SLZ2726Y	Insured Vehicle No :	GY4723G	
Date of Loss:	23/05/2019	Nature of Claim:	TP	Claim No: SNM19D202349C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ2726Y	Engine No:	G4FGJH697441
Make & Model:	KIA CERATO K3, 1.6 (A)	Chassis No:	KNAFX411MJ5768005
Reg. Date:	27/04/2018 (Man. Year: 2017)	Odometer:	17211 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,499.00	4,622.70	2,876.30	38.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,450.00	1,730.00	54.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,679.00	6,072.70	4,606.30	43.13
Approved Total (Overridden) (\$\$)		4,800.00		
Nett Amount (\$\$)	10,679.00	4,800.00	5,879.00	55.05

INSPECTION

Date of Assignment:	28/05/2019	
Date Inspected:	28/05/2019 Inspected At:	Hiap Hong Motor Repair (HQ) 2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit Autohub Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2019)
Parts:	143	KIA CERATO K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ2726Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	637.00 F	*637.00 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
3	1		*FRONT BUMPER SIDE HOLDER	N/s Damaged	80.00 F	*40.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	496.00 F	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	118.00 F	*- FL
6	1		*FRONT BUMPER SIDE AIR VENT LH	Not Necessary	35.00 F	*- FL
7	1		*FRONT BUMPER FOG LAMP LH	Cracked	263.00 F	*263.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Cracked	185.00 F	*185.00 FL
9	1		*HEADLAMP LH	Cracked	1,870.00 F	*1,870.00 FL
10	1		*FRONT SUPPORT PANEL	Cracked	662.00 F	*662.00 FL
11	1		*FRONT LH FENDER	Dented	435.00 F	*435.00 FL
12	1		*FRONT LH FENDER INNER SHIELD	Torn	116.00 F	*116.00 FL
13	1		*FRONT LH FENDER INNER SHIELD CLIPS	Necessary	20.00 F	*20.00 FL
14	1		*FRONT LH WHEEL RIM	Cut	850.00 FS	*480.00 FS
15	1		*FRONT LH TYRE	Not Necessary	280.00 FS	*- FS
16	1		*FRONT LH LOWER ARM	Not Necessary	352.00 F	*- FL
17	1		*FRONT LH KNUCKLE ARM	Not Necessary	399.00 F	*- FL
18	1		*FRONT LH SHOCK ABSORBER	Not Necessary	326.00 F	*- FL
19	1		*FRONT LH WHEEL HUB C/W BEARING	Damaged	345.00 F	*345.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,499.00	5,083.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	460.30
Total Parts (\$\$)	7,499.00	4,622.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,300.00	700.00
2	SPRAY PAINTING	New	1,000.00	400.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	0.00
5	TO REMOVE CONDENSER,RADIATOR AND TO TOP UP AIR CON GAS	New	180.00	120.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
7	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	120.00
Gross Labour Cost (\$\$)			3,180.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >