Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19009398/AKA3Q2

Date: 08/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800033819

Claimant
Webicle No: SLM4822H

Vehicle No:

Date of Loss: 24/05/2019 Nature of Claim: TP Claim No: 7642228891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT6999R

 Make & Model:
 TOYOTA WISH, 1.8 (A)
 Engine No:
 1ZZ2891073

 Reg. Date:
 20/04/2007 (Man. Year: 2007)
 Chassis No:
 ZNE100362873

 Colour:
 Blue
 Odometer:
 220316 km

Engine Capacity: 1794 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,539.00	3,083.25	3,455.75	52.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,600.00	310.00	16.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,449.00	4,683.25	3,765.75	44.57
Approved Total (Overridden) (S\$)		3,750.00		
Nett Amount (S\$)	8,449.00	3,750.00	4,699.00	55.62
+ Car Rental (8.0 x S\$12	20.00/day) (S\$)	960.00		
+ Doc/S	7.45			
Ne	tt Liability (S\$)	4,717.45		
Global Sum S	Global Sum Settlement (S\$)			

INSPECTION

Date of Assignment: 27/05/2019

Date Inspected: 27/05/2019 Inspected At: Best Solution Autocare Pte Ltd (HQ)

53 UBI AVE 1 #03-01 PAYA UBI

INDUSTRIAL PARK Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: Khanchna Pothuraj

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	495.00 F	*495.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	150.00 F	*150.00 FL
3	1		*SET REAR BUMPER CLIP	Necessary	30.00 F	*30.00 FL
4	1		*TAILGATE	Dented	1,475.00 F	*1,270.00 FL
5	1		*TAILGATE GLASS SEALANT	Necessary	48.00 F	*48.00 FL
6	1		*TAILGATE WINDSTRIP	Cut	325.00 F	*325.00 FL
7	1		*N/S TAILAMP	Cracked	575.00 F	*409.00 FL
8	1		*N/S REAR FENDER	Repair	789.00 F	*- FL
9	1		*N/S REAR FENDER GLASS SEALANT	Not Necessary	48.00 F	*- FL
10	1		*REAR BUMPER LOWER SPOILER	Not Necessary	550.00 F	*- FL
11	1		*REAR END PANEL	Dented	487.00 F	*487.00 FL
12	1		*REAR BUMPER BRACKET	N/S Dented	150.00 F	*75.00 FL
13	1		*SET REVERSE SENSOR	Damaged	200.00 F	*200.00 FL
14	1		*N/S REAR BUMPER REFLECTOR	Not Necessary	65.00 F	*- FL
15	1		*WINDSCREEN SEALANT	Necessary	48.00 F	*48.00 FL
16	1		*TAILGATE CHROME HANDLE	Not Necessary	245.00 F	*- FL
17	1		*TAILGATE INNER LOCK	Damaged	165.00 F	*165.00 FL
18	1		*REAR NUMBER PLATE	Not Necessary	60.00 F	*- FL
19	1		*TAILGATE INNER GARNISH	Not Necessary	225.00 F	*- FL
20	1		*O/S TAILLAMP	Cracked	409.00 F	*409.00 FL
F=Fra	nchise	part. L=ListIte	emDisc.	-		
				Sub Total (S\$)	6,539.00	4,111.00
- List Item Discount on L Items 0.00/25.00% (S\$)				0.00	1,027.75	
				Total Parts (S\$)	6,539.00	3,083.25
Report was unsubmitted during this print-out.						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE DAMAGED PARTS ,PANEL BEAT ,REPAIR	New	800.00	700.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	800.00	700.00
3	WIRING CHECK	New	80.00	30.00
4	TAILGATE GLASS	New	150.00	120.00
5	REVERSE SENSOR	New	80.00	50.00
	Gross Labour Cost (S\$)		1,910.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >