



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2018 MASERATI GHIBLI GRANSPO
MASXXX (SMD1378D)

Date of Loss 17 May 2019

Time of Loss 10.20

Loss Description SMD1378D (INSD) C/W SLS5573M (TP)

Comment

Workshop Details

Total Rebate Amount 128248

Nett Loss Amount \$171,752.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SMD1378D

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

03/08/2018



Mileage

10534

Age of Vehicle

0

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2018

2018

Make

MASERATI GIBLI
GRANSPO

MASERATI

Model

MASXXX

GHIBLI GRANSPO

Driver Details

CATEGORY

FNOL
INFORMATIONPOST SURVEY
INFORMATION

Driver Name

KOH CHUAN
YONG

Date of Birth

13 June 1977

dd/mm/yyyy



Age

42

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	ZAMXS57C001296850	ZAMXS57C00129
Engine No	409310	409310
Engine Capacity		2979
Sum Insured	368000	0
Market Value	0	300000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	SG, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Unknown	
Marital status	Unknown	
Identification #	S7715532E	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

28/05/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

8000

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/40ZR20

Rear Tyre Size

285/35ZR20

Front left side

PIRELLI7mm

Rear left side

PIRELLI7mm

Front right side

PIRELLI7mm

Rear right side

PIRELLI7mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts																
AddApproveDenySubmit All																
	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMARK
		0	1		FRONT BUMPER	Damaged	0	2553	No					2553	Reviewing	
		0	1		BRACKET	Necessary	0	27	No					27	Reviewing	
		0	1		UPPER CENTRAL FRT BUMPER SHOCK ABSORBER	Serviceable	0	0	No					0	Deny	
		0	1		LOWER CENTRAL FRONT BUMPER PANEL	Serviceable	0	0	No					0	Deny	
		0	1		LH FRONT BUMPER BRACKET	Serviceable	0	0	No					0	Deny	
		0	1		REINFORCEMENT BRACKET	Serviceable	0	0	No					0	Deny	
		0	1		RH LOWER GRILLE	Serviceable	0	0	No					0	Deny	
		0	1		RH PLATE	Serviceable	0	0	No					0	Deny	
		0	1		CENTRAL GRILL	Serviceable	0	0	No					0	Deny	
		0	1		UPPER COVER	Serviceable	0	0	No					0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMARKS
		0	2		SCREW	Serviceable	0	0	No					0	Deny	
		0	1		AIR DUCT ASSEMBLY	Serviceable	0	0	No					0	Deny	
		0	1		GRILL	Serviceable	0	0	No					0	Deny	
		0	8		SCREW	Serviceable	0	0	No					0	Deny	
		0	1		TRIM KIT	Serviceable	0	0	No					0	Deny	
		0	1		RH MUDGUARD SUPPORT BRACKET	Bent	0	135	No					135	Reviewing	
		0	1		RH MUDGUARD FRONT LOWER REINFORCEMENT	Bent	0	58.8	No					58.8	Reviewing	
		0	1		MUDGUARD SIDE BRACKET	Serviceable	0	0	No					0	Deny	
		0	1		RH MUDGUARD CENTRAL MOUNTING BRACKET	Serviceable	0	0	No					0	Deny	
		0	1		FRONT RH MUDGUARD ASSEMBLY	Dented	0	1042	No					1042	Reviewing	
		0	2		SCREW	Serviceable	0	0	No					0	Deny	
		0	2		SCREW	Serviceable	0	0	No					0	Deny	
		0	8		SCREW	Serviceable	0	0	No					0	Deny	
		0	1		RH FRONT WHEELHOUSE GUARD FRONT SIDE	Damaged	0	258	No					258	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REP
		0	1		RH FRONT WHEELHOUSE GUARD REAR SIDE	Serviceable	0	0	No					0	Deny	
		0	6		BLOCK	Serviceable	0	0	No					0	Deny	
		0	14		SCREW	Serviceable	0	0	No					0	Deny	
		0	4		NUT	Serviceable	0	0	No					0	Deny	
		0	2		SCREW	Serviceable	0	0	No					0	Deny	
		0	2		PIN	Serviceable	0	0	No					0	Deny	
		0	2		FASTENER BUTTON	Serviceable	0	0	No					0	Deny	
		0	6		FASTENER BUTTON	Serviceable	0	0	No					0	Deny	
		0	6		FASTENER BUTTON	Serviceable	0	0	No					0	Deny	
		0	1		FRONT RIGHT RIM	Cut	0	2394	No					2394	Reviewing	
		0	1		RH HEADLIGHT	Broken	0	4480	No					4480	Reviewing	
		0	4		FASTENER BUTTON	Necessary	0	2.8	No					11.2	Reviewing	
		0	2		RIVET	Missing	0	4.2	No					8.4	Reviewing	
		0	4		FASTENER BUTTON	Necessary	0	2.8	No					11.2	Reviewing	
		0	6		RIVERT	Serviceable	0	0	No					0	Deny	
		0	4		RIVERT	Necessary	0	2.8	No					11.2	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMARKS
		0	1		FRONT MASERATI EMBLEM	Necessary	0	210	No					210	Reviewing	
		0	1		GRANSPORT SIDE LOGO	Necessary	0	140	No					140	Reviewing	
		0	1		FRONT NUMBER PLATE	Necessary	0	50	No					50	Reviewing	
		0	1		FRONT PARKING SENSOR	Damaged	0	273	No					273	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMARKS
		0		LABOUR TO SWAP TYRE	0	60	0	0	Reviewing		
		0		LABOUR TO CARRY OUT ACCIDENT REPAIR	0	2640	0	0	Reviewing		
		0		LABOUR TO CARRY OUT SPRAY PAINTING	0	2600	0	0	Reviewing		
		0		LABOUR TO CALIBRATE REDAR	0	990	0	0	Reviewing		
		0		LABOUR TO CLEAR FAULTS AFTER ACCIDENT REPAIR	0	1200	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS
OF
REPAIR
: 5
DAYS

Reviewing

0





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$11,152.80

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$11,662.80

Labour

\$0.00

\$7,490.00

Excess

-\$8,000.00

[Submit for Review](#)