

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19009405/AKA3Q2

Date: 28/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994166

Claimant
Vehicle No : SKT969U **Insured Vehicle No :** SKK6858P

Date of Loss: 10/04/2019 Nature of Claim: TP Claim No: 4315922286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT969U		
Make & Model:	TOYOTA HARRIER, 2.0 (A)	Engine No:	3ZRB668097
Reg. Date:	25/01/2016 (Man. Year: 2015)	Chassis No:	ZSU600062201
Colour:	Black	Odometer:	65059 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,187.83	3,145.40	9,042.43	74.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,850.00	1,220.00	2,630.00	68.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,037.83	4,365.40	11,672.43	72.78
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	16,037.83	3,500.00	12,537.83	78.18
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,907.49		
Global Sum Settlement (S\$)		3,857.00		

INSPECTION

Date of Assignment: 27/05/2019

Date Inspected: 27/05/2019 Inspected At: Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61
Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	1,883.20 FL	*1,381.00 FL
2	1		*REAR BUMPER LOWER LIP	Cut	617.50 FL	*389.00 FL
3	1		*REAR BUMPER SIDE HOLDER	N/S Necessary	377.40 FL	*85.10 FL
4	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
5	1		*REAR LH FENDER	Repair	1,339.30 FL	*- FL
6	1		*REAR LH FENDER QUARTER GLASS	Not Necessary	1,069.70 FL	*- FL
7	1		*REAR LH DOOR	Repair	1,339.90 FL	*- FL
8	1		*REAR LH DOOR INNER LOCK	Not Necessary	617.80 FL	*- FL
9	1		*REAR LH DOOR GLASS OUTER MOULDING	Not Necessary	298.70 FL	*- FL
10	1		*REAR LH DOOR INNER BOARD	Not Necessary	1,068.20 FL	*- FL
11	1		*REAR LH DOOR TOP HINGE	Not Necessary	189.30 FL	*- FL
12	1		*REAR LH DOOR LOWER HINGE	Not Necessary	189.30 FL	*- FL
13	1		*REAR LH DOOR STOPPER	Not Necessary	254.50 FL	*- FL
14	1		*REAR LH SPORT RIM	Cut	2,245.13 FS	*680.00 FS
15	1		*REAR LH KNUCKLE	Not Necessary	617.80 FL	*- FL
16	1		*REAR LH KNUCKLE BEARING	Damaged	640.10 FL	*640.10 FL
17	1		*REAR LH ROCKER PANEL GARNISH	Cut	1,069.30 FL	*688.00 FL
18	1		*REAR LH MUD FLAP	Cut	301.50 FL	*74.00 FL
19	1		*REAR LH DOOR PROTECTOR	Not Necessary	310.10 FL	*- FL
20	1		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
21	1		*REAR LH TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,248.73	3,967.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,060.90	821.80
Total Parts (\$\$)	12,187.83	3,145.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	60.00
2	REMOVE & REINSTALL BOOTLID INNER GARNISH	New	200.00	0.00
3	REMOVE & REINSTALL QUARTER GLASS	New	100.00	0.00
4	REMOVE & REINSTALL LH SUSPENSION	New	300.00	60.00
5	REMOVE & REINSTALL DOOR GLASS	New	150.00	0.00
6	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,500.00	400.00
7	RESPRAY PAINTING	New	1,300.00	700.00
8	TUFF KOTE	New	150.00	0.00
Gross Labour Cost (\$\$)			3,850.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >