AIG /LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates	SI	LT 1393 L	Not Notherike
Parts (a) Cost / List Price Items	\$	2,075.50	Rewny B& pain
Plus/Less25%	\$	518.88	
Total of Cost / List (b) Nett Price Items Less Total of Nett Items	\$	1,556.63	LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are surject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary tentis I must be resurveyed and is subject to final approval from insurance Company
(c) Special Nett Items	φ		Acknowledged by Repairer
Total Parts Cost	\$	1,756.63	Signature: Date:
Labour	\$	2,120.00	
Total	\$	3,876.63	
The above total will be subjected to	7% G.S.T.		

Nan	ne of Surveyor	Kennerh
	npany	2815119 at
	vey conducted on narks By Surveyor	
(a)		Prized / is not authorized until further notice.
(b)	Recommended Days of Repair Resurvey	:day(s) : Required / Not Required
(d)	Excess	:\$
(e)	Signature of surveyor	Le Date: 28/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

C			Pai	40
-	na	F 64	rai	15

Vehicle No. :	SLT 1393 L	Submit By	:	SERENCE
Make & Model :	TOYOTA PRIUS	Year Manufacture	:	2017
Chassis No :	JTDKB3FU303574217	Engine No.	:	

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	not	1	\$200.00	S.N	
2	Rear bumper	Bu	1	\$497.50		
3	Rear bumper clip	M	10	\$40.00		_
4	Rear bumper side retainer LH	Sa	1	\$112.70		×
5	Rear bumper side retainer RH	Sn	1	\$112.70		
6	Rear bumper reinforcement		1	\$398.90		7
7	Rear bumper lower garnish centre	nu	1	\$582.60		
8	Rear bumper lower garnish LH	Sn	1	\$149.70		*
9	Rear bumper lower garnish RH	Sa	1	\$149.70		X
10	Rear bumper tow cover	San	1	\$31.70		×
11						
12						
13	A CHARLES AND CONTRACTOR					
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	SLT 1393 L	Submit By :	SERENCE
Make & Model	:	TOYOTA PRIUS	Year of Manufacture:	2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL,SPARE		
	TYRE COMPARTMENT)	\$800.00	2001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL,SPARE		00
	TYRE COMPARTMENT)	\$800.00	2201
3	To tuff coat.	\$50.00	X
4	TO Check wiring	\$50.00	101
5	To remove & refit reverse sensor	\$150.00	501
6	To conduct water leakage tests to ensure proper air and		
	sealing ***	\$120.00	X
7	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	*

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.