

Jin Le

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 51321
Date Estimated : 27/05/2019
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Phua Boon Keng
32 Yio Chu Kang Road
#01-18

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 545551

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD7117B	WC09009	28/02/2018	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front bumper, front RH fender include removing attachments to facilitate repairs and knocking out dents caused by the accident	1275.00		1,275.00 /
* To spray paint front bumper and front RH fender	1730.70		1,730.70 /
To check electrical wiring systems at the front section for proper function	150.00		150.00 /
Sundries	80.00		80.00 /

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

SUPPLEMENTARY ITEMS

Total Labour :	3,235.70 /
Total Parts :	0.00
Total Labour & Parts :	3,235.70
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,235.70
GST @7%:	226.50
Grand Total :	3,462.20

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197481559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

27 MAY 2019

ESTIMATE

Estimate No. : b1 51321
Date Estimated : 27/05/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Phua Boon Keng
32 Yio Chu Kang Road
#01-18

Singapore 545551

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMD7117B	WC09009	28/02/2018	5201	0

DESCRIPTION

Remove right front side fender front bumper and remove attachment etc include repair on accident damage area

Spray painting front bumper and right front side fender

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

Sundries.

VALUE

2,125.00

1275

1779.70 1550.70 1,923.00

150 177.00

40.00

Total Labour 4,265.00

CLKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time _____ Excess S\$ _____

Surveyor's Name _____ Sign _____

Surveyor's Tel _____ Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail _____

No. of Working Days Recommend _____

Labour 1	:	4,265.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	298.55
Grand Total	:	4,563.55

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Steve (CLKK) with Repaire 10/6/19, 11.20 am
P/P Reay before spray
4 days