

Date : 27/05/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Cecilia

Our Customer : Ascend Com Pte Ltd

Vehicle No : GBG9219S

Model : Toyota Dyna 150 5MT

Manufacture Year : 2017

Date of Accident : 26/5/2019

Total Estimate Repair Days : 15

Total Pages : 2

Attn : Motor Claims Department

Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against SJA3627Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front lining RH <i>Replaced</i>	1	\$365.20	\$365.20	✓
2	Front fender mudflap RH <i>Replaced</i>	1	\$68.00	\$68.00	+
3	Front fender centre RH <i>Replaced</i>	1	\$180.00	\$180.00	✓
4	Radiator spare tank w/cap <i>Replaced</i>	1	\$178.00	\$178.00	✓
5	Air filter housing <i>Replaced</i>	1	\$675.00	\$675.00	✓
6	Fuel tank <i>Replaced</i>	1	\$925.00	\$925.00	✓
7	Fuel tank cap <i>Replaced</i>	1	\$78.00	\$78.00	+
8	Fuel tank bracket - front <i>Replaced</i>	2	\$190.00	\$380.00	120 (SN)
9	Fuel tank bracket - rear <i>Replaced</i>	2	\$90.00	\$180.00	120 (SN)
10	Exhaust tail pipe <i>Replaced</i>	1	\$594.80	\$594.80	+
11	Exhaust mounting <i>Replaced</i>	2	\$58.00	\$116.00	+
12	Exhaust bracket <i>Replaced</i>	2	\$98.00	\$196.00	+
13	Tail gate stopper bracket RH <i>Replaced</i>	1	\$183.20	\$183.20	✓
14	Tail gate stopper RH <i>Replaced</i>	1	\$121.60	\$121.60	40 (SN)
15	Rear fender RH <i>Replaced</i>	1	\$180.00	\$180.00	+
16	Rear mudflap RH <i>Replaced</i>	1	\$98.00	\$98.00	+
17	Rear axle <i>Replaced</i>	1	\$3,785.80	\$3,785.80	+
18	Rear axle spring bush <i>Replaced</i>	2	\$68.00	\$136.00	+
	2686.40 SW:280		Total	\$8,440.60	
	2014.80		Less 25%	\$2,110.15	
			Sub Total 1	\$6,330.45	
B.	Spare Parts (S/Nett)				
1	Deck bed complete <i>Replaced</i>	1	\$3,500.00	\$3,500.00	+
2	Deck bed lower bracket RH <i>Replaced</i>	1	TBA	80 TBA	✓
3	Rear tyre RH <i>Replaced</i>	2	\$350.00	\$700.00	150
4	Rear rim RH <i>Replaced</i>	2	\$300.00	\$600.00	180
5	Reverse sensor (set) <i>Replaced</i>	1	\$250.00	\$250.00	+
6	Diesel <i>Replaced</i>	60L	\$150.00	\$150.00	50
7	Coolant <i>Replaced</i>	1	\$80.00	\$80.00	40
8	Rear bracket assy RH <i>Replaced</i>	1	\$550.00	\$550.00	+
9	Rear box up - front door RH <i>Replaced</i>	1	TBA	1800 TBA	1200
10	Rear box up - rear door RH <i>Replaced</i>	1	TBA	TBA	+
11	Rear box up - front pillar RH <i>Replaced</i>	1	TBA	1500 TBA	800

Replaced

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
12	Rear box up - rear door pillar RH <i>detached</i>	1	1500 TBA	TBA	860
13	Rear box up lock RH <i>new</i>	1	TBA	TBA	8
14	Front fender lining clip <i>new</i>	10	\$5.00	\$50.00	30
	Sub Total 2			\$5,880.00	
	2580				
	Total for Parts			\$12,210.45	
C.	Labour				
1	To check wiring.			\$120.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			1000 TBA	650
3	Spray painting all affected parts & areas.			1000 TBA	7500
4	To remove and replace fuel tank.			\$250.00	80
5	To remove and replace rear box up.			500 TBA	x
6	To remove and replace exhaust silencer.			\$250.00	x
7	To spray anti-rust undercoat.			\$150.00	50
	Total Labour			\$770.00	
	Total Repair Cost			\$12,980.45	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary : 60
Admission, total 6244.
L/s 28/05/19. H/s. 5K.
07 Days. (SLC)

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 28/5/2019

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : Ascend Com Pte Ltd
Vehicle No : GBG9219S
Model : Toyota Dyna 150 5MT
Manufacture Year : 2017
Date of Accident : 26/5/2019
Total Estimate Repair Days : 15
Total Pages : 1

Attn : Motor Claims Department
Email : motor.survey@axa.com.sg

Re: Supplementary Repair Estimate For Third Party Claim against SJA3627Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts (S/Nett)				
1	Sliding door rail front RH <i>Pair</i>	1	repair	repair	<i>X.</i>
2	Bracket stopper RH <i>Missing</i>	1	\$58.00	\$58.00	<i>30(SN)</i>
3	Bracket stopper RH rivet <i>New</i>	2	\$5.00	\$10.00	<i>✓</i>
4	Bracket reflector sticker RH <i>new</i>	1	\$68.00	\$68.00	<i>✓</i>
5	Bracket aluminium plate rivet <i>new</i>	4	\$5.00	\$20.00	<i>✓</i>
Total Supplementary Repair Cost				\$156.00	

Supplementary : 60(SN).

Yours faithfully,

Aun Teng

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize