

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19009433/ADA3Q2

Date: 30/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0100513824

Claimant
Vehicle No : SJA1989S **Insured Vehicle No :** SCW8166X

Date of Loss: 24/05/2019 Nature of Claim: TP Claim No: 9236380891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA1989S	Engine No:	CVN016743
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF47HA020454
Reg. Date:	20/09/2016 (Man. Year: 2016)	Odometer:	55984 km
Colour:	Brown		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,954.00	3,447.12	1,506.88	30.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,872.00	1,522.00	350.00	18.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,826.00	4,969.12	1,856.88	27.20
+ GST 7.00/7.00% (S\$)	477.82	347.84	129.98	27.20
Nett Amount (S\$)	7,303.82	5,316.96	1,986.86	27.20
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,468.96		

INSPECTION

Date of Assignment: 29/05/2019

Date Inspected: 29/05/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,422.00 FS	*1,992.80 FS
2	1		*REAR BUMPER SECURING STRIP	Not Necessary	203.00 FS	*- FS
3	1		*REAR BUMPER SPOILER GRILLE-CENTRE	Cracked	265.00 FS	*212.00 FS
4	1		*REAR BUMPER SPOILER	Cut	714.00 FS	*571.20 FS
5	2		*REAR BUMPER SIDE TRIM-LH/RH	Not Necessary	74.00 FS	*- FS
6	2		*REAR BUMPER REFLECTOR-LH/RH	Not Necessary	76.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Bent	819.00 FS	*655.20 FS
8	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	81.00 FS	*- FS
9	1		*SUNDRIES	Necessary	300.00 FS	*15.92 FS
					Total Parts (\$\$)	4,954.00 3,447.12

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CALIBRATE PART ASSISTANCE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER AND LOWER SPOILER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	700.00	500.00
3	TO RESPRAY REAR BUMPER	New	700.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			1,872.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >