

25/05/2019

ASS. REC. BY:

REF: CS3/CT19009447/GC d302

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Elaine Chong

of CT1

Date/Time: 28.5.19 19:14p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJH 4494X

Insured: 9BD 6664

at Workshop m/s MJE motor

Tel: 92251391

of Blk F sin ming Sector C #01-92

Policy No: DMCVSN3033071 9000

Claim No: SMM19D 20238102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25.5.2019

CA / REV / REP. / REV 24 HRS

"sup"

H.O.D. Endorsement:

Date/Time: 29.5.19 9:20a.m

Person Contacted: Jo

Vehicle IN / OUT

Date/Time	Action/Instruction
	Ishtimate (X) Inspection: Blk F sin ming Sector C #01-94
	SJE 4494X - CCG / AIG 14017449 / A 30342
	9BD 6664 - X
	Diamond: 30/5/2019
	After repair: 3/6/2019

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2019		28 May 2019 19:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ABLE PACK (S) PTE LTD, Co. Reg. No.: 199607262G		
Main Claimant:	RELIANT CONSTRUCTION PTE LTD, Co. Reg. No.: 201203678D		
Vehicle Reg. No.:	SJH4494X	Date of Loss:	25/05/2019 13:00 - :59 [129 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202381C02	Policy/Cover Note No.:	DMCVSN30330719000 (Comprehensive) Coverage: 07/05/2019 - 06/05/2020
Vehicle Reg. No. (Insured):	GBD6665Y	Policy No. (Claimant):	5106317154
		Excess:	S\$0.00
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2019]		
Driver/Custodian (Insured):	YEOW KOK KEONG (56 / Male) , NRIC: S1534264A Email:		
Adj Asg. Remarks:	to contact YY / Jo at 9225 1391 or 6454 2203 to arrange for survey. Workshop - MJE Motor Blk 7 Sin Ming Sector C #01-94 Singapore 575642. thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	3678D
Vehicle No.:	SJH4494X
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	1N2D152657
Chassis No.:	NZE1416092573
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,308.00
Original Registration Date:	07 Aug 2008
First Registration Date:	07 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$12,308.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	06 Aug 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$17,099.00
COE Rebate Amount:	\$14,322.00
Total Rebate Amount:	\$14,322.00
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 May 2019

OK

Lea - 87555787 | Ben - 90913551 | Mr Ho - 96811390 | Nic - 81001945

Toyota Corolla Axio 1.5A X **\$49,600** \$5,400 /yr 01-Aug-2008 1,496 cc - **Available**
(COE till 07/2028)

Gearbox Filter, Gearbox Cooler, Pan Gasket, Lower Arm, Steering Rack, Tie Rod, Japan Engine Mounting Changed Total \$4K. No Leaking At All.

Office No. - -

Vincent - 90255655

Toyota Corolla Axio 1.5A X **\$25,500** \$6,030 /yr 20-Aug-2008 1,496 cc 125,000 km **Available**
(COE till 08/2023)

New BC Racing V1 Coilovers, New Michelin PS4 Tyres, New Radiator, New Coils, New Water Piping. Well Maintained By Car Lover! No Wear And Tear Needed To Be Replaced. Only Use FK Massimo Engine Oil. Loa...

Office No. - -

AC - 88181155

Toyota Corolla Axio 1.5A X **\$25,888** \$5,950 /yr 03-Oct-2008 1,496 cc - **Available**
(COE till 10/2023)

Only 1 Owner For The Last 10.5 Years, Accident-Free, Quiet Engine, Smooth Gearbox, Strong Acceleration. Recently Changed Suspension, Lower Arm, Engine Mounting, And Aircon Compressor. Clean And Well M...

Office No. - -

Steven Ling - 83228882

Toyota Corolla Axio 1.5A X **\$28,800** \$5,750 /yr 28-Oct-2008 1,496 cc 120,000 km FredLink Auto Trading **Available**
(New 5-yr COE)

Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

Office No. - 67788997 / 67788995

Daniel Loh - 83938889 | Mohammad - 81121493 | Freddy Lee - 96923373

Toyota Corolla Axio 1.5A X **\$24,766** \$5,590 /yr 03-Nov-2008 1,496 cc 109,586 km Creative Auto **Available**
(COE till 11/2023)

Loan Available. Engine And Gearbox Inspected By Our Mechanic, Even Undercarriage All In Very Good Condition, Definitely Worth Renewing COE, Don't Miss Out, Call Or Sms Our Staffs To Arrange For Viewin...

Office No. - -

Francis Yao - 93275727 | Alex Tan - 97556887 | Terence Leow - 90290899

Toyota Corolla Axio 1.5A X **\$37,800** \$3,970 /yr 12-Dec-2008 1,496 cc 143,373 km Fonda Motors Pte Ltd **Available**
(COE till 11/2028)

-

Office No. - 63555555

Vincent - 97637337

Toyota Corolla Axio 1.5A X **\$38,766** \$4,050 /yr 19-Dec-2008 1,496 cc 115,500 km Creative Auto **Available**
(COE till 12/2028)

Full Loan Amount Stated, Flexible Loan Package. Beautifully Maintained, Low Mileage Usage With Excellent Engine And Gear Condition, Definitely Worth Renew For 10 Years COE, Very Good Fuel Efficiency, ...

Office No. - -

Yang - 87480430 | Alex Tan - 97556887 | Terence Leow - 90290899

Toyota Corolla Axio 1.5A X **\$28,800** \$6,120 /yr 10-Feb-2009 1,496 cc - ABWIN (1994) Pte Ltd **Available**
(COE till 02/2024)

Reliable, Very Well Maintained By Careful Owner. Stable Good Road Holding And Best Fuel Saving! 100% Loan Available. Bank Or In House Loan. Low Maintenance Cost! Flexible Loan, Low Monthly Installment...

Office No. - -

Zhen Yuan - 93632818 | Soon - 97475901

Toyota Corolla Axio 1.5A X **\$41,800** \$4,280 /yr 02-Mar-2009 1,496 cc 110,000 km Creative Auto **Available**
Special Edition (COE till 03/2029)

Rare In The Market Premium Special Edition Axio! Loan 40,800. 100% Accident Free, Seldom Use, Service Regularly Without Fail. Axio Not Only Provides You A Powerful Drive Yet It Gives You And Your Fami...

Office No. - -

NEO - 92222719 | Alex Tan - 97556887 | Terence Leow - 90290899

Toyota Corolla Axio 1.5A X **\$27,888** \$5,830 /yr 11-Mar-2009 1,496 cc - New Autodrive **Available**
(COE till 03/2023)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 18:47
Date Of Accident	25/05/2019 13:00
Exact Location Of Accident	275A COMPASSVALE LINK EXIT CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH4494X
Insured/Policyholder	
Name Of Registered Owner	RELIANT CONSTRUCTION PTE LTD
Co Reg No	201203678D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-82663609
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106317154
Cover Note Number	
Driver	
Name of Driver	JAYAKUMARAN S/O SUBRAMANIAM
NRIC No	S7506803D
Date Of Birth	09/02/1975
Occupation	OUTDOOR
Date Of Driving Pass	09/02/2010
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82663609
Fax Number	
Contact Number	OFFICE-82663609
EEmail Address	DAVIDJAYAKS09@GMAIL.COM

Address	APT BLK 476A UPPER SERANGOON VIEW #06-506 SINGAPORE
Postcode	531476
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD6665Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	YEOW KOK KEONG
NRIC/Passport Number	S1534264A
Contact Number	96490115
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

2000 年 12 月 15 日


•

MP 62

Figure 1. Schematic diagram of the experimental setup.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/08/19 Saturday about 13:00 at blk 3/3A
 Compassvale link I was exiting the carpark
 In front of me was a grey 430 6657 having moved
 to exit I wanted to alert him he reversed his lorry I
 started to honk to alert him but he did not see or
 hear me as his back view was blocked
 He then hit my front side of the car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

RELIANT CONSTRUCTION PTE LTD
 Biz Regn No: 2012036790
 32 Upper Duxton Road 402-02 57650008 201 491
 Tel: 62910085 Fax: 62920752
 Email: rbl@reliantconstruction.com

Driver's signature
 If driver is not the policyholder

Reporting agent's name and driver's signature
 name:


































...CLAIM SUBFOLDER...(Pending for Survey Report)














































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		28 May 2019 19:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case


















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ABLE PACK (S) PTE LTD , Co. Reg. No.: 199607262G								
Main Claimant:	RELIANT CONSTRUCTION PTE LTD , Co. Reg. No.: 201203678D								
Vehicle Reg. No.:	SJH4494X	Date of Loss:	25/05/2019 13:00 - :59 [129 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202381C02	Policy/Cover Note No.:	DMCVSN30330719000 (Comprehensive) Coverage: 07/05/2019 - 06/05/2020						
Vehicle Reg. No. (Insured):	GBD6665Y	Policy No. (Claimant):	5106317154						
		Excess:	S\$0.00						
Repairer:	Mje Motor (HQ) BLK 7 SIN MING SECTOR C, #01-82, 575642 Sin Ming - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 07/06/2019]								
Driver/Custodian (Insured):	YEOW KOK KEONG (56 / Male) , NRIC: S1534264A Email:								
Adj Asg. Remarks:	to contact YY / Jo at 9225 1391 or 6454 2203 to arrange for survey. Workshop - MJE Motor Blk 7 Sin Ming Sector C #01-94 Singapore 575642. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents
















*SJH4494X (SNM19D202381C02)
[GBD6665Y]
TP
RELIANT CONSTRUCTION PTE LTD
May 25 2019 1:00PM
[ABLE PACK (S) PTE LTD]
Mje Motor

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)					Thumbnail	Print	
1	27/05/19 18:56	Accident Statement					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
2	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
3	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
4	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
5	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
6	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
7	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
8	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
9	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
10	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
11	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
12	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
13	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
14	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
15	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
16	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
17	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
18	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
19	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
20	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
21	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
22	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
23	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
24	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
25	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
26	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
27	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
28	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
29	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
30	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
31	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
32	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
33	13/06/19 13:56	General View					Load JPG	<input checked="" type="checkbox"/>	
34	13/06/19 13:57	Photographs of Damaged Parts					Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	13/06/19 13:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	13/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
81	13/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
82	13/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
83	13/06/19 14:00	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
84	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
88	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	13/06/19 14:00	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/05/19 19:10	INSD GBD6665Y GIA REPORT	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	27/05/19 18:56	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	27/05/19 18:55	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Boon Lay)	Thumbnail	Print
1	27/05/19 18:55	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/05/19 18:55	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19009447/GCD3E2

Date: 20/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30330719000

Claimant Vehicle
No: SJH4494XInsured Vehicle
No: GBD6665Y

Date of Loss: 25/05/2019

Nature of Claim: TP

Claim
No: SNM19D202381C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJH4494X

Make & Model: TOYOTA COROLLA AXIO, 1.5 (A)

Reg. Date: 07/08/2008 (Man. Year: 2008)

Colour: Blue

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1NZD152657

Chassis No: NZE1416092573

Odometer: 165831 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Front Left Side: KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Tyre Size: 205/55 R16

Rear Left Side: KAPSEN 6 mm

Rear Right Side: KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 29/05/2019 Inspected At:

Mje Motor (HQ)
BLK 7 SIN MING SECTOR C, #01-82
Singapore 575642

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 20 Jun 2019)

Parts: 143 TOYOTA COROLLA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJH4494X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >