



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 3668M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	990.00	990.00
2	FRONT BUMPER SIDE RETAINER (CONSISTENT)	N/S NECESSARY	85.80	42.90
1	FRONT BUMPER SPONGE (CONSISTENT)	NOT NECESSARY	25.50	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	639.00	-
1	FRONT LH HEADLAMP (CONSISTENT)	CRACKED	577.50	577.50
1	FRONT LH HEADLAMP LOWER BRACKET (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT LH FENDER (CONSISTENT)	DENTED	647.75	647.75
1	FRONT LH FENDER INNER SHIELD (CONSISTENT)	NOT NECESSARY	87.30	-
	LESS 10% DISCOUNT		-317.28	-225.81
			2,855.57	2,032.34
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	60.00	30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			110.00	30.00
	<u>LABOUR</u>			
	CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	PANEL BEATING ON AFFECTED AREAS.		500.00	400.00
	SPRAY PAINTING ON AFFECTED AREAS.		700.00	400.00
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
			1,410.00	830.00
GRAND TOTAL			4,375.57	2,892.34
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS3/ASM18009559/Apa3s2-1

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.