

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009449/KQD3E2
Date: 17/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	D29096812QMY
Claimant Vehicle No :	FH3836Y	Insured Vehicle No :	SKQ9271E
Date of Loss:	19/04/2019	Nature of Claim:	TP
		Claim No:	591211

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FH3836Y	Engine No:	2UX004446
Make & Model:	YAMAHA RXZ, 133cc (M)	Chassis No:	2UX004446
Reg. Date:	18/01/1990 (Man. Year: 1989)	Odometer:	22409 km
Colour:	Yellow/Blue		
Engine Capacity:	133 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	80/80 R18	Rear Tyre Size:	80/90 R18
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Golden Boy 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,695.00	2,893.50	801.50	21.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	380.00	225.00	155.00	40.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,075.00	3,118.50	956.50	23.47
Approved Total (Overridden) (S\$)		800.00		
Nett Amount (S\$)	4,075.00	800.00	3,275.00	80.37

INSPECTION

Date of Assignment:	29/05/2019		
Date Inspected:	29/05/2019	Inspected At:	Ga Motor (HQ) Blk 32 Sin Ming Drive, #01-331 Singapore 575706
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

MARKET VALUE: \$900.00 (EST)-LTA REIMBURSEMENT VALUE: \$29.00 =NETT VALUE: \$871.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 16 Jul 2019)	
Parts:	N/A	YAMAHA RXZ 133cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/FH3836Y/17/07/2019 12:07	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET HEAD LIGHT	Bent/Cracked	125.00 F	*125.00 FL
2	1		*HEAD LIGHT BRACKET	Distorted	75.00 F	*75.00 FL
3	1		*HEAD LIGHT FAIRING & WINDSHIELD	Missing	135.00 F	*135.00 FL
4	1		*HEAD LIGHT FAIRING BRACKET	Distorted	90.00 F	*90.00 FL
5	1		*SIGNAL LIGHT (RIGHT)	Broken	65.00 F	*65.00 FL
6	1		*HANDLE BAR (RIGHT)	Bent	90.00 F	*90.00 FL
7	1		*SET HANDLE BALANCER	Dented	28.00 F	*28.00 FL
8	1		*SET MIRROR	Cracked	45.00 F	*45.00 FL
9	1		*HORN	Serviceable	15.00 F	*- FL
10	1		*HORN BRACKET	Repair	20.00 F	*- FL
11	1		*TOP BRAKE PUMP	Mtg Cracked	80.00 F	*80.00 FL
12	1		*BRAKE LEVER	Bent	16.00 F	*16.00 FL
13	1		*I.U UNIT	Cracked	156.00 F	*156.00 FL
14	1		*I.U BRACKET	Bent	40.00 F	*40.00 FL
15	1		*RIGHT HAND SWITCH	Dented	65.00 F	*65.00 FL
16	1		*SET METER	Cracked	530.00 F	*530.00 FL
17	1		*FRONT MUDGUARD	Cracked	98.00 F	*98.00 FL
18	1		*FRONT NO PLATE	Missing	12.00 F	*12.00 FL
19	2		*FRONT FORK INNER TUBE	Serviceable	220.00 F	*- FL
20	2		*FORK OIL SEAL	Serviceable	50.00 F	*- FL
21	1		*BOTTOM STEERING STEM	Serviceable	120.00 F	*- FL
22	1		*STEERING CONE & BEARING	Serviceable	55.00 F	*- FL
23	1		*TANK	Bent	380.00 F	*380.00 FL
24	1		*SIDE COVER (RIGHT)	Cracked	120.00 F	*120.00 FL
25	1		*SET FRONT FOOTREST	Distorted	80.00 F	*80.00 FL
26	1		*SET REAR FOOTREST	Bent	50.00 F	*50.00 FL
27	1		*FOOTREST BRACKET (RIGHT)	Bent	85.00 F	*85.00 FL
28	1		*BRAKE PEDAL	Distorted	35.00 F	*35.00 FL
29	1		*EXHAUST PIPE	Dented	450.00 F	*450.00 FL
30	1		*REAR TAIL BOARD	Cracked	125.00 F	*125.00 FL
31	1		*REAR BOX	Dented/Cut	120.00 F	*120.00 FL
32	1		*REAR CARRIER	Distorted/Bent	120.00 F	*120.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,695.00	3,215.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	321.50

Total Parts (\$\$)	3,695.00	2,893.50
---------------------------	-----------------	-----------------

LKK Auto Consultants Pte Ltd/FH3836Y/17/07/2019 12:07. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	30.00	25.00
2	LABOUR	New	350.00	200.00
Gross Labour Cost (\$\$)			380.00	225.00

LKK Auto Consultants Pte Ltd/FH3836Y/17/07/2019 12:07. Not valid without Reference section.

< END OF ESTIMATES >