

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19009455/JGA3Q2

Date: 06/07/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0001317
Claimant Vehicle No :	SHC4471L	Insured Vehicle No :	PC6339D
Date of Loss:	24/05/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0000553

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4471L		Engine No:	2ZR1400758
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)		Chassis No:	JTDKN36U905748299
Reg. Date:	10/09/2014 (Man. Year: 2014)		Odometer:	502116 km
Colour:	Maroon			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	61,650.88	14,338.96	47,311.92	76.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,303.00	4,930.00	9,373.00	65.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	75,953.88	19,268.96	56,684.92	74.63
Approved Total (Overridden) (S\$)		16,500.00		
Nett Amount (S\$)	75,953.88	16,500.00	59,453.88	78.28
+ Loss of Use (18.0 x S\$40.00/day) (S\$)		720.00		
+ Car Rental (18.0 x S\$105.93/day) (S\$)		1,906.74		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		19,133.74		

INSPECTION

Date of Assignment:	29/05/2019	
Date Inspected:	30/05/2019 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	12.0 days	

Adjuster: ONG HWEE JIE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2019)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4471L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*QUARTER GLASS RR/RH (DISC 25%)	Damaged	846.50 F	*634.88 F
2	1		*END PANEL (DISC 25%)	Damaged	602.10 F	*451.58 F
3	2		*REINFORCEMENT ,RR (DISC 25%)	Damaged	69.20 F	*51.90 F
4	1		*TAIL LAMP BRACKET ,LH (DISC 25%)	Damaged	30.70 F	*23.03 F
5	1		*FENDER RR/LH (DISC 25%)	Damaged	766.80 F	*575.10 F
6	1		*LID ASSY ,FULE (DISC 25%)	Damaged	102.00 F	*76.50 F
7	1		*QUARTER GLASS RR/LH (DISC 25%)	Damaged	168.10 F	*126.08 F
8	1		*TAIL LAMP BRACKET ,RH (DISC 25%)	Damaged	30.70 F	*23.03 F
9	1		*FENDER RR/RH (DISC 25%)	Damaged	766.80 F	*575.10 F
10	2		*DUCT ASSY ,QUARTER (DISC 25%)	Damaged	140.80 F	*105.60 F
11	1		*BUMPER REAR (DISC 25%)	Damaged	458.60 F	*343.95 F
12	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
13	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Damaged	205.70 F	*154.28 F
14	1		*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Damaged	139.60 F	*104.70 F
15	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Damaged	139.60 F	*104.70 F
16	1		*BUMPER LIP COVER RR/LH (DISC 25%)	Damaged	72.20 F	*54.15 F
17	1		*BUMPER LIP COVER RR/RH (DISC 25%)	Damaged	118.10 F	*88.58 F
18	1		*BUMPER LIP REAR (DISC 25%)	Damaged	228.90 F	*171.68 F
19	1		*BUMPER SEAL ,RR LH (DISC 25%)	Damaged	88.90 F	*66.68 F
20	1		*BUMPER SEAL ,RR RH (DISC 25%)	Damaged	65.70 F	*49.28 F
21	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Damaged	94.80 F	*71.10 F
22	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Damaged	94.80 F	*71.10 F
23	1		*EXHAUST TAIL PIPE (DISC 25%)	Damaged	656.20 F	*492.15 F
24	2		*SUPPORT ,EXHAUST REAR (DISC 25%)	Damaged	67.20 F	*50.40 F
25	1		*TAILGATE ASY (DISC 25%)	Damaged	1,007.90 F	*755.93 F
26	1		*DAM ,BACK DOOR GLASS ADHESIVE NO.1 (DISC 25%)	Damaged	27.30 F	*20.48 F
27	1		*TAIL GATE DOOR GLASS MOULDING LH (DISC 25%)	Damaged	29.40 F	*22.05 F
28	1		*TAIL GATE DOOR GLASS MOULDING RH (DISC 25%)	Damaged	29.40 F	*22.05 F
29	1		*MOULDING BACK WINDOW LOWER NO.1 (DISC 25%)	Damaged	29.40 F	*22.05 F
30	1		*DAM ,BACK DOOR GLASS ADHESIVE NO.2(DISC 25%)	Damaged	17.40 F	*13.05 F
31	1		*MOULDING BACK WINDOW LOWER NO.2 (DISC 25%)	Damaged	29.40 F	*22.05 F
32	1		*MOULDING BACK WINDOW ,OUTSIDE LH (DISC 25%)	Damaged	29.40 F	*22.05 F
33	1		*MOULDING BACK WINDOW ,OUTSIDE RH (DISC 25%)	Damaged	29.40 F	*22.05 F
34	1		*TAILGATE LOWER WINDOW GLASS (DISC 25%)	Damaged	721.30 F	*540.98 F
35	1		*TAILGATE OUTSIDE GARNISH (DISC 25%)	Damaged	504.90 F	*378.68 F
36	1		*EMBLEM REAR (DISC 25%)	Damaged	60.30 F	*45.23 F
37	1		*NAME PLATE (HYBRID) (DISC 25%)	Damaged	51.90 F	*38.93 F
38	1		*NAME PLATE (PRIUS) (DISC 25%)	Damaged	60.80 F	*45.60 F
39	1		*NAME PLATE (TOYOTA) (DISC 25%)	Damaged	51.90 F	*38.93 F
40	1		*SPOILER REAR (DISC 25%)	Damaged	953.70 F	*715.28 F
41	1		*END PANEL COVER DECK TRIM HOLE (DISC 25%)	Damaged	46.10 F	*34.58 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*END PANEL COVER DECK TRIM RR (DISC 25%)	Damaged	121.10 F	*90.83 F
43	1		*MEMBER SUB-ASSY ,RR LH (DISC 25%)	Damaged	174.10 F	*130.58 F
44	1		*FLOOR PANEL RR/LH (DISC 25%)	Damaged	102.00 F	*76.50 F
45	1		*BOX ,DECK FLOOR ,RR (DISC 25%)	Damaged	649.70 F	*487.28 F
46	1		*BOX RR FLOOR ,BOARD (DISC 25%)	Damaged	679.60 F	*509.70 F
47	1		*BOARD ASSY ,RR RH (DISC 25%)	Damaged	379.20 F	*284.40 F
48	1		*BOX ,DECK FLOOR ,LH (DISC 25%)	Damaged	196.80 F	*147.60 F
49	1		*COVER ASSY ,TONNEAU (DISC 25%)	Damaged	602.10 F	*451.58 F
50	1		*PROTECTOR ,SPARE (DISC 25%)	Damaged	143.70 F	*107.78 F
51	1		*CARRIER ,SPARE (DISC 25%)	Damaged	19.70 F	*14.78 F
52	1		*PANEL ASSY ,DECK LH (DISC 25%)	Damaged	307.00 F	*230.25 F
53	1		*GARNISH SIDE UPPER,LHR (DISC 25%)	Damaged	261.70 F	*196.28 F
54	1		*TROUGH ,BACK DOOR LH (DISC 25%)	Damaged	110.90 F	*83.18 F
55	1		*FENDER LINER RR/LH (DISC 25%)	Damaged	141.30 F	*105.98 F
56	1		*UNDER COVER SUB-ASSY ,RR FLOOR (DISC 25%)	Damaged	514.50 F	*385.88 F
57	1		*EXHAUST HEAT SHIELD ,REAR (DISC 25%)	Damaged	107.40 F	*80.55 F
58	1		*TAILGATE DOOR HINGE LH/RH (DISC 25%) (2 PCS)	Damaged	116.60 F	*87.45 F
59	1		*TAILGATE DOOR LOCK (DISC 25%)	Damaged	444.10 F	*333.08 F
60	1		*TAILGATE DOOR WEATHERSTRIP (DISC 25%)	Damaged	353.40 F	*265.05 F
61	1		*TAILGATE TRIM ,LOWER (DISC 25%)	Damaged	180.70 F	*135.53 F
62	1		*TAILGATE ,BOARD ASSY (DISC 25%)	Damaged	246.90 F	*185.18 F
63	1		*3RD BRAKE LAMP (DISC 25%)	Damaged	231.30 F	*173.48 F
64	1		*TAIL LAMP LH (DISC 10%)	Damaged	548.40 F	*493.56 F
65	1		*TAIL LAMP RH (DISC 10%)	Damaged	557.80 F	*502.02 F
66	1		*ANTENNA ,ELECTRICAL LOWER REAR (DISC 10%)	Damaged	157.40 F	*141.66 F
67	1		*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F
68	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
69	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
70	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
71	1		*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F
72	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
73	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
74	1		*SENSOR REVERSE (SN)	Necessary	180.00 F	*180.00 F
75	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
76	3		*SEALANT W/SCREEN (SN)	Necessary	111.00 F	*111.00 F
77	1		*NUMBER PLATE (SN)	Necessary	15.00 F	*15.00 F
78	1		*NUMBER PLATE FRAME (SN)	Necessary	12.00 F	*12.00 F
79	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
80	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
81	1		*BATTERY (SN)	Necessary	278.00 F	*278.00 F
82	3		*SEALANT SIKAFLEX (SN)	Necessary	111.00 F	*111.00 F
83	1		*ROOF PANEL	Not Necessary	1,102.80 F	*- F
84	1		*ROOF LINING ASSY	Not Necessary	1,877.60 F	*- F
85	1		*MLDG DRIP LH ROOF	Not Necessary	78.80 F	*- F
86	1		*END PANEL COVER ,DECK TRIM HOLE	Not Necessary	46.10 F	*- F
87	1		*END PANEL COVER ,DECK TRIM RR	Not Necessary	121.10 F	*- F
88	1		*SPARE TYRE PANEL	Not Necessary	667.70 F	*- F
89	1		*MEMBER SUB-ASSY ,RR LH	Not Necessary	174.10 F	*- F
90	1		*MEMBER SUB-ASSY ,RR RH	Not Necessary	174.10 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1		*MEMBER SUB ASSY ,REAR FLOOR CROSS NO.1	Not Necessary	436.40 F	*- F
92	1		*MEMBER SUB ASSY ,REAR FLOOR CROSS NO.2	Not Necessary	655.70 F	*- F
93	1		*BRACE SUB-ASSY ,REAR SUSPENSION	Not Necessary	307.00 F	*- F
94	1		*FLOOR PANEL RR/LH	Not Necessary	102.00 F	*- F
95	1		*FLOOR PANEL RR/RH	Not Necessary	209.90 F	*- F
96	1		*BOX ,DECK FLOOR ,RR	Not Necessary	649.70 F	*- F
97	1		*BOX ,RR FLOOR BOARD	Not Necessary	679.60 F	*- F
98	1		*BOARD ,RR FLOOR	Not Necessary	392.30 F	*- F
99	1		*BOARD ASSY ,RR RH	Not Necessary	379.20 F	*- F
100	1		*SPACER ,RR FLOOR	Not Necessary	130.60 F	*- F
101	1		*BOX ,DECK FLOOR COVER LH	Not Necessary	230.10 F	*- F
102	1		*BOX ,DECK FLOOR ,LH	Not Necessary	196.80 F	*- F
103	1		*COVER ASSY ,TONNAU	Not Necessary	602.10 F	*- F
104	1		*CUSHION ,SPARE WHEEL	Not Necessary	230.80 F	*- F
105	1		*PROTECTOR ,SPARE	Not Necessary	143.70 F	*- F
106	1		*CARRIER ,SPARE	Not Necessary	19.70 F	*- F
107	1		*TYRE	Not Necessary	126.74 F	*- F
108	1		*WHEEL ,DISC	Not Necessary	1,490.20 F	*- F
109	1		*CAP SUB-ASSY ,WHEEL	Not Necessary	174.10 F	*- F
110	1		*BREAKDOWN SIGN	Not Necessary	35.00 F	*- F
111	1		*PANEL ASSY ,DECK LH	Not Necessary	307.00 F	*- F
112	1		*PANEL ASSY ,DECK RH	Not Necessary	307.00 F	*- F
113	1		*GARNISH SIDE UPPER ,LHR	Not Necessary	261.70 F	*- F
114	1		*BATTERY	Not Necessary	278.00 F	*- F
115	1		*BATTERY ASSY HV	Not Necessary	5,544.40 F	*- F
116	1		*BATTERY CLAMP	Not Necessary	16.10 F	*- F
117	1		*BATTERY TRAY	Not Necessary	42.80 F	*- F
118	1		*WIRE ,FRAME	Not Necessary	1,680.90 F	*- F
119	1		*WIRE ,ENGINE NO.3	Not Necessary	74.00 F	*- F
120	1		*WIRE ,FLOOR	Not Necessary	1,675.00 F	*- F
121	1		*WIRE ,FLOOR ,NO.2		1,305.40 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
122	1		*RECEIVER ,DOOR CONTROL	Not Necessary Not Necessary	239.70 F	*- F
123	1		*PANEL SUB-ASSY ,QTR	Not Necessary	326.70 F	*- F
124	1		*PANEL SUB-ASSY ,QTR	Not Necessary	588.40 F	*- F
125	1		*PANEL SUB-ASSY ,QTR WHEEL HOUSE	Not Necessary	588.40 F	*- F
126	1		*PANEL QUARTER WHEEL HOUSE ,OUTER LH	Not Necessary	326.70 F	*- F
127	1		*REINFORCE ,ROOF SIDE OUTER LH	Not Necessary	91.90 F	*- F
128	1		*REINFORCEMENT ,BACK DOOR SIDE LH	Not Necessary	89.50 F	*- F
129	1		*REINFORCEMENT ,ROOF SIDE INNER LH	Not Necessary	60.30 F	*- F
130	1		*PANEL ROOF SIDE OUTER LH	Not Necessary	134.80 F	*- F
131	1		*PANEL ROOF SIDE /LH SIDE	Not Necessary	134.80 F	*- F
132	1		*PANEL ROOF SIDE INNER LH	Not Necessary	134.80 F	*- F
133	1		*RAIL ROOF SIDE LH	Not Necessary	273.60 F	*- F
134	1		*TROUGH BACK DOOR LH	Not Necessary	110.90 F	*- F
135	1		*FENDER LINER RR/LH	Not Necessary	141.30 F	*- F
136	1		*CABLE SUB-ASSY ,FUEL LID	Not Necessary	63.90 F	*- F
137	1		*RETAINER ,FUEL LID CABLE	Not Necessary	5.90 F	*- F
138	1		*CAP ASSY ,FUEL TANK	Not Necessary	68.10 F	*- F
139	1		*PIPE SUB-ASSY ,FUEL NECK	Not Necessary	230.80 F	*- F
140	1		*TUBE ,FUEL TANK	Not Necessary	36.10 F	*- F
141	1		*TANK SUB-ASSY ,FUEL	Not Necessary	745.10 F	*- F
142	1		*TYRE	Not Necessary	126.74 F	*- F
143	1		*TROUGH ,BACK DOOR	Not Necessary	110.90 F	*- F
144	1		*FENDER LINER RR/RH	Not Necessary	141.30 F	*- F
145	1		*HINGE UPPER LHR ,DOOR	Not Necessary	81.70 F	*- F
146	1		*HINGE LOWER LHR ,DOOR	Not Necessary	72.20 F	*- F
147	1		*CHECK ASSY ,RR DOOR	Not Necessary	150.30 F	*- F
148	1		*DOOR LOCK STRIKER	Not Necessary	40.50 F	*- F
149	1		*DOOR LOCK RR/LH	Not Necessary	709.30 F	*- F
150	1		*HINGE LOWER RHR ,DOOR	Not Necessary	52.00 F	*- F
151	1		*HINGE UPPER RHR DOOR		81.70 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
152	1		*CHECK ASSY ,RR DOOR	Not Necessary	150.30 F	*- F
153	1		*DOOR LOCK RR/RH	Not Necessary	709.30 F	*- F
154	1		*DOOR LOCK STRIKER	Not Necessary	40.50 F	*- F
155	1		*UNDER COVER SUBASSY RR FLOOR	Not Necessary	514.50 F	*- F
156	1		*EXHAUST HEAT SHIELD REAR	Not Necessary	107.40 F	*- F
157	1		*EXHAUST PIPE FRT	Not Necessary	4,184.70 F	*- F
158	1		*SUPPORT EXHAUST PIPE ,NO 4	Not Necessary	40.30 F	*- F
159	2		*TAILGATE DOOR HINGE LH/RH	Not Necessary	58.30 F	*- F
160	1		*TAILGATE DOOR LOCK	Not Necessary	444.10 F	*- F
161	1		*TAILGATE DOOR STAY LH	Not Necessary	241.50 F	*- F
162	1		*TAILGATE DOOR STAY RH	Not Necessary	241.50 F	*- F
163	1		*TAILGATE DOOR WEATHERSTRIP	Not Necessary	353.40 F	*- F
164	1		*TAILGATE LOCK COVER	Not Necessary	15.70 F	*- F
165	1		*STRIKER BACK DOOR	Not Necessary	48.90 F	*- F
166	1		*TAILGATE TRIM LH	Not Necessary	85.90 F	*- F
167	1		*TAILGATE TRIM LOWER	Not Necessary	180.70 F	*- F
168	1		*TAILGATE TRIM RH	Not Necessary	88.30 F	*- F
169	1		*TAILGATE TRIM UPPER	Not Necessary	49.60 F	*- F
170	1		*TAILGATE BOARD ASSY	Not Necessary	246.90 F	*- F
171	1		*WIRE ,BACK DOOR NO.1	Not Necessary	582.40 F	*- F
172	1		*MOTOR ASSY ,RR WIPER	Not Necessary	734.60 F	*- F
173	1		*CAMERA ASSY ,TELEVISION RR	Not Necessary	1,436.60 F	*- F
174	1		*SWITCH ASSY ,BACK DOOR OPENER	Not Necessary	146.10 F	*- F
175	1		*LICENSE PLATE LAMP	Not Necessary	35.70 F	*- F
176	1		*3RD BRAKE LAMP	Not Necessary	231.30 F	*- F
177	1		*WHEEL DISC	Repair	1,490.20 F	*- F
178	1		*DOOR RR/LH	Repair	954.50 F	*- F
179	1		*DOOR RR/RH	Repair	954.50 F	*- F
180	1		*SOLAR FILM (SN)	Necessary	375.00 F	*375.00 F

F=Franchise part.

Total Parts (\$\$) 61,650.88 14,338.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	2,873.00	1,980.00
2	SPRAY PAINT	New	8,064.00	2,300.00
3	TOWING CHARGE	New	126.00	90.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	40.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	30.00
8	TO REMOVE/REFIT SEAT	New	120.00	40.00
9	TO ALING CHASSIS	New	350.00	0.00
10	TO REMOVE & REFIT FUEL TANK	New	120.00	0.00
11	TO REMOVE & REFIT EXHAUST	New	120.00	40.00
12	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
13	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	50.00
14	TO REST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	30.00
15	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	30.00
16	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	20.00
17	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	100.00
18	TO REMOVE AND REFIX REAR WINDSCREEN	New	240.00	80.00
19	TO REMOVE & REFIT ROOF LINING	New	120.00	0.00
20	TO REMOVE & REFIT REAR QUARTER GLASS RH	New	120.00	40.00
21	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	40.00
22	TO REMOVE AND REFIT WIRE HARNESS	New	300.00	0.00
23	TO REPLACE SUNDRY PARTS	New	100.00	0.00
24	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			14,303.00	4,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >