Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CC6/III19009461/AEA3Q2 Our File No:

Date: 16/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015 Claimant SKD8730Y Insured Vehicle No: SHC8931A

Vehicle No:

Date of Loss: 25/05/2019 Nature of Claim: TP Claim No: MCT19050706

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKD8730Y Reg No:

Make & Model: TOYOTA VIOS, 1.5 E (M) Engine No: 1NZY450511

Chassis No: Reg. Date: 16/01/2012 (Man. Year: 2011) MR053HY9305283596

Colour: Odometer: 194037 km Silver

Engine Capacity: 1497 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: No Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15 Rear Left Side: Front Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,383.27	2,794.07	589.20	17.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	2,000.00	1,090.00	35.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,473.27	4,794.07	1,679.20	25.94
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	6,473.27	3,800.00	2,673.27	41.30
+ GST 7.00/7.00% (S\$)	453.13	266.00	187.13	41.30
Nett Amount (S\$)	6,926.40	4,066.00	2,860.40	41.30
+ Loss of Use (7.0 x S\$10	00.00/day) (S\$)	700.00		
Ne	tt Liability (S\$)	4.766.00		

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 28/05/2019 Inspected At: Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 7.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jan 2020)

Parts: 143 TOYOTA VIOS 1.5 E (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKD8730Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	407.50 FL	*407.50 FL
2	1		*REAR BUMPER BRACKET	O/S Bent	127.40 FL	*63.70 FL
3	1		*REAR BUMPER RETAINER RH	Necessary	92.30 FL	*92.30 FL
4	1		*REAR BUMPER RETAINER RH (SMALL)	Not Necessary	28.40 FL	*- FL
5	1		*REAR BUMPER REFLECTOR -RH	Cracked	82.80 FL	*82.80 FL
6	1		*BOOT LID	Buckled	584.80 FL	*584.80 FL
7	1		*BOOT LID LOGO	Necessary	50.80 FL	*50.80 FL
8	1		*BOOT LID VIOS EMBLEM	Necessary	44.20 FL	*44.20 FL
9	1		*BOOT LID E EMBLEM	Necessary	34.40 FL	*34.40 FL
10	2		*BOOT LID HINGE	Not Necessary	95.80 FL	*- FL
11	1		*BOOT LID LOCK	Not Necessary	95.80 FL	*- FL
12	1		*BOOT LID LOCK CHECKER	Not Necessary	24.80 FL	*- FL
13	1		*BOOT LID RUBBER	Cut	175.30 FL	*175.30 FL
14	1		*REAR FENDER TRIM RH	Not Necessary	224.20 FL	*- FL
15	1		*TAIL LAMP -RH	Cracked	409.90 FL	*325.00 FL
16	1		*REAR PANEL	Dented	571.80 FL	*571.80 FL
17	1		*REAR PANEL TRIM	Deformed	200.70 FL	*200.70 FL
18	1		*SPARE TYRE COVER	Torn	144.70 FL	*144.70 FL
19	1		*SPARE TYRE PANEL RH SPONGE	Deformed	214.10 FL	*214.10 FL
20	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
21	1		*L PLATE	Bent	50.00 FS	*50.00 FS
22	2		*L PLATE BRACKET	Necessary	70.00 FS	*40.00 FS
23	1		*SET REAR BUMPER STICKER	Necessary	195.00 FS	*195.00 FS
24	1		*BOOT LID NUMBER PLATE 292 STICKER	Necessary	35.00 FS	*35.00 FS
25	1		*SET REAR FENDER TRIM CLIPS RH	Not Necessary	48.00 FS	*- FS
26	1		*REAR FENDER STICKER RH	Necessary	190.00 FS	*190.00 FS
27	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
F=Fra	ınchise	part. S=Spcl	Nett. L=ListItemDisc.			
Sub Total (S\$)			4,285.70	3,542.10		
	- List Item Discount on L Items 25.00/25.00% (S\$)			902.43	748.03	
				Total Parts (S\$)	3,383.27	2,794.07
				Total Parts (5\$)	3,303.21	2,794.07

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	30.00
2	TO REPLACE STICKERS	New	80.00	50.00
3	TO SPRAY UNDERSEAL	New	180.00	60.00
4	(REAR) TO SPRAY PAINTING	New	1,300.00	1,000.00
5	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTION FOR CUTTING/WELDING WORKS	New IS ,AND	1,300.00	800.00
6	TO REMOVE AND REFIX INNER TRIM	New	180.00	60.00
	Gross Labour Cost (S\$)		3,090.00	2,000.00
	Report was unsubmitte	ed during this print-out.		

< END OF ESTIMATES >